

15/02/2018

INS. CASE OWNER:

Ypntmka

CCY / AXA1900

1202, PI 9.2352

LKK:  
IDAC:

Surveyor:

21

DOI:

ASSIGNMENT  
28/2/19

Date / Time :

21/1/19.

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SKO 97MYS

Claim No. :

SAMOLA 21/ 90056

Name of Insured :

TRANS-17B SIKRMS RW

Policy No. :

VPT / P1680520

Insured Tel No. :

HP:

011/1111

Make / Model :

WIKOUBT

Excess Sec II :SS

D.O.A :

011/1111

Place of Accident :

PIE TMS BKE

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident :

If NO. Driver Name / Age :

TAN TIAM SIEW

OI GIA REPORT: YES / NO

YES / NO : TP GIA REPORT (YES / NO)

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SKM 66610



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

MOVA



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/ Time	STAGE	DATE / PIC
21/1/19	SKM 66610 - X	SKO 97MYS - X
21/1/19	Sumit Drim	
21/2	LOI send	
21/6	Rec WOR sent to TP ( Pending LOI in )	
24/6	LOI in via email ( Seek mandate IA, Pending approval ) - Approved @ Ek Call-in offer CTS \$2000 ( Pending acceptance )	
30/7	TP reject offer. counter propose \$2554.49. seek AXA instruction.	
6/8/19	AXA approved \$2000. offer TP CTS \$2000.00 ( Pending acceptance )	
8/8/19	TP reject offer. counter proposed \$2554.49. ( Pending approval from AXA )	
9/8	AXA maintain offer of \$2000 - ( Pending acceptance ) - TP reject, counter propose \$2500 - TP	
11/8	AXA instruct to maintain & to highlight to TP	
PRELIMINARY ADVICE	Date/Time: Sent By:	Confirm by: KAMM

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: US	SS 2100.00	( 3 days ) Reduction: \$101E - 38 % 333	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 14/1/2020	Confirm with: KAMM	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	( Agreed / Assessed ) BOLA S/N No. 27	If NO or B 28. Ass. Lia :
Repair Cost: (W/EST)	SS 2247.00		01 rear wheel TP.
Loss of Rental (LOR):	SS	( days )	
Loss of Use (LOU):	SS 240.00	( \$ 80 x 3 days )	
Loss of Income (LOI):	SS	( \$ x days )	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[ Tick only one ]	
GLA/LTA Search	SS 7.49		
Medical:	SS		
Disbursement:	SS	( e.g. Tow / Independent )	
Legal Cost	SS		
Total:	SS 2447.49	Global Sum SS: 2400.00	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 2400.00	Name 1: MOVA Automotive PE Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT 16/01/2020

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$350.00

✓ GMA







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19001302/pb3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 21-01-2019	
		Code : ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHD 9234S	Veh. Inspected	SKM 6661D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/01/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	16/01/2019	Inspection Date	
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Celia

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
Assessment number: CK133815  
Version: 1712  
Date calculated: 01/18/2019 05:27 PM

Full Report  
Registration: SKM6661D  
Printed: 01/18/2019 5:27 PM

### Summary Information

Claim Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Tan SG	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-16
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

Vehicle Manufacturer:	HONDA	
Model:	CIVIC (FD)	
Sub Model:	SPORT	
Model Sheet Number:	35 48 23	
Registration:	SKM6661D	
VIN number:		
Odometer:		
Model Specs		
FROM MODEL 2009	TWO COAT METALLIC	PREPARE OFF VEHICLE

### Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
71501-SNB	RENEW REAR BUMPER		3.0	13.50
34105-SNB	R + R L/NUMBER PLATE LAMP		1.0	4.50
33551-SNB)	R + R L/OUTER TAILLAMP		4.0	18.00
33501-SNB)	R + R R/OUTER TAILLAMP		4.0	18.00
34156-SNB)	R + R L/INNER TAILLAMP		1.0	4.50
34151-SNB)	R + R R/INNER TAILLAMP		1.0	4.50
84620-SNB	R + R LOWER TAILGATE TRIM		2.0	9.00
74890-SNB	R + R BOOTLID MOULDING		1.0	4.50
74851-SNA)	R + R BOOTLID LOCK		2.0	9.00
74861-SNB)	R + R BOOTLID LOCK CYLINDER		2.0	9.00
74862-SE3	R + R BOOTLID STRIKER PIN		2.0	9.00
2711	REAR PANEL CPL REPAIR		60.0*	270.00
2931	BOOTLID REPAIR		40.0*	180.00

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: CK133815  
 Version: 1712  
 Date calculated: 01/18/2019 05:27 PM

Full Report  
 Registration: SKM6661D  
 Printed: 01/18/2019 5:27 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	12.30	123.0	553.50
<b>Total of Labour</b>			<b>553.50</b>

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	13.0
	REAR PANEL CPL REPAIR PAINTING <50%	11.0
	BOOTLID REPAIR PAINTING <50%	17.0

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	64.94
2711	REAR PANEL CPL REPAIR PAINTING <50%	12.92
2931	BOOTLID REPAIR PAINTING <50%	28.42

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		41.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>71.0</b>	<b>319.50</b>

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	64.94
Repair Painting	41.34
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>143.88</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER ✓	71501SNNE01ZZ			950.00 ✓
2619	L/R BUMPER BRACKET	71598SNAA01	Xsu		25.00
2620	R/R BUMPER BRACKET	71593SNAA01	Xsu		25.00

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: CK133815  
 Version: 1712  
 Date calculated: 01/18/2019 05:27 PM

Full Report  
 Registration: SKM6661D  
 Printed: 01/18/2019 5:27 PM

Code	Description	Part Number	Supplier	Price SGD
2621	L/R INN BUMPER BRKT	71540SNAA00	? } Xsu	15.00
2622	R/R INN BUMPER BRKT	71540SNAA00	? } Xsu	15.00
2650	RR BUMPER CLAMP KIT	u/		40.00 ✓
2665	MOUNTING CLAMP	91503SZ3003	X } Xsu	0.00
2666	MOUNTING CLAMP	91505S9A003	X } Xsu	0.00
2981	REAR LOCK CYL	74861SNB003	X } Xsu	0.00
3361	L/NO. PLATE LAMP	34105SNB003	X } Xsu	0.00
1000	REAR BMP LWR	REAR BMP LWR	? } de	450.00 ✓
1002	TYPE R LOGO	TYPE R LOGO	X an	90.00
				0.00
f: OEM Parts	<b>Savings</b>			
n: Non-OEM Parts	<b>Subtotal</b>			1,610.00
u: Used parts	<b>Addition(+15.00%)</b>			241.50
	<b>Total</b>			<b>1,851.50</b>

**Extras**

Code	Description	Price SGD
1001	REAR PARKG SENSOR ? nu /	200 250.00* ✓
	<b>Total Extras</b>	<b>250.00</b>

Handwritten calculations:

$$P = 1656.00$$

$$S/N = 200.00$$

$$L = 780.87$$

$$T = 2636.87$$

$$L/S = 2109.50 (50/100)$$

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: CK133815  
 Version: 1712  
 Date calculated: 01/18/2019 05:27 PM

**Full Report**  
**Registration: SKM6661D**  
**Printed: 01/18/2019 5:27 PM**

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,610.00	
Addition(+15.00%)	241.50	
<b>Total Parts</b>		<b>1,851.50</b>
<b>Labour Time Base 10 WU/h</b>		
Total 123.0 WU X 45.00 SGD/h	553.50	364.50
<b>Total of Labour</b>		<b>553.50</b>
<b>Total Of Extras</b>		<b>250.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 71.0 WU X 45.00 SGD/h	319.50	279
Material Cost	143.88	137.37
<b>Total Paint Including Material</b>		<b>463.38</b>
<b>Repair Cost Excludes GST</b>		<b>3,118.38</b>
GST (+7.0%)		218.29
<b>Repair Cost Included GST</b>		<b>3,336.67</b>

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

*Resu*  
*4p 20010068*  
*3 days*  
*4s*  
*27/02/19 @ 1300*  
*Resu after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature:  
 Date:

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: CK133815  
 Version: 1810  
 Date calculated: 20/06/2019 11:54 AM

Full Report  
 Registration: SKM6661D  
 Printed: 20/06/2019 11:54 AM

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	13.0
	REAR PANEL CPL REPAIR PAINTING <50%	11.0
	BOOTLID SURFACE PAINT	8.0

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	64.94
2711	REAR PANEL CPL REPAIR PAINTING <50%	12.92
2931	BOOTLID SURFACE PAINT	21.91

**Labour Cost - Paint**

Factor	45.00 SGD/h	Hrs	WU	Price SGD
Time Paint			32.0	
Preparation Main Work Metal		2.50	25.0	112.50
Preparation Comp. Work Plastic		0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>6.20</b>	<b>62.0</b>	<b>279.00</b>

**Material Cost - Paint**

	Price SGD
New Part Painting - Plastic K1R	64.94
Repair Painting	12.92
Surface-/Blend Paint	21.91
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>137.37</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER	71501SNNE01ZZ			950.00
2650	RR BUMPER CLAMP KIT				40.00
2665	MOUNTING CLAMP	91503SZ3003		1440	0.00
2666	MOUNTING CLAMP	91505S9A003			0.00
3361	L/NO. PLATE LAMP	34105SNB003			0.00
1000	REAR BMP LWR	REAR BMP LWR			450.00

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

**Claim Reference:**  
**Assessment number: CK133815**  
**Version: 1810**  
**Date calculated: 20/06/2019 11:54 AM**

**Full Report**  
**Registration: SKM6661D**  
**Printed: 20/06/2019 11:54 AM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Tan SG	Currency:	SGD
Claim Reference:		Date of Incident:	16/01/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer: HONDA  
 Model: CIVIC (FD)  
 Sub Model: SPORT  
 Model Sheet Number: 35 48 23  
 Registration: SKM6661D  
 VIN number:  
 Odometer:

**Model Specs**

FROM MODEL 2009      TWO COAT METALLIC      PREPARE OFF VEHICLE

**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
71501-SNB	RENEW REAR BUMPER		3.0	13.50
34105-SNB	R + R L/NUMBER PLATE LAMP		1.0	4.50
33551-SNB)	R + R L/OUTER TAILLAMP		4.0	18.00
33501-SNB)	R + R R/OUTER TAILLAMP		4.0	18.00
34156-SNB)	R + R L/INNER TAILLAMP		1.0	4.50
34151-SNB)	R + R R/INNER TAILLAMP		1.0	4.50
84620-SNB	R + R LOWER TAILGATE TRIM		2.0	9.00
74890-SNB	R + R BOOTLID MOULDING		1.0	4.50
74851-SNA)	R + R BOOTLID LOCK		2.0	9.00
74862-SE3	R + R BOOTLID STRIKER PIN		2.0	9.00
2711	REAR PANEL CPL REPAIR		60.0*	270.00
<b>Labour Cost</b>			<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>			<b>8.10</b>	<b>81.0</b>
<b>Total of Labour</b>				<b>364.50</b>

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: CK133815  
 Version: 1810  
 Date calculated: 20/06/2019 11:54 AM

Full Report  
 Registration: SKM6661D  
 Printed: 20/06/2019 11:54 AM

Code	Description	Part Number	Supplier	Price SGD
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			1,440.00
u: Used parts	<b>Addition(+15.00%)</b>			216.00
	<b>Total</b>			1,656.00

**Extras**

Code	Description	Price SGD
1001	REAR PARKG SENSOR <i>S/W</i>	200.00*
	<b>Total Extras</b>	200.00

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,440.00	
<i>Addition(+15.00%)</i>	216.00	
<b>Total Parts</b>		1,656.00
<b>Labour Time Base 10 WU/h</b>		
Total 81.0 WU X 45.00 SGD/h	364.50	
<b>Total of Labour</b>		364.50
<b>Total Of Extras</b>		200.00
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 62.0 WU X 45.00 SGD/h	279.00	
Material Cost	137.37	
<b>Total Paint Including Material</b>		416.37
<b>Repair Cost Excludes GST</b>		2,636.87
GST (+7.0%)		184.58
<b>Repair Cost Included GST</b>		2,821.45

*Parts \$1440 cost 15%  
 \$1656 ✓  
 Sn \$200  
 Labour \$364.50 ✓  
 Paint \$279.00  
 material \$137.37*

*total \$2636.87 - 20% = 2109.50*

*L/S \$2100 30 DAYS*

*—#*

**MOVA Automotive Pte Ltd  
Blk 1008, Bukit Merah Lane  
3, #01-04/06/08. Singapore  
159722**

**Claim Reference:**

**Assessment number: CK133815**

**Version: 1810**

**Date calculated: 20/06/2019 11:54 AM**

**Full Report**

**Registration: SKM6661D**

**Printed: 20/06/2019 11:54 AM**

---

**Comments**

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

**Claim Reference:**  
**Assessment number: CK133815**  
**Version: 1712**  
**Date calculated: 01/18/2019 05:27 PM**

**Full Report**  
**Registration: SKM6661D**  
**Printed: 01/18/2019 5:27 PM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Tan SG	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-16
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer: HONDA  
 Model: CIVIC (FD)  
 Sub Model: SPORT  
 Model Sheet Number: 35 48 23  
 Registration: SKM6661D  
 VIN number:  
 Odometer:

**Model Specs**

FROM MODEL 2009      TWO COAT METALLIC      PREPARE OFF VEHICLE

**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
71501-SNB	RENEW REAR BUMPER		3.0	13.50
34105-SNB	R + R L/NUMBER PLATE LAMP		1.0	4.50
33551-SNB)	R + R L/OUTER TAILLAMP		4.0	18.00
33501-SNB)	R + R R/OUTER TAILLAMP		4.0	18.00
34156-SNB)	R + R L/INNER TAILLAMP		1.0	4.50
34151-SNB)	R + R R/INNER TAILLAMP		1.0	4.50
84620-SNB	R + R LOWER TAILGATE TRIM		2.0	9.00
74890-SNB	R + R BOOTLID MOULDING		1.0	4.50
74851-SNA)	R + R BOOTLID LOCK		2.0	9.00
74861-SNB)	R + R BOOTLID LOCK CYLINDER		2.0	9.00
74862-SE3	R + R BOOTLID STRIKER PIN		2.0	9.00
2711	REAR PANEL CPL REPAIR ?		60.0*	270.00
2931	BOOTLID REPAIR X		40.0*	180.00

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: CK133815  
 Version: 1712  
 Date calculated: 01/18/2019 05:27 PM

Full Report  
 Registration: SKM6661D  
 Printed: 01/18/2019 5:27 PM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	12.30	123.0	553.50
<b>Total of Labour</b>			<b>553.50</b>

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR BUMPER NEW PART PAINT K1R	13.0
	REAR PANEL CPL REPAIR PAINTING <50%	11.0
	BOOTLID REPAIR PAINTING <50%	17.0

**Paint Material Per Part**

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	64.94
2711	REAR PANEL CPL REPAIR PAINTING <50%	12.92
2931	BOOTLID REPAIR PAINTING <50%	28.42

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		41.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>71.0</b>	<b>319.50</b>

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	64.94
Repair Painting	41.34
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>143.88</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
2583	REAR BUMPER 	71501SNNE01ZZ			950.00
2619	L/R BUMPER BRACKET	71598SNAA01	?		25.00
2620	R/R BUMPER BRACKET	71593SNAA01	?		25.00

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

Claim Reference:  
 Assessment number: CK133815  
 Version: 1712  
 Date calculated: 01/18/2019 05:27 PM

Full Report  
 Registration: SKM6661D  
 Printed: 01/18/2019 5:27 PM

Code	Description	Part Number	Supplier	Price SGD
2621	L/R INN BUMPER BRKT	71540SNAA00	?	15.00
2622	R/R INN BUMPER BRKT	71540SNAA00	?	15.00
2650	RR BUMPER CLAMP KIT	u /		40.00
2665	MOUNTING CLAMP	91503SZ3003	✓	0.00
2666	MOUNTING CLAMP	91505S9A003	✓	0.00
2981	REAR LOCK CYL	74861SNB003	✓	0.00
3361	L/NO. PLATE LAMP	34105SNB003	✓	0.00
1000	REAR BMP LWR	REAR BMP LWR	?	450.00
1002	TYPE R LOGO	TYPE R LOGO	✓	90.00
				0.00
	<b>Savings</b>			
	<b>Subtotal</b>			1,610.00
	<b>Addition(+15.00%)</b>			241.50
	<b>Total</b>			1,851.50

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

**Extras**

Code	Description	Price SGD
1001	REAR PARKG SENSOR ?	200 250.00*
	<b>Total Extras</b>	250.00

**MOVA Automotive Pte Ltd**  
**Blk 1008, Bukit Merah Lane**  
**3, #01-04/06/08. Singapore**  
**159722**

**Claim Reference:**  
**Assessment number: CK133815**  
**Version: 1712**  
**Date calculated: 01/18/2019 05:27 PM**

**Full Report**  
**Registration: SKM6661D**  
**Printed: 01/18/2019 5:27 PM**

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,610.00	
Addition(+15.00%)	241.50	
<b>Total Parts</b>		<b>1,851.50</b>
<b>Labour Time Base 10 WU/h</b>		
Total 123.0 WU X 45.00 SGD/h	553.50	
<b>Total of Labour</b>		<b>553.50</b>
<b>Total Of Extras</b>		<b>250.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 71.0 WU X 45.00 SGD/h	319.50	
Material Cost	143.88	
<b>Total Paint Including Material</b>		<b>463.38</b>
<b>Repair Cost Excludes GST</b>		<b>3,118.38</b>
GST (+7.0%)		<b>218.29</b>
<b>Repair Cost Included GST</b>		<b>3,336.67</b>

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

*Resul*  
*4p 90010068*  
*3 days*  
*4/3*  
*27/02/19 @ 1300*  
*Resy after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## ◀ Service Request Details

Claim

S9M01B29

Reference

None ✎

Loss Date

January 16, 2019

Request Date

January 21, 2019

Due Date

January 28, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*21/01/2019 @ 9:52am  
Suzanne veh not in.*

Actions

Next Step

Agree to perform service

Decline Work	Accept Work
--------------	-------------

### Vehicle Information

Incident Vehicle Registration #

SKM6661D

Make

TPVD HONDA

Service Address

...

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD  
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

LOH Cynthia  
6568804843  
cynthia.loh@axa.com.sg

Additional instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes



TYPE



SENT

1/21/19 9:10 AM

FROM

LOH Cynthia

SUBJECT

PROCEED DS / TP EXCESS \$5000

BODY

ID-H2R



## Catherine Chong (LKK Auto)

---

**From:** Nitha <nitha@mova.com.sg>  
**Sent:** Friday, 18 January, 2019 5:53 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** tanyw@mova.com.sg; 'Enny'  
**Subject:** TP CLAIMS - SKM6661D AGAINST SHD9234S DOA 16/01/19 AT PIE BEFORE BKE ENTARNCE  
**Attachments:** EST.pdf; GIA RPT.PDF  
**Categories:** SHEKHAR

Dear All,

REF : SHD9234S

Kindly assist to assign surveyor and revert officer in change for the above mention case.

Thank you.

Best Regards,  
Nitha  
Claims Officer  
Mova Automotive Pte Ltd  
Tel: 6272 3892 Fax: 6270 8314





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 26/06/2019

### Survey Details:

Date of loss	16-Jan-19
Date of appointment	21-Jan-19
Date of survey	27-Feb-19
Location of survey	MOVA AUTOMOTIVE PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SKM 6661D
Make and Model	HONDA CIVIC
Date of registration	15/6/2009
Excess	
Market Value	\$19,000
Parf Rebate	\$16,681
Nett Loss	\$2,319

### Repair details:

Initial Estimate	\$	3,118.38
------------------	----	----------

### Proposed/Revised repair cost:

Parts	\$	1,150.00
Check items (estimate)	\$	-
Labour	\$	780.87
<b>Total</b>	<b>\$</b>	<b>2,636.87</b>
<b>Lump Sum(if applicable)</b>	<b>\$</b>	<b>2,100.00</b>

Number of days for repair	3
---------------------------	---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

--

**Mandate:**

Liability(TP)		100%	
Proposed repair cost (W/GST)	\$	2,247.00	\$ -
Loss of use (3days x \$100)	\$	300.00	\$ -
Loss of rental		-	\$ -
Loss of income		-	\$ -
LTA search fees	\$	7.49	\$ -
Others		-	\$ -
<b>Proposed Total</b>	<b>\$</b>	<b>2,554.49</b>	<b>\$ -</b>

 <MANDATE IA> - S9M01B29 {ACCIDENT INVOLVING SHD 9234S(OI) & SKM 6661D(TP) ON 16/01/2019}

Type

 Question

Message

Liability: 100% Informed OI about TP claim and NCD issue. Agreed to settle at best. We seek your mandate at \$2554.49(claiming LOU). Mandate IA had already uploaded in Smartclaim. Kindly let us have your approval/instruction. Thank you. - Cecilia 26/06/2019

Reply

⏪ **Re:<MANDATE IA> - S9M01B29 {ACCIDENT INVOLVING SHD 9234S(OI) & SKM 6661D(TP) ON 16/01/2019}**

Type

🔔 Question

Message

Pls proceed to settle at \$2k all in.

Reply



**Re:RE: Re:RE: Re:<MANDATE IA> - S9M01B29  
{ACCIDENT INVOLVING SHD 9234S(OI) & SKM  
6661D(TP) ON 16/01/2019}**

Type

 Question

Message

Pls maintain stand.

Reply



**Re:RE: Re:RE: Re:RE: Re:RE: Re:RE: Re:<MANDATE IA> - S9M01B29 {ACCIDENT INVOLVING SHD 9234S(OI) & SKM 6661D(TP) ON 16/01/2019}**

Type

 Question

Message

Our offer is fair & reasonable, pls maintain stand and highlight to tp on net loss repair limit.

Reply



RE: Re:RE: Re:RE: Re:RE: Re:RE: Re:RE: Re:<MANDATE  
IA> - S9M01B29 {ACCIDENT INVOLVING SHD 9234S(OI)  
& SKM 6661D(TP) ON 16/01/2019}

Type

🔍 Question

Message

HI SAW THENG, TP REJECT OFFER, PROPOSE G/S \$2400.00, KINDLY LET US HAVE YOUR  
APPROVAL/INSTRUCTION. THANKS - CCL

Reply

Cecilia

**Workshop Address:** Blk 1008, Bukit Merah Lane 3  
# 01-04/06/08  
Singapore 159722



**"WITHOUT PREJUDICE"**

Your Ref : SHD9234S  
Our Ref : SKM6661D / T090419

Date : 14 January 2020

**LKK AUTO CONSULTANT PTE LTD**  
51, Ubi Avenue 1  
#01-25 Paya Ubi Industrial Park  
Singapore 408933.

ATTN : MOTOR CLAIMS DEPT

Dear Sir / Madam,

**ACCIDENT INVOLVING SLM6661D & SHD9234S ON 16/01/2019 ALONG PIE BEFORE BKE ENTRANCE**

We refer to the above.

Enclosed herewith are documents for your attention and actions.

Please issue payment in favor of **MOVA AUTOMOTIVE PTE LTD.**

If you have any enquiries, please contact us at 6272 3892 or alternatively:

1. Ms Enny, [enny@mova.com.sg](mailto:enny@mova.com.sg) for feedback, workshop & claims matters, Lawyer Cases and all Own Damages & Windscreen matters.
2. Ms Suanne Chiu, [suann@mova.com.sg](mailto:suann@mova.com.sg) for all Third Party matters.

Thank you.

**Note:** Enclosed tax invoice & discharge voucher.

Yours faithfully  
For Claims Manager  
Claims Department  
Tel: 62723892  
Fax: 627083149

# Tax Invoice

14/01/2020

AXA INSURANCE PTE LTD  
8 SHENTON WAY  
AXA TOWER #27-01  
SINGAPORE 068811

Attention :- **XA009**

Page # :- 1 133815

Veh # :- SKM6661D

Veh Model :- HONDA CIVIC

Tax # :- CK632365

JOB # :- T090419

ACC. Date :- 16/01/19

Terms :- C.O.D Days

Remarks :-

**Main Office:**

Mova Building  
No. 22, Jalan Klang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 100B,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
	Lump Sum Amount			2,100.00

E. &amp; O.E



AMOUNT S\$ 2,100.00

GST @ 7 % 147.00

AMOUNT DUE S\$ 2,247.00

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

AUTHORIZATION TO ACT

I, Lim Jian Ji. Bernard ("the third party claimant")  
of \_\_\_\_\_ (address),  
owner of SKM6661D (vehicle no.) hereby authorize  
MOVA AUTOMOTIVE PTE LTD  
("the workshop") to act for me with respect to my claim for  
repair costs and/or rental and/or loss of use ("claim") for my  
vehicle no. SKM6661D that was damaged pursuant to the  
accident which occurred on 16/01/19 (date) along  
PIE before BKE entrance (location)  
involving vehicle no/s SHD 9234S  
("the accident").

I further authorize the workshop to settle my above mentioned  
claim in a manner that they deem fit and the workshop is further  
authorized to receive payment further to settlement of my claim  
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach  
on my behalf is on a without prejudice and without admission of  
liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 4 day of 4 (month) 20 15 (year)

Signed by "the third party claimant"

Signed by "the workshop"  
(with chop)





The acceptance of this offer is without prejudice to any personal injury claim/insure's claim/expenses

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SHD 9234S (Insd veh)	Model:HONDA CIVIC TYPE R
	SKM 6661D (TP veh)	
Date of Accident/ Time:	16/01/2019	

Repair Estimate	: \$		
Final Repair Cost	: \$	2,247.00	( W/GST)
Loss of Use	: \$	240.00	03 days at \$ 80.00 per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$	7.49	
Others:	: \$		
	: \$		
Final Settlement Sum	: \$	2,400.00	GLOBAL SUM (ALL-IN)

Payee Name : MOVA AUTOMOTIVE PTE LTD

Is Third Party Workshop GIA Registered?  YES [ ] NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____(%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ <del>Yes</del> BOLA Scenario No: <u>27</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____(%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks:

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp  
 Name of Representative:  
 Date: 14/1/2020



MKB



Signature of Witness / Workshop stamp (if applicable)  
 Name of Witness:  
 Date: 14/1/2020

*[Handwritten signature]*

Signature of AXA's surveyor/representative:  
 Name of AXA's surveyor /Representative:  
 Date:

MOVA AUTOMOTIVE PTE LTD  
 Blk 100, 01-01, AERAH LANE 3  
 #01-04 (S) 159722  
 Tel: 62723892 Fax: 62708314  
 GST Reg No : M2-0088864-2



Automotive Pte Ltd

**Main Office:**

Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel: (65) 6476 3333  
Fax: (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**

Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel: (65) 6272 3892  
Fax: (65) 6270 8314

Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Tax Invoice

14/01/2020

AXA INSURANCE PTE LTD  
8 SHENTON WAY  
AXA TOWER #27-01  
SINGAPORE 068811

Page # :- 1 133815  
Veh # :- SKM6661D  
Veh Model :- HONDA CIVIC  
Tax # :- CK632365  
JOB # :- T090419  
ACC. Date :- 16/01/19  
Terms :- C.O.D Days  
Remarks :-

Attention :- XA009

No.	Description	Qty	U.Price	Amounts S\$
	Lump Sum Amount			2,100.00

E. & O.E

AMOUNT S\$	2,100.00
GST @ 7 %	147.00
AMOUNT DUE S\$	2,247.00

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

**Enquire Vehicle Insurer**

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SHD92345	16 Jan 2019 / 22:00:00	Successful	A12	AXA INSURANCE PTE LTD

Previous

OK



Re:RE: Re:RE: Re:RE: Re:RE: Re:RE: Re:RE: Re:<MANDATE  
IA> - S9M01B29 {ACCIDENT INVOLVING SHD 9234S(OI)  
& SKM 6661D(TP) ON 16/01/2019}

Type

📍 Question

Message

Your IA is \$2554.49 right? Please proceed at \$2,500 all in.

Reply

Workshop Address: Blk 1008, Bukit Merah Lane 3  
# 01-04/06/08  
Singapore 159722



**"WITHOUT PREJUDICE"**

Your Ref : SHD9234S  
Our Ref : SKM6661D / T090419

Date : 14 January 2020

LKK AUTO CONSULTANT PTE LTD  
51, Ubi Avenue 1  
#01-25 Paya Ubi Industrial Park  
Singapore 408933.

ATTN : MOTOR CLAIMS DEPT

Dear Sir / Madam,

**ACCIDENT INVOLVING SLM6661D & SHD9234S ON 16/01/2019 ALONG PIE  
BEFORE BKE ENTRANCE**

We refer to the above.

Enclosed herewith are documents for your attention and actions.

Please issue payment in favor of **MOVA AUTOMOTIVE PTE LTD.**

If you have any enquiries, please contact us at 6272 3892 or alternatively:

1. Ms Enny, [enny@moval.com.sg](mailto:enny@moval.com.sg) for feedback, workshop & claims matters, Lawyer Cases and all Own Damages & Windscreen matters.
2. Ms Suanne Chiu, [suann@moval.com.sg](mailto:suann@moval.com.sg) for all Third Party matters.

Thank you.

**Note:** Enclosed tax invoice & discharge voucher.

Yours faithfully  
For Claims Manager  
Claims Department  
Tel: 62723892  
Fax: 627083149

\*This is a computer generated letter and does not require a signature.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001302/R1ga3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN: CYNTHIA LOH

Date : 28-01-2020



Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 9234S	Veh. Inspected	SKM 6661D
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S9M01B29	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	21/01/2019

### 2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC TYPE R 2.0 M	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	FD21600578	Colour	BLACK
Odometer	187631	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	16/01/2019	Inspection Date	27/02/2019
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 6661D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER (WCP) (CONSISTENT)	DEFORMED	950.00	950.00
1	L/R BUMPER BRACKET (WCP) (CONSISTENT)	SERVICEABLE	25.00	-
1	R/R BUMPER BRACKET (WCP) (CONSISTENT)	SERVICEABLE	25.00	-
1	L/R INN BUMPER BRKT (WCP) (CONSISTENT)	SERVICEABLE	15.00	-
1	R/R INN BUMPER BRKT (WCP) (CONSISTENT)	SERVICEABLE	15.00	-
1	RR BUMPER CLAMP KIT (WCP) (CONSISTENT)	NECESSARY	40.00	40.00
1	MOUNTING CLAMP (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	MOUNTING CLAMP (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	REAR LOCK CYL (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	L/NO. PLATE LAMP (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	REAR BMP LWR (WCP) (CONSISTENT)	DEFORMED	450.00	450.00
1	TYRE R LOGO (WCP) (CONSISTENT)	NOT NECESSARY	90.00	-
	COST PLUS 15%		241.50	216.00
			1,851.50	1,656.00
<b>SPECIAL NETT ITEMS</b>				
1	REAR PARKG SENSOR (SN) (CONSISTENT)	NOT WORKING	250.00	200.00
			250.00	200.00
<b>LABOUR</b>				
	TOTAL LABOUR.		553.50	364.50
	PAINT WORK: LABOUR COST.		319.50	279.00
	PAINT WORK: MATERIAL COST.		143.88	137.37
			1,016.88	780.87
<b>GRAND TOTAL</b>			<b>3,118.38</b>	<b>2,636.87</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,100.00</b>

Report Ref No. CC4/ASM19001302/R1ga3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.