



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD	Ref : CC4/ASM19001302/R1ga3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811	Date : 28-01-2020
ATTN: SAW THENG	Code : ASM



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SHD 9234S	<b>Veh. Inspected</b>	SKM 6661D
<b>Policy No.</b>	VPX/P1680520	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S9M01B29	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SAW THENG	<b>Assign Date</b>	21/01/2019

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	HONDA CIVIC TYPE R 2.0 M	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	FD21600578	<b>Colour</b>	BLACK
<b>Odometer</b>	187631	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	225/45 R17	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/45 R17	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/45 R17	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	225/45 R17	BRIDGESTONE	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	16/01/2019	<b>Inspection Date</b>	27/02/2019
<b>Survey held at</b>	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**