



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19001304/Gga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 04-02-2020



ATTN: LEE GREEN TEE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 1583S	Veh. Inspected	SLF 9531B
Policy No.	CV1/GA422004	Coverage (\$)	0.00
Claim No.	S9M01B5N	Excess (\$)	0.00
Assign From	LEE GREEN TEE	Assign Date	21/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600077097	Colour	BLACK
Odometer	66006	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/01/2019	Inspection Date	24/01/2019
Survey held at	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------