

**CONNECT 3**

566 Woodlands Road ( Mandai Estate ) Singapore 728697  
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT19/CB7301P/TPC-387

**AXA Insurance Singapore Pte Ltd**

8 Shenton Way, #27-01 AXA Tower  
Singapore 068811

**QUOTATION**

Dear Sir,

Cost of Repair to Vehicle CB7301P


With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear bumper <i>BA ✓</i>	1	1,845.00	1,845.00
2.	Rear bumper inner structure <i>repair ✓</i>	1	680.00	680.00
3.	Rear bumper bracket <i>BA ✓</i>	1	225.00	225.00
4.	Rear end panel <i>BA ✓</i>	1	1,650.80	1,650.80
5.	Spare tyre <i>X</i>	1	250.00	250.00
6.	Labour charges	1	1,500.00	<i>600</i> 1,500.00
7.	Spray painting	1	1,200.00	<i>600</i> 1,200.00
8.	Apply anti rust	1	180.00	<i>60</i> 180.00
SUB-TOTAL				S\$7,530.80

- Price exclude 7%gst

Yours faithfully,

*Winnie*  
Winnie Chai  
HP: 9850-9666



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Resue*  
*HP 90010068*

*4 days*

*W/S*

*22/01/19 @ 1000*

*Reg after repair*