COMFORTDELGRO ENGINEERING PTE LTD **REPAIR ESTIMATE***

VEHICLE NO: SHD 6675Y

MAKE

MODEL

: MERCEDES BENZ

by the insurance company.

EQ Ins PAP

DATE 1/18/2019

LKK-

Parts Description/ Labour	Type	Unit Price		Amount
Rear Bumper Lower Cover			\$	325.00
				325.00
				65.00 260.00
DISCOUNTED TOTAL			Ψ	200.00
Rear Bumper Rubber Mat			\$	50.00
Rear Bumper Sensor			\$	388.00
			•	438.00
Labour Charge			Φ	430.00
Panel Beating			\$	400.00
Spray Painting Charge			\$	300.00
			\$	30.00
Remove/Renx Reverse Sensor			\$	_120.00
TOTAL LABOUR			\$	850.00
ESTIMATE TOTAL		LA CONTRACTOR	\$	1,548.00
NAZ LKK	- 1			
18/1/19 1600	7			
P/9				
2 DAYS		54 2 Sav		
CHECK ITEMS PLATES				
REFORE PANT PHOTOS.	he Repaire fo resurvey fo display d Parts prices find party s illegal m	er of the following: before/after apray painting amaged part(a) during recurvey are subject to confirmation survey is on a "Without Projudio stiffection(s) is allowed	o' basis	
	is subject to	final approval from Insurance C	ompany	
	Rear Bumper Lower Cover SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Rubber Mat Rear Bumper Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor TOTAL LABOUR ESTIMATE TOTAL NAZ LUC 18/1/19 1600 P/C 2 DAYS CHECK ITEMA PHOTO	Rear Bumper Lower Cover SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Rubber Mat Rear Bumper Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor TOTAL LABOUR ESTIMATE TOTAL NAZ LUC 18/1/19/1600 P/C 2 DAYS CHECK ITEMA PLATE **Repairs prices ind party in display of Parts prices ind party in display of Parts prices	SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Rubber Mat Rear Bumper Sensor Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor TOTAL LABOUR ESTIMATE TOTAL NAZ LLL 18/1/19/16/2 P/P 2 DAYS CHECK ITEM PLATE REFORE (ANT PLATE) Sinspired among autily during recurvey. Party prices are included to confirmation of party survey is on a "Without Production and party survey is on a "W	SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Rubber Mat Rear Bumper Sensor S Labour Charge Panel Beating Spray Painting Charge Wiring Charge Remove/Refix Reverse Sensor TOTAL LABOUR ESTIMATE TOTAL NR2 LLL 18/1/19 1600 P/P 2 DAYS CHECK ITEM PLATE REFORE (ANT PLATE) S LKK Auto Consultanta honce notify The Repairer of the following: 10 reserves pleoning the superplanting 10 reserves pleoning the