

REPAIR ESTIMATE*

VEHICLE NO : SH 7127E

DATE 1/18/2019 14:39

MAKE :

MODEL : HYUNDAI i40

China
JH

PIP

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Bracket Top (LH)			\$ 22.40
	Front Bumper Retainer Mounting (LH)			\$ 9.20
	Front Fender (LH)			\$ 566.30
	Front Fender Shield (LH)			\$ 175.90
	Front Fender Retainer (LH)			\$ 24.60
	Front Door (LH)			\$ 2,256.40
	Front Door Mirror Assy (LH)			\$ 670.00
	Front Wheel Hub Cap (LH)			\$ 107.10
	SUB TOTAL			\$ 4,884.10
	LESS 20%			\$ 976.82
	DISCOUNTED TOTAL			\$ 3,907.28
	Front Fender Advertisement Logo (LH)			\$ 100.00
	Front Door Comfort Logo (LH)			\$ 75.00
	Front Door Advertisement Logo (LH)			\$ 100.00
				\$ 275.00
	Labour Charge			
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 30.00
	Tuff Kote			\$ 50.00
	Transfer of Door			\$ 120.00
	TOTAL LABOUR			\$ 2,000.00
	ESTIMATE TOTAL			\$ 6,182.28

/CRK

?

?

/DEF

?

/CLK

/DEF

/BR

/SCR

Nett /NEC

Nett /NEC

Nett /NEC

600

600

/NR

40

50

NAZ LKIC

18/1/19 PIP

4 days

CHECK ITEMS PHOTOS

BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.