

INSURANCE

INS. CASE OWNER:

CC 3 /AIG1900

LKK:
IDAC:

Surveyor:

RAGUL

DOI:

ASSIGNMENT

25/01/19

Date / Time:

21/1/19

Registered in Merimen:

21/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUQ 9880K

Name of Insured:

UHO SEOW HWEI TEOH.

Insured Tel No.:

HP:

D.O.A. 18/1/19.

Excess Sec II :\$S

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age: SEOW HWEI TEOH UHO

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

2777265556

Policy No.:

R00072543

Make / Model:

OPEL

Place of Accident:

KUNING HUE 5

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

21/1/19

21/1/19

25-1-19-19

25-1-19-19

FINALED

TP VIDEO UPLOADED IN MERIMEN

TP LOB IN BY EMAIL

25-1-19 @ 1140

CONFIRMED ALL.

SHE HAVE PROTECTOR

EXP. VIDEO. AGREED.

SHE WANTS TO KNOW COR.

02/12/19

Orig. TP LOB IN

UPLOADED IF NO UPLOADED

GOOD ACCEPTANCE EMAIL TO TP

ALL WORK IN ORDER

TO CLOSE.

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

204 25-1-19

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:

Others:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG19001336/jb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 21-01-2019		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 9880K	Veh. Inspected	SKZ 3551P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	21/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/01/2019	Inspection Date		
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	24 Benoi Sector
Contact No	:	6474 3323
Fax No	:	6264 6786
Reference	:	PAC/TP /003/2019/GW
Date	:	22-Jan-19

Vehicle not in workshop . Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tay Teck How
Address	:	Blk 842 Sims Ave
	:	#06-762
	:	Singapore 400482
Telephone	:	(HP)93638386
Type of Claim	:	Third Party Claims
Policy No.	:	P10030393R01
Vehicle No	:	SKZ 3551 P
Model Code	:	Mazda3 Sedan 2.0 Sports
Model / Year	:	Jan-16
Engine No	:	PE20718994
Chassis No	:	JM6BM4278C0328992
Mileage	:	
Date In	:	
Liability	:	
Excess Cost	:	
Estimated By	:	Allan Wu
Accident Date	:	17-Jan-19
Place of Accident	:	Eunos Avenue 5

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKZ 3551 P

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall front bumper wiring harness.	S/N S 150.00 <i>150</i>
2	To remove and transfer rhs rear door's and front door multi lock system and power window devices. Inspect for damages.	S/N S 150.00 <i>75</i>
3	To dismantle front bumper. Renew rhs front fender, rhs front and rear doors, align to position. Repair rhs rear fender and rear bumper. Reinstall parts removed.	(300 L) S 1,800.00 <i>1350 1200</i>
4	To respray paint on rhs front fender, rhs front door, rhs rear door, rhs wing mirror cover, rhs rear fender and rear bumper.	(150) S 2,000.00 <i>1800 1375</i>
5	To renew rhs front rim and rear rim and carry out wheel alignment.	S/N S 280.00
6	To carry out diagnostic check.	S/N S 150.00
TOTAL LABOUR CHARGES		: <u><u>\$ 4,530.00</u></u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKZ 3551 P

S/N	Parts Description	Damaged Parts & Prices S/Nett	
1	FRONT FENDER-RH PA/	\$	276.00 ✓
2	FRONT FENDER INNER SHEILD-RH PA ? X sur	\$	104.00
4	FRONT FENDER SHIELD CLIP SET neu/ X an	\$	30.00
5	FRONT DOOR-RH PA/	\$	805.00 ✓
6	FRONT DOOR CHECK ROD-RH X sur	\$	58.00
7	FRONT DOOR SEAL-RH neu X an	\$	81.00
9	REAR DOOR-RH repair	\$	920.00
10	REAR DOOR CHECK ROD-RH X	\$	42.00
11	REAR DOOR SEAL-RH X	\$	92.00
12	FRONT WHEEL BEARING HUB-RH ?	\$	426.00
13	REAR WHEEL BEARING HUB-RH X	\$	334.00
14	WHEEL RIM sur/	1pc X \$	1,380.00 ✓ 690
15	SUNDRIES ? X an	\$	200.00
TOTAL SPARE PARTS CHARGES		:	\$ 4,748.00
TOTAL LABOUR CHARGES		:	\$ 4,530.00
GRAND TOTAL		:	\$ 9,278.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Name	:	Rashid - Hp 90010068
Surveyed Date	:	23/04/19 @ 1400hrs
Authorised Date	:	
Excess Cost	:	10 days
Liability	:	
Remarks	:	Resurvey by paint

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP /003/2019/GW
Date : 22-Jan-19

Vehicle not in workshop . Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Rasul,
5 Working days*

Attn: - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tay Teck How
Address : Blk 842 Sims Ave
#06-762
Singapore 400482
Telephone : (HP)93638386
Type of Claim : Third Party Claims
Policy No. : P10030393R01
Vehicle No : **SKZ 3551 P**
Model Code : Mazda3 Sedan 2.0 Sports
Model / Year : Jan-16
Engine No : PE20718994
Chassis No : JM6BM4278G0328992
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 17-Jan-19
Place of Accident : Eunus Avenue 5

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKZ 3551 P

S/n	Nature of Jobs		Estimated Charges		Remark
1	To remove and reinstall front bumper wiring harness.	S/N	\$ 150.00	\$	150.00
2	To remove and transfer rhs rear door's and front door multi lock system and power window devices. Inspect for damages.	S/N	\$ 150.00	\$	75.00
3	To dismantle front bumper. Renew rhs front fender, rhs front and rear doors, align to position. Repair rhs rear fender and rear bumper. Reinstall parts removed.		\$ 1,800.00	\$	1,200.00
4	To respray paint on rhs front fender, rhs front door, rhs rear door, rhs wing mirror cover, rhs rear fender and rear bumper.		\$ 2,000.00	\$	1,375.00
5	To renew rhs front rim and rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$	280.00
6	To carry out diagnostic check.	S/N	\$ 150.00	\$	150.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,530.00</u>	\$	<u>3,230.00</u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No.SKZ 3551 P

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT FENDER-RH	\$ 276.00	\$ 276.00
2	FRONT FENDER INNER SHEILD-RH	\$ 104.00	
4	FRONT FENDER SHIELD CLIP SET	\$ 30.00	
5	FRONT DOOR-RH	\$ 805.00	\$ 805.00
6	FRONT DOOR CHECK ROD-RH	\$ 58.00	
7	FRONT DOOR SEAL-RH	\$ 81.00	
9	REAR DOOR-RH	\$ 920.00	
10	REAR DOOR CHECK ROD-RH	\$ 42.00	
11	REAR DOOR SEAL-RH	\$ 92.00	
12	FRONT WHEEL BEARING HUB-RH	\$ 426.00	
13	REAR WHEEL BEARING HUB-RH	\$ 334.00	
14	WHEEL RIM	2 \$ 1,380.00	\$ 690.00
15	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		\$ 4,748.00	\$ 1,771.00
TOTAL LABOUR CHARGES		\$ 4,530.00	\$ 3,230.00
GRAND TOTAL		\$ 9,278.00	\$ 5,001.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	24 Benoi Sector
Contact No	:	6474 3323
Fax No	:	6264 6786
Reference	:	PAC/TP /003/2019/GW
Date	:	22-Jan-19

Vehicle not in workshop . Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Tay Teck How
Address	:	Blk 842 Sims Ave #06-762 Singapore 400482
Telephone	:	(HP)93638386
Type of Claim	:	Third Party Claims
Policy No.	:	P10030393R01
Vehicle No	:	SKZ 3551 P
Model Code	:	Mazda3 Sedan 2.0 Sports
Model / Year	:	Jan-16
Engine No	:	PE20718994
Chassis No	:	JM6BM4278G0328992
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Allan Wu
Accident Date	:	17-Jan-19
Place of Accident	:	Eunos Avenue S

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.
Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKZ 3551 P

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall front bumper wiring harness.	S/N \$ 150.00 150 <i>new</i>
2	To remove and transfer rhs rear door's and front door multi lock system and power window devices. Inspect for damages.	S/N \$ 150.00 <i>75</i>
3	To dismantle front bumper. Renew rhs front fender, rhs front and rear doors, align to position. Repair rhs rear fender and rear bumper. Reinstall parts removed.	(300 L) S 1,800.00 <i>1350 1200</i>
4	To respray paint on rhs front fender, rhs front door, rhs rear door, rhs wing mirror cover, rhs rear fender and rear bumper.	(250) S 2,000.00 <i>1800 1375</i>
5	To renew rhs front rim and rear rim and carry out wheel alignment.	S/N \$ 280.00 <i>/</i>
6	To carry out diagnostic check.	S/N \$ 150.00 <i>/</i>
TOTAL LABOUR CHARGES		: <u>\$ 4,530.00</u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No.SKZ 3551 P

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	
1	FRONT FENDER-RH <i>PA</i>	\$	276.00
2	FRONT FENDER INNER SHEILD-RH <i>PA?</i>	\$	104.00
4	FRONT FENDER SHIELD CLIP SET <i>new</i>	\$	30.00
5	FRONT DOOR-RH <i>PA</i>	\$	805.00
6	FRONT DOOR CHECK ROD-RH <i>X</i>	\$	58.00
7	FRONT DOOR SEAL-RH <i>new</i>	\$	81.00
9	REAR DOOR-RH <i>repair</i>	\$	920.00
10	REAR DOOR CHECK ROD-RH <i>X</i>	\$	42.00
11	REAR DOOR SEAL-RH <i>X</i>	\$	92.00
12	FRONT WHEEL BEARING HUB-RH <i>?</i>	\$	426.00
13	REAR WHEEL BEARING HUB-RH <i>X</i>	\$	334.00
14	WHEEL RIM <i>scd</i>	<i>1pc</i> <i>X</i> \$	1,380.00
15	SUNDRIES <i>?</i>	\$	200.00
TOTAL SPARE PARTS CHARGES		:	\$ 4,748.00
TOTAL LABOUR CHARGES		:	\$ 4,530.00
GRAND TOTAL		:	\$ 9,278.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name

: Rasm - Hp 90010068

Surveyed Date

: 23/01/19 @ 1400hrs

Authorised Date

:

Excess Cost

:

10 days

Liability

:

Remarks

:

Resurvey by paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6474 3323 for appointment.

Yours faithfully,

Premium Autocare Centre

Allan Wu

Body Shop Manager

Joy Irene (LKKAUTO)

From: Teresa Choo <teresa_c_s_h@yahoo.com.sg>
Sent: Sunday, 10 March 2019 5:47 PM
To: Joy Irene (LKKAUTO)
Subject: RE: ACCIDENT INVOLVING SLQ 9880K AND SKZ 3551P ON 17/01/2019

Hi, may I know the status of the case ?

Thank you.

Sent from Yahoo Mail on Android

On Sat, 26 Jan 2019 at 11:29 am, Teresa Choo <teresa_c_s_h@yahoo.com.sg> wrote:

Hi Joy Irene,

I also ask to highlight to you , I checked his repair cost with my workshop and they quoted between 350 to 400 for his cost.

So it's their claim is exorbitant , then it wouldn't be entertained.

Thank you and do keep me updated.

Have a good weekend.

Regards
Teresa

Sent from Yahoo Mail on Android

On Fri, 25 Jan 2019 at 3:42 pm, Teresa Choo <teresa_c_s_h@yahoo.com.sg> wrote:

My husband.

Thank you.

Sent from Yahoo Mail on Android

On Fri, 25 Jan 2019 at 3:32 pm, Joy Irene (LKKAUTO) <JoyIrene@lkkauto.com> wrote:

Dear Madam,

Attached is a copy of your report for your easy reference. The name of the driver was indicated there.

May we check and confirm with you, who drove your car at the time of the collision?

Please advise.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

From: Teresa Choo [mailto:teresa_c_s_h@yahoo.com.sg]

Sent: Friday, 25 January 2019 3:09 PM

To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: Re: ACCIDENT INVOLVING SLQ 9880K AND SKZ 3551P ON 17/01/2019

Are you aware that I am not the driver at the time of incident?

Did you receive my report ? With pics of his car as well.

Sent from Yahoo Mail on Android

On Fri, 25 Jan 2019 at 11:46 am, Joy Irene (LKKAuto)

<JoyIrene@lkkauto.com> wrote:

Our ref: CC3/AIG19001336/jb3

CHOO SEOW HWEE TERESA

* Policy Holder

Dear Madam,

ACCIDENT INVOLVING SLQ 9880K AND SKZ 3551P ON 17/01/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

BREAKDOWN OF PAYMENT

Vehicle No: SKZ 3551 P
Accident on 17/01/2019 at Eunos Avenue 5
Involving vehicle/s SLA 9880 K

1) Repair cost \$ 5,351.07 Payable to: Premium Autocare Centre

2) GIA/LTA search fee \$ - Payable to: Premium Autocare Centre

3) Loss of Use or Rental Car \$ 802.50 Payable to: Premium Autocare Centre

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2019 Edit Reg		23 Jan 2019 00:00 Edit Adj Rpt	S\$5,001.00 Edit Estimates	S\$5,001.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Choo Seow Hwee Teresa , ID: S8034230F									
Main Claimant: TAY TECK HOW , ID: S7435938H									
Vehicle Reg. No.: SKZ3551P		Date of Loss: 17/01/2019 21:00 - :59 [36 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 3723968805SG		Policy/Cover Note No.: 1800079547 (Comprehensive)							
Vehicle Reg. No. (Insured): SLQ9880K		Policy No. (Claimant): P10030393R01							
		Excess:							
Repairer: Premium Autocare Centre (Alexandra) 281 Alexandra Road, 159938 Alexandra - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com									
Claimant's Insurer: Auto & General Insurance (Singapore) Pte. Limited. (HQ) - Tel: 6540 2180									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/01/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ3551P (3723968805SG)
[SLQ9880K]
TP
TAY TECK HOW
Jan 17 2019 9:00PM
[Choo Seow Hwee Teresa]
Premium Autocare Centre

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	22/01/19 14:12	Video - Accident from claimant							Load MP4		
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	22/01/19 12:54	Accident Statement <small>From-SC - Reg. No: SLQ9880K, Claimant: CHOO SEOW HWEI TERESA</small>							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	08/08/19 17:05	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	08/08/19 17:05	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
3	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
4	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
5	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
6	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
7	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
8	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
9	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
10	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
11	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
12	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
13	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
14	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
15	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
16	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
17	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
18	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
19	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
20	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
21	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
22	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
23	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
24	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
25	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
26	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
27	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
28	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
29	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
30	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
31	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	
32	08/08/19 17:05	General View							Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
33	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
34	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
35	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
36	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
37	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
38	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
39	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
40	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
41	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
42	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
43	08/08/19 17:05	General View		<input checked="" type="checkbox"/>
44	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
45	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
46	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
47	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
48	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
49	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
50	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
51	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
52	08/08/19 17:06	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/19 17:53	TP GIA REPORT		<input type="checkbox"/>
2	25/01/19 17:20	TP ESTIMATE- MARKED		<input type="checkbox"/>
3	02/12/19 10:52	TP ESTIMATE - FINALIZED		<input type="checkbox"/>
4	02/12/19 10:52	TP LOD		<input type="checkbox"/>
5	06/12/19 08:36	WORKSHOP INVOICE		<input type="checkbox"/>
6	06/12/19 08:36	AUTHORISATION TO ACT FORM		<input type="checkbox"/>
7	06/12/19 08:36	Release Voucher		<input type="checkbox"/>
8	06/12/19 08:36	RENTAL RECEIPT		<input type="checkbox"/>
9	06/12/19 08:36	LOD		<input type="checkbox"/>
10	06/12/19 08:36	LETTER TO OI		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ9880K (Insd veh)	Model:	MAZDA 3 1.5 (A)
	SKZ3551P (TP veh)		
Date of Accident:	17/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	9,927.46
Final Repair Cost	:	\$	5,351.07
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	802.50 5 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,153.57
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Premium Autocare Centre	:	\$ 6,153.57
2)		:	\$

JOANNE LEE KHANG MIN

06 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park.

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19001338/R1HB3Q2

Date: 06/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800079547
 Claimant: SKZ3551P Insured Vehicle No: SLQ9880K
 Vehicle No: SKZ3551P Date of Loss: 17/01/2019 Nature of Claim: TP Claim No: 3723968805SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ3551P
 Make & Model: MAZDA 3, 1.5 (A) Engine No: PE20718994
 Reg. Date: 01/01/2016 (Man. Year: 2016) Chassis No: JM6BM4278G0328992
 Colour: Grey Odometer: 57229 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,748.00	1,771.00	2,977.00	62.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	3,230.00	1,300.00	28.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,278.00	5,001.00	4,277.00	46.10
+ GST 7.00/7.00% (S\$)	649.46	350.07	299.39	46.10
Nett Amount (S\$)	9,927.46	5,351.07	4,576.39	46.10
+ Car Rental (5.0 x S\$150.00/day + 7.00% GST) (S\$)		802.50		
	Nett Liability (S\$)	6,153.57		

INSPECTION

Date of Assignment: 23/01/2019
 Date Inspected: 23/01/2019 Inspected At: Premium Autocare Centre (Alexandra)
 281 Alexandra Road
 Singapore 159938
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER -RH	Bent	276.00 FS	*276.00 FS
2	1		*FRONT FENDER INNER SHIELD -RH	Serviceable	104.00 FS	*- FS
3	1		*SET FRONT FENDER SHIELD CLIP	Not Necessary	30.00 FS	*- FS
4	1		*FRONT DOOR -RH	Bent	805.00 FS	*805.00 FS
5	1		*FRONT DOOR CHECK ROD -RH	Serviceable	58.00 FS	*- FS
6	1		*FRONT DOOR SEAL -RH	Not Necessary	81.00 FS	*- FS
7	1		*REAR DOOR -RH	Repair	920.00 FS	*- FS
8	1		*REAR DOOR CHECK ROD -RH	Serviceable	42.00 FS	*- FS
9	1		*REAR DOOR SEAL -RH	Serviceable	92.00 FS	*- FS
10	1		*FRONT WHEEL BEARING HUB-RH	Serviceable	426.00 FS	*- FS
11	1		*REAR WHEEL BEARING HUB -RH	Serviceable	334.00 FS	*- FS
12	2		*WHEEL RIM	Scratched (1 PCS ONLY)	1,380.00 FS	*690.00 FS
13	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
Total Parts (\$\$)					4,748.00	1,771.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT BUMPER WIRING HARNESS	New	150.00	150.00
2	TO REMOVE AND TRANSFER RHS REAR DOORS AND FRONT DOOR MULTI LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	150.00	75.00
3	TO DISMANTLE FRONT BUMPER .RENEW RHS FRONT FENDER ,RHS FRONT AND REAR DOORS .ALIGN TO POSITION ,REPAIR RHS REAR FENDER AND REAR BUMPER .REINSTALL PARTS REMOVED	New	1,800.00	1,200.00
4	TO RESPRAY PAINT ON RHS FRONT FENDER ,RHS FRONT DOOR ,RHS REAR DOOR ,RHS WING MIRROR COVER ,RHS REAR FENDER AND REAR BUMPER	New	2,000.00	1,375.00
5	TO RENEW RHS FRONT RIM AND REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	150.00	150.00
Gross Labour Cost (S\$)			4,530.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >