

VLC

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP /003/2019/GW
Date : 22-Jan-19

Vehicle not in workshop . Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tay Teck How
Address : Blk 842 Sims Ave
#06-762
Singapore 400482
Telephone : (HP)93638386
Type of Claim : Third Party Claims
Policy No. : P10030393R01
Vehicle No : **SKZ 3551 P**
Model Code : Mazda3 Sedan 2.0 Sports
Model / Year : Jan-16
Engine No : PE20718994
Chassis No : JM6BM4278G0328992
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 17-Jan-19
Place of Accident : Eunus Avenue 5

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKZ 3551 P

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall front bumper wiring harness.	S/N \$ 150.00 150.00 ✓
2	To remove and transfer rhs rear door's and front door multi lock system and power window devices. Inspect for damages.	S/N \$ 150.00 150.00 75 ✓
3	To dismantle front bumper, Renew rhs front fender, rhs front and rear doors, align to position. Repair rhs rear fender and rear bumper. Reinstall parts removed.	(300 L) S 1,800.00 1800.00 1200 ✓
4	To respray paint on rhs front fender, rhs front door, rhs rear door, rhs wing mirror cover, rhs rear fender and rear bumper.	(250) S 2,000.00 2000.00 1375 ✓
5	To renew rhs front rim and rear rim and carry out wheel alignment.	S/N \$ 280.00 ✓
6	To carry out diagnostic check.	S/N \$ 150.00 ✓
TOTAL LABOUR CHARGES		: \$ 4,530.00

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No.SKZ 3551 P

S/N	Parts Description	Damaged Parts & Prices S/Nett	
1	FRONT FENDER-RH PA ✓	\$	276.00 ✓
2	FRONT FENDER INNER SHEILD-RH PA ? X sur	\$	104.00
4	FRONT FENDER SHIELD CLIP SET new X an	\$	30.00
5	FRONT DOOR-RH PA ✓	\$	805.00 ✓
6	FRONT DOOR CHECK ROD-RH X sur	\$	58.00
7	FRONT DOOR SEAL-RH new X an	\$	81.00
9	REAR DOOR-RH repair	\$	920.00
10	REAR DOOR CHECK ROD-RH X	\$	42.00
11	REAR DOOR SEAL-RH X	\$	92.00
12	FRONT WHEEL BEARING HUB-RH ?	\$	426.00
13	REAR WHEEL BEARING HUB-RH X	\$	334.00
14	WHEEL RIM sur ✓	1pc X \$	1,380.00 ✓ 690
15	SUNDRIES ? X an	\$	200.00
TOTAL SPARE PARTS CHARGES		:	\$ 4,748.00
TOTAL LABOUR CHARGES		:	\$ 4,530.00
GRAND TOTAL		:	\$ 9,278.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name	:	Rasm - Hp 90010068
Surveyed Date	:	23/01/19 @ 1400hrs
Authorised Date	:	
Excess Cost	:	10 days
Liability	:	
Remarks	:	Resurvey by paint

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP /003/2019/GW
Date : 22-Jan-19

Vehicle not in workshop . Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

*Hi Rasul,
5 Working days*

Attn: - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tay Teck How
Address : Blk 842 Sims Ave
#06-762
Singapore 400482
Telephone : (HP)93638386
Type of Claim : Third Party Claims
Policy No. : P10030393R01
Vehicle No : **SKZ 3551 P**
Model Code : Mazda3 Sedan 2.0 Sports
Model / Year : Jan-16
Engine No : PE20718994
Chassis No : JM6BM4278G0328992
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 17-Jan-19
Place of Accident : Eunus Avenue 5

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKZ 3551 P

S/n	Nature of Jobs		Estimated Charges		Remark
1	To remove and reinstall front bumper wiring harness.	S/N	\$ 150.00	\$	150.00
2	To remove and transfer rhs rear door's and front door multi lock system and power window devices. Inspect for damages.	S/N	\$ 150.00	\$	75.00
3	To dismantle front bumper. Renew rhs front fender, rhs front and rear doors, align to position. Repair rhs rear fender and rear bumper. Reinstall parts removed.		\$ 1,800.00	\$	1,200.00
4	To respray paint on rhs front fender, rhs front door, rhs rear door, rhs wing mirror cover, rhs rear fender and rear bumper.		\$ 2,000.00	\$	1,375.00
5	To renew rhs front rim and rear rim and carry out wheel alignment.	S/N	\$ 280.00	\$	280.00
6	To carry out diagnostic check.	S/N	\$ 150.00	\$	150.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,530.00</u>	\$	<u>3,230.00</u>

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No.SKZ 3551 P

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT FENDER-RH	\$ 276.00	\$ 276.00
2	FRONT FENDER INNER SHEILD-RH	\$ 104.00	
4	FRONT FENDER SHIELD CLIP SET	\$ 30.00	
5	FRONT DOOR-RH	\$ 805.00	\$ 805.00
6	FRONT DOOR CHECK ROD-RH	\$ 58.00	
7	FRONT DOOR SEAL-RH	\$ 81.00	
9	REAR DOOR-RH	\$ 920.00	
10	REAR DOOR CHECK ROD-RH	\$ 42.00	
11	REAR DOOR SEAL-RH	\$ 92.00	
12	FRONT WHEEL BEARING HUB-RH	\$ 426.00	
13	REAR WHEEL BEARING HUB-RH	\$ 334.00	
14	WHEEL RIM	2 \$ 1,380.00	\$ 690.00
15	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS CHARGES		: \$ 4,748.00	\$ 1,771.00
TOTAL LABOUR CHARGES		: \$ 4,530.00	\$ 3,230.00
GRAND TOTAL		: \$ 9,278.00	\$ 5,001.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6474 3323 for appointment.

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager