



**Main Office :** No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

**Service Centre :** Block 100B, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

**Mova Spray Centre**  
2K Oven Spray Painting System

**Power-M Automotive Pte Ltd**  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

**Hilton Car Rental Centre**  
**Hilton Auto Trading**  
Dealing In New/Used Cars, Hire Purchase & Insurance.



**TP INSURER:** India International Insurance Pte Ltd (HQ)

0

Singapore

**Claimant Insurer:** AXA Insurance Pte Ltd

*TP India Aln 9689276*

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/01/2019
Vehicle Reg. No.:	SGJ2306U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	KEE TEOW KHENG		
Make/Model:	mitsubishi LANCER, 1.6 (A)	Vehicle Reg. Date:	04/07/2006
Vehicle Colour:	GREY		
Engine No:	4G18HJ7605	Chassis No:	JMYSNCS3A6U007382
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO THE SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	4,843.50
Miscellaneous Items	10.00
Labour	2,950.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>7,803.50</b>
<b>+ GST 7.00% (S\$)</b>	<b>546.25</b>
<b>Nett Amount (S\$)</b>	<b>8,349.75</b>

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

## Reference

**Part Source:** MRM-SG                      Version: 1.0 (Last Synchronised: 21 Jan 2019)  
**Parts:** 143                                      MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's                      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SGJ2306U)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>TORN /</i>	10.00	0.00	*580.00 FL
2	1		*REAR BUMPER BRACKET LH <i>bt /</i>	10.00	0.00	*45.00 FL
3	1		*REAR BUMPER CENTER SUPPORT <i>X</i>	10.00	0.00	*280.00 FL
4	2		*TAIL LAMP L & R <i>LH-990 / RH-?</i>	10.00	0.00	*960.00 FL
5	1		*TAIL LAMP PANEL LH <i>bt /</i>	10.00	0.00	*190.00 FL
6	1		*BOOT LID RUBBER <i>X</i>	10.00	0.00	*230.00 FL
7	1		*BOOT LID LOGO <i>new /</i>	10.00	0.00	*40.00 FL
8	1		*BOOT LID (LANCER) EMBLEM <i>new /</i>	10.00	0.00	*50.00 FL
9	1		*BOOT LID (GLS) EMBLEM <i>new /</i>	10.00	0.00	*40.00 FL
10	1		*END PANEL GARNISH <i>?</i>	10.00	0.00	*150.00 FL
11	1		*END PANEL ASSY <i>bt /</i>	10.00	0.00	*510.00 FL
12	1		*REAR FENDER LH <i>new /</i>	10.00	0.00	*1,430.00 FL
13	1		*REAR FENDER INNER SHIELD LH <i>cut /</i>	10.00	0.00	*100.00 FL
14	1		*REAR FENDER INNER TRIM LH <i>.</i>	10.00	0.00	*310.00 FL
15	10		*REAR BUMPER CLIPS <i>new /</i>	10.00	0.00	*40.00 FL
16	1		*REAR WINDSCREEN MOULDING <i>new /</i>	10.00	0.00	*160.00 FL
17	1		*REAR WINDSCREEN SEALANT <i>new /</i>	0	0.00	*40.00 FS ✓
18	1		*REAR PARKING SENSOR <i>?</i>	0	0.00	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,355.00
- List Item Discount on L Items (\$\$)	511.50
Total Parts (\$\$)	4,843.50

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST	New	<del>40.00</del> 30
2	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00
3	TO REMOVE & INSTALL FUEL TANK	New	<del>80.00</del> 60
4	TO REMOVE & INSTALL REAR COMPARTMENT, CARPET, GARNISHES, ROOF LINING & ETC IN ORDER TO CUT OFF DAMAGED PANEL	New	<del>200.00</del> 100
5	TO CUT OFF END PANEL, LH REAR FENDER, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	<del>1,200.00</del> 900
6	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	<del>60.00</del> 40
7	TO APPLY RUST PROOF ON AFFECTED AREAS	New	<del>150.00</del> 80
8	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	<del>1,100.00</del> 800
Gross Labour Cost (S\$)			2,950.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Hand*  
*Hp 90010568*  
*8 days*  
*HS*  
*21/01/19 @ 1450*

*Resurvey after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: