



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
0

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/01/2019
Vehicle Reg. No.:	SGJ2306U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	KEE TEOW KHENG		
Make/Model:	MITSUBISHI LANCER, 1.6 (A)	Vehicle Reg. Date:	04/07/2006
Vehicle Colour:	GREY	Chassis No:	JMYSNCS3A6U007382
Engine No:	4G18HJ7605		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO THE SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS	Amount
Parts	4,843.50
Miscellaneous Items	10.00
Labour	2,950.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,803.50
+ GST 7.00% (S\$)	546.25
Nett Amount (S\$)	8,349.75

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS	
Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2019)
Parts: 143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ2306U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	10.00	0.00	*580.00 FL
2	1		*REAR BUMPER BRACKET LH	10.00	0.00	*45.00 FL
3	1		*REAR BUMPER CENTER SUPPORT	10.00	0.00	*280.00 FL
4	2		*TAIL LAMP L & R	10.00	0.00	*960.00 FL
5	1		*TAIL LAMP PANEL LH	10.00	0.00	*190.00 FL
6	1		*BOOT LID RUBBER	10.00	0.00	*230.00 FL
7	1		*BOOT LID LOGO	10.00	0.00	*40.00 FL
8	1		*BOOT LID (LANCER) EMBLEM	10.00	0.00	*50.00 FL
9	1		*BOOT LID (GLS) EMBLEM	10.00	0.00	*40.00 FL
10	1		*END PANEL GARNISH	10.00	0.00	*150.00 FL
11	1		*END PANEL ASSY	10.00	0.00	*510.00 FL
12	1		*REAR FENDER LH	10.00	0.00	*1,430.00 FL
13	1		*REAR FENDER INNER SHIELD LH	10.00	0.00	*100.00 FL
14	1		*REAR FENDER INNER TRIM LH	10.00	0.00	*310.00 FL
15	10		*REAR BUMPER CLIPS	10.00	0.00	*40.00 FL
16	1		*REAR WINDSCREEN MOULDING	10.00	0.00	*160.00 FL
17	1		*REAR WINDSCREEN SEALANT	0	0.00	*40.00 FS
18	1		*REAR PARKING SENSOR	0	0.00	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,355.00
- List Item Discount on L. Items (S\$)	511.50
Total Parts (S\$)	4,843.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & INSTALL REAR WINDSCREEN	New	120.00
3	TO REMOVE & INSTALL FUEL TANK	New	80.00
4	TO REMOVE & INSTALL REAR COMPARTMENT, CARPET, GARNISHES, ROOF LINING & ETC IN ORDER TO CUT OFF DAMAGED PANEL	New	200.00
5	TO CUT OFF END PANEL, LH REAR FENDER, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1,200.00
6	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00
7	TO APPLY RUST PROOF ON AFFECTED AREAS	New	150.00
8	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,100.00
Gross Labour Cost (\$\$)			2,950.00

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**
 < END OF ESTIMATES >