

Cecilia

Vantage Automotive Limited

Company Registration No. 192600045M
305 Alexandra Road Singapore 159942
Tel: 64777409 Fax: 64777398
www.vantageauto.com.sg



RE: VEHICLE REPAIR QUOTATION

Owner : JENNY ONG
Insurance : ERGO INSURANCE
Model : TOYOTA ALTIS 1.6 CVT
Reg : SKU6930K
Chassis : MR053REH104536479
Accident Date : 07/01/2019

TO CONDUCT TP CLAIM - ERGO INSURANCE AGAINST SGY4293E

LABOUR LIST	PRICE
SUNDRIES	\$ 80.00
TO SUPPLY AND INSTALL FRONT NUMBER PLATE WITH HOLDER.(NETT)	\$ 70.00
LABOUR TO REMOVE, REALIGN, REPLACE FRONT BUMPER, BONNET, HEADLAMP, FRONT REINFORCEMENT, SUPPORT PANEL AND ALL AFFECTED AREAS.	\$ 2,400.00 ⁶⁰⁰
LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, BONNET, LH & RH FENDER, SUPPORT PANEL AND ALL AFFECTED AREAS	\$ 1,800.00 ⁶⁰⁰
ELECTRICAL WIRING CHECK FOR PROPER FUNCTIONING.(NETT)	\$ 200.00
TUFF KOTE, ANTI RUST PRESERVATION, BODY CAVITY PRESERVATIONS. (PER PANEL \$60 NETT)	\$ 300.00 ¹²⁰
HEADLAMP ADJUST FOCUS AND ANGLE PROGRAMME HEADLAMP CORRECTOR. (NETT)	\$ 200.00 ✓
TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS. (NETT)	\$ X 300.00
TO REMOVE AND REFIX A/C CONDENSOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS, VACUUM REFILL, RECHARGE AIRCON GAS.(NETT)	\$ 300.00 X 120
LABOUR TO REMOVE, REALIGN, REPLACE AND REPAIR, REAR BUMPER, BOOT LID, LHS & RHS REAR FENDER, END PANEL, SPARE TYRE PANEL AND ALL AFFECTED AREAS.	\$ 2,400.00 ¹²⁰⁰
LABOUR TO PUTTY AND RESPRAY REAR BUMPER, BOOT LID, LHS & RHS REAR FENDER, END PANEL, SPARE TYRE PANEL AND ALL AFFECTED AREAS.	\$ 1,800.00 ¹²⁰⁰
TO REMOVE AND REFIX REAR BUMPER REVERSE SENSOR, CONDUCT DISTANCE SETTING (NETT)	\$ 150.00 ✓
TUFF KOTE, ANTI RUST PRESERVATION, BODY CAVITY PRESERVATIONS. (PER PANEL \$60 NETT)	\$ 360.00 ¹⁸⁰
TO SUPPLY AND INSTALL REAR NUMBER PLATE WITH HOLDER.(NETT)	\$ X 70.00
Total Labour \$ 10,430.00	

30
bt ✓

Vantage Automotive Limited

Company Registration No. 192600045M
 305 Alexandra Road Singapore 159942
 Tel: 64777409 Fax: 64777398
 www.vantageauto.com.sg



PARTS LIST	PRICE
FRONT BONNET ASSY	\$ vt / 1,240.40
FRONT GRILL ASSY	\$ int / 564.00
FRONT GRILL UPPER COVER	\$ X 73.00
LHS HEADLAMP ASSY	\$ R 2,901.60
RHS HEADLAMP ASSY	\$ wa / 2,901.60
FRONT SUPPORT PANEL	\$ R 1,074.00
BONNET ASSY	\$ X 1,240.40 <i>Repaired</i>
BONNET HINGES LHS & RHS	\$ R 130.20
BONNET LOCK	\$ R 127.50
FRONT BUMPER ASSY	\$ gr / 511.20
FRONT BUMPER LOWER CENTER GARNISH	\$ del 129.00
FRONT BUMPER UNDER COVER	\$ X 180.00
FRONT BUMPER RETAINER LHS & RHS	\$ ru / 110.00
FRONT BRACE PANEL	\$ X 80.90
FRONT BUMPER REINFORCEMENT ASSY	\$ X 386.00
FRONT BUMPER REINFORCEMENT ABSORBER	\$ X 80.00
FRONT FOG LAMP ASSY LHS & RHS	\$ X 220.40
FRONT FOG LAMP COVER LHS/RHS	\$ X 214.20
AIR - CON CONDENSOR ASSY	\$ X 1,289.00
RADIATOR ASSY	\$ X 1,601.54
BOOT LID ASSY	\$ R 710.00
BOOT LID HINGES LHS & RHS	\$ R 162.00
BOOT LID "TOYOTA" EMBLEM	\$ ru 52.10
BOOT LID "COROLLA " EMBLEM	\$ ru 44.10
BOOT LID "ALTIS " EMBLEM	\$ ru 48.10
BOOT LID "VVT-I" EMBLEM	\$ ru 56.70
BOOT LID "CENTER CHROME GARNISH"	\$ X 275.60
BOOT LID RUBBER	\$ del 175.70
BOOT LID INNER GARNISH	\$ X 451.10
BOOT LID LOCK ASSY	\$ X 357.00
BOOT LOCK GARNISH	\$ X 60.30
BOOT LID TAIL LAMP ASSY LHS & RHS	\$ X 346.20
TAIL LAMP ASSY LHS & RHS	\$ X 676.20
REAR BUMPER ASSY	\$ del 486.50
REAR BUMPER RETAINER LHS & RHS	\$ ru / 208.20
REAR BUMPER REFLECTOR LHS & RHS	\$ X 124.40
REVERSER SENSOR LHS & RHS	\$ ru / 331.60
REAR END PANEL ASSY	\$ ht / 689.20
SPARE TYRE COMPARTMENT PANEL ASSY	\$ R 790.80
LHS FENDER AIR VIRT	\$ X 113.40
Total Parts : \$ 21,214.14	

Vantage Automotive Limited

Company Registration No. 192600045M

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398

www.vantageauto.com.sg



Total Parts and Labour : \$ 31,644.14
GST 7% : \$ 2,215.09
Grant total : \$ 33,859.23

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749
'WP' 22/1/19
Lumpsum
Resurvey after repair
12 days
taufik consultants.com