

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 21 January 2019

To : LKK

Attn : Bryan Ang

Tel : 97237799

By Fax: 6256-4315

VEHICLE NO : JSQ 7684

155 Yamaha MX

ACCIDENT DATE: 16 January 2019

Description	Qty	Quotation \$
1 Rear Mudguard new mainly broken	1 x ✓	
2 Rear Absorber new distorted	1 set x ✓	
3 Rear Brake Disc new	1 x	
4 Tail Lamp new cracked mainly	1 x ✓	
5 Rear Rim new distorted	1 x ✓	
6 Rear Side RH Panel cut LH	1 ✓	
Sub-Total		0.00
Less 10%		0.00
Sub-Total		0.00

Nett items

1	Rear number plate	25.00	15/-
2	R/LH N Max emblem		
3	R/LH 155 Sticker		
4	Towing fee	40.00	30/-
5	Remove & replace parts, align & etc	250.00	150/-
6	Remove & replace rear shock absorber, brake disc, rim & alignment	200.00	150/-
Spray painting		200.00	150/-
Sub-Total			
Nett Total			

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you.

SG 98 MOTOR PTE LTD

21/01/2019 @ 11:00am

LKK Antenna

2/3mm

Bryan

LKK Antenna

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: