

Case Details

Case Reference Number : TAX/01/19/2085
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1132R

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5399-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 17/01/2019 06:15 AM
 Vehicle Age(In Months) : 49

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval		
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace ▾ <i>PRF</i>
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace ▾ <i>CRF</i>
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Not Give ▾
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Not Give ▾
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Not Give ▾
One Time Key In	Main			LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace ▾ <i>SCR</i>
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Not Give ▾
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace ▾ <i>SCR</i>
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace ▾ <i>BUL</i>
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾ <i>NEC</i>
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check ▾

Total Spare Part Cost 3,898.26

Surveyor Total 2,442.14

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,118.61

Final Sur Total 1,953.71

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check ▾
One Time Key In	Main			CAP SUB-ASSY, WHEEL	1	174.10	174.10	25.00	130.57	Replace	1	130.57	Replace ▾ <i>SCR</i>
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0	Not Give ▾
Total Spare Part Cost									3,898.26		Surveyor Total	2,442.14	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									3,118.61		Final Sur Total	1,953.71	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT LH PORTION	845.00	450	
Total:		845.00	450.00	

Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO RESPRAY FRONT FENDER LH	378.00	200	
3	RESPRAY WHEEL CAP	180.00	50	
4	TO RESPRAY RIM	180.00	0	
Total:		1,116.00	450.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
Total:		480.00	140.00	

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	TO WASH AND VACUUM	60.00	0	
Total:		480.00	140.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,118.61	1,953.71
Total Labour Cost	845.00	450.00
Total Spray Painting	1,116.00	450.00
Other	480.00	140.00
Overall Total	5,559.61	2,993.71
Lump Sum Repair Option	☒	☒
Lump Sum Total	5,550.00	3,000.00
Surveyor Approved Amount		3,000.00
No of Repair Days*	6	4
Remarks	-	L/S repair, photo after paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	18/01/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: