

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 21 January 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : FBG 6692C

Rieju Marathon PRO125

ACCIDENT DATE: 7 January 2019

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>	
1 Handle Bar <i>distorted</i>	1	150.00	✓
2 Hand Guard <i>HW</i>	1 set	180.00	X
3 Clutch Lever <i>broken</i>	1	75.00	✓
4 Mirror with Holder <i>cut N/S</i>	1 set	120.00	✓
5 Balancer <i>cut N/S</i>	1 set	120.00	✓
6 Head Lamp <i>broken</i>	1	220.00	✓
7 Head Lamp Cover <i>broken</i>	1	120.00	✓
8 Head Lamp Guard <i>cut / broken</i>	1	150.00	✓
9 Front RH Signal <i>broken</i>	1	75.00	✓
10 Front LH Signal <i>broken</i>	1	75.00	✓
11 Front Mudguard <i>cut</i>	1	250.00	✓
12 Fork Assy <i>1st</i>	1 set	480.00	✓
13 Meter Bracket <i>1st</i>	1	220.00	✓
14 Fork Guard RH <i>cut</i>	1	120.00	✓
15 Front Rim <i>HW</i>	1	320.00	✓
16 Fork Under Bracket <i>1st</i>	1	150.00	X
17 Handle Bar Bracket <i>1st</i>	1	90.00	✓
18 Front LH Side Fairing <i>damaged</i>	1	135.00	✓
19 Rear LH Signal <i>broken</i>	1	75.00	✓
20 Flasher Relay <i>broken</i>	1	125.00	✓
21 Head Lamp Relay Connector <i>broken</i>	1	135.00	✓
Sub-Total		3,385.00	
Less 10%		338.50	
Sub-Total		3,046.50	

VEHICLE NO: : FBG 6692C

Rieju Marathon PRO125

Nett items

1	Rear number plate <i>1st</i>	15.00 ✓
2	Towing fee <i>400</i>	50.00 301-
3	Remove & replace parts, align & etc	280.00 2001-
4	Remove & replace fork assy, top up fork oil	150.00 801-
5	Supply body sticker	180.00 801-
6	Remove & replace front rim & check alignment	80.00 501-
7	Check harness & reconnect eletrical wiring	60.00 301-

Sub-Total 815.00

Nett Total 3,861.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

:LG

21/01/2019 e 1100hrs

Nett Amount

4/5mm

4 days.

[Signature]

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 25 January 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel : 97237799

VEHICLE NO : FBG 6692C

Rieju Marathon PRO125

ACCIDENT DATE: 7 January 2019

Supplementary Items

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Ignition Switch <i>Dm</i>	1	180.00 ✓
	Sub-Total	180.00
	Less 10%	18.00
	Sub-Total	162.00

Special Nett items

1 Meter Assy <i>broken mainly</i>		650.00 ✓
	Sub-Total	650.00
	Nett Total	812.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

:LG

25/01/2019

[Signature]
LKK Auto