

ISSUANCE

INS. CASE OWNER:

Lynn Chan CC 4, Asm 1900 1355, Jfa3s2

LKK: 94291
IDAC:

21/1/2019

ASSIGNMENT

SAVED BY: OAJ

DATE: 21/1/2019

Time: 9

Registered in M.L. area:

Pre-assign / CCU / FTE



Insured Vehicle No. : SLL 1969T

Claim No. : 59m01A0J

Name of Insured : Susanto nguryan

Policy No. :

Insured Tel No. : HP: 15/1/2019

Make / Model : PRIN PANJANG RD

Excess Sec II : SS

D.O.A : 15/1/2019

Place of Accident :

Is driver the owner? (YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : %

Final ? Yes / No

SAC 4752B



INSRS:

WSP: SMART.MR

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

1/2
OAJ

SAC 4752B - call report to MITS (Swa3) on 16/1/19
- call MITS on 18/1/19 (16/1/19) ; call 18/1/19
- call AXA on 17/1/19 (16/1/19) ; call 18/1/19
SLL 1969T, X
OI video uploaded in Smart.
- Pending investigation. TP stopped in the middle to pick up passenger. To reject ltr. Pending inquiry pending LOD to reject TP claim
Investigation result in, pending LOD to reject TP claim
8/10 - COR not killy. to check to Steve.
16/10 - TP disagree with rejection. seek AXA instructions
23/10 - Email LOI.
- Rec COR to TP (pending LOD)
11/12 - LOD in, pending LTA search inv.
13/12 - LTA search inv in, to seek mandate.
- Pending mandate approval.
13/1 - Offw & settle @ \$33,390.65 as per LOD on send (pench per m)

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	7 CPL 25/10/19
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
After call ltr to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release Voucher:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>
Towing Invoice:	<input checked="" type="checkbox"/>
LTA / GIA :	<input checked="" type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>
PIR:	<input checked="" type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
LOD	<input checked="" type="checkbox"/>
Payment Breakdown Form:	<input checked="" type="checkbox"/>
Post-Repair Photos:	<input checked="" type="checkbox"/>
Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 21/1/2019 Sent By: Steve

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Steve

Repair Cost:

PK

SS \$24,380.81 (13 days) Reduction: \$68,124.14 % 74.

Email

Call

FINAL SETTLEMENT

Date/Time: 13/1/2020

Confirm with: Lee Gek

Email

Call

Final Liability:

% 100 (Agreed / Assessed) BOLA S/N No. : 21.

If NO or B 28, Ass. Lia :

Repair Cost:

SS \$24,380.81

Loss of Rental (LOR):

SS \$902.84 (79 days) x \$113.96

Loss of Use (LOU):

SS - (\$ x days)

Loss of Income (LOI):

SS - (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search

SS \$7.00

Medical:

SS -

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS - (e.g. Tow/ Independent)

2) Report Format: TP

Legal Cost:

SS -

3) Survey fee: \$350/-

Total:

SS \$33,390.65 Global Sum SS: -

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS \$33,390.65 Name: SMART TAXIS Pte Ltd

Payee 2 (Strike if N.A.)

SS -

Payee 3 (Strike if N.A.)

SS -

COPY SENT 31/1/2020

✓ GIA

Hire Die

REF: ASMLAXA)

ASSIGNMENT

From: _____ Date: **21/01/2019**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: **SHC 4752B**

at Workshop m/s: **SMRT**

of: **Woodlands**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No


GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: **17** days Res.: Yes or No

Lum Sum: **1-B-1** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**



Veh No: **SHC 4752B** Yr Regn: **1/4/2016**

Type: M.Gar / M.Cycle / Bus / Van / Lorry / **Taxi** / Prime Mover /

Truck / Trailer or _____

Make: **Toyota Prius** G.C. **1798**

Colour: **Maroon** A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JTDKN36U505767755**

Gen. Cond: Good / **Fair** / Poor / Burnt

Steering: **Insured** / Jammed / Leaked / Burnt or _____

Brake: **Insured** / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: **195/65R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **westlake**

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 15/1/19	D.O.I. 21/1/19

Survey held at **SMRT**

Des. of Damages **Front** / **Rear** / O/S / N/S / UIC / Rooftop or _____

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

01/19/2012

P/P \$24,380.81 (Red = \$68,124.14 / 74%) SLL1969T SHA 719895

* 13 repair days + 2 Saturdays + 2 Sundays + 2 PRS + 2 PH +

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1) _____ + PRS _____

2) Photos _____

3) Other _____

4) _____

TOTAL _____



Add Fee: Site Insp (\$) _____

Interview (\$) _____

Tech. Invs (\$) _____

Weekend (\$) _____

Section A - Accident Details	
Registration Number	SHC4752B
Case Reference Number	TAX/01/19/2072
Registration Date	1/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ABDULLAH BIN MOHAMED NOR
Type of Accident	Head to Rear
Accident Date and Time	15/1/2019 12:05 AM
Accident Reported Date and Time	15/1/2019 10:02 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	15/1/2019 12:39 AM
Replacement Vehicle issued?	No
Job Card Number	24099690
Special Instruction to ARC, if any	TOWED \$90 / AXA
Prepared Date and Time	16/1/2019 3:35 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,723.00	\$2,300.00
Total Spray Cost	\$9,158.00	\$2,610.00
Total Spare Part Cost	\$59,048.75	\$18,030.81
Total Other Cost	\$4,996.00	\$1,440.00
TOTAL COST	\$77,925.75	\$24,380.81 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	22.0	13.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AXA
ARC / Surveyor Sign Off Date	22/01/2019 7:43 PM	21/01/2019 6:51 PM
Signature		
Remarks		P/P PHOTO BEFORE PAINT

Part - 8975.59 ✓
 Labour - 2300
 Spray - 2610 ✓
 Other - 1440 ✓
 Supp - 9055.22 ✓
 24,380.81

92504.95



Case Details

Case Reference Number : TAX/01/19/2072
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4752B

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5377-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 14/01/2019 04:05 PM
 Vehicle Age(In Months) : 33

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			PANEL, ROOF SIDE, / LH SIDE	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	X NN
One Time Key In	Main			PANEL, ROOF SIDE OUTER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	X NN
One Time Key In	Main		10	RAIL, ROOF SIDE LH	1	273.60	273.60	25.00	205.20	Replace	1	0	Repair	X RR
One Time Key In	Main		10	DOOR RR/LH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	X RS
One Time Key In	Main			DOOR LOCK RR/LH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	X NN
One Time Key In	Main			HINGE LOWER LHR, DOOR	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	X NN
One Time Key In	Main			HINGE UPPER LHR, DOOR	1	81.70	81.70	25.00	61.28	Replace	0	0	Not Give	X NN
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	100.30	100.30	25.00	112.73	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Not Give	X NN
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	X NN

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	X NI
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	X NN
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	X NN
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	X NN
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	X NN
One Time Key In	Main			DUCT ASSY, QUARTER	2	70.40 140.80	140.80	25.00	105.60	Replace	2	105.60	Replace	/ BUC
One Time Key In	Main			BACK ASSY, REAR SIDE SEAT, RH	1	643.80	643.80	25.00	482.85	Replace	0	0	Not Give	X NN
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give	X NN
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	X NN
One Time Key In	Main		LD	DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	X R
One Time Key In	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	X NN
One Time Key In	Main			HINGE LOWER RHR, DOOR	1	52.00	52.00	25.00	39.00	Replace	0	0	Not Give	X NN
One Time Key In	Main			HINGE UPPER RHR, DOOR	1	61.70	61.70	25.00	61.28	Replace	0	0	Not Give	X NN
One Time Key In	Main			DOOR LOCK STRIKER	1	40.50	40.50	25.00	30.38	Replace	0	0	Not Give	X NN
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361.50	Replace	/ DR
Total Spare Part Cost						49,993.55	Surveyor Total						8,975.50	
Lump Sum Discount (%)						0.00	Lump Sum Dis (%)						0	
Final Spare Part Cost						49,993.55	Final Sur Total						8,975.50	

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER CLIPS	10	1.61 16.10	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ NCL
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Check	X NMI
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	X NMI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	X NMI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	X NMI
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	✓ SCR
One Time Key In	Main		10%	FOG LAMP LH	1	280.10	280.10	10.00	252.09	Replace	1	252.09	Replace	✓ SCR
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	X NMI
One Time Key In	Main			COVER, FR BUMPER HOLE LH	1	18.50	18.50	25.00	13.88	Replace	1	13.88	Replace	✓ SCR
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	1	57.30	Replace	✓ CRA
One Time Key In	Main			BRACKET, FR TURN CENTER LH	1	58.20	58.20	25.00	43.65	Replace	0	0	Check	X NMI
One Time Key In	Main			BRACKET, FR TURN UPPER LH	1	24.40	24.40	25.00	18.30	Replace	0	0	Check	X NMI
One Time Key In	Main			BRACKET, FR TURN LOWER LH	1	26.00	26.00	25.00	19.50	Replace	0	0	Check	X NMI
One Time Key In	Main		10%	LENS & BODY, FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	1	460.62	Replace	✓ SCR
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Check	X NMI

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SUPPORT SUB-ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Check	X NN
One Time Key In	Main		107	HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	1	850.68	Replace	/ CRA
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace	/ OZF
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ NEC
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check	X NN
One Time Key In	Main			FENDER LINER PAD, FR WHEEL LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give	X NB
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0	Check	X NN
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Check	X MI
One Time Key In	Main		15	WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	X R
One Time Key In	Main		16	DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair	X R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ Me
One Time Key In	Main		17	PILLAR, FR BODY, LH	1	363.10	363.10	25.00	272.33	Replace	1	0	Repair	X R
One Time Key In	Main			SEAL, FRONT FENDER TO COWL SIDE, LH	1	15.20	15.20	25.00	11.40	Replace	1	11.40	Replace	/ NEC
One Time Key In	Main			COOLANT	1	12.32	12.32	0.00	12.32	Replace	0	0	Check	X NN
One Time Key In	Main			QUARTER GLASS FRT/LH	1	234.90	234.90	25.00	176.18	Replace	0	0	Not Give	X NN
Total Spare Part Cost									49,993.55	Surveyor Total			8,975.50	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									49,993.55	Final Sur Total			8,975.50	

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	X NAI
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	/ DEF
One Time Key In	Main			BUMPER CLIPS	10	1.61 16.10	16.10	25.00	12.08	Replace	10	12.08	Replace	/ NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace	/ DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	/ DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	/ DD
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	X NAI
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	/ Shorts
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ NEC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace	/ DEF
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	X NAI
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.66	Replace	1	171.66	Replace	/ DEF
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace	/ NEC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace	/ NEC
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	/ C.R.B

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Surveyor Approval			Remarks	
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give *	X NN
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	1	385.88	Replace *	/ DEF
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Check *	X NN
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Not Give *	X NN
One Time Key In	Main			EXHAUST PIPE FRT	1	4,184.70	4,184.70	25.00	3,138.52	Replace	0	0	Not Give *	X NN
One Time Key In	Main			SUPPORT EXHAUST PIPE, NO.4	2	40.30	80.60	25.00	60.45	Replace	0	0	Not Give *	X NN
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Not Give *	X NN
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace *	/ DD
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace *	/ NEC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace *	/ NEC
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	1	818.18	Replace *	/ CRA
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace *	/ NEC
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace *	/ CRA
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace *	/ NEC
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Check *	X NN

Total Spare Part Cost 49,993.55

Surveyor Total 8,975.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 49,993.55

Final Sur Total 8,975.50

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Surveyor Approval				Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.67	Replace	/ DEF
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, LOWER	1	190.70	190.70	25.00	135.52	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, RH	1	68.30	68.30	25.00	66.22	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0	Check	X NN
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Check	X NN
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Check	X NN
One Time Key In	Main			MOTOR ASSY, RR WIPER	1	734.60	734.60	10.00	661.14	Replace	0	0	Check	X NN
One Time Key In	Main			ARM, RR WIPER	1	84.70	84.70	25.00	63.53	Replace	0	0	Check	X NN

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Surveyor Approval				Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BLADE ASSY, REAR WIPER	1	55.00	55.00	25.00	41.25	Replace	0	0	Check	* X NN
One Time Key In	Main			CAMERA ASSY, TELEVISION, RR	1	1,436.60	1,436.60	10.00	1,292.94	Replace	0	0	Check	* X NN
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	10.00	131.49	Replace	0	0	Check	* X NN
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace	* / BUC
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / NEC
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check	* X NN
One Time Key In	Main			LID ASSY, FUEL	1	102.00	102.00	25.00	76.50	Replace	0	0	Check	* X NN
One Time Key In	Main			* CABLE SUB-ASSY, FUEL LID	1	63.90	63.90	25.00	47.92	Replace	0	0	Check	* X NN
One Time Key In	Main			RETAINER, FUEL LID CABLE	1	5.90	5.90	25.00	4.43	Replace	0	0	Check	* X NN
One Time Key In	Main			CAP ASSY, FUEL TANK	1	68.10	68.10	25.00	51.07	Replace	0	0	Not Give	* X NN
One Time Key In	Main			PIPE SUB-ASSY, FUEL NECK	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	* X NN
One Time Key In	Main			TUBE, FUEL TANK	1	36.10	36.10	25.00	27.08	Replace	0	0	Not Give	* X NN
One Time Key In	Main			TANK SUB-ASSY, FUEL	1	745.10	745.10	25.00	558.83	Replace	0	0	Not Give	* X NN
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	1	126.07	Replace	* / NEC

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

BOM Type	Costing Type	Portion	Material Number	Part Name	SMRT Recommendation						Surveyor Approval			Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	/ NEC
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	X NN
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give	X NN
One Time Key In	Main			REINFORCEMENT, ROOF SIDE INNER LH	1	60.30	60.30	25.00	45.22	Replace	0	0	Check	X NN
One Time Key In	Main			REINFORCE, ROOF SIDE OUTER LH	1	91.90	91.90	10.00	82.71	Replace	0	0	Check	X NN
One Time Key In	Main			REINFORCEMENT, BACK DOOR SIDE LH	1	89.50	89.50	25.00	67.13	Replace	0	0	Check	X NN
One Time Key In	Main			EXTENSION, QUARTER PANEL FRONT LH	1	83.50	83.50	25.00	62.63	Replace	0	0	Check	X NN
One Time Key In	Main			EXTENSION, QUARTER PANEL REAR LH	1	108.50	108.50	10.00	97.65	Replace	0	0	Check	X NN
One Time Key In	Main			PANEL, ROOF SIDE, INNER LH	1	134.80	134.80	25.00	101.10	Replace	0	0	Check	X NN
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	/ NEC
One Time Key In	Main			LICENSE PLATE LAMP	2	35.70	71.40	25.00	53.55	Replace	0	0	Check	X NN
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	/ BUC
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	/ BUC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ NEC
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	/ NEC

Total Spare Part Cost 49,993.55

Surveyor Total 8,975.50

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 49,993.55

Final Sur Total 8,975.50

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ NEC
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	0	Repair	X R
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	X NN
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ NEC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	X NN
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Check	X NN
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0	Check	X NN
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	X NN
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	X NN
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB ASSY, REAR FLOOR CROSS NO.1	1	436.40	436.40	25.00	327.30	Replace	0	0	Check	X NN
One Time Key In	Main			MEMBER SUB ASSY, REAR FLOOR CROSS NO.2	1	655.70	655.70	25.00	491.78	Replace	0	0	Check	X NN

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation											Surveyor Approval				
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0	Check *	X NAI	
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Check *	X NN	
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Check *	X NAI	
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Check *	X NAI	
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Check *	X NAI	
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0	Check *	X NN	
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0	Check *	X NN	
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0	Check *	X NAI	
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0	Check *	X NN	
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Check *	X NN	
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Check *	X NN	
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Check *	X NN	
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Check *	X NAI	
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give *	X NN	
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give *	X NN	
Total Spare Part Cost									49,993.55	Surveyor Total		8,975.50			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0			
Final Spare Part Cost									49,993.55	Final Sur Total		8,975.50			

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Check	X NAI
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check	X NAI
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0	Check	X NAI
One Time Key In	Main			GARNISH SIDE UPPER, LHR	1	261.70	261.70	25.00	196.27	Replace	0	0	Check	X NAI
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Check	X NAI
One Time Key In	Main			BATTERY ASSY, HV	1	5,544.40	5,544.40	10.00	4,989.96	Replace	0	0	Check	X NAI
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Check	X NAI
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Check	X NAI
One Time Key In	Main			WIRE, FRAME	1	1,680.90	1,680.90	25.00	1,260.68	Replace	0	0	Check	X NAI
One Time Key In	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Not Give	X NAI
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Check	X NAI
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Check	X NAI
One Time Key In	Main			RECEIVER, DOOR CONTROL	1	239.70	239.70	10.00	215.73	Replace	0	0	Check	X NAI
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	X NAI
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	X NAI

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	X NN
One Time Key In	Main			PANEL, QUARTER WHEEL HOUSE, OUTER LH	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	X NN
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	X NN
One Time Key In	Main		10/17	TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	1	493.56	Replace	✓ CRB
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	10.00	99.81	Replace	0	0	Check	X NN

Total Spare Part Cost	49,993.55	Surveyor Total	8,975.50
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	49,993.55	Final Sur Total	8,975.50

Labour's Cost Detail

8975.59

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	400	
2	Main	TO REPAIR REAR PORTION	2,028.00	600	
Total:			2,873.00	1,200.00	+ 1100 (supp) = 2300

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
5	Main	TO RESPRAY RIM	540.00	50	
6	Main	TO RESPRAY FRONT PILLAR LH	180.00	80	
7	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
Total:			7,542.00	1,710.00	