

INS. CASE OWNER:

CC 4, ASM 1900

1360, K1paz⁵

LKK:

IDAC:

94686

Surveyor:

DOI:

Date / Time

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJM 7733K

SHC 6648G

SHC 5005 T

SHD 6661 L

INSRS:
WSP:
Tel:
Liability:
RMKS:

01

INSRS:
WSP: *brunner*
Tel:
Liability:
RMKS:

TP

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

11/2

SHC 6648G - X; SJM 7733K - X

7/2

4VC; OI LAST.

21/1/19

File -> built toward BS from KAM

25-6-19 @ 515PM

W/OI. HE CONFIRM
DUA SAT NIGHT COZ
SUNDAY IS CLOSE SO
HE MADE A REPORT
ON MONDAY 21/1/19.
AGREED & AWARE
NCD ISSUE.

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	☐	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice	☐	☐
LTA / GIA:	☒	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☒	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☐	☐
Others: Purchase Invoice	☒	☐

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

Email

Call

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(13 days) X\$114.06

Loss of Use (LOU):

S\$

(\$ - x - days)

Loss of Income (LOI):

S\$

(\$ - x - days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$: 113W-W

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Premier Automotive Services Pte Ltd @GIA

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
21/1/19

1) Claim status: Normal/Reject/Private Settle
2) Report Format: 9P
3) Survey fee: \$350-W

Surveyor: Kolvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 66486 Yr Regt: 24 Jan 43
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1685Colour: silver A/C: Insured / Std / NI / NASp. Reading: 882562 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAG A414AD5370289

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 26/1/19 D.O.I. 21/8/19Survey held at Praser

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front / Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/8/19	Work. can accept <u>45 \$ 9200</u> / 10 Rep. <u>AXA</u>
	<u>215 \$ 9200. w/creed 12711.10 58%</u>
	Bulk Value: <u>\$ 31420.50</u>
	17A Rebaer: <u>\$ 22214.00</u>
	NBV = <u>\$ 9206.50</u>

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL _____

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

1 pc	Bonnet — <i>Del</i>	\$	979.00
1 pc	Bonnet lock <i>X su</i>	\$	36.00
1 pc	Bonnet lifter <i>X su</i>	\$	70.00
1 pc	Bonnet lock base <i>X su</i>	\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 <i>X su</i>	\$	46.00
1 pc	Bonnet grille — <i>su</i>	\$	385.00
1 pc	Support panel — <i>Del</i>	\$	645.00
1 pc	Front bumper — <i>su</i>	\$	531.00
1 pc	Front bumper emblem — <i>su</i>	\$	44.00
1 pc	Front bumper centre grille — <i>su</i>	\$	174.00
1 pc	Front bumper lower stiffer <i>X su</i>	\$	134.00
1 pc	Front bumper tow hook cover <i>X su</i>	\$	14.00
1 pc	Front bumper lip <i>X su</i>	\$	52.00
1 pc	Front bumper inner sponge <i>X su</i>	\$	110.00
1 pc	Front bumper reinforcement — <i>Del</i>	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 <i>X su</i>	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 <i>n/s su o/s X su</i>	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 <i>n/s su o/s X su</i>	\$	132.00
1 pc	Air con condenser — <i>Del</i>	\$	805.00
1 pc	Radiator — <i>Del</i>	\$	669.00
1 pc	Air duct <i>X su</i>	\$	210.00
1 pc	Intercooler — <i>Del</i>	\$	800.00
1 pc	Blower assy <i>X su</i>	\$	596.00
1 pc	Boot lid — <i>Del</i>	\$	1,119.00
1 pc	Boot lid lock — <i>Del</i>	\$	99.00
1 pc	Bootlid lock cable — <i>su</i>	\$	35.00
1 pc	Bootlid striker — <i>su</i>	\$	21.00
1 pc	Bootlid emblem — <i>su</i>	\$	27.00
1 pc	Bootlid CRDi — <i>su</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip <i>X su</i>	\$	96.00
1 pc	Boot lid lower garnish — <i>su</i>	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 — <i>Del</i>	\$	132.00
1 pc	Bootlid inner trim <i>X su</i>	\$	190.00
1 pc	End panel — <i>Del</i>	\$	250.00
1 pc	End panel inner garnish — <i>su</i>	\$	74.00
1 pc	Rear n/s fender — <i>Del</i>	\$	1,205.00
1 pc	Rear n/s fender inner shield <i>X su</i>	\$	120.00
1 pc	Rear windscreen moulding — <i>su</i>	\$	87.00
1 pc	Rear bumper — <i>Del</i>	\$	696.00

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

1 pc	Rear bumper lower cover	— <i>cs</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	<i>n/s on ds x se</i>	\$	58.00
1 pc	Rear bumper inner sponge	— <i>cs</i>	\$	114.00
1 pc	Rear bumper reinforcement	— <i>cs</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	<i>Bar</i>	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	<i>X se</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	<i>X se</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	<i>16 one o/s x se</i>	\$	92.00
2 pcs	n/s & o/s tail lamp @ \$421.00	<i>n/s - on o/s x se</i>	\$	842.00
2 pcs	n/s & o/s reflector @ \$350.00	<i>n/s - on o/s x se</i>	\$	700.00
1 pc	n/s tail lamp panel	— <i>2 n/s</i>	\$	215.00
1 pc	Floorboard panel	<i>X se</i>	\$	625.00
1 pc	Floorboard panel trim	<i>X se</i>	\$	205.00
				\$ 17,239.00
Less 10%				\$ 1,723.90
				\$ 15,515.10

S/NETT

1 set	Rear bumper clips	— <i>se</i>	\$	48.00
1 set	End panel inner garnish clips	— <i>se</i>	\$	30.00
1 set	Bootlid inner trim clips	— <i>se</i>	\$	52.00
1 set	Bootlid lower garnish clips	— <i>se</i>	\$	60.00
1 set	Bootlid stickers	— <i>se</i>	\$	100.00
1 set	Reverse sensor	— <i>old</i>	\$	280.00 200.
1 pc	Rear bumper top protector	— <i>se</i>	\$	80.00 50
1 set	Floorboard compartment insulating paddings	<i>se</i>	\$	120.00 50
1 pc	Rear no. plate with casing	<i>Best</i>	\$	50.00 35
1 pc	Coolant 6L	<i>se</i>	\$	40.00
1 pc	Front no. plate with casing	<i>Best</i>	\$	50.00 35
1 pc	Front bumper clips	<i>se</i>	\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00	<i>se</i>	\$	12.00 16 - o/s x se
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00	<i>se</i>	\$	6.00 16 - o/s x se

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

Sundry	n/s \$	50.00 20
Towing Fee	\$	50.00
To check for wiring and to focus head lamps	\$	80.00 20
To top up aircon gas	\$	120.00 50
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
To dismantle and refit the rear windscreen	\$	120.00 100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s chassis	\$	2,200.00 1800
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s fender, rear n/s taillamp panel, front bumper, bonnet, rear n/s & o/s chassis member	\$	2,200.00 1440
To apply rustproofing on the repaired and replaced panels.	\$	300.00 100
	\$	<u>21,911.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants must notify the Repairer of the following:

- To resurvey before/after body painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modifications allowed
- Supplementary items must be approved and is subject to final approval by insurance company

Knownledged by Repairer
Signature:
Date:

18/2/19
LKK 45\$ 12600/10 Rr.
N

Kahilly
N 21/1/19 1635hr
10 Rr.
45
Allen Rr. pth

Enquire Transaction History**Transaction History Details**

Log Date/Time:	24 Jan 2013 / 10:27:44	Receipt No.:	AACCK001-AX239-130124-000008
Asset Type:	Vehicle	Transaction Amount:	\$70,810.00
Asset ID:	SHC6648G	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20130124102744232560		
Vehicle No.:	SHC6648G		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	24 Jan 2013		
Original Registration Date:	24 Jan 2013		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MD5370289		
Engine No.:	D4FDCH306762		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2012		
Open Market Value:	\$17,515.00		
Minimum PARF Benefit:	\$6,009.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	24 Jan 2013 10:27:44		
COE No.:	2013012401000867Z		
COE Expiry Date:	23 Jan 2021		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$60,655.00		
Lifespan Expiry Date:	23 Jan 2021		
Owner ID Type:	Company		
Owner ID:	200304975H		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

1 pc	Bonnet ✓	\$	979.00
1 pc	Bonnet lock ✕	\$	36.00
1 pc	Bonnet lifter ✕	\$	70.00
1 pc	Bonnet lock base ✕	\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 ✕	\$	46.00
1 pc	Bonnet grille ✓	\$	385.00
1 pc	Support panel ✓	\$	645.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille ✓	\$	174.00
1 pc	Front bumper lower stiffer ✕	\$	134.00
1 pc	Front bumper tow hook cover ✕	\$	14.00
1 pc	Front bumper lip ✕	\$	52.00
1 pc	Front bumper inner sponge ?	\$	110.00
1 pc	Front bumper reinforcement ✓	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ?	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 n/s - o/s ?	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 n/s - o/s ✕	\$	132.00
1 pc	Air con condenser ?	\$	805.00
1 pc	Radiator ?	\$	669.00
1 pc	Air duct ?	\$	210.00
1 pc	Intercooler ?	\$	800.00
1 pc	Blower assy ?	\$	596.00
1 pc	Boot lid ✓	\$	1,119.00
1 pc	Boot lid lock ✓	\$	99.00
1 pc	Bootlid lock cable ✓	\$	35.00
1 pc	Bootlid striker ✓	\$	21.00
1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip ?	\$	96.00
1 pc	Boot lid lower garnish ✓	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 ✓	\$	132.00
1 pc	Bootlid inner trim ✕	\$	190.00
1 pc	End panel ✓	\$	250.00
1 pc	End panel inner garnish ✓	\$	74.00
1 pc	Rear n/s fender ✓	\$	1,205.00
1 pc	Rear n/s fender inner shield ✕	\$	120.00
	Rear windscreen moulding ✓	\$	87.00
1 pc	Rear bumper ✓	\$	696.00

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

1 pc	Rear bumper lower cover	✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	n/s - ds ?	\$	58.00
1 pc	Rear bumper inner sponge	✓	\$	114.00
1 pc	Rear bumper reinforcement	✓	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	1b - o/s x	\$	92.00
2 pcs	n/s & o/s tail lamp @ \$421.00	n/s - o/s x	\$	842.00
2 pcs	n/s & o/s reflector @ \$350.00	n/s - o/s x	\$	700.00
1 pc	n/s tail lamp panel	✓	\$	215.00
1 pc	Floorboard panel	X 142	\$	625.00
1 pc	Floorboard panel trim	X	\$	205.00
				\$ 17,239.00
				Less 10%
				\$ 1,723.90
				\$ 15,515.10

S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 set	End panel inner garnish clips	✓	\$	30.00
1 set	Bootlid inner trim clips	✓	\$	52.00
1 set	Bootlid lower garnish clips	✓	\$	60.00
1 set	Bootlid stickers	✓	\$	100.00
1 set	Reverse sensor	✓	\$	280.00
1 pc	Rear bumper top protector	✓	\$	200
1 set	Floorboard compartment insulating paddings		\$	80.00
1 pc	Rear no. plate with casing		\$	120.00
1 pc	Coolant 6L		\$	50.00
1 pc	Front no. plate with casing		\$	40.00
1 pc	Front bumper clips		\$	50.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00		\$	48.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00		\$	12.00
				6.00

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

Sundry	\$	50.00 20
Towing Fee	\$	50.00 —
To check for wiring and to focus head lamps	\$	80.00 20
To top up aircon gas	\$	120.00 50?
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 30
To dismantle and refit the rear windscreen	\$	120.00 100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s chassis	\$	2,200.00 1800
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s fender, rear n/s taillamp panel, front bumper, bonnet, rear n/s & o/s chassis member	\$	2,200.00 1440
To apply rustproofing on the repaired and replaced panels.	\$	300.00 100
	\$	<u>21,911.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahiri 16/1/19

21/1/19 1635hrs

10 Pys.

4/s

Allen Pys. p. 16

LKIC Auto Consultants is a notary
the Reparer of the following:

- To resurvey before/after repair
- To display damaged parts during resurvey
- Parts prices are subject to market value
- Third party survey is done on a "no prejudice" basis
- No illegal modification to vehicle
- Supplementary work is done as required and is subject to final approval by insurance company

Known by Reparer:

Signature:

Date:

CASH SALE/WORK ORDER

No:AD 4868



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 19.6.19

買號
Messrs: Premier

車號
Vehicle No: S14C 66486 車型
Model No: OPTIMA

由
From: Marina Bay Sands

到
To: Omega

其他
Remark: (1 key)

時間
Time: 22:50-23:30-00:10 AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人
Authorised by:  收貨人
Received by: 

Service Request Details

Claim

S9M01B84

Reference

None 

Loss Date

January 19, 2019

Request Date

January 21, 2019

Due Date

January 28, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHC6648G

Make

TPVD

21/01/2019 @ 3:10pm
Vincent veh in
Kelvin.

Service Address

...

Primary Contact/Insured

CHUA TIONG KEE
BLK 33 MARSILING DRIVE, #05-363, 730033, Singapore
91095010
NCDDANNY@GMAIL.COM

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Monday, 21 January, 2019 1:32 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: Vincent Chua
Subject: Pre-inpsection SHC6648G & SJM7733K on 19.01.19
Attachments: 21012019132933-0001.pdf

Categories: Pragati

Dear All

We refer to the above mentioned.

Kindly arrange for survey

We prefer LKK Auto as SJE

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511 Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

☑ Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION ☑

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4975H
Vehicle Details	
Vehicle No.:	SHC6648G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	D4FDCH306762
Chassis No.:	KNAGM414MD5370289
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$17,515.00
Original Registration Date:	24 Jan 2013
First Registration Date:	24 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$10,015.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jan 2021
PARF Rebate Amount:	\$7,010.00
Intended COE Rebate Details	
COE Expiry Date:	23 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,655.00
COE Rebate Amount:	\$15,204.00
Total Rebate Amount:	\$22,214.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Jan 2019

OK

Cost of Taxi: \$107,655.00



Service Request Details

Claim

S9M01B84

Reference

CC4/ASM19001360/K1ja3 

Loss Date

19 January 2019

Report Date

21 Jan 2019 11:41:00 AM

Request Date

21 January 2019

Due Date

21 January 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work

More ▾

Vehicle Information

Make
TPVD

Model
TBC

Service Address

Primary Contact/Insured

CHUA TIONG KEE
BLK 33 MARSILING DRIVE, #05-363, 730033, Singapore
91095010
NCDDANNY@GMAIL.COM

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE

SENT

FROM

SUBJECT

BODY

2/7/19 12:08 PM

LKK AUTO CONSULTANTS PTE LTD (TP)

RE: MANDATE IA - PREMIER- SHC 6648G

WE WOULD LIKE TO FOLLOW-UP FOR MANDATE.



LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu

SENT 25/6/19 5:35 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT MANDATE IA - PREMIER- SHC 6648G

BODY FOR YOUR QUANTUM APPROVAL. THANK YOU



TYPE



SENT 25/1/19 5:20 PM

FROM ANG Richard

SUBJECT Pls proceed to engage OI & propose DS. TY.

BODY





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 24/1/2019

Survey Details:

Date of loss	19-Jan-19
Date of appointment	21-Jan-19
Date of survey	21-Jan-19
Location of survey	PREMIER AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHC6648G
Make and Model	KIA OPTIMA 1.7(A) DIESEL
Date of registration	24-Jan-13
Parf Rebate	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	21,911.10
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 12,138.40
Check items (estimate)	
Labour	\$ 3,660.00
Total	\$ 15,798.40
Lump Sum(if applicable)	\$ 12,600.00

Number of days for repair	10 days
---------------------------	---------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

4 VEHICLE CHAIN ; OI IS THE LAST VEHICLE. BOLA 28

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	13,482.00	
Loss of rental	\$	1,482.78	\$114.06 x 13
LTA search fees	\$	2.00	
Others			
Proposed Total	\$	14,966.78	

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 13 August 2019 11:15 AM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 94686, vehicle number SHC6648G

13/8/19 9:34 AM

*** Message Hi, pls advise on the book value of the taxi. TY. - ANG Richard

-----Original Message-----

From: richard.angbs@axa.com.sg [mailto:richard.angbs@axa.com.sg]
Sent: Tuesday, 13 August, 2019 9:35 AM
To: admin-d@lkkauto.com
Subject: New message for service request 94686, vehicle number SHC6648G

AXA Insurance has sent you a message for claim number S9M01B84.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.