

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

1 pc	Bonnet ✓	\$	979.00
1 pc	Bonnet lock ✕	\$	36.00
1 pc	Bonnet lifter ✕	\$	70.00
1 pc	Bonnet lock base ✕	\$	13.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00 ✕	\$	46.00
1 pc	Bonnet grille ✓	\$	385.00
1 pc	Support panel ✓	\$	645.00
1 pc	Front bumper ✓	\$	531.00
1 pc	Front bumper emblem ✓	\$	44.00
1 pc	Front bumper centre grille ✓	\$	174.00
1 pc	Front bumper lower stiffer ✕	\$	134.00
1 pc	Front bumper tow hook cover ✕	\$	14.00
1 pc	Front bumper lip ✕	\$	52.00
1 pc	Front bumper inner sponge ?	\$	110.00
1 pc	Front bumper reinforcement ✓	\$	328.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00 ?	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00 ?	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00 n/s ✓ o/s ?	\$	2,056.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00 n/s ✓ o/s ✕	\$	132.00
1 pc	Air con condenser ?	\$	805.00
1 pc	Radiator ?	\$	669.00
1 pc	Air duct ?	\$	210.00
1 pc	Intercooler ?	\$	800.00
1 pc	Blower assy ?	\$	596.00
1 pc	Boot lid ✓	\$	1,119.00
1 pc	Boot lid lock ✓	\$	99.00
1 pc	Bootlid lock cable ✓	\$	35.00
1 pc	Bootlid striker ✓	\$	21.00
1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip ?	\$	96.00
1 pc	Boot lid lower garnish ✓	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 ✓	\$	132.00
1 pc	Bootlid inner trim ✕	\$	190.00
1 pc	End panel ✓	\$	250.00
1 pc	End panel inner garnish ✓	\$	74.00
1 pc	Rear n/s fender ✓	\$	1,205.00
1 pc	Rear n/s fender inner shield ✕	\$	120.00
	Rear windscreen moulding ✓	\$	87.00
1 pc	Rear bumper ✓	\$	696.00

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

1 pc	Rear bumper lower cover	✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	n/s - d/s ?	\$	58.00
1 pc	Rear bumper inner sponge	✓	\$	114.00
1 pc	Rear bumper reinforcement	✓	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	?	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	1/s - o/s x	\$	92.00
2 pcs	n/s & o/s tail lamp @\$421.00	n/s - o/s x	\$	842.00
2 pcs	n/s & o/s reflector @\$350.00	n/s - o/s x	\$	700.00
1 pc	n/s tail lamp panel	✓	\$	215.00
1 pc	Floorboard panel	X 142	\$	625.00
1 pc	Floorboard panel trim	X	\$	205.00
				\$ 17,239.00
Less 10%				\$ 1,723.90
				\$ 15,515.10

S/NETT

1 set	Rear bumper clips	✓	\$	48.00
1 set	End panel inner garnish clips	✓	\$	30.00
1 set	Bootlid inner trim clips	✓	\$	52.00
1 set	Bootlid lower garnish clips	✓	\$	60.00
1 set	Bootlid stickers	✓	\$	100.00
1 set	Reverse sensor	✓	\$	280.00 200
1 pc	Rear bumper top protector	✓	\$	80.00 50
1 set	Floorboard compartment insulating paddings		\$	120.00 50
1 pc	Rear no. plate with casing		\$	50.00 35
1 pc	Coolant 6L		\$	40.00 ✓
1 pc	Front no. plate with casing		\$	50.00 35
1 pc	Front bumper clips		\$	48.00 ✓
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00		\$	12.00 16 - o/s x
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00		\$	6.00 n/s - o/s x

21-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6648 G

Sundry	\$ 50.00 20
Towing Fee	\$ 50.00 —
To check for wiring and to focus head lamps	\$ 80.00 20
To top up aircon gas	\$ 120.00 50?
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30
To dismantle and refit the rear windscreen	\$ 120.00 100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard panel, rear n/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s chassis	\$ 2,200.00 1800
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s fender, rear n/s taillamp panel, front bumper, bonnet, rear n/s & o/s chassis member	\$ 2,200.00 1480
To apply rustproofing on the repaired and replaced panels.	\$ 300.00 100
	<u>\$ 21,911.10</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Ka Li 16/1/19

21/1/19 1635hr

10 Pgs.

4/s

Allen Png pth

CASH SALE/WORK ORDER

No:AD 4868



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 19.6.19

寶號 *Pioneer*
Messrs:

車號 *S14C 6648G* 車型 *OPTIMA*
Vehicle No: Model No:

由 *Marina Bay Sands*
From:

到 *@ megar*
To:

其他 *(1 car)*
Remark:

時間 *22:50-23:30-00:10* AMOUNT: \$
Time: AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人 *[Signature]* 收貨人 *[Signature]*
Authorised by: Received by: