

INS. CASE OWNER:

CC 6, ALG 1900 1361, 07/05/19

LKK:

IDAC:

Surveyor:

Xhd

DOI:

ASSIGNMENT

18/1/19

Time:

18/1/19

Registered in Merimen:

21/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDN SIME

Name of Insured:

WY KUT BOON

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

17/1/19

Is driver the owner?

(YES (P))

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SDY 43346



INSRS:

WSP:

Tel:

Liability:

RMKS:

WPH



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

18/1/19
CMTSDY 43346 - C8/ALG 09224916/91 ; DOA: 6/4/19
SDN SIME - X18/3/19
20/3/19Call ODI - Inform TP claim & aware NCD affected.
Send LOI - File pass to VIC to check.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 18/3/19 CCM/DA

After call ltr to OI: 20/3/19 CCM/DA VIC-DE

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: X69

Repair Cost:

P/P SS 4,061.95

(4 days)

Reduction:

48 %

Email

Call

FINAL SETTLEMENT

Date/Time: 04.09.19

Confirm with: PEGGY

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

71

If NO or B 28, Ass. Lia:

Repair Cost:

01/09 SS 4,353.71

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 500.00

(\$100 x 5 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only ☐ LOU only ☒

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 2.40

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+ 330

Total:

SS 4,854.71

Global Sum SS:

FINAL PAYMENT

Date/Time: 04.09.19

Confirm with: PEGGY

Email

Call

Payee 1:

SS 4,854.71

Name 1:

WPH ADD SERVICE

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
14/9/19

Xkd.

REF:

ALG

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

NPH Anto

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt.: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SDY 4334G Yr Regn: /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier c.c. 1998

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

18398

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTEKB36H20J000992

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

235/55 R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

18-01-19

Survey held at

w/s

4pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/1 Estimate Give later

PIP: +4.067.95 (250): +3.813.25 4870

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S * RS: \$

Pix/Agg

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692

Your Ref : GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
Our Ref : TP0006/01/19 E-mail: nphauto@pacific.net.sg

Page : 1/2
Date : 19/01/2019



THIRD PARTY CLAIM

N/S : YIP TAI SENG
BLK 27 BALAM ROAD
#13-31
SINGAPORE 370027

Attn :

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SDY4334G - TOYOTA HARRIER
INSURED : YIP TAI SENG
DATE OF ACCIDENT : 17/01/2019
POLICY NO : 5105794835

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: ENGINEER : D

Date: CHASSIS# : E

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<u>Replacement of Parts</u>				
1 rear boot Harrier Emblem / <i>YMC</i>	10	97.70	97.70	97.70
2 rear boot turbo emblem / <i>YMC</i>	10	60.00	60.00	60.00
3 rear bumper / <i>re</i>	10	995.00	995.00	995.00
4 rear bumper parking sensor - <i>DM 444.75 x 2 = 889.50</i>	40	477.00	477.00	1,908.00
5 rear bumper lower spoiler - <i>cut</i>	10	455.00	455.00	455.00
6 rear bumper reflector lamp L & R X <i>SW</i>	20	57.60	57.60	115.20
7 rear bumper side retainer L & R X <i>SW</i>	20	85.00	85.00	170.00
8 rear bumper sponge X <i>CNA</i>	10	125.00	125.00	125.00
9 rear bumper support bar X <i>SW</i>	10	1340.00	1340.00	1,340.00
10 rear bumper clips / <i>MC</i>	90	5.00	5.00	45.00
11 rear exhaust box X	10	1185.00	1185.00	1,185.00
12 rear exhaust chrome pipe X	10	125.00	125.00	125.00
13 rear exhaust mounting X	10	33.60	33.60	33.60
14 rear bumper exhaust top cover X	10	172.20	172.20	172.20
Less 25%				6,826.70
Total Material				-1,706.68
Labour & Misc				\$5,120.02

1616.15 1741.75
25% *1242.56*
1306.31

- 1 Remove and install rear lamp, rear bumper, bumper lower spoiler. Cut out and renew rear lamp panel, rear lamp center panel lower, knock rear boot, rear spare tyre panel & restraighthen body and chassis.
- 2 Spray painting
- 3 Check wiring system.
- 4 Remove and install rear boot carpet.
- 5 Remove and reset parking sensor.

900.00 *800*

800.00 *600*

25.00

120.00

100.00

Total *4067.96*

~~Insurance report 20/01/19~~ P/P

4 Days

After repair photo's.

18/1/19 Gmo Qmp.

P-3283.85

25.2

2462.96

44067.96



NPH AUTO SERVICE



Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
E-mail: nphauto@pacific.net.sg

Your Ref :
Our Ref : TP0005/01/19
Page : 2/2
Date : 19/01/2019

THIRD PARTY CLAIM

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
6 Remove and install Exhaust /				100.00
				2,045.00
Total Labour				\$2,045.00
Nett Total Before Get				\$7,165.02

Your faithfully

NPH AUTO SERVICE
(Manager)



NPH AUTO SERVICE

Block 9005 Tampines Street 45 #01-241/242/243 Singapore 628830 Tel: 67840692 Fax: 67840692
 Block 9005 Tampines Street 45 #01-241/242/243 Singapore 628830 Tel: 67840692 Fax: 67840692 (8 Lines)
 GST Reg No: MX 066440890 Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Your Ref : Page : 1/1
 Our Ref : RP0046/01/19 Date : 15/03/2019

SUPPLEMENTARY
 M/S : YIP TAI SENG
 BLK 27 BALAM ROAD
 #13-31
 SINGAPORE 370027

Attn : T.S YIP

Dear Sir/Madam

RE: ACCIDENT REPAIR ON : SDY4334G - TOYOTA HARRIER
 INSURED : I.T.S ADVERTISING & RENOVATION ENGINE# : D
 DATE OF ACCIDENT : 07E01TD019 CHASSIS# : E
 POLICY NO : 5105794835

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & TO BE REPLACED:

	Qty	U/Cost	U/Price	Total
		\$	\$	\$
<u>Replacement of Parts</u>				
1 parking sensor wire	short 10	179.40	179.40	179.40 ✓
2 parking sensor ring bracket	one 20	21.30	21.30	42.60 ✓
4 rear lamp lower retainer L & R	11 20	121.10	121.10	242.20 X
5 keyless sensor	short 10	64.10	64.10	64.10 ✓
6 rear bumper enforcement bracket L & R	two 20	213.30	213.30	426.60 ✓
				954.90
Less 25%				-238.73
Total Material				\$716.18
Nett Total Before Gst				\$716.17

Your faithfully

NPH AUTO SERVICE
 (Manager)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2037J
Vehicle Details	
Vehicle No.:	SDY4334G
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER G GRADE
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	8ARZ100488
Chassis No.:	JTEKB3GH20J000992
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$33,308.00
Original Registration Date:	15 Dec 2017
First Registration Date:	15 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$38,632.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Dec 2027
PARF Rebate Amount:	\$28,974.00
Intended COE Rebate Details	
COE Expiry Date:	14 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,996.00
COE Rebate Amount:	\$43,450.00
Total Rebate Amount:	\$72,424.00

The information contained herein is correct as at 05 Apr 2019

OK

Asher Sng (LKKAuto)

From: peggy <nphauto@pacific.net.sg>
Sent: Friday, 30 August 2019 2:56 PM
To: Asher Sng (LKKAuto)
Subject: FW: ACCD INLVG SDY4334G AND SDN5121E ON 17/01/2019
Attachments: SKMBT_C224e19083014350.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Dear Asher

We refer to the above matter and claiming against you as follows:

Cost of repair	\$ 4,352.71
Loss of Use	\$ 500.00
GIA	2.00

Total	\$ 4,854.71
	=====

Attach documents and please let us have your reply.

REGARDS

PEGGY FOO
NPH AUTO SERVICE
Email : peggy@nphauto.com
TEL: 67840663
FAX: 67840692



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19001361/Gpa3

20 March 2019

LOH KIAT YOON

659 Changi Road
Singapore 419951

Dear Sir/Madam,

ACCIDENT INVOLVING SDN 5121E AND SDY 4334G ON 17/01/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

As spoken, kindly forward accident scene photos for our reference.

Please call us if you have further queries.

Yours faithfully,

Cecilia Chong
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: ceciliachong@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORIZATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, YIP TAI SENG (the third party claimant") of BLK 27 BALAM ROAD #13-31 SINGAPORE 370027 (address), owner of SDY 4334G (vehicle no.) hereby authorize NPH AUTO SERVICE ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no SDY 4334G that was damaged pursuant to the accident which occurred on 17/01/2019 (date) along PIE ENTERING INTO SERANGOON ROAD (location) involving vehicle no/s SDN 5121E ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of NPH AUTO SERVICE.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 6th (day) of Sept (month) 20 19 (year)


Signed by "the third party claimant"
(with chop if applicable)


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, NPH AUTO SERVICE ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,352.71 (Repair Cost), S\$500.00 (Loss of Use/~~Rental~~), S\$2.00 (Disbursement) for vehicle no. SDY 4334G that was damaged pursuant to the accident which occurred on 17/01/2019 (date) along PIE ENTERING INTO SERANGOON ROAD (location) involving vehicle no/s SDN 5121E.

This is pursuant to the inspection conducted on 18/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner YIP TAI SENG ("the third party claimant") of vehicle no. SDY 4334G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SDY 4334G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 09 (day) of 09 (month) 2019 (year)


XGO
Signed by appointed surveyor


Signed by "the workshop" (with chop)



NPH AUTO SERVICE

Block 9005 Tampines Street 93 #01-246/254 Singapore 528839 Tel: 67840663 (8 Lines) Fax: 67840692
 GST Reg No: MX-0869103-NO Business Reg No: 394773/00D
 E-mail: nphauto@pacific.net.sg



Our Ref : TP0006/01/19
 Your Ref :
 YIP TAI SENG
 YIP TAI SENG
 BLK 27 BALAM ROAD
 #13-31
 SINGAPORE 370027

TAX INVOICE NO. : 06547
 Date of
 Accident Date : 17/01/2019
 Policy Number : 5105794835
 Model : TOYOTA HARRIER
 Veh Reg No : SDY4334G
 Date : 08/04/2019

Replacement of Parts

rear boot Harrier Emblem	61.75
rear boot turbo emblem	60.00
rear bumper	995.00
rear bumper lower spoiler	455.00
rear bumper sponge	125.00
rear bumper clips	45.00
parking sensor ring brace	42.60
keyless sensor	64.10
rear bumper reinforcement bracket L&R	426.60
rear bumper parking sensor	829.48
parking sensor wire	179.40
Total Material	\$3,283.93
Less 25%	-820.98
	\$2,462.95

Labour & Misc

Remove and install rear lamp, rear bumper, bumper lower spoiler. Cut out and renew rear lamp panel, rear lamp center panel lower, knock rear boot, rear spare tyre panel & restraighthen body and chassis.	800.00
ray painting	600.00
Cneck wiring system.	25.00
Remove and install rear boot carpet.	60.00
Remove and reset parking sensor.	40.00
Remove & install rear exhaust box.	80.00
Total Labour	\$1,605.00
Less 0%	50.00
	\$1,605.00

Nett Total Before GST	\$4,067.95
Add GST @ 7%	\$284.76
Nett Total After GST	\$4,352.71

Third Party Insurer Enquiry

Our Ref No: GR-19-010722

Date of Request: 18/01/2019

Your Ref No: Online Purchase

NPH Auto Service
Blk 9005 Tampines Street 93
#01-246/254
Singapore 528839

Dear Sir/Madam,

Enquiry Date 18/01/2019
Enquiry By Mark Ng Yong Xiang
TP Vehicle No. SDN5121E
Accident Date 17/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SDN5121E	AIG Asia Pacific Insurance Pte. Ltd.	23/05/2018-22/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2019 Edit Reg		18 Jan 2019 00:00 Edit Adj Rpt	S\$4,067.95 Edit Estimates	S\$4,067.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LOH KIAT YOON, ID: S1436549D		
Main Claimant:	YIP TAI SENG, ID: S1462037J		
Vehicle Reg. No.:	SDY4334G	Date of Loss:	17/01/2019 21:00 - :59 [13 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8968405180SG	Policy/Cover Note No.:	2100022385 (Third Party Only)
Vehicle Reg. No. (Insured):	SDN5121E	Policy No. (Claimant):	5105794835
		Excess:	
Repairer:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254, 528839 Tampines - Tel: 6784 0663		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/01/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDY4334G (89684051805G)

[SDN5121E]

TP
























































YIP TAI SENG

Jan 17 2019 9:00PM

[LOH KIAT YOON]

NPH Auto Service

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Letters/Correspondences										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	[Draft]	Third Party Express Settlement – Payment Breakdown								1	Edit		
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
2	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
3	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
4	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
5	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
6	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
7	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
8	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
9	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
10	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
11	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
12	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
13	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
14	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
15	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
16	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
17	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
18	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
19	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
20	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
21	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
22	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
23	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
24	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
25	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
26	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
27	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
28	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
29	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
30	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
31	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
32	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
33	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
34	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
35	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
36	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
37	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
38	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
39	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	
40	11/04/19 17:39	General View								1	Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	11/04/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
42	11/04/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
43	11/04/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
44	11/04/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
45	11/04/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
46	11/04/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
47	11/04/19 17:39	General View	 Load JPG	<input checked="" type="checkbox"/>
48	11/04/19 17:40	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
49	11/04/19 17:40	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
50	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
86	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
87	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
88	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
89	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
90	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
91	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
92	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
93	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
94	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
95	11/04/19 17:40	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
96	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
97	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
98	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
99	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
100	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
101	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
102	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
103	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
104	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
105	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
106	11/04/19 17:40	Dismantled Parts		Load JPG	<input checked="" type="checkbox"/>
107	11/04/19 17:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
108	11/04/19 17:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
109	11/04/19 17:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
110	11/04/19 17:41	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
111	11/04/19 17:41	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
112	11/04/19 17:41	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/01/19 09:20	TP GIA REPORT		Load PDF	
2	13/09/19 07:52	WORKSHOP INVOICE		Load PDF	
3	13/09/19 07:52	AUTHORISATION TO ACT FORM		Load PDF	
4	13/09/19 07:52	Release Voucher		Load PDF	
5	13/09/19 07:52	GIA SEARCH		Load PDF	
6	13/09/19 07:52	LOD		Load PDF	
7	13/09/19 07:52	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	23/01/19 14:16	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDN5121E (Insd veh)	Model:	TOYOTA HARRIER 2.0 G
	SDY4334G (TP veh)		GRADE (A)
Date of Accident:	17/01/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	8,432.88	
Final Repair Cost	:	\$	4,352.71	
Loss of Use	:	\$	500.00	5.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	4,854.71	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	NPH Auto Service	:	\$ 4,854.71
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

13 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001361/GEA3Q2

Date: 13/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100022385
Claimant SDY4334G **Insured Vehicle No :** SDN5121E
Vehicle No : SDY4334G **Nature of Claim:** TP **Claim No:** 8968405180SG
Date of Loss: 17/01/2019

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDY4334G**
 Make & Model: TOYOTA HARRIER, 2.0 G GRADE (A) Engine No: 8ARZ100488
 Reg. Date: 15/12/2017 (Man. Year: 2017) Chassis No: JTEKB3GH20J000992
 Colour: Red Odometer: 18398 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,836.20	2,462.95	3,373.25	57.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,045.00	1,605.00	440.00	21.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,881.20	4,067.95	3,813.25	48.38
+ GST 7.00/7.00% (S\$)	551.68	284.76	266.92	48.38
Nett Amount (S\$)	8,432.88	4,352.71	4,080.17	48.38
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,854.71		

INSPECTION

Date of Assignment: 18/01/2019

Date Inspected: 18/01/2019 Inspected At:

NPH Auto Service (HQ)
 Blk 9005 Tampines Steet 93, #01-
 246/254
 Singapore 528839

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT HARRIAR EMBLEM	Necessary	97.70 FL	*61.75 FL
2	1		*REAR BOOT TURBO EMBLEM	Necessary	60.00 FL	*60.00 FL
3	1		*REAR BUMPER	Deformed	995.00 FL	*995.00 FL
4	4		*REAR BUMPER PARKING SENSOR	Damaged (2 PCS ONLY)	1,908.00 FL	*829.48 FL
5	1		*REAR BUMPER LOWER SPOILER	Cut	455.00 FL	*455.00 FL
6	2		*REAR BUMPER REFLECTOR LAMP L&R	Not Necessary	115.20 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER L&R	Not Necessary	170.00 FL	*- FL
8	1		*REAR BUMPER SPONGE	Cracked	125.00 FL	*125.00 FL
9	1		*REAR BUMPER SUPPORT BAR	Not Necessary	1,340.00 FL	*- FL
10	9		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
11	1		*REAR EXHAUST BOX	Not Necessary	1,185.00 FL	*- FL
12	1		*REAR EXHAUST CHROME PIPE	Not Necessary	125.00 FL	*- FL
13	1		*REAR EXHAUST MOUNTING	Not Necessary	33.60 FL	*- FL
14	1		*REAR BUMPER EXHAUST TOP COVER	Not Necessary	172.20 FL	*- FL
15	1		*PARKING SENSOR WIRE	Shorted	179.40 FL	*179.40 FL
16	2		*PARKING SENSOR RING BRACKET	Cracked	42.60 FL	*42.60 FL
17	2		*REAR LAMP LOWER RETAINER L&R	Not Necessary	242.20 FL	*- FL
18	1		*KEYLESS SENSOR	Shorted	64.10 FL	*64.10 FL
19	2		*REAR BUMPER ENFORCEMENT BRACKET L&R	Twisted	426.60 FL	*426.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,781.60	3,283.93
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,945.40	820.98
Total Parts (\$\$)	5,836.20	2,462.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND INSTALL REAR LAMP ,REAR BUMPER ,BUMPER LOWER SPOILER ,CUT OUT AND RENEW REAR LAMP PANEL,REAR LAMP CENTER PANEL LOWER,KNOCK REAR BOOT ,REAR SPARE TYRE PANEL & RESTRAIGHTEN BODY AND CHASSIS	New	900.00	800.00
2	SPRAY PAINTING	New	800.00	600.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	REMOVE AND INSTALL REAR BOOT CARPET	New	120.00	60.00
5	REMOVE AND RESET PARKING SENSOR	New	100.00	40.00
6	REMOVE AND INSTALL EXHAUST	New	100.00	80.00
Gross Labour Cost (S\$)			2,045.00	1,605.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >