



FINAL REPORT

Estimate No. : **b1 49830**
Date Estimated : **21/01/2019**
Prepared By : **Han Kwan Yong**

Page No. :

REPAIR FOR -
Yang Jian
35 Amber Road
#13-17 The Seaview

Singapore 439945

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKV6976Z	L493357	29/06/2012	X5 xDRIVE35i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
* To replace rear bumper and attachments, boot lid include knocking out dented areas caused by the accident	1700.00		1,700.00	
To respray rear bumper and boot lid	1805.00		1,805.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID BOTTOM	1,649.35	1.00		1,649.35
# TRIM PANEL BUMPER RR BOTTOM (PDC) *	277.95	1.00		277.95
RR BUMPER PRIMED	1,607.05	1.00		1,607.05
EXPANDING RIVET	1.35	30.00		40.50

SUPPLEMENTARY ITEMS

Total Labour :	4,286.00
Total Parts :	3,574.85
Total Labour & Parts :	7,860.85
Deduction for Excess :	0.00
Total Repair Costs less Excess:	7,860.85
GST @7%:	550.26
Grand Total :	8,411.11