

IN CASE OWNER:

Joel

CC 4, 501 1900

13/6/3, T1 3/3/19

LKK:

IDAC:

Insurer:

Tampik

(NOI):

## ASSIGNMENT

28/1/2019

Date/Time:

7/1/19

Registered in Merimen:

Pre-assign / CCU / FTE

SLB 997X



Insured Vehicle No.:

Name of Insured:

Tan Eng Chai

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A.:

18/1/19

Is driver the owner?

(YES NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLP 27104



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

23/1  
CPC

Sup 7104 - X, SLB 997X - X

BOLA 28, 100%, 3 car chain collision and TP  
7s first vehicle, 01 7s second vehicle, 01 front  
damage more severe than rear. Send letter to 01

Pending finalise LOR

1719 - settle @ \$7623.10, NO DV required  
(File pass Admin to close).

better print photo

## STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI: 9/5/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

## PRELIMINARY ADVICE

Date/Time:

27/2/2019

Sent By:

HMK

## FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Tampik

Repair Cost:

PIP

S\$ 6842.15

(5 days)

Reduction:

4443.75 % 21

## FINAL SETTLEMENT

Date/Time:

24/1/19/12-45pm

Confirm with:

Caroline

Email:

Call:

Final Liability:

% 100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ GST)

S\$ 7321.10

Loss of Rental (LOR):

S\$ -

(5 days)

Loss of Use (LOU):

S\$ 300

(360 x 5 days)

Loss of Income (LOI):

S\$ -

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 7623.10

Global Sum S\$:

-

## FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$ 7623.10

Name 1:

Performance motors limited

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

-

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

-

COPY SENT

Taufer

REF: E61

13031910

# ASSIGNMENT

Form: Date: 28012019

Estimated Cost:

OL / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

SLP 2710U  
Performane  
303 Alexandra Rd

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Yaguel

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days Res: Yes or No

Lum Sum:

1-2-1 % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

SLP2710U - 2017 May

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 318I

C.C.

1499.

Colour:

Black

A/C

Insured / Std / NI / NA

Sp. Reading

49571

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA RE 36 600 NU 78982

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / Shim / STD A/Rim or

Tyre Size:

F: 225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIK / SUMI /

TOYO / YOKO or

Front

6

Rear

R/Bal.

6 mm

R/Bal

6 mm

L/Bal.

6 mm

L/Bal

6 mm

D.O.A.

D.O.A.

28/1/19

Survey held at

FWL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

P/P - 46842.15 (Red = 81793.75/21%)

Date/Time: File Pass to?



: Preli. Report

1)



: Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1. ... + ...

2. ...

3. ...

4. ...

Total

Report Format:

Lump Sum / I.B.T. / S

Add Fee:



Site Insp \$



Interview \$



Tech Invs \$



Work-and \$

MS Dealer:

# Performance Motors Limited

A member of the Sime Darby Group.  
Co. Reg. No. 187401539W GST Reg. No. M2-0020081-X



333, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 43190160 (Sales & Admin)  
43190111 (AfterSales)  
Fax. 44747770

380, Pasirong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 43190886 (AfterSales)  
Fax. 43449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 43190538 (AfterSales)  
43190531/439 (Motorrad)  
Fax. 44796601 (AfterSales)  
44796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

18 JAN 2019

## ESTIMATE

Estimate No. : b1 49817  
Date Estimated : 18/01/2019  
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Shahrom Bin Mohamed Ariff  
Blk 609, Choa Chu Kang St 62  
#10-85

Singapore 680609

- ACCOUNT - 45912  
EQ Insurance Company Limited  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2710U	NU78982	31/05/2017	318iA/4Dr	0

### DESCRIPTION

Replacing rear bumper panel and attachments, bootlid, etc  
to knock out dents caused by the accident

1700 <sup>1730</sup> 2,550.00

Spray rear bumper and bootlid

1730 1,923.00

To check electrical wiring systems and lightings at the  
rear section for proper function.

150 177.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

Sundries *h*

80 ? 150.00

Total Labour 1: 4,918.00

### DESCRIPTION

BOOTLID  
REAR BUMPER CENTRE GUIDE  
REAR BUMPER CARRIER (ECE)  
REAR BUMPER LH SIDE GUIDE  
REAR BUMPER PANEL PRIMED (LINES)  
LETTERING 318i  
GROMMET  
PLAQUE 74MM  
TRUNK LID GASKET  
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC
1	1,179.80
1	32.90
1	467.95
1	58.50
1	1,172.30
1	64.10
2	0.75
1	71.25
1	76.40
4	5.05

61 1,179.80  
xhn 32.90  
xnt 467.95  
xnt 58.50  
de 1,172.30  
ne 64.10  
ne 1.50  
ne 71.25  
xnn 76.40  
ne 20.20

Total Parts : 3,144.90

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



101, Alexandra Road  
Sime Darby Performance Centre  
Singapore 119941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

290, Rongong Avey Road  
East Coast Centre  
Singapore 438185  
Tel. 63190000 (AfterSales)  
Fax. 63449773

115, Alexandra Road  
Sime Darby Business Centre  
Singapore 119944  
Tel. 63190520 (AfterSales)  
63190513/530 (MotorRAD)  
Fax. 64794601 (AfterSales)  
64794624 (MotorRAD)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 49817  
Date Estimated : 18/01/2019  
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2710U	NU78982	31/05/2017	3181A/4Dr	0

Circle L1 / L2 / L3 / L4 / L5 / L6 / L7 / L8 / L9 / L10 / L11 / L12 / L13 / L14 / L15 / L16 / L17 / L18 / L19 / L20 / L21 / L22 / L23 / L24 / L25 / L26 / L27 / L28 / L29 / L30 / L31 / L32 / L33 / L34 / L35 / L36 / L37 / L38 / L39 / L40 / L41 / L42 / L43 / L44 / L45 / L46 / L47 / L48 / L49 / L50 / L51 / L52 / L53 / L54 / L55 / L56 / L57 / L58 / L59 / L60 / L61 / L62 / L63 / L64 / L65 / L66 / L67 / L68 / L69 / L70 / L71 / L72 / L73 / L74 / L75 / L76 / L77 / L78 / L79 / L80 / L81 / L82 / L83 / L84 / L85 / L86 / L87 / L88 / L89 / L90 / L91 / L92 / L93 / L94 / L95 / L96 / L97 / L98 / L99 / L100

Claim No. \_\_\_\_\_  
Date: 20/1/19 11:10  
Excess: \$0  
Surveyor's Name: Tanyu  
Surveyor's Tel: 97493249  
Authorized: Yes / No  
Authorized Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
SURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No  
Surveyor's E-mail: tanyu@plants.com  
No. of Working Days Recommended: 5 days

### LKK Auto Consultants hence notify the Repairer of the following:

- To survey before the repair starts
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary costs must be resolved and is subject to final approval from insurance company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_



Labour 1	:	4,918.00
Parts	:	3,144.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	564.40
Grand Total	:	8,627.30

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



## SUPPLEMENTARY

Estimate No. : b1 49817  
Date Estimated : 18/01/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -

Shahrom Bin Mohamed Ariff  
Blk 609, Choa Chu Kang St 62  
#10-85

Singapore 680609

- ACCOUNT -

45912

EQ Insurance Company Limited  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SLP2710U	NU78982	31/05/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function *	451.00		451.00 ✓
----------------------------------------------------------------------------------------------------------------------------------------------	--------	--	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING NUT *	1.00	2.00		2.00 ✓ NEC
# SET MOUNTING PDC/PMA SENSOR REAR *	66.95	1.00		66.95 ✓ NEC
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05 ✓ NEC

Total Labour :	451.00
Total Parts :	122.00
Total Labour & Parts :	573.00

Liability Consultant to verify the following of the following:

- To verify labour rates apply
- To verify damaged parts being replaced
- To verify parts are subject to confirmation
- To verify parts are subject to "Provisional" basis
- To verify parts are subject to "Provisional" basis
- To verify parts are subject to "Provisional" basis
- To verify parts are subject to "Provisional" basis

Approved by Requester

Signature:

Date:

42635.90



## FINAL REPORT

Estimate No. : b1 49817  
Date Estimated : 18/01/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Shahrom Bin Mohamed Ariff  
Blk 609, Choa Chu Kang St 62  
#10-85

- ACCOUNT - 45912  
EQ Insurance Company Limited  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

Singapore 680609

REGN. NO	CHASSIS NO.	REGN. DATE	MODEL	M LEASE
SLP2710U	NU78982	31/05/2017	318iA/4Dr	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace rear bumper and attachments, boot lid include knocking out dents caused by the accident	1700.00		1,700.00
To spray paint rear bumper and boot lid	1730.00		1,730.00
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00
To carry out body cavity preservation (Per panel)	100.00		100.00
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function *	451.00		451.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,179.80	1.00		1,179.80
# EXPANDING NUT *	1.00	2.00		2.00
REAR BUMPER PANEL PRIMED (LINES)	1,172.30	1.00		1,172.30
# SET MOUNTING PDC/PMA SENSOR REAR *	66.95	1.00		66.95
LETTERING 318i	64.10	1.00		64.10
GROMMET	0.75	2.00		1.50
PLAQUE 74MM	71.25	1.00		71.25
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

### # SUPPLEMENTARY ITEMS

Total Labour :	4,211.00
Total Parts :	2,631.15
Total Labour & Parts :	6,842.15
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,842.15
GST @7%:	478.95
Grand Total :	7,321.10

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/538 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

18 JAN 2019

## ESTIMATE

Estimate No.	: b1 49817	Page No. :	1 of 5
Date Estimated	: 18/01/2019		
Prepared By	: Joseph Yaguel		

<b>- ESTIMATE REPAIR FOR -</b> <b>Shahrom Bin Mohamed Ariff</b> <b>Blk 609, Choa Chu Kang St 62</b> <b>#10-85</b>  <b>Singapore 680609</b>	<b>- ACCOUNT - 45912</b> <b>EQ Insurance Company Limited</b> <b>5 Maxwell Road, #17-00 Tower Block</b> <b>MND Complex</b> <b>Singapore 069110</b>
-----------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2710U	NU78982	31/05/2017	318iA/4Dr	0

DESCRIPTION	VALUE
Replacing rear bumper panel and attachments, bootlid, etc to knock out dents caused by the accident	1720 2,550.00
Spray rear bumper and bootlid	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	600 118.00
Sundries	? 150.00

Total Labour 1: **4,918.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,179.80	61- 1,179.80
REAR BUMPER CENTRE GUIDE	1	32.90	? 32.90
REAR BUMPER CARRIER (ECE)	1	467.95	? 467.95
REAR BUMPER LH SIDE GUIDE	1	58.50	? 58.50
REAR BUMPER PANEL PRIMED (LINES)	1	1,172.30	de- 1,172.30
LETTERING 318i	1	64.10	ne- 64.10
GROMMET	2	0.75	ne- 1.50
PLAQUE 74MM	1	71.25	ne- 71.25
TRUNK LID GASKET	1	76.40	? 76.40
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	ne- 20.20

Total Parts : **3,144.90**



303, Alexandra Road  
Elite Darby Performance Centre  
Singapore 159941  
Tel. 43190100 (Sales & Admin)  
43190311 (AfterSales)  
Fax. 44747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 83390888 (AfterSales)  
Fax. 83449773

315, Alessandra Road  
Sine Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/310 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 49817  
Date Estimated : 18/01/2019  
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2710U	NU78982	31/05/2017	318iA/4Dr	0

0

26/1/17 e1110

Toughen

9749549

paper

REMOVED DATE PHOTO BY SURVEYOR 01/1/17

Surveyor's E-mail toughen@plants.com

File of Working Date Recommended 5 days

225 | 50 R17 PIR.

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before repairs by painter
- To display damaged parts and resurvey
- Parts prices are subject to confirmation
- Third party survey is on a without prejudice basis
- No illegal modifications allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance company

#### Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_



Labour 1	:	4,918.00
Parts	:	3,144.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	564.40
Grand Total	:	8,627.30

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\***

**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***



**Catherine Chong (LKK Auto)**

---

**From:** Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>  
**Sent:** Monday, 21 January, 2019 10:45 AM  
**To:** assignments  
**Subject:** FW: REQUEST FOR DIRECT SETTLEMENT - SLP2710U & SLB997X (EQ) ON 17/01/2019  
**Attachments:** SLP2710U.PDF; SLB997X.PDF

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Dear Sir / Madam,

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

*21-01-2019 @ 1:20pm  
Confine with not in*

---

**From:** Joel Goh <joel.goh@eqinsurance.com.sg>  
**Sent:** Monday, 21 January, 2019 10:39 AM  
**To:** Admin A <admin-a@lkkauto.com>  
**Subject:** RE: REQUEST FOR DIRECT SETTLEMENT - SLP2710U & SLB997X (EQ) ON 17/01/2019

Dear LKK

Attached both accident reports for your attention.

Best Regards,

**Joel Goh**

Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t*

---

**From:** Joel Goh  
**Sent:** Monday, January 21, 2019 10:34 AM  
**To:** 'PBSP'  
**Cc:** Admin A  
**Subject:** RE: REQUEST FOR DIRECT SETTLEMENT - SLP2710U & SLB997X (EQ) ON 17/01/2019

Without Prejudice

Dear Caroline

We welcome direct settlement and will appoint LKK to handle it.

Dear LKK

Please take over this direct settlement.

Best Regards,

Joel Goh  
Executive | Claims



**EQ Insurance Company Limited**  
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** PBSP [<mailto:pml-pbsp@simedatby.com.sg>]  
**Sent:** Friday, January 18, 2019 4:07 PM  
**To:** EQI PRS  
**Subject:** REQUEST FOR DIRECT SETTLEMENT - SLP2710U & SLB997X ON 17/01/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Cecilia Chong (LKK Auto)

---

**From:** Olivia Lau (LKKAuto)  
**Sent:** Thursday, 12 September 2019 1:32 PM  
**To:** PBSP; Cecilia Chong (LKK Auto)  
**Cc:** Admin A; Hsiao Tong (LKKAuto)  
**Subject:** [EQ]: LOD REMINDER - SLP2710U & SLB997X ON 17/01/2019 // LKK Ref: CC4/EQI19001363/T1ga3

LKK Ref: CC4/EQI19001363/T1ga3

*Without Prejudice*

Hi Caroline,

Thank you for your email.

Cecilia – FYNA please.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: [olivialau@lkkauto.com](mailto:olivialau@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make  
good  
use of  
Today

---

**From:** PBSP [mailto:[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)]  
**Sent:** Thursday, 12 September 2019 12:45 PM  
**To:** Poh Kin (LKKAuto) <[pohkin@lkkauto.com](mailto:pohkin@lkkauto.com)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** Re: LOD REMINDER - SLP2710U & SLB997X ON 17/01/2019

Dear Sirs

We have instructions to accept your offer of settlement.

Please proceed with payment ASAP.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Wednesday, 11 September 2019 5:06 PM  
**To:** Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>  
**Cc:** 甯瑤 @ <admin-a@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>  
**Subject:** Re: LOD REMINDER - SLP2710U & SLB997X ON 17/01/2019

Dear Joseph

A gentle reminder - Please confirm customer's acceptance on LOU.

Thank you.

Regards,  
Caroline

---

**From:** PBSP  
**Sent:** Friday, 26 July 2019 10:57 AM  
**To:** Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>  
**Cc:** 甯瑤 @ <admin-a@lkkauto.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>  
**Subject:** Re: LOD REMINDER - SLP2710U & SLB997X ON 17/01/2019

Dear Joseph

Please assist to confirm customer's acceptance.

BMW 318  
LOU OFFERED      \$    300.00  
MCA Submitted    \$    500.00    \$100 x 5

Thank you.

Regards,  
Caroline

---

**From:** Poh Kin (LKKAuto) <pohkin@lkkauto.com>  
**Sent:** Friday, 26 July 2019 10:38 AM  
**To:** PBSP <pml-pbsp@simedarby.com.sg>  
**Cc:** 甯瑤 @ <admin-a@lkkauto.com>  
**Subject:** RE: LOD REMINDER - SLP2710U & SLB997X ON 17/01/2019

**WITHOUT PREJUDICE**  
**SAVE AS TO COSTS**

Our Ref:            CC3/EQ19001363/T1fa3

Your Ref: SLP 2710U

Dear Caroline,

We refer to above matter.

Apologies for late revert.

Towards an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair (w/gst)	S\$ 7,321.10
2. Loss of Use	S\$ 300.00
3. GIA search fee	S\$ 2.00
	<b><u>S\$ 7,623.10</u></b>

kindly confirm acceptance on this matter.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



EQ Insurance Company Limited  
5 Maxwell Road  
#17-00 Tower Block  
MND Complex  
Singapore 069110  
Attention: Motor Claims

Date: 29/05/2019  
Our Ref: PM19H000210/26  
Officer: Joel Aoh  
We acknowledge receipt of your letter & enclosures dated 29/05/2019  
We are investigating your/client's claim and will reply to you substantively soon.  
EQ Insurance

"Without Prejudice"

Your Ref:  
Our Ref:  
Date:  
Subject:

27 May 2019

**ACCIDENT INVOLVING VEHICLES SLP2710U & SLB997X ON 17.01.2019**

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	7321.10
Loss of use	:	S\$	500.00 (S\$100.00 x 5 days)
GIA search fee	:	S\$	2.00
Total	:	S\$	7823.10

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving Licence
5. Copy of Letter of Authorisation

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to [pml-pbsp@sime-darby.com.sg](mailto:pml-pbsp@sime-darby.com.sg).

Yours sincerely

Cresendo Lagman  
Customer Service Manager, Body & Paint

Performance Motors  
Limited  
1800-Call-BMW  
(1800-2255-269)  
[www.pml.com.sg](http://www.pml.com.sg)

303 Alexandra Road  
Sime Darby  
Performance Centre  
Singapore 159941  
Tel Sales 6319 0100  
Tel AfterSales  
6319 0111  
Fax 6474 7770

315 Alexandra Road  
#01-01  
Sime Darby  
Business Centre  
Singapore 159944  
Tel Sales 6319 0511  
Tel AfterSales  
6319 0527  
Fax 6479 6624

280  
Kampong Ayer Rd  
East Coast Centre  
Singapore 438180  
Tel AfterSales  
6319 0088  
Fax 6344 1332

Registered office  
305 Alexandra Road  
#02-01  
Vantage  
Automotive Centre  
Singapore 159942

Co. Reg. No.  
197401559N



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/EQ119001363/T1fa3**

09 MAY 2019

**TAN ENG CHAI**  
89 CASHEW ROAD  
#05-02  
SINGAPORE 679660

Dear Sir/Madam,

**ACCIDENT INVOLVING SLB 997X / SLP 2710U / OTHERS ALONG/ AT PIE  
EXIT BKE (WOODLANDS) ON 17/01/2019**

We refer to the above accident where we are acting for EQ Insurance to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: pohkin@lkkauto.com

c.c. *EQ Insurance*  
*(Motor Claims Dept)*



# Performance Motors Limited

A member of the Sime Darby Group



## LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLP2710U & SLB997X <sup>AND SLP3976Z</sup> ON 17.01.19.

I, SHAHROM BIN MOHAMED ADIFF owner of Vehicle Registration No. SLP2710U  
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and  
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all  
documents whatsoever in relation to this matter and to accept and receive any payment  
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation  
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if  
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement  
amount in respect of such claim shall constitute the full discharge of my claim in respect of  
such loss and damage.

Signed by:

Name: SHAHROM BIN MOHAMED ADIFF (Date) 18 JAN 2019  
NRIC No.: S6935061A

In the presence of:

Name: [Signature] (Date)  
NRIC No.: PERFORMANCE MOTORS LIMITED

303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
TEL: 63190100 (Sales)  
63190111 (AfterSales)

18/1/2019

FORM B1 VERSION 1 - SEPT 2017

## Performance Motors Limited

A member of the Sime Darby Group  
Co Reg No. 19740155W GST Reg. No. M2-0020061-9

103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747772

199, Kampong Arang Road  
East Coast Centre  
Singapore 438196  
Tel. 63190888 (AfterSales)  
Fax. 63447771

515, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190328 (AfterSales)  
63190333 (Motorrad)  
64796001 (AfterSales)  
64796024 (Motorrad)



## SERVICE TAX INVOICE

Repair Order No. : B1 1333920	Page No. : 1 of 2
Date IN : 28/01/2019	Invoice Number : 2102605 / WSB
Motor Claim Advisor: Joseph Yaguel	Invoice Date : 23/05/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -  
Mr Shahrom Bin Mohamed Ariff  
Blk 609, Choa Chu Kang St 62  
#10-85

Singapore 680609

- INVOICE TO - 45912  
EQ Insurance Company Limited  
5 Maxwell Road, #17-00 Tower Block  
MND Complex  
Singapore 069110

REGN. NO. SLP2710U	CHASSIS NO. NU78982	REGN. DATE 31/05/2017	MODEL 318I	MILEAGE 49571
-----------------------	------------------------	--------------------------	---------------	------------------

## - - - - LABOUR 1 - - - -

	NETT
To replace rear bumper and attachments, bootlid including knock out dented area caused by the accident.	1,700.00
To respray rear bumper and bootlid.	1,730.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To carry out body cavity preservation.	100.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 17.01.2019. 3RD PARTY CAR : SLB997X.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO ON 28.01.2019 AT 11:10AM. AUTHORIZED REPAIR BY MR JOEL GOH FROM EQ INSURANCE ON 21.01.2019 VIA EMAIL.	
PROPOSE LOSS OF USE = \$100x5. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00
Total Labour 1:	4,211.00

## - - - - PARTS - - - -

	Qty	Retail Price	NETT
REAR BUMPER PANEL PRIMED (LINES)	1	1,172.30	1,172.30
LETTERING 318I	1	64.10	64.10
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
(DG/SL) ADHESIVE SET K6	1	53.05	53.05
SET MOUNTING PDC/PMA SENSOR REAR	1	66.95	66.95
BOOTLID	1	1,179.80	1,179.80
EXPANDING NUT	2	1.00	2.00
Total Parts :			2,631.15

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 187401559N GST Reg. No. M2-0020081-X



103, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747775

190, Kembangan Road  
East Coast Centre  
Singapore 436186  
Tel. 63190888 (AfterSales)  
Fax. 63449773

116, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190028 (AfterSales)  
63190033/330 (Motorrad)  
Fax. 64796801 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1333920	Page No. : 2 of 2
Date IN : 28/01/2019	Invoice Number : 2102605 / WSB
Motor Claim Advisor: Joseph Yaguel	Invoice Date : 23/05/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

Labour Charges : 4,131.00	Total Labour & Parts Charges : S\$ 6,842.15
Parts Charges : 2,631.15	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 80.00	Invoice Total Amount Exclude GST : S\$ 6,842.15
	GST @ 7% : S\$ 478.95
	Invoice Total Amount Include GST : S\$ 7,321.10

Computer generated invoice. No signature is required.	Amount Payable Include GST : S\$ 7,321.10
-------------------------------------------------------	-------------------------------------------

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-19-010508  
Date of Request: 18/01/2019

Your Ref No: Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 18/01/2019  
Enquiry By: Melanie Setiawati  
TP Vehicle No.: SLB997X  
Accident Date: 17/01/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLB997X	EQ Insurance Company Ltd	28/03/2018-27/03/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-19-010508

Date of Request: 18/01/2019

Your Ref No:

Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 18/01/2019  
Enquiry By Melanie Setiawati  
TP Vehicle No. SLB997X  
Accident Date 17/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 25/09/2019

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	SLB 997X (Insd Veh)	Your Ref. No. : DMPPHQ18-001566
	SLP 2710U (TP Veh)	Our Ref. No. : CC4/EQI19001363/T1ga3q2
Date of Accident	17/1/2019	

Liability	100%	
Final Repair Cost	: \$ 7,321.10	
Loss of Use	: \$ 300.00	5 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	7,623.10	
Final Settlement Sum	: \$ 7,623.10	
Remarks	:	

**Payment Instruction: Payee's Breakdown**

1	PERFORMANCE MOTORS LIMITED	: \$ 7,623.10
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ19001363/T1ga3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 25-09-2019	
			Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLB 997X	Veh. Inspected	SLP 2710U	
Policy No.	DMPPHQ18-001566	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JOEL	Assign Date	21/01/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 318i	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA8E36000NU78982	Colour	BLACK	
Odometer	49571	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	PIRELLI	6 mm	
L/H Front Tyre	225/50 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/01/2019	Inspection Date	28/01/2019	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 2710U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	BOOTLID (SN)	BENT	1,179.80	1,179.80
1	REAR BUMPER CENTRE GUIDE (SN)	NOT NECESSARY	32.90	-
1	REAR BUMPER CARRIER (ECE)(SN)	NOT NECESSARY	467.95	-
1	REAR BUMPER LH SIDE GUIDE (SN)	NOT NECESSARY	58.50	-
1	REAR BUMPER PANEL PRIMED (LINES) (SN)	DEFORMED	1,172.30	1,172.30
1	LETTERING 318I (SN)	NECESSARY	64.10	64.10
2	GROMMET (SN)	NECESSARY	1.50	1.50
1	PLAQUE 74MM (SN)	NECESSARY	71.25	71.25
1	TRUNK LID GASKET (SN)	NOT NECESSARY	76.40	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NECESSARY	20.20	20.20
2	EXPANDING NUT (SN) (ADDITIONAL)	NECESSARY	2.00	2.00
1	SET MOUNTING PDC /PMA SENSOR REAR (SN) (ADDITIONAL)	NECESSARY	66.95	66.95
1	(DG/SL) ADHESIVE SET K6 (SN) (ADDITIONAL)	NECESSARY	53.05	53.05
			3,416.90	2,711.15
<b>LABOUR</b>				
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.(ADDITIONAL)		451.00	451.00
	REPLACING REAR BUMPER PANEL AND ATTACHMENTS ,BOOTLID ,ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT .		2,550.00	1,700.00
	SPRAY REAR BUMPER AND BOOTLID.		1,923.00	1,730.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION .		177.00	150.00
	TO CARRY OUT BODY CAVITY PRESERVATION . (PER PANEL).		118.00	100.00
			5,219.00	4,131.00
<b>GRAND TOTAL</b>			<b>8,635.90</b>	<b>6,842.15</b>

Report Ref No. CC4/EQI19001363/T1ga3q2



**RECOMMENDED COST OF REPAIRS****6,842.15**

Report Ref No. CC4/EQI19001363/T1ga3q2

**MOHAMAD TAUFIKH****M.MATAI, AMSAE-A****Automotive Assessor****HO LEONG CHUAN****Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## Joanne Lee (LKK Auto)

---

**From:** Joanne Lee (LKK Auto) <[report@lkkauto.com](mailto:report@lkkauto.com)>  
**Sent:** Thursday, 26 September 2019 4:02 PM  
**To:** 'Joel Goh'  
**Cc:** 'CeciliaChong@lkkauto.com'  
**Subject:** TP Direct Settlement - Accident Involving SLB 997X (OI) and SLP 2710U (TP) on 17/01/2019  
**Attachments:** LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933