

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

18 JAN 2019

ESTIMATE

Estimate No. : b1 49817	Page No. : 1 of 5
Date Estimated : 18/01/2019	
Prepared By : Joseph Yaguel	

- ESTIMATE REPAIR FOR - Shahrom Bin Mohamed Ariff Blk 609, Choa Chu Kang St 62 #10-85 Singapore 680609	- ACCOUNT - 45912 EQ Insurance Company Limited 5 Maxwell Road, #17-00 Tower Block MND Complex Singapore 069110
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2710U	NU78982	31/05/2017	318iA/4Dr	0

DESCRIPTION	VALUE
Replacing rear bumper panel and attachments, bootlid, etc to knock out dents caused by the accident	1770 2,550.00
Spray rear bumper and bootlid	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries	? 150.00

Total Labour 1: **4,918.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,179.80	bt 1,179.80
REAR BUMPER CENTRE GUIDE	1	32.90	? 32.90
REAR BUMPER CARRIER (ECE)	1	467.95	? 467.95
REAR BUMPER LH SIDE GUIDE	1	58.50	? 58.50
REAR BUMPER PANEL PRIMED (LINES)	1	1,172.30	de 1,172.30
LETTERING 318i	1	64.10	ne 64.10
GROMMET	2	0.75	ne 1.50
PLAQUE 74MM	1	71.25	ne 71.25
TRUNK LID GASKET	1	76.40	? 76.40
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	ne 20.20

Total Parts : **3,144.90**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 49817
Date Estimated : 18/01/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2710U	NU78982	31/05/2017	318iA/4Dr	0

Claims QD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/1/17 @ 1110 Excess S\$ _____

Surveyor's Name Tan Jia Sign [Signature]

Surveyor's Tel 9749849 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjia@pml.com

No. of Working Days Recommend 5 days.

225 / 50 R17 PIR.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items, must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	4,918.00
Parts	:	3,144.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	564.40
Grand Total	:	8,627.30

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **