

Co. Reg. No: 201416720C
 1 Kaki Bukit Ave 6 #01-80 Autobay@Kaki Bukit Singapore 41/853
 Tel: 6636 9100 Fax: 6636 9113

Date: 21/01/2019

TO: AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120

Our Customer: Chng Yai Wun
 Vehicle No: SGJ6748B
 Model: Nissan Latio 1.5L T
 Manufacture Year: 2006
 Date of Accident: 21/01/2019
 Total Estimate Repair Days: 12
 Total Pages: 2

Attn: Motor Claims Department
 Fax: 6415 3727

Asher.

Re: Repair Estimate For Third Party Claim against GBF96022

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Painted</i>	1	\$609.90	\$609.90	✓
2	Rear bumper bracket RH <i>Painted</i>	1	\$91.70	\$91.70	✓
3	Rear bumper bracket LH <i>Painted</i>	1	\$91.70	\$91.70	✓
4	Rear bumper foam <i>Painted</i>	1	\$147.20	\$147.20	✓
5	Rear end panel <i>Painted</i>	1	\$491.80	\$491.80	✓
6	Tail lamp panel RH <i>Painted</i>	1	\$164.80	\$164.80	✓
7	Tail lamp panel LH <i>Painted</i>	1	\$164.80	\$164.80	✓
8	Boot lid <i>Painted</i>	1	\$764.60	\$764.60	✓
9	Rear end fender RH <i>Repair</i>	1	\$957.00	\$957.00	+
10	Rear end fender LH <i>Repair</i>	1	repair	repair	+
11	Rear fender inner trim RH <i>Painted</i>	1	\$242.40	\$242.40	+
12	Rear fender inner trim LH <i>Painted</i>	1	\$242.40	\$242.40	+
13	Spare tyre panel <i>Painted</i>	1	\$771.40	\$771.40	+
14	Spare tyre board <i>Painted</i>	1	\$615.20	\$615.20	495
	Total			\$5,354.90	
	Less 30%			\$1,606.47	
	Sub Total 1			\$3,748.43	
B.	Spare Parts (Nett)				
1	Rear bumper clip <i>new</i>	8	\$4.90	\$39.20	✓
2	Rear bumper side retainer RH <i>new</i>	1	\$35.20	\$35.20	✓
3	Rear bumper side retainer LH <i>new</i>	1	\$35.20	\$35.20	✓
4	Rear end panel garnish <i>Painted</i>	1	\$82.00	\$82.00	✓
5	Rear end panel garnish clip <i>new</i>	8	\$4.90	\$39.20	10
6	Boot lid lock <i>new</i>	1	\$112.50	\$112.50	✓
7	Boot lid lower catch	1	\$58.20	\$58.20	✓
8	Boot lid chrome <i>Painted</i>	1	\$283.10	\$283.10	✓
9	Boot lid "Nissan" logo <i>new</i>	1	\$52.50	\$52.50	✓
10	Boot lid "Latio" emblem <i>new</i>	1	\$64.60	\$64.60	✓
11	Boot lid hinge <i>new</i>	2	\$51.10	\$102.20	+
12	Boot lid weatherstrip <i>new</i>	1	\$68.80	\$68.80	✓
13	Rear license plate lamp <i>new</i>	2	\$54.00	\$108.00	+
14	Tail lamp RH <i>Painted</i>	1	\$252.30	\$252.30	✓
15	Tail lamp LH <i>Painted</i>	1	\$252.30	\$252.30	✓
16	Rear fender inner trim clip <i>new</i>	16	\$4.90	\$78.40	+
17	Air vent RH <i>Painted</i>	1	\$48.00	\$48.00	+
18	Air vent LH <i>Painted</i>	1	\$48.00	\$48.00	+
19	Rear windscreen moulding <i>new</i>	1	\$140.90	\$140.90	x

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 41/883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
20	Exhaust silencer <i>Bent</i>	1	\$478.00	\$478.00	✓
21	Exhaust silencer mounting <i>new</i>	2	\$34.70	\$69.40	+
	<i>1926.10</i>		Total	\$2,448.00	
	<i>1733.49</i>		Less 10%	\$244.80	
			Sub Total 2	\$2,203.20	
C.	Spare Parts (S/Nett)				
✓ 1	Rear number plate w/casing <i>new Bent</i>	1	\$70.00	\$70.00	✓
2	Reverse sensor (Set) <i>Range</i>	1	\$250.00	\$250.00	200
3	Rear windscreen sealant <i>new</i>	1	\$60.00	\$60.00	+
4	Chinese wording <i>new</i> <i>300</i>	1	\$60.00	\$60.00	30.
			Sub-Total 3	\$440.00	
			Total for Parts	\$6,391.63	
D.	Labour				
1	To check wiring.			\$120.00	80
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,400.00	1000
3	Spray painting all affected parts & areas.			\$1,400.00	1200
4	To spray anti-rust undercoat.			\$120.00	50
5	To remove and refit rear windscreen glass.			\$120.00	+
6	To remove and replace exhaust silencer.			\$180.00	80
7	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00	80
			Total Labour	\$3,590.00	
			Total Repair Cost	\$9,981.63	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Adrian L
L/S 21/01/19.
08 Days.
Supplementary: 194.76
total: 6783.30
L/S: 54K ✓

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 22/01/2019

TO: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Our Customer : Chng Yai Wun
Vehicle No : SGJ6748B
Model : Nissan Latio 1.5L T
Manufacture Year : 2006
Date of Accident : 21/01/2019
Total Estimate Repair Days : 12
Total Pages : 1

Attn : Motor Claims Department
Fax : 6415 3727

Re: Supplementary Repair Estimate For Third Party Claim against GBF9602Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
B.	Spare Parts (Nett)				
1	Tail lamp lower bracket RH <i>3rd</i>	1	\$30.70	\$30.70	✓
2	Tail lamp lower bracket LH	1	\$30.70	\$30.70	✓
3	Tail lamp gasket RH <i>2nd</i>	1	\$35.00	\$35.00	✓
4	Tail lamp gasket LH	1	\$35.00	\$35.00	✓
5	Boot lid sensor <i>2nd</i>	1	\$85.00	\$85.00	✓
	Total			\$216.40	
			Less 10%	\$21.64	
	Total Supplementary Repair Cost			\$194.76	

216.40
194.76

Adrian
H/S 22/01/19.

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No