

(5/20/2014)

INS. CASE OWNER:

Daniel

CC 6 / III 1900

1415, Kefu

LKK

IDAC

Surveyor:

ESC

DOI:

ASSIGNMENT

2/1/14

Date / Time:

2/1/14

Registered in Merimen:

2/1/14

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHL 8894 Z

Name of Insured:

CTOL

Insured Tel No.:

HP:

Excess Sec II : \$

D.O.A.:

14/1/14

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

16K MIN BENG before

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MUT 1900568

Policy No.:

ML000015

Make / Model:

HUMMER

Place of Accident:

CNY 280 ARE

OI GIA REPORT:

YES / NO

TP GIA REPORT:

YES / NO

Insured Liability:

%

Final ? Yes / No

SUA 6809S



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hui Yang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

2/1/14

VK

24/1/14

SUA 6809S - 14/1/14 00:00:00 / 14/1/14 00:00:00

SHL 8894 Z

seek mandate, BOLA 15

pending funds (LR)

LOD

24/1/14 file pass to type mandate report

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA:

Medical Bill

PIR

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

SS 12,500.83

(6 days)

Reduction:

Sb164.03

% 33

FINAL SETTLEMENT

Date/Time:

24/1/14 5:30pm

Confirm with:

Bel.

Email:

Call:

Final Liability:

SS

100

(Agreed / Assessed) BOLA S/N No.:

15

Repair Cost:

(w/651)

SS

13,481.82

Loss of Rental (LOR):

SS

710.40

(6 days)

x 2120.84

(w/651)

Loss of Use (LOU):

SS

-

(5 x days)

Loss of Income (LOI):

SS

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOU + LO

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/Independent)

Legal Cost

SS

-

Total:

SS

14,292.22

Global Sum \$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS

14,292.22

Name 1:

Hui Yang motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

T6 /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Soon: _____ Consistent? : Yes or No

Est. Repairs: 5-6 days Res.: Yes or NoLum Sum: 1-2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU 680 PS Yr Regn: 12, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Privia c.c. 1797Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 126956 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZVW50 - 6100319Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or JourneyFront 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 19/1/19Survey held at ✓Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

22/1 File pass to ColP/P \$12,599.83(Red = \$6164.03 / 33%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees:

Others

TOTAL

Report Format:

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III19001415/Kfb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 22-01-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8894Z	Veh. Inspected	SLU 6809S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/01/2019

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/01/2019	Inspection Date	21/01/2019
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

1pc	front bonnet	853.60			
* 2pcs	front bonnet hinge @\$85.00				
1pc	front bonnet inner cardboard				
8pcs	front bonnet inner cardboard clip @\$5.00				
1pc	front bonnet inner lock	130			
* 2pcs	front headlamp @\$2250.00				
2pcs	front headlamp panel @\$281.50				
1pc	front headlamp LH HID control unit				
1pc	front bumper	495.50			
15pcs	front bumper clip @\$5.00				
1pc	front bumper "TOYOTA" logo				
1pc	front bumper centre grille				
2pcs	front bumper towing cover @\$85.50				
* 2pcs	front bumper fog lamp @\$295.85				
2pcs	front bumper fog lamp cover @\$181.50				
1pc	front bumper top rubber				
1pc	front bumper top garnish				
10pcs	front bumper top garnish clip @\$5.00				
1pc	front bumper lower grille				
* 1pc	front bumper lower garnish				
1pc	front bumper top reinforcement				
1pc	front bumper top sponge				
2pcs	front bumper side retainer @\$131.35				
1pc	front support top panel				
* 2pcs	front support side panel @\$375.25	151.60			
2pcs	front support panel side garnish @\$177.75				
* 1pc	front support panel lower panel				
* 1pc	front air-con condenser				
1pc	front air-con condenser motor				
1pc	front air-con condenser motor fan				
1pc	front air-con condenser pipe 1				
1pc	front air-con condenser pipe 2				

balance c/f

\$ 16,047.45



Not Authorised
LLP @ 12,599.83
Accroy After Repair
5-bda

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

	balance b/f		\$ 16,047.45
1pc	* front radiator	Ry	\$ 1,520.00 ✓
1pc	front radiator top hose	1pc	\$ 121.50 X
1pc	front radiator lower hose	1pc	\$ 120.50 X
1pc	front radiator cowling	1pc	\$ 255.80 X
1pc	front radiator cowling motor	1pc	\$ 291.50 X
1pc	front radiator cowling motor fan	1pc	\$ 171.50 X
1pc	front LH fender	1pc	\$ 981.85 X
1pc	front RH fender "HYBRID" emblem	1pc	\$ 65.85 ✓
			\$ 19,575.95
	less 25%		\$ 4,893.99
			\$ 14,681.96
1set	front number plate & casing	Ry	s.nett \$ 50.00 455m
	remove & refit air-con & gas		\$ 120.00 100l
	remove & refit radiator & coolant		\$ 120.00 50l
	tuffkote		\$ 120.00 60l
	wiring		\$ 180.00 20l
	spray painting		\$ 1,200.00 800l
	labour charges		\$ 1,400.00 700l
	Total		\$ 17,871.96



輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

SUPPLEMENTARY TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

1pc	* front bumper lower reinforcement	R	\$	381.85	✓
1pc	* front bumper lower reinforcement garnish	Di/cm	\$	181.85	✓
1pc	* front support lower panel garnish	CM	\$	185.50	✓
1pc	* front support lower air-duct	CM	\$	281.50	✓
1pc	* front support panel centre pillar	R	\$	158.50	✓
less 25%		\$ 1,189.20			
Total					
		\$ 297.30			
		\$ 891.90			



18763.86

KP

辉 阳 汽 车 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

Not Notarise

Price \$11,707.93
After PAINT

5-6 days

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

1pc	front bonnet	853-60	R	\$	980.00	✓
2pcs	front bonnet hinge @\$85.00		Oil	\$	170.00	✓
1pc	front bonnet inner cardboard		in	\$	285.50	X
8pcs	front bonnet inner cardboard clip @\$5.00		nn	\$	40.00	X
1pc	front bonnet inner lock	130	Oil	\$	274.10	✓
2pcs	front headlamp @\$2250.00	oil / tag cm	oil / tag	\$	4,500.00	✓
2pcs	front headlamp panel @\$281.50		oil / tag	\$	563.00	✓
1pc	front headlamp LH HID control unit		in	\$	581.85	X
1pc	front bumper	495-50	R	\$	972.45	✓
15pcs	front bumper clip @\$5.00		nn	\$	75.00	✓
1pc	front bumper "TOYOTA" logo		nn	\$	95.85	✓
1pc	front bumper centre grille		cm	\$	381.85	✓
2pcs	front bumper towing cover @\$85.50		oil / tag	\$	171.00	✓
2pcs	front bumper fog lamp @\$295.85		oil / tag	\$	591.70	X
2pcs	front bumper fog lamp cover @\$181.50		oil / tag	\$	363.00	X
1pc	front bumper top rubber		nn	\$	281.70	✓
1pc	front bumper top garnish		Bu	\$	277.10	✓
10pcs	front bumper top garnish clip @\$5.00		nn	\$	50.00	✓
1pc	front bumper lower grille		Oil	\$	281.85	✓
1pc	front bumper lower garnish		cm	\$	281.10	✓
1pc	front bumper top reinforcement		R	\$	561.60	✓
1pc	front bumper top sponge		cm	\$	172.40	✓
2pcs	front bumper side retainer @\$131.35		Oil	\$	262.70	✓
1pc	front support top panel		Bu	\$	381.45	✓
2pcs	front support side panel @\$375.25	151-60	R	\$	750.50	✓
2pcs	front support panel side garnish @\$177.75		in	\$	355.50	X
1pc	front support panel lower panel		R	\$	370.50	✓
1pc	front air-con condenser		oil / tag	\$	1,150.00	✓
1pc	front air-con condensor motor		in	\$	281.50	✓
1pc	front air-con condensor motor fan		in	\$	171.50	✓
1pc	front air-con condensor pipe 1		in	\$	181.25	✓
1pc	front air-con condensor pipe 2		in	\$	191.50	✓

balance c/f

\$16,047.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- These items are subject to confirmation
- Resurvey is on a "Without Prejudice" basis
- Resurvey is allowed
- Supplies for (s) must be resurveyed and
- Resurvey must be approved from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Bldg 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

	balance b/f		\$ 16,047.45
1pc	front radiator	By	\$ 1,520.00 ✓
1pc	front radiator top hose	1pc	\$ 121.50 X
1pc	front radiator lower hose	1pc	\$ 120.50 X
1pc	front radiator cowling	1pc	\$ 255.80 X
1pc	front radiator cowling motor	1pc	\$ 291.50 X
1pc	front radiator cowling motor fan	1pc	\$ 171.50 X
1pc	front LH fender	1pc	\$ 981.85 X
1pc	front RH fender "HYBRID" emblem	1pc	\$ 65.85 ✓
			<u>\$ 19,575.95</u>
	less 25%		<u>\$ 4,893.99</u>
			<u>\$ 14,681.96</u>
1set	front number plate & casing	By s.nett	\$ 50.00 45.00
	remove & refit air-con & gas		\$ 120.00 100.00
	remove & refit radiator & coolant		\$ 120.00 50.00
	tuffkote		\$ 120.00 60.00
	wiring		\$ 180.00 20.00
	spray painting		\$ 1,200.00 800.00
	labour charges		\$ 1,400.00 700.00
	Total		<u>\$ 17,871.96</u>



輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

Not Authorised
Libby B?
Henry Ate Paim
5-6 days

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

1pc	front bonnet	R	\$ 980.00	✓
2pcs	front bonnet hinge @\$85.00		\$ 170.00	✓
1pc	front bonnet inner cardboard	L	\$ 285.50	X
8pcs	front bonnet inner cardboard clip @\$5.00	nn	\$ 40.00	X
1pc	front bonnet inner lock	D-1	\$ 274.10	✓
2pcs	front headlamp @\$2250.00	N/S M	\$ 4,500.00	✓
2pcs	front headlamp panel @\$281.50	N/S Bu	\$ 563.00	✓
1pc	front headlamp LH HID control unit		\$ 581.85	?
1pc	front bumper	R	\$ 972.45	✓
15pcs	front bumper clip @\$5.00	nn	\$ 75.00	✓
1pc	front bumper "TOYOTA" logo	nn	\$ 95.85	✓
1pc	front bumper centre grille	CM	\$ 381.85	✓
2pcs	front bumper towing cover @\$85.50	N/S M	\$ 171.00	✓
2pcs	front bumper fog lamp @\$295.85	N/S ?	\$ 591.70	✓
2pcs	front bumper fog lamp cover @\$181.50	N/S	\$ 363.00	X
1pc	front bumper top rubber	nn	\$ 281.70	✓
1pc	front bumper top garnish	Bu	\$ 277.10	✓
10pcs	front bumper top garnish clip @\$5.00	nn	\$ 50.00	✓
1pc	front bumper lower grille	D-1	\$ 281.85	✓
1pc	front bumper lower garnish		\$ 281.10	?
1pc	front bumper top reinforcement	R	\$ 561.60	✓
1pc	front bumper top sponge	CM	\$ 172.40	✓
2pcs	front bumper side retainer @\$131.35	D-1	\$ 262.70	✓
1pc	front support top panel	Bu	\$ 381.45	✓
2pcs	front support side panel @\$375.25		\$ 750.50	?
2pcs	front support panel side garnish @\$177.75		\$ 355.50	?
1pc	front support panel lower panel		\$ 370.50	?
1pc	front air-con condenser		\$ 1,150.00	?
1pc	front air-con condensor motor		\$ 281.50	?
1pc	front air-con condensor motor fan		\$ 171.50	?
1pc	front air-con condensor pipe 1		\$ 181.25	?
1pc	front air-con condensor pipe 2		\$ 191.50	?

balance c/f

\$ 16,047.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation

No display is on a "Without Prejudice" basis

No display is allowed

Supplies (any item(s)) must be resurveyed and

Supplies must be approved from Insurance Company

Acknowledged by Repairer

Signature:

Date:

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

19/01/2019

Owner: FAVORIDE PTE LTD

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID - SLU6809S

	balance b/f		\$ 16,047.45
1pc	front radiator		\$ 1,520.00 ?
1pc	front radiator top hose	1/2	\$ 121.50 X
1pc	front radiator lower hose		\$ 120.50 ?
1pc	front radiator cowling		\$ 255.80 ?
1pc	front radiator cowling motor		\$ 291.50 ?
1pc	front radiator cowling motor fan		\$ 171.50 ?
1pc	front LH fender	1/2	\$ 981.85 X
1pc	front RH fender "HYBRID" emblem	1/2	\$ 65.85 ✓
			<u>\$ 19,575.95</u>
	less 25%		<u>\$ 4,893.99</u>
			<u>\$ 14,681.96</u>
1set	front number plate & casing	1/2 s.nett	\$ 50.00 45.50
	remove & refit air-con & gas		\$ 120.00 100.00
	remove & refit radiator & coolant		\$ 120.00 50.00
	tuffkote		\$ 120.00 60.00
	wiring		\$ 180.00 20.00
	spray painting		\$ 1,200.00 800.00
	labour charges		\$ 1,400.00 700.00
	Total		<u><u>\$ 17,871.96</u></u>



Print Received Message

This mail is associated with :

***SLU6809S (MCT19010568)**
[SHC8894Z]

TP

FAVORIDE PTE LTD

Jan 19 2019 8:00AM

[COMFORT TRANSPORTATION PTE LTD]

Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/01/2019 15:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SLU6809S - Claim Handler: Pooi Chin Han Daniel

Approved:0.00.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 25 July 2019 5:30 PM
To: Hui Yang Motor
Cc: Cecilia Chong (LKK Auto); Admin A
Subject: RE: Your Ref: CC6/III19001415/Kfb3 Our Ref: SLU6809S / DOA: 19/01/2019
Attachments: DV SLU 6809S.pdf

Importance: High

WITHOUT PREJUDICE

SAVE AS TO COSTS

Our Ref: CC6/III19001415/Kfb3
Your Ref: SLU 6809S

Dear Bel,

We refer to the above matter and your Letter of Demand.

Thank you for patient waiting on this matter.

We have instruction to confirmed settlement as below:

1. Cost of Repair (w/gst)	S\$ 13,481.82
2. Loss of Rental	<u>S\$ 770.40</u>
	<u>S\$14,252.22</u>

Please duly sign the DV attached and return for payment processing.

We need **original copy DV**.

Your prompt action will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Print Received Message

This mail is associated with :

***SLU6809S (MCT19010568)
[SHC8894Z]**

TP

FAVORIDE PTE LTD

Jan 19 2019 8:00AM

[COMFORT TRANSPORTATION PTE LTD]

Hui Yang Motor Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 23/07/2019 15:12 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14252.22) - SLU6809S - Claim Handler: Pooi Chin Han Daniel

Approved:14252.22:Please request TP WS to raise Tax Invoice for Cost of repairs in III's name

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 14/02/2019

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-00 IOB Building

Singapore 049711

RE: ACCIDENT INVOLVING SLU6809S & SHC8894Z ON 19-01-2019

ALONG ENG NEO AVE TWDS BUKIT TIMAH RD

SETTLEMENT OF OUR CLAIM FOR SLU6809S

Part By Part repair cost as recommended by surveyor (TP0543)	\$ 13,481.82
6 days Loss of Rental @ \$128.40 per day	\$ 770.40
Total	<u>\$ 14,252.22</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, FAVORIDE PTE LTD hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number S2116809S and other vehicles registration number SHL 8894Z along ENG NEO AVENUE TOWNS SIKIT TIMAH ROAD on 19/01/2019

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.



.....
Signature of registered owner and/or Company's stamp

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: TP / MCT19010588
Claimant Ref: SLU 6809S

We/I, Hui Yang Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd, LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 13,481.82 (repair cost), S\$ 770.40 (loss of use/rental), S\$ — (search fee), vehicle no. SLU 6809S that was damaged pursuant to the accident which occurred on 19/01/2019 (date) at ENG NEO AVENUE (location) involving vehicle no. SHC 8894Z (insured vehicle). This is pursuant to the inspection conducted on 21/01/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner FAVORIDE PTE LTD ("the third party claimant") of vehicle no. SLU 6809S to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLU 6809S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 14,252.22 to Hui Yang Motor Pte Ltd

Dated this 25 day of July, 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Hui Yang Motor Pte Ltd

NRIC:

201629438M

Address:

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

51 Ubi Ave 1, Bang Ubi Industrial Park

#03-25 Singapore 408933

Nationality:

Occupation:

THIS SETTLEMENT AGREEMENT IS VALID AND EFFECTIVE
FROM THE DATE OF SIGNATURE AND SEAL OF BOTH PARTIES
AND NO FURTHER ACTION IS REQUIRED TO BE TAKEN
BY EITHER PARTY TO COMPLETE THE SETTLEMENT
AND NO FURTHER ACTION IS REQUIRED TO BE TAKEN
BY EITHER PARTY TO COMPLETE THE SETTLEMENT

HUI YANG MOTOR PTE LTD

TAX INVOICE

Bill To:

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-00 IOB Building
Singapore 049711

TP Claim Invoice No: TP0543
Bill Date: 14/02/2019

	Description	Amount
	Date of Accident : 19/01/2019 Owner : FAVORIDE PTE LTD Vehicle No : <u>SLU6809S</u> Make & Model : <u>TOYOTA PRIUS HYBRID 1.8S</u> <u>Part By Part repair cost as recommended by surveyor</u>	\$ 12,599.83
	Sub-Total :	\$ 12,599.83
	Add 7% GST :	\$ 881.99
	Total Amount SGD :	\$ 13,481.82

Reg No.:201629438M

GST No:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

HYMS CAR LEASING PTE LTD

BLK 176 SIN MING DRIVE
#04-02 AUTOCARE
SINGAPORE 575721
HP : 8333 6725 FAX : 6451 4658
REG NO : 201320561K
GST REGISTER NO: 201320561K

TAX INVOICE

BILL TO: HUI YANG MOTOR PTE.LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE
SINGAPORE 575721

TAX INVOICE NO : LT012019-011
DATE : 26/01/2019
REFERENCE NO : SLU6809S

NO.	DESCRIPTION	AMOUNT
	AGREEMENT NO : 13562 HIRER'S NAME : PAUL CHEN YONG YIN REGISTRATION NO : SLH5931X MAKE : TOYOTA PRIUS HYBRID DURATION : 19/1/19 - 25/1/19 PER DAY \$120 X 6 DAYS	\$720.00
	SUB TOTAL	\$720.00
	7% GST	\$50.40
	TOTAL AMOUNT	\$770.40

Payment:

- A. For cheque payment, please crossed and issue to "HYMS CAR LEASING PTE LTD".
Please indicate vehicle number on the back of the cheque and mail the cheque to:

HYMS CAR LEASING PTE LTD

Blk 176 Sin Ming Drive
#04-02 Sin Ming AutoCare
Singapore 575721



- B. For internet banking transfer, please indicate vehicle number and transfer to:
Bank OCBC Current Account 531-756864-001

RENT RECEIPT

No.: RC19-03

Date: 26/01/2019

Received from Hui Yang motor pte ltd

the sum of Dollars Seven Hundred Seventy and Cents Forty Only

being the rent of SL4 5931 X (d 120 x 6 days) + 7-1-69 A/H: 13562

due for the period from 19/01/2019 to 25/01/2019

\$ 770.40

Cash / Cheque No.

Important: No subletting of the above premise or any part thereof, or assigning the tenancy of the premise is allowed without the written consent of the landlord.

预先支付

Payable in advance.



Signature of Landlord

HYMS CAR LEASING PTE LTD


Blk 176 Sin Ming Drive #04-02 Sin Ming AutoCare Singapore 575721 Hp: 8333 6725 Fax 6451 4658

RENTAL AGREEMENT

SLH 68095 (Dave)

RENTAL TERMS AND CONDITIONS

No.: 13562

NAME Hui Yang Motor Pte Ltd		REG. NO. SLH 5931X	CAR MAKE TOYOTA PRIUS HYBRID
ADDRESS Blk 176 Sin Ming Drive #04-02 Sin Ming AutoCare (S) 575721		KM OUT	DATE & TIME OUT 19/11/19 10:20am
		KM IN	DATE & TIME IN 20/11/19 11:00am
TEL HP 93606765	KM DRIVEN		TIME USED
NAMED DRIVER Paul Chen Yang Yih		Deposit	
DRIVING LICENCE NO. S9413076C	DATE OF EXPIRY	PLACE OF ISSUE	HOURS @ \$
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	6 DAYS @ \$ 170.00
ADD NAMED DRIVER			WEEKS @ \$
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE	MONTHS @ \$
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)
REMARKS 			SUB-TOTAL \$ 720.00
THIS VEHICLE IS USE WITHIN SINGAPORE ONLY. OUR INSURANCE DOES NOT COVER IN MALAYSIA			TOTAL RENTAL
			DELIVERY FEE
			COLLECTION FEE
			7% GST \$ 50.40
			PER DAY \$ PER WEEK \$ PER MONTH \$
			BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)
			PER DAY \$ PER WEEK \$ PER MONTH \$
			PREPAYMENT TOTAL CHARGE \$ 770.40
			CHECK DEPOSIT
			CASH
			RECEIPT NO. NETT CHARGE
			AMOUNT DUE/ REFUND
FORM OF PAYMENT IN ADVANCE CASH BILL CHARGE CLUB CHEQUE NO.			
I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF. I UNDERTAKE NOT TO USE OR LET OTHERS USE THE VEHICLE TO CARRYOUT ANY ILLEGAL OR CRIMINAL ACTS INCLUDING CARRYING OF DUTY UNPAID GOODS ESPECIALLY CIGARETTES.			
SIGNED BY THE PARTIES HERETO ON THE _____ DAY OF _____			
X 		X 	
OWNER		RENTER'S/DRIVER'S SIGNATURE	

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2019 Edit Reg		21 Jan 2019 00:00 Edit Adj Rpt	S\$12,599.82 Edit Estimates	S\$12,599.82 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	FAVORIDE PTE LTD , Co. Reg. No.: 201524792C								
Vehicle Reg. No.:	SLU6809S	Date of Loss:	19/01/2019 08:00 - :59 [13 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19010568	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHC8894Z	Policy No. (Claimant):	999994329						
		Excess:							
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (23/07/2019): Alert - Adj Mandate Approved (S\$14252.22) - SLU6809S - Claim Handler: Pooi Chin ... - III_SG (24/01/2019): Alert - Adj Mandate Approved (S\$0.00) - SLU6809S - Claim Handler: Pooi Chin Han ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU6809S (MCT19010568)
[SHC8894Z]
TP
FAVORIDE PTE LTD
Jan 19 2019 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Video										1 per page		☒
No	Finalized On	India International Insurance Pte Ltd (HQ)								Thumbnail	Print	
1	23/01/19 10:07	Video - Accident TP									Load MP4	
Photos/Images										3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	25/01/19 16:15	General View									Load JPG	☒
2	25/01/19 16:15	General View									Load JPG	☒
3	25/01/19 16:15	General View									Load JPG	☒
4	25/01/19 16:15	General View									Load JPG	☒
5	25/01/19 16:15	General View									Load JPG	☒
6	25/01/19 16:15	General View									Load JPG	☒
7	25/01/19 16:15	General View									Load JPG	☒
8	25/01/19 16:15	General View									Load JPG	☒
9	25/01/19 16:15	General View									Load JPG	☒
10	25/01/19 16:15	General View									Load JPG	☒
11	25/01/19 16:15	General View									Load JPG	☒
12	25/01/19 16:15	General View									Load JPG	☒
13	25/01/19 16:15	General View									Load JPG	☒
14	25/01/19 16:15	General View									Load JPG	☒
15	25/01/19 16:15	General View									Load JPG	☒
16	25/01/19 16:15	General View									Load JPG	☒
17	25/01/19 16:15	General View									Load JPG	☒
18	25/01/19 16:15	General View									Load JPG	☒
19	25/01/19 16:15	General View									Load JPG	☒
20	25/01/19 16:15	General View									Load JPG	☒
21	25/01/19 16:15	General View									Load JPG	☒
22	25/01/19 16:15	General View									Load JPG	☒
23	25/01/19 16:15	General View									Load JPG	☒
24	25/01/19 16:15	General View									Load JPG	☒
25	25/01/19 16:15	Odometer Reading									Load JPG	☒
26	25/01/19 16:15	Chassis Number									Load JPG	☒
27	25/01/19 16:15	General View									Load JPG	☒
28	02/07/19 14:35	Reinspection Photo									Load JPG	☒
29	02/07/19 14:35	Reinspection Photo									Load JPG	☒
30	02/07/19 14:35	Reinspection Photo									Load JPG	☒
31	02/07/19 14:35	Reinspection Photo									Load JPG	☒
32	02/07/19 14:35	Reinspection Photo									Load JPG	☒
33	02/07/19 14:35	Reinspection Photo									Load JPG	☒
34	02/07/19 14:35	Reinspection Photo									Load JPG	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
35	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
36	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
37	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
38	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
39	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
40	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
41	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
42	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
43	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
44	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
45	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
46	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
47	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
48	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
49	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
50	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
51	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
52	02/07/19 14:35	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/01/19 17:49	TP ESTIMATE- MARKED	 Load PDF	
2	22/01/19 17:49	TP GIA REPORT	 Load PDF	
3	28/06/19 09:16	WORKSHOP INVOICE	 Load PDF	
4	28/06/19 09:16	RENTAL RECEIPT	 Load PDF	
5	28/06/19 09:16	LOD	 Load PDF	
6	13/08/19 11:19	AUTHORISATION TO ACT FORM	 Load PDF	
7	13/08/19 11:19	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/01/19 09:24	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19001415/KGB3Q2

Date: 13/08/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SLU6809S

Insured Vehicle No: SHC8894Z

Date of Loss: 19/01/2019

Nature of Claim:

TP

Claim No: MCT19010568

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU6809S

Make & Model: TOYOTA PRIUS HYBRID, 1.8 S CVT (A)

Engine No: 2ZR8252421

Reg. Date: 11/12/2017 (Man. Year: 2017)

Chassis No: ZVW506100319

Colour: Metallic Black

Odometer: 126956 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Journey 8 mm

Rear Left Side: Journey 8 mm

Front Right Side: Journey 8 mm

Rear Right Side: Journey 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,623.86	10,869.82	4,754.04	30.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	1,730.00	1,410.00	44.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,763.86	12,599.82	6,164.04	32.85
+ GST 7.00/7.00% (S\$)	1,313.47	881.99	431.48	32.85
Nett Amount (S\$)	20,077.33	13,481.81	6,595.52	32.85
+ Car Rental (6.0 x S\$120.00/day + 7.00% GST) (S\$)		770.40		
	Nett Liability (S\$)	14,252.21		

INSPECTION

Date of Assignment: 21/01/2019

Date Inspected: 21/01/2019 Inspected At:

Hui Yang Motor Pte Ltd (HQ)
176 Sin Ming Drive #04-02, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2019)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU6809S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	980.00 FL	*853.60 FL
2	2		*FRONT BONNET HINGE	Distorted	170.00 FL	*170.00 FL
3	1		*FRONT BONNET INNER CARDBOARD	Serviceable	285.50 FL	*- FL
4	8		*FRONT BONNET INNER CARDBOARD CLIP	Not Necessary	40.00 FL	*- FL
5	1		*FRONT BONNET INNER LOCK	Distorted	274.10 FL	*130.00 FL
6	2		*FRONT HEADLAMP	O/S Mtg Cracked / N/S Cracked	4,500.00 FL	*4,500.00 FL
7	2		*FRONT HEADLAMP PANEL	Buckled	563.00 FL	*563.00 FL
8	1		*FRONT HEADLAMP LH HID CONTROL UNIT	Serviceable	581.85 FL	*- FL
9	1		*FRONT BUMPER	Bent	972.45 FL	*495.50 FL
10	15		*FRONT BUMPER CLIP	Necessary	75.00 FL	*75.00 FL
11	1		*FRONT BUMPER TOYOTA LOGO	Dented	95.85 FL	*95.85 FL
12	1		*FRONT BUMPER CENTRE GRILLE	Cracked	381.85 FL	*381.85 FL
13	1		*FRONT BUMPER TOWING COVER	N/S Deformed	171.00 FL	*85.50 FL
14	2		*FRONT BUMPER FOG LAMP	Serviceable	591.70 FL	*- FL
15	2		*FRONT BUMPER FOG LAMP COVER	No such part	363.00 FL	*- FL
16	1		*FRONT BUMPER TOP RUBBER	Necessary	281.70 FL	*281.70 FL
17	1		*FRONT BUMPER TOP GARNISH	Buckled	277.10 FL	*277.10 FL
18	10		*FRONT BUMPER TOP GARNISH CLIP	Necessary	50.00 FL	*50.00 FL
19	1		*FRONT BUMPER LOWER GRILLE	Distorted	281.85 FL	*281.85 FL
20	1		*FRONT BUMPER LOWER GARNISH	Cracked	281.10 FL	*281.10 FL
21	1		*FRONT BUMPER TOP REINFORCEMENT	Bent	561.60 FL	*561.60 FL
22	1		*FRONT BUMPER TOP SPONGE	Cracked	172.40 FL	*172.40 FL
23	2		*FRONT BUMPER SIDE RETAINER	Distorted	262.70 FL	*262.70 FL
24	1		*FRONT SUPPORT TOP PANEL	Buckled	381.45 FL	*381.45 FL
25	2		*FRONT SUPPORT SIDE PANEL	Bent	750.50 FL	*303.20 FL
26	2		*FRONT SUPPORT PANEL SIDE GARNISH	Serviceable	355.50 FL	*- FL
27	1		*FRONT SUPPORT PANEL LOWER PANEL	Bent	370.50 FL	*370.50 FL
28	1		*FRONT AIR-CON CONDENSER	Bent	1,150.00 FL	*1,150.00 FL
29	1		*FRONT AIR-CON CONDENSER MOTOR	Serviceable	281.50 FL	*- FL
30	1		*FRONT AIR-CON CONDENSER MOTOR FAN	Serviceable	171.50 FL	*- FL
31	1		*FRONT AIR-CON CONDENSER PIPE 1	Serviceable	181.25 FL	*- FL
32	1		*FRONT AIR-CON CONDENSER PIPE 2	Serviceable	191.50 FL	*- FL
33	1		*FRONT RADIATOR	Bent	1,520.00 FL	*1,520.00 FL
34	1		*FRONT RADIATOR TOP HOSE	Serviceable	121.50 FL	*- FL
35	1		*FRONT RADIATOR LOWER HOSE	Serviceable	120.50 FL	*- FL
36	1		*FRONT RADIATOR COWLING	Serviceable	255.80 FL	*- FL
37	1		*FRONT RADIATOR COWLING MOTOR	Serviceable	291.50 FL	*- FL
38	1		*FRONT RADIATOR COWLING MOTOR FAN	Serviceable	171.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*FRONT LH FENDER	Repair	981.85 FL	*- FL
40	1		*FRONT LH FENDER HYBRID EMBLEM	Not Necessary	65.85 FL	*- FL
41	1		*SET FRONT NUMBER PLATE & CASING	Bent	50.00 FS	*45.00 FS
42	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	381.85 FL	*381.85 FL
43	1		*FRONT BUMPER LOWER REINFORCEMENT GARNISH	Distorted / Cracked	181.85 FL	*181.85 FL
44	1		*FRONT BUMPER LOWER PANEL GARNISH	Cracked	185.50 FL	*185.50 FL
45	1		*FRONT SUPPORT LOWER AIR-DUCT	Cracked	281.50 FL	*281.50 FL
46	1		*FRONT SUPPORT PANEL CENTRE PILLAR	Bent	158.50 FL	*158.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 20,815.15 14,478.10

- List Item Discount on L Items 25.00/25.00% (\$\$) 5,191.29 3,608.28

Total Parts (\$\$) 15,623.86 10,869.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT AIR-CON & GAS	New	120.00	100.00
2	REMOVE & REFIT RADIATOR & COOLANT	New	120.00	50.00
3	TUFFKOTE	New	120.00	60.00
4	WIRING	New	180.00	20.00
5	SPRAY PAINTING	New	1,200.00	800.00
6	LABOUR CHARGES	New	1,400.00	700.00
Gross Labour Cost (S\$)			3,140.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >