

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U**AAD1901-159***Not Authorised**1/1 Imp &**Book Value ??*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 651U

VF1ABL15AUC278388

RENAULT

LATITUDE

17.1.2019

III

30/6/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>Ry</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>CM</i> 135.97	✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>CM</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>Bu</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>Ry</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Ry</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Dis</i> 225.95	✓
13	1 BOOT REAR	\$	<i>Ry</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Warp</i> 470.06	✓
15	1 BOOT WHEATERSTRIP	\$	<i>Gr</i> 323.05	<i>Solia</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Oru</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>ru</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>ru</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>Ry</i> 367.84	✓
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>CM</i> 586.45	✓
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	X
26	1 BOOT LOCK	\$	<i>Nel</i> 202.67	✓
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	X

Trans-cab Auto Services Pte Ltd**AAD1901-159**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U

30	1 FENDER PANEL REAR LH	\$	Bu 3,299.13 ✓
31	1 WHEELARCH REAR LH	\$	cm 543.47 ✓
32	1 FENDER PANEL INNER TRIM REAR LH	\$	671.45 ?
33	1 WHEEL HOUSING PANEL REAR LH	\$	4,682.09 ?
34	1 TAILLAMP LH	\$	cm 552.55 ✓
35	1 TAILLAMP PANEL LH	\$	Bu 986.70 ✓
36	1 OUTER PANEL REAR (End Panel)	\$	Bu 1,471.77 —
37	1 OUTER PANEL REAR (End Panel)TRIM	\$	Diy 404.56 —
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/Bu 2,189.88 ✓
39	1 SPARE WHEEL PANEL TRIM	\$	Sm 612.21 X
40	1 DOOR PANEL REAR LH	\$	n 2,844.66 X
41	1 KUCKLE ARM REAR LH L70Y	\$	736.67 ?
42	1 BRAKE DISC REAR L70Y	\$	525.91 ?
43	1 ABS SENSOR REAR LH L70Y	\$	375.93 ?
44	1 REAR AXLE L70Y	\$	4,167.03 ?
45	1 LOWER ARM REAR LH L70Y	\$	905.99 ?
46	2 ABSORBER REAR	\$	389.75 ?
47	1 STABILIZER BAR REAR L70Y	\$	604.65 ?

TOTAL	\$	37,328.76
10%	\$	3,732.88
	\$	33,595.89

Special Nett

1	1SET PARKING AID	\$	Ta 700.00 600.00
2	1SET REAR BUMPER CLIP	\$	na 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	na 33.00 —
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na 20.00 X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na 20.00 X
8	1SET BUMPER LOWER REAR RIVET	\$	na 22.00 X
9	1SET BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
10	1 EXHAUST MOUNTING REAR	\$	na 17.82 X
11	1SET BOOT FINISHER CLIP	\$	na 24.20 X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	na 80.00 300.00
13	1 REAR BOOT STICKER '6555-3333'	\$	na 80.00 300.00
14	1 REAR DOOR STICKER '6555-3333'	\$	na 80.00 X

Trans-cab Auto Services Pte Ltd**AAD1901-159**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U

16 1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00 X
17 1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00 ✓
18 1 FENDER INNER TRIM CLIP LH	\$	na 28.00 ✓
18 1 FENDER INNER TRIM CLIP RH	\$	na 28.00 X
18 1 TAILLAMP CLIP LH	\$	na 5.00 ✓
18 2 REAR WINDSCREEN SELANT	\$	na 80.00 40sm
19 1 WINDSCREEN MOULDING	\$	na 100.00 ✓
20 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 30sm
21 1 LEFT REAR TYRE	\$	na 330.00 X
22 1 LEFT REAR TYRE RIM	\$	na 380.00 X

TOTAL \$ 1,640.02**TOTAL PARTS \$ 35,235.91****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 17601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 22001
To Rust-Proofing Of The Affected Areas.	\$	170.00 1201
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To repair and realign rear exhaust pipe.	\$	170.00 } 801
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 }
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1901-159**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 801
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 1201
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 1201
To check steering geometry and computer wheel alignment	\$	220.00 601
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00 ?
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 2501

TOTAL \$ 11,340.00**Over All Total \$ 46,575.91****(LUMP SUM)****Repair Days****30 DAYS**

20 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: