

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U**AAD1901-159***Not Auth'd**11 Sep @ 15,200. Max
Book Value ??*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 651U

VF1ABL15AUC278388

RENAULT

LATITUDE

17.1.2019

III

30/6/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>Ry</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>CM</i> 135.97	—
8	1 BUMEP R RETAINER LH REAR	\$	<i>CM</i> 44.99	—
9	1 BUMPER REFLECTOR LH	\$	<i>BW</i> 43.61	—
10	1 BUMPER BEAM REAR	\$	<i>Ry</i> 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Ry</i> 225.95	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Dir</i> 225.95	—
13	1 BOOT REAR	\$	<i>Ry</i> 2,872.68	—
14	1 BOOT FINISHER	\$	<i>Wap</i> 470.06	—
15	1 BOOT WHEATERSTRIP	\$	<i>Wt</i> 323.05	<i>5011a</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	—
17	1 BOOT REFLECTOR LAMP RH	\$	<i>BW</i> 493.35	—
18	1 BOOT BADGE 'RENAULT'	\$	<i>W</i> 225.36	—
19	1 BOOT BADGE	\$	<i>W</i> 225.36	—
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>Ry</i> 367.84	—
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>CM</i> 586.45	—
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	X
26	1 BOOT LOCK	\$	<i>Nel</i> 202.67	—
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	X

*161.53
SN*

Trans-cab Auto Services Pte Ltd**AAD1901-159**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U

30	1 FENDER PANEL REAR LH	\$	Bu	3,299.13	✓
31	1 WHEELARCH REAR LH	\$	CM	543.47	✓
32	1 FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45	✓
33	1 WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	✓
34	1 TAILLAMP LH	\$	CM	552.55	✓
35	1 TAILLAMP PANEL LH	\$	Bu	986.70	✓
36	1 OUTER PANEL REAR (End Panel)	\$	Bu	1,471.77	—
37	1 OUTER PANEL REAR (End Panel)TRIM	\$	DIY	404.56	—
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/Bu	2,189.88	✓
39	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
40	1 DOOR PANEL REAR LH	\$	R	2,844.66	X
41	1 KUCKLE ARM REAR LH L70Y	\$	SL	736.67	✓
42	1 BRAKE DISC REAR L70Y	\$	SL	525.91	✓
43	1 ABS SENSOR REAR LH L70Y	\$	SL	375.93	✓
44	1 REAR AXLE L70Y	\$	SL	4,167.03	✓
45	1 LOWER ARM REAR LH L70Y	\$	SL	905.99	✓
46	2 ABSORBER REAR	\$	SL	389.75	✓
47	1 STABILIZER BAR REAR L70Y	\$	R	604.65	✓

TOTAL	\$	37,328.76
10%	\$	3,732.88
	\$	33,595.89

Specical Nett

1	1SET PARKING AID	\$	Tu	700.00	Good
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	3000
13	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	3000
14	1 REAR DOOR STICKER '6555-3333'	\$	na	80.00	X

Trans-cab Auto Services Pte Ltd**AAD1901-159**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U

16 1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00 X
17 1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00 ✓
18 1 FENDER INNER TRIM CLIP LH	\$	na 28.00 ✓
18 1 FENDER INNER TRIM CLIP RH	\$	na 28.00 X
18 1 TAILLAMP CLIP LH	\$	na 5.00 ✓
18 2 REAR WINDSCREEN SELANT	\$	na 80.00 4000
19 1 WINDSCREEN MOULDING	\$	na 100.00 ✓
20 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 3000
21 1 LEFT REAR TYRE	\$	na 330.00 X
22 1 LEFT REAR TYRE RIM	\$	na 380.00 X

TOTAL \$**1,640.02 2350.02****TOTAL PARTS \$****35,235.91 35945.91****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 17600
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 22000
To Rust-Proofing Of The Affected Areas.	\$	170.00 1200
To reinstall rear bumper parking sensor.	\$	170.00 600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 600
To repair and realign rear exhaust pipe.	\$	170.00 } 800
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 }
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1901-159

No. 2 Ang Mo Kio Street 63 Singapore 569111.

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 651U

✓ To transfer of rear luggage floor panel fittings,
attachment and perform water seepage test.

\$ 170.00 X

To supply and re-do rear luggage floor panel
insulation padding.

\$ 380.00 801

← To transfer of rear fender fittings, attachment and
perform water seepage test.

\$ 380.00 1201

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ 170.00 1201

To check steering geometry and computer wheel
alignment

\$ 220.00 601

To transfer of rear door fittings, attachment and
perform water seepage test.

\$ 380.00 X

To dismantle and refit rear axle housing assy, remove
and renewal of parts, final checking and testing.

\$ 380.00 X

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ 380.00 2501

TOTAL \$ 11,340.00 2480**Over All Total \$ 46,575.91****(LUMP SUM)****Repair Days****30 DAYS**

48425.91*

20 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____