



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

**TP INSURER:** India International Insurance Pte Ltd (HQ)  
**NIL**

Singapore

**Claimant Insurer:** AXA Insurance Pte Ltd**PARTICULARS OF CLAIM**

|                               |                                                  |                    |                            |
|-------------------------------|--------------------------------------------------|--------------------|----------------------------|
| Claim Type:                   | THIRD PARTY                                      | Ref. No:           |                            |
| Policy No:                    |                                                  | Date of Loss:      | 17/01/2019                 |
| Vehicle Reg. No.:             | <b>SBM5555R</b>                                  | Driveable?         |                            |
| Party At Fault:               | UNKNOWN                                          |                    |                            |
| Driver (TP):                  | CHOW WEE JIA, ANASTACIA                          | Driver (Insured):  | CHENG POH KHUAN            |
| Make/Model:                   | TOYOTA COROLLA ALTIS, 1.6 (A)                    | Vehicle Reg. Date: | 02/11/2016                 |
| Vehicle Colour:               | GREY                                             |                    |                            |
| Engine No:                    | 1ZRY316965                                       | Chassis No:        | MR053REH104554810          |
| Odometer:                     | 0 KM                                             |                    |                            |
| Paint Type:                   |                                                  |                    | <i>Not Authorised</i>      |
| Total Loss?                   | <b>NO</b>                                        |                    | <i>Resuming B&amp;Pain</i> |
| Est. Duration of Repair (day) | 6 ✓                                              |                    |                            |
| Description of Accident/Loss  | PLEASE REFER TO SKETCH PLAN.                     |                    |                            |
| Remarks:                      | VEHICLE IS IN AND ARRANGE FOR SURVEY. THANK YOU. |                    |                            |
| Present Location:             | K KIM HIN AUTO PTE LTD (HQ)                      |                    |                            |

| <b>COST OF CLAIMS</b>     | <b>Amount</b>   |
|---------------------------|-----------------|
| Parts                     | 5,653.69        |
| Miscellaneous Items       | 10.00           |
| Labour                    | 2,370.00        |
| Paintwork Labour          | 0.00            |
| Towing                    | 0.00            |
| <b>Gross Total (\$\$)</b> | <b>8,033.69</b> |
| <b>+ GST 7.00% (\$\$)</b> | <b>562.36</b>   |
| <b>Nett Amount (\$\$)</b> | <b>8,596.05</b> |

**This claim is handled by: WONG SHU MAN**

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 22 Jan 2019)

**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SBM5555R)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                              |                     | %Disc | %Depr | Amount      |   |
|-----|-----|----------|------------------------------------------|---------------------|-------|-------|-------------|---|
| 1   | 1   |          | *REAR BUMPER                             | R <sub>1</sub>      | 0.00  | 0.00  | *486.50 F   | ✓ |
| 2   | 2   |          | *REAR BUMPER SIDE RETAINER-LONG LH/RH    | D.Y                 | 0.00  | 0.00  | *240.00 F   | ✓ |
| 3   | 2   |          | *REAR BUMPER SIDE RETAINER-SHORT LH/RH   | D.Y                 | 0.00  | 0.00  | *160.00 F   | ✓ |
| 4   | 10  |          | *REAR BUMPER CLIPS                       | N <sub>2</sub>      | 0.00  | 0.00  | *50.00 F    | ✓ |
| 5   | 2   |          | *REAR BUMPER REFLECTOR                   | S <sub>2</sub>      | 0.00  | 0.00  | *134.00 F   | X |
| 6   | 1   |          | *REAR BUMPER REINFORCEMENT               | R <sub>1</sub>      | 0.00  | 0.00  | *395.00 F   | ✓ |
| 7   | 2   |          | *REAR BUMPER REINFORCEMENT BRACKET LH/RH |                     | 0.00  | 0.00  | *136.00 F   | ? |
| 8   | 1   |          | *REAR BUMPER PARKING SENSOR SET          | Short               | 0.00  | 0.00  | *421.70 F   | ✓ |
| 9   | 1   |          | *SMART KEY ANTENNA                       |                     | 0.00  | 0.00  | *165.00 F   | ? |
| 10  | 2   |          | *TAILLAMP ASSY LH/RH                     | S <sub>2</sub>      | 0.00  | 0.00  | *790.00 F   | X |
| 11  | 1   |          | *REAR END PANEL                          | R <sub>1</sub>      | 0.00  | 0.00  | *649.20 F   | ✓ |
| 12  | 1   |          | *REAR END PANEL TOP GARNISH              | M/D 1               | 0.00  | 0.00  | *240.00 F   | ✓ |
| 13  | 2   |          | *REAR END PANEL TOP GARNISH CLIPS        | N <sub>2</sub>      | 0.00  | 0.00  | *5.00 F     | ✓ |
| 14  | 1   |          | *SPARE TYRE PANEL TOP BOARD              | S <sub>2</sub>      | 0.00  | 0.00  | *334.87 F   | X |
| 15  | 1   |          | *SPARE TYRE LOCK SCREW                   |                     | 0.00  | 0.00  | *65.00 F    | ? |
| 16  | 2   |          | *REAR FENDER INNER TRIM LH/RH            | S <sub>2</sub>      | 0.00  | 0.00  | *1,518.00 F | X |
| 17  | 1   |          | *BOOTLID                                 | B <sub>2</sub>      | 0.00  | 0.00  | *758.00 F   | ✓ |
| 18  | 1   |          | *BOOTLID LOGO                            | N <sub>2</sub>      | 0.00  | 0.00  | *52.15 F    | ✓ |
| 19  | 1   |          | *BOOTLID COROLLA EMBLEM                  | N <sub>2</sub>      | 0.00  | 0.00  | *48.00 F    | ✓ |
| 20  | 1   |          | *BOOTLID ALTIS EMBLEM                    | N <sub>2</sub>      | 0.00  | 0.00  | *48.00 F    | ✓ |
| 21  | 2   |          | *BOOTLID HINGES LH/RH                    | R                   | 0.00  | 0.00  | *136.00 F   | X |
| 22  | 1   |          | *BOOTLID LOCK                            | N <sub>2</sub>      | 0.00  | 0.00  | *382.50 F   | ✓ |
| 23  | 1   |          | *BOOTLID LOCK CATCH                      | R                   | 0.00  | 0.00  | *35.00 F    | X |
| 24  | 1   |          | *BOOTLID WEATHERSTRIP                    | N <sub>2</sub> 1011 | 0.00  | 0.00  | *185.00 F   | ✓ |
| 25  | 10  |          | *BOOTLID INSULATOR CLIPS                 | N <sub>2</sub>      | 0.00  | 0.00  | *50.00 F    | X |
| 26  | 1   |          | *REAR NUMBER PLATE                       | N <sub>2</sub>      | 0     | 0.00  | *40.00 FS   | ✓ |

F=Franchise part. S=SpcNett.

|                                         |                 |
|-----------------------------------------|-----------------|
| Sub Total (\$\$)                        | 7,524.92        |
| - Add. Disc. on L,N Items 25.00% (\$\$) | 1,871.23        |
| <b>Total Parts (\$\$)</b>               | <b>5,653.69</b> |

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

## Estimates on Miscellaneous Items

| No                         | Qty | Particulars          | Amount |
|----------------------------|-----|----------------------|--------|
| <u>Miscellaneous Items</u> |     |                      |        |
| 1                          | 1   | OD/TP Case (Insurer) | 10.00  |
| Sub Total (\$\$)           |     |                      | 10.00  |

## Estimates on Labour

| No                       | Particulars                                                                                                             | Lab.Type | Amount       |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------|----------|--------------|
| <u>Labour Items</u>      |                                                                                                                         |          |              |
| 1                        | TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.                     | New      | 700 900.00   |
| 2                        | TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.                                                             | New      | 201 50.00    |
| 3                        | TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS. | New      | 601 120.00   |
| 4                        | TO APPLY UNDERSEALING.                                                                                                  | New      | 601 120.00   |
| 5                        | TO REMOVE AND REFIT REVERSE SENSOR ASSY.                                                                                | New      | 501 80.00    |
| 6                        | TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.                                                                              | New      | 800 1,100.00 |
| Gross Labour Cost (\$\$) |                                                                                                                         |          | 2,370.00     |

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: