



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)

0

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

Alan 96869276

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/01/2019
Vehicle Reg. No.:	SGF4789S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LEE KOK SENG (LI GUOSHENG)		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	12/04/2006
Vehicle Colour:	SILVER	Chassis No:	MR053HY4204178874
Engine No:	1NZX393608		
Odometer:	0 KM		
Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	MOVA AUTOMOTIVE PTE LTD (FAN YOONG)		

COST OF CLAIMS

	Amount
Parts	8,422.75
Miscellaneous Items	10.00
Labour	4,010.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	12,442.75
+ GST 7.00% (\$)	870.99
Nett Amount (\$)	13,313.74

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jan 2019)
Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGF4789S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER <i>DE</i>	25.00	0.00	*480.00 FL
2	2		*FRONT BUMPER SIDE RETAINER <i>ne</i>	25.00	0.00	*60.00 FL
3	2		*FRONT FOG LAMP COVER <i>X</i>	25.00	0.00	*180.00 FL
4	1		*FRONT BUMPER REINFORCEMENT <i>X</i>	25.00	0.00	*260.00 FL
5	20		*FRONT BUMPER CLIPS <i>ne</i>	25.00	0.00	*100.00 FL
6	2		*FRONT FENDER L & R <i>PA</i>	25.00	0.00	*620.00 FL
7	2		*FRONT FENDER INNER SHIELD <i>ne</i>	25.00	0.00	*220.00 FL
8	20		*INNER SHIELD CLIPS <i>ne</i>	25.00	0.00	*100.00 FL
9	<i>2 1pc</i>		*FRONT FENDER SIGNAL LAMP <i>LH-Mo / RH-XM</i>	25.00	0.00	*120.00 FL
10	1		*FRONT GRILLE <i>X</i>	25.00	0.00	*198.00 FL
11	2		*HEADLAMP <i>SC</i>	25.00	0.00	*860.00 FL
12	2		*HEADLAMP PANEL <i>X</i>	25.00	0.00	*230.00 FL
13	2		*HEADLAMP CLIPS <i>ne</i>	25.00	0.00	*20.00 FL
14	1		*LH FRONT DOOR <i>PA</i>	25.00	0.00	*979.00 FL
15	<i>1pc</i>		*LH FRONT DOOR HINGE <i>PA (bottom) / top-X</i>	25.00	0.00	*200.00 FL
16	1		*LH FRONT DOOR CHECKER <i>X</i>	25.00	0.00	*110.00 FL
17	1		*LH FRONT DOOR PROTECTOR <i>ne</i>	25.00	0.00	*130.00 FL
18	1		*LH FRONT DOOR RUBBER <i>ne</i>	25.00	0.00	*230.00 FL
19	1		*LH FRONT DOOR INNER TRIM <i>X</i>	25.00	0.00	*430.00 FL
20	1		*LH FRONT DOOR PILLAR <i>repair</i>	25.00	0.00	*770.00 FL
21	2		*LH FRONT SPORT RIMS <i>SC (2 pcs)</i>	25.00	0.00	*1,300.00 FL <i>600 S/A</i>
22	1		*LH FRONT LOWER ARM <i>?</i>	25.00	0.00	*230.00 FL
23	1		*LH FRONT KNUCKLE <i>?</i>	25.00	0.00	*380.00 FL
24	1		*LH FRONT SHOCK ABSORBER <i>?</i>	25.00	0.00	*240.00 FL
25	1		*LH FRONT ABSORBER MOUNTING <i>?</i>	25.00	0.00	*130.00 FL
26	1		*LH FRONT WHEEL BEARING <i>?</i>	25.00	0.00	*160.00 FL
27	1		*LH FRONT STABILIZER LINK <i>?</i>	25.00	0.00	*110.00 FL
28	1		*LH FRONT WHEEL HOUSE PANEL - TBA <i>?</i>	25.00	0.00	-
29	1		*REAR BUMPER <i>DE</i>	25.00	0.00	*480.00 FL
30	2		*REAR BUMPER SIDE RETAINER <i>X</i>	25.00	0.00	*80.00 FL
31	1		*REAR AXLE <i>X</i>	25.00	0.00	*700.00 FL
32	1		*REAR EXHAUST ASSY <i>PA</i>	25.00	0.00	*420.00 FL
33	2		*REAR EXHAUST MOUNTING <i>ne</i>	25.00	0.00	*60.00 FL
34	1		*RH FRONT WHEEL BEARING <i>?</i>	25.00	0.00	*110.00 FL
35	2		*FRONT TYRE L & R <i>X</i>	0	0.00	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,097.00
- List Item Discount on L Items (\$\$)	2,674.25
Total Parts (\$\$)	8,422.75

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & REPLACE FRONT & REAR UNDERCARRIAGE DAMAGED PARTS	New	500.00
3	TO CHECK ALL WHEEL ALIGNMENT	New	80.00
4	TO REMOVE & INSTALL CARPET, SEAT, GARNISHES, IN ORDER TO CUT OFF LH FRONT DOOR PILLAR	New	200.00
5	TO CUT OFF LH FRONT DOOR PILLAR, LH FRONT WHEEL HOUSE PANEL & STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1,500.00
6	TO REMOVE & TRANSFER ITEMS TO LH FRONT NEW DOOR	New	80.00
7	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	50.00
8	TO APPLY RUST PROOF ON AFFECTED AREAS	New	150.00
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,400.00
Gross Labour Cost (S\$)			4,010.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Resue

Hp 90010068

12 days

HS

22/01/19 @ 1100

Resue after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: