


NTUC



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

A&G/NTUC/III
DOA: 20/01/2019@0800

NTUC INCOME INSURANCE CO LTD

21/1/2019

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SGX 2097 Z - HONDA STREAM SUNROOF 1.8L A
CHASSIS NO: JHMRN68407S200335 (2017)

1 pc	Front door LH <i>nt</i>	\$	877.00
1 pc	Front door frame sticker <i>ne</i>	\$	65.00
1 pc	Rear door LH <i>df</i>	\$	878.00
1 pc	Rear door frame sticker LH <i>ne</i>	\$	55.00
1 pc	LH side skirt <i>car</i>	\$	425.00
		\$	2,300.00
	LESS 20%	\$	460.00
		\$	1,840.00

Remove and reinstall front door assy & door glass LH. \$ ~~60.00~~ 40
 Remove and reinstall rear door assy & door glass LH. \$ ~~60.00~~ 40

Remove necessary parts: jacking, panel beating, repair and straighten front door LH, rear door LH and LH side skirt. \$ ~~600.00~~ 500

Putty and respray front door LH, rear door LH and LH side skirt. \$ ~~600.00~~ 500
 \$ 3,160.00

ADD 7% GST \$ 221.20
 \$ 3,381.20

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resul
Hp 900 10068
5 days
4s
23/01/19 @ 1245
Resurvey after repair