

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19001429/GEA3Q2**Date:** 30/03/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLU9149T	Insured Vehicle No :	SHC8704P
Date of Loss:	21/01/2019	Nature of Claim:	TP
		Claim No:	MCT19010622

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU9149T	Engine No:	LEB5965907
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31265887
Reg. Date:	18/12/2017 (Man. Year: 2017)	Odometer:	144766 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	400.00	200.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	600.00	400.00	200.00	33.33
+ GST 7.00/7.00% (S\$)	42.00	28.00	14.00	33.33
Nett Amount (S\$)	642.00	428.00	214.00	33.33
+ Car Rental (1.0 x S\$75.00/day) (S\$)		75.00		
(S\$)		503.00		
Liabile Amount (50.00%) (S\$)		251.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		258.95		
Global Sum Settlement (S\$)		260.00		

INSPECTION

Date of Assignment:	22/01/2019		
Date Inspected:	24/01/2019	Inspected At:	Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266
Estimated Period of Repair:	1.0 days		

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU9149T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY /SANDPRIPER /SPRAY /ADJUST) POLISH AND WASH (FRONT BUMPER ,FENDER,FENDER ARC)	New	600.00	400.00
Gross Labour Cost (\$)			600.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >