

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SLB997X

No.	Qty	List Items		
1	1	Front bumper	Bu \$	1,416.35 ✓
2	1	Front bumper lower spoiler	\$	606.35 ?
3	1	Front bumper RH fog lamp cover	\$ Bu	112.45 X
4	1	Front bumper RH fog lamp	\$ Bu	397.10 X
5	1	Front bumper grille	\$ D/I	483.10 ✓
6	1	Front bumper RH side retainer	\$ D/I	110.35 ✓
7	1 set	Front bumper clips	\$ Bu	40.00 ✓
8	1	Front bumper inner reinforcement	\$	417.10 ?
9	1	Front bumper inner centre beam	\$	291.10 ?
10	1	Front bumper inner RH side beam	\$	223.10 ?
11	1	Front bumper inner centre foam	\$	129.45 ?
12	1	Front bumper inner RH side foam	\$	69.45 ?
13	2	Headlamp <i>also X</i>	ols ? \$	6,374.80
14	1	Front grille assy	\$ CR	519.10 ✓
15	1	Front bonnet lock	\$ R	165.10 X
16	1	Front bonnet top chrome	\$	359.10 ?
17	1	Front support panel	\$ R	819.10 X
18	1	Air con condenser	\$	1,204.95 ?
19	1	Front RH fender	\$ Bu	707.10 ✓
20	1	Front RH fender under shield	\$	201.10 ?
21	1 set	Front fender under shield clips	\$ Bu	30.00 ?
22	1	Rear bumper	\$ Bu	1,410.35 ✓
23	1	Rear bumper lower spoiler	Red/GW \$	654.10 ✓
24	2	Rear bumper reflector	\$ Bu	220.70 X
25	2	Rear bumper side retainer	\$ Bu	248.20 X
26	1 set	Rear bumper clips	\$ Bu	40.00 ✓
27	1	Rear bumper inner foam	\$	159.10 ?
28	1	Rear tailgate	\$ Bu	1,816.10 ✓
29	1	Rear tailgate centre top "TOYOTA" logo	\$ Bu	75.10 ✓
30	1	Rear tailgate "HARRIER" emblem	\$ Bu	110.35 ✓
31	1	Rear tailgate top lock	\$	599.10 ?
32	1	Rear tailgate lower lock catch	\$ R	40.30 X
33	1	Rear tailgate weatherstrip	\$ Bu	399.10 X
34	1	Rear tailgate inner trim board	\$ Bu	680.10 X
35	1 set	Rear tailgate inner trim board clips	\$ Bu	60.00 X
36	1 set	Rear tailgate windscreen moulding	\$ Bu	210.10 ✓
37	1	Rear end panel	\$	597.10 ?
38	1	Rear end panel top garnish	\$	395.45 ?
39	1	Rear exhaust silencer	\$ R	1,019.45 X
			\$	23,410.95
Less 25%			\$	5,852.74
Total :			\$	17,558.21

NOT WITHIN
 21 Day 8?
 Recovery After Paint
 8-10 days

Special Nett Items

40	1	Front number plate	\$	<i>Sur</i> 50.00	<i>45.50</i>
41		1 set Reverse sensors	\$	250.00	<i>?</i>
42		1 set Rear windscreen sealant	\$	<i>na</i> 80.00	<i>40.50</i>
43		1 set Rear end panel sealant	\$	50.00	<i>?</i>
Total :			\$	430.00	

Labour

1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,300.00	<i>?</i>
2		To putty and spray Spray Paintings charges.	\$	1,600.00	<i>1100</i>
3		To remove, refit rear windscreen glass.	\$	140.00	<i>120</i>
4		To check wirings and lightings.	\$	50.00	<i>40</i>
5		To remove, refit reverses sensors & reverse camera.	\$	120.00	<i>60</i>
6		To remove, refit rear tailgate fittings.	\$	80.00	<i>60</i>
7		To remove, refit rear upholstery and attachments.	\$	120.00	<i>?</i>
8		To remove, refit rear exhaust silencer.	\$	<i>na</i> 80.00	<i>X</i>
9		To supply and apply anti rust treatment	\$	100.00	<i>?</i>
Total :			\$	3,590.00	

Total Parts and Labour : \$ 21,578.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: