

源摩哆廠 GUAN MOTOR WORKS

Business Regd. No. 081026000

1, 1st Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003 • 10 days

REPAIR ESTIMATE FOR SLB997X

No.	Qty	List Items	
1	1	Front bumper 1310	Bu \$ 1,416.35
2	1	Front bumper lower spoiler 387.40	\$ CM 606.35
3	1	Front bumper RH fog lamp cover	\$ R 112.45 X
4	1	Front bumper RH fog lamp	\$ R 397.10 X
5	1	Front bumper grille 390	\$ D1 483.10
6	1	Front bumper RH side retainer	\$ D1 110.35
7	1 set	Front bumper clips	\$ R 40.00
8	1	Front bumper inner reinforcement	\$ B1 417.10
9	1	Front bumper inner centre beam	\$ Bu 291.10
10	1	Front bumper inner RH side beam	\$ B1 223.10
11	1	Front bumper inner centre foam	\$ CM 129.45
12	1	Front bumper inner RH side foam	\$ CM 69.45
13	2	Headlamp 115.50	015 2 \$ 6,374.80
14	1	Front grille assy	\$ CM 519.10
15	1	Front bonnet lock	\$ R 165.10 X
16	1	Front bonnet top chrome	\$ CM 359.10
17	1	Front support panel	\$ R 819.10 X
18	1	Air con condenser	\$ Bu 1,204.95
19	1	Front RH fender	\$ Bu 707.10
20	1	Front RH fender under shield	\$ CM 201.10
21	1 set	Front fender under shield clips	\$ R 30.00
22	1	Rear bumper 1381.50	\$ Bu 1,410.35
23	1	Rear bumper lower spoiler 396.80	neg/lt 654.10
24	2	Rear bumper reflector	\$ R 220.70 X
25	2	Rear bumper side retainer	\$ R 248.20 X
26	1 set	Rear bumper clips	\$ R 40.00
27	1	Rear bumper inner foam	\$ CM 159.10
28	1	Rear tailgate 1712.03	\$ B1 1,816.10
29	1	Rear tailgate centre top "TOYOTA" logo	\$ R 75.10
30	1	Rear tailgate "HARRIER" emblem	\$ R 110.35
31	1	Rear tailgate top lock 381.70	\$ R 599.10
32	1	Rear tailgate lower lock catch	\$ R 40.30 X
33	1	Rear tailgate weatherstrip	\$ R 399.10 X
34	1	Rear tailgate inner trim board	\$ R 680.10 X
35	1 set	Rear tailgate inner trim board clips	\$ R 60.00 X
36	1 set	Rear tailgate windscreen moulding	\$ R 210.10
37	1	Rear end panel	\$ B1 597.10
38	1	Rear end panel top garnish	my \$ CM 395.45
39	1	Rear exhaust silencer	\$ R 1,019.45 X
			\$ 23,410.95
Less 25%			\$ 5,852.74
Total :			\$ 17,558.21

Special Nett Items

40	1 Front number plate	\$	50.00	50.00
41	1 set Reverse sensors	\$	250.00	250.00
42	1 set Rear windscreen sealant	\$	80.00	80.00
43	1 set Rear end panel sealant	\$	50.00	50.00
Total :		\$	430.00	430.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	1,300.00	1,300.00
2	To putty and spray Spray Paintings charges.	\$	1,600.00	1,600.00
3	To remove, refit rear windscreen glass.	\$	140.00	140.00
4	To check wirings and lightings.	\$	50.00	50.00
5	To remove, refit reverses sensors & reverse camera.	\$	120.00	120.00
6	To remove, refit rear tailgate fittings.	\$	80.00	80.00
7	To remove, refit rear upholstery and attachments.	\$	120.00	120.00
8	To remove, refit rear exhaust silencer.	\$	80.00	80.00
9	To supply and apply anti rust treatment	\$	100.00	100.00
Total :		\$	3,590.00	3,590.00

Total Parts and Labour : \$ 21,578.21