

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP AIG`

Claim Type: Third Party

Accident Date: 06/01/2019

Estimate No: ES1991067/WS

Date: 21 Jan 2019

Policy No:

Veh Reg No: SLW9865Z

Make/Model: MAZDA MAZDA 3
SEDAN

Chassis No: JM6BN22A8H0168844

Engine No:

Reg. Date: 13/03/2018

Estimate Repair Cost to Vehicle No :SLW9865Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER		1 PC		
2 FRONT BUMPER SIDE RETAINER LH		1 PC		
3 FRONT BUMPER CLIP		6 PCS		
4 FRONT BUMPER RIVET		6 PCS		
5 FRONT BUMPER FOG LAMP GARNISH LH		1 PCS		
6 FRONT FENDER CLIP LH		4 PCS		
7 HEADLAMP LH		1 PC		
			0.00	0.00
Labour				
8 TO PERFORM PANEL BEATING, KNOCK AND REPAIR FRT LH FENDER	400	1 LA	400.00	200
9 PUTTY AND RESPRAY ON FRT BUMPER, FRT LH FENDER	450	1 LA	450.00	400
			850.00	850.00
			Total	S\$ 850.00
			Add GST @ 7%	59.50
			Total Amount Payable	S\$ 909.50

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE