

Kj

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Notarized ESTIMATE

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way,

AIG Building #09-16

Singapore 079120

Attn: Motor Claims Department

61 Lp 822501
Resurvey After Paint
Solaris

Date:

22/01/2019

Vehicle No:

SJQ1317Y

Veh Make/Model:

Toyota Vios E 1.5 A

YOM:

2009

Chassis No:

MR053HY9305109433

Date of Accident:

20/01/2019

No	Qty	Description	Amount \$
List Items:-			
1	1	Boot lid	\$ Bu 678.00 ✓
2	1	Boot lid center garnish	\$ Bu 395.91 X
3	1	Boot lid "VIOS" emblem	\$ Bu 71.50 ✓
4	1	Boot lid "E" emblem	\$ Bu 81.50 ✓
5	1	Boot lid logo	\$ Bu 61.42 ✓
6	1	Boot lid lock	\$ Bu 97.31 ✓
7	1	LH tail lamp	\$ Bu 127.69 X
8	1	LH tail lamp gasket	\$ Bu 48.70 X
9	1	RH tail lamp	\$ Bu 187.60 X
10	1	RH tail lamp gasket	\$ Bu 48.60 X
11	1	Rear bumper	\$ Bu 379.81 ✓
12	2	Rear bumper side retainer	\$ N/S 70.57 ✓
13	2	Rear bumper side bracket	\$ Bu 49.18 X
14	10	Rear bumper clip	\$ Bu 48.00 ✓
15	1	Rear bumper reflector (LH)	\$ CM 76.35 ✓
16	1	Rear bumper reflector (RH)	\$ Bu 76.35 X
17	1	LH air duct	\$ Bu 96.17 X
18	1	RH air duct	\$ Bu 96.17 X
19	1	End panel	\$ Bu 495.90 X
20	1	End panel top garnish	\$ Bu 156.81 ✓
21	6	End panel top garnish clips	\$ Bu 28.80 ✓
22	1	Floor panel	\$ Bu 697.84 X
Total - List Item			\$ 4,070.18
Less 25%			\$ 1,017.55
Total			\$ 3,052.64
Balance b/f			\$ 3,052.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way,

AIG Building #09-16

Singapore 079120

Attn: Motor Claims Department

Date : 22/01/2019

Vehicle No : SJQ1317Y

Veh Make/Model : Toyota Vios E 1.5 A

YOM : 2009

Chassis No : MR053HY9305109433

Date of Accident : 20/01/2019

No	Qty	Description	Amount \$
		Balance c/f	\$ 3,052.64
		<u>Special Nett Items:-</u>	
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor	\$ 380.00
3	1	Boot lid compartment waterproof sealant	\$ 200.00
		Total - SN Item	\$ 635.00
		<u>Labour Charges:-</u>	
1		Spray painting on all affected area.	\$ 900.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,100.00
3		To apply anti rust treatment.	\$ 120.00
4		To check wiring system & light.	\$ 80.00
5		To remove and replace reverse sensor.	\$ 120.00
6		To check and test boot lid water leaking.	\$ 100.00
7		To adjust exhaust silencer system.	\$ 150.00
		Total - L/C	\$ 2,570.00
		Sub-Total	\$ 6,257.64
		7% GST	\$ 438.03
		Total	\$ 6,695.67

455a
200m
X

6001
600
301
201
501
201
X