

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised
1.2/
Resurvey Beyond
3 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 21.01.2019

Accident Date : 20.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Kia Forte K3" Reg. No. SKF803M Claiming Against Your Insured Reg. No. SLN5887J		
1pc	Rear Bumper	4.50	779.00 ✓
10pcs	Rear Bumper Clips		45.00 ✓
1pc	Rear Bumper Bracket RH		36.00 X
1pc	Rear Bumper Sponge		214.00 7
1pc	Rear Bumper Reinforcement		395.00 7
1pc	Rear Bumper Lower Diffuse Cover		241.00 ✓
1pc	Rear Bumper Reflector RH		125.00 X
1pc	Rear Bumper Auto Boot Sensor	12.00	185.00 7
4pcs	Rear Bumper Plastic Inner Plastic Retainers		48.00 7
1pc	Boot Emblem		41.00 ✓
1pc	Boot Badge "Forte"		39.00 ✓
1pc	Boot Badge "K3"		36.00 ✓
1pc	Boot Badge C&C		38.00 ✓
	Less 10%		2,222.00
			222.20
			1,999.80
1pc	Rear Bumper Reverse Sensor		280.00 SN ✓
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring Etc		120.00 50/
	Labour Charge - Panel Beating, Repairing Of Boot, End Panel and Parts Replacement		500.00 300/
	To Respray Affected Areas (Pear White)		700.00 440/
	Total :		3,599.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: