

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : HON INDUSTRIES PTE LTD
 BLK 20 ANG MO KIO INDUSTRIAL PARK 2A
 #07-33 AMK TECHLINK
 SINGAPORE 567761

Estimate No: MC1900054
 Date: 16 Jan 2019
 Policy No: GA266048
 Veh Reg No: SLR4451T
 Make/Model: HONDA FIT 1.3 GA

ATTN:

Your Ref No: SLR4451T

Claim Type: Third Party

Accident Date: 14/01/2019

TP Veh Reg No: SLH9929C

Estimate Repair Cost to Vehicle No :SLR4451T

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 TAILGATE	1 PC	771.55	X
2 TAILGATE "FIT" LOGO	1 PC	35.00	✓
3 REAR WINDSCREEN MOULDING	1 PC	36.50	X
4 TAILAMP LH	1 PC	206.00	✓
5 REAR BUMPER	1 PC	497.40	✓
6 REAR BUMPER SIDE RETAINERS LH / RH	2 PC	33.00	✓
7 REAR BUMPER CLIPS	15 PC	58.50	✓
8 REAR BUMPER LOWER SPOILER	1 PC	958.00	✓
9 REAR END PANEL	1 PC	276.50	?
10 REAR FENDER COWLING LH	1 PC	42.90	✓
		2,915.35	
	Less 20%	583.07	2,332.28
Special Nett			
11 REAR BUMPER LOWER SPOILER MOULDING - CHK PRICE	1 PC	0.0000	X
12 REVERSE SENSOR	1 SET	200.00	✓
13 INNER SEAL	1 PC	20.00	X
14 SEALANT	1 PC	40.00	X
		260.00	260.00
LABOUR			
15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	2cl
16 TO REMOVE AND REINSTALL/REPLACE DASHBOARD.	1 PC	120.00	X
17 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	80.00	7
18 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	X
19 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	5cl
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
21 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	7
22 TO SPRAY TAILGATE, REAR BUMPER, END PANEL, REAR FENDER LH	1 PC	800.00	75cl
		2,060.00	2,060.00

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 FAX: 6483 6170

Not Authorised
 11 Jan 2019
 Murray Ate Paint

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : HON INDUSTRIES PTE LTD
BLK 20 ANG MO KIO INDUSTRIAL PARK 2A
#07-33 AMK TECHLINK
SINGAPORE 567761

Estimate No: MC1900054
Date: 16 Jan 2019
Policy No: GA266048
Veh Reg No: SLR4451T
Make/Model: HONDA FIT 1.3 GA

ATTN:

Your Ref No: SLR4451T
Claim Type: Third Party
Accident Date: 14/01/2019
TP Veh Reg No: SLH9929C

Estimate Repair Cost to Vehicle No :SLR4451T

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 4,652.28
		Add GST @ 7%	325.66
		Total Amount Payable	S\$ 4,977.94

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND NINE HUNDRED SEVENTY SEVEN AND CENTS NINETY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY


AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: