ASS. REC. BY:		REF: (S/UM	19001448/Kt	d312 Special Instruction:	
Surveyor -			MENT (Office)	22000 014	
Estimated Cos	st:		Bill to:	Date/Time:	
OD/EP/W	S/TP RES / OD I chicle No:	RES/EVA/INV/M	V / CS	Insured: SLG 4463U	
of		Truns (ab No. 2 AMK St	63	Tel: 6603 1459	
Policy No:	DHOMIZU	00817018	Claim No:		
Make of Veh:(Client's Record)			D.O.A. 00.017019		
	/ REP. / REV 24		led:	H.O.D. Endorsement:	
Date/Time	Action/Instruction SHD 740 G - SLG LILLEN	X	nte		
-	4				

ASS. REC. BY:	
Kenneth	SSIGNMENT
Estimated Cost: OD LIP WS TP RES OD RES EVA INV MV To Inspect Vehicle No: at Workshop m/s of Insured:	Veh No: SIAD #406Yr Regn: 12, 17 Type: M.Car / M.Cycle / Bus / Van / Lorry / Paxi? Prime Mover / Truck / Trailer or Make: Rencult (97, Tuol, c.c. 199. Colour B. White / Ref AIC: Insured / Std / NI / NA Sp.Reading 182437 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
Claims No.	CNO: VI-1ABLISAUC 283353
Sum Insured: Excess: (Client's Record) Make of Veh:	Gen. Cond: Qood) Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or Modi: Mil / S/Rim / STD A/Rim or
(Policy Condition) Remark: The veh had commenced its repair at the time of Inspection. Bal, or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: OZ days Res.: Yes or No	Tyre Size: F: 2/5/60R/6 R: BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/ TOYO/YOKO or Gi7/ Front Rear R/Bal. J mm R/Bal. Z mm L/Bal. J mm
Est. Repairs: O2 days Res.: Yes or No Lum Sum: I-B. 1 % 3 Val.: Yes or No	D.O.A. 20/1/19 D.O.I. 22/1/19
Date: Person Contacted: Date / Time Action / Instruction 23/1 File pars To Car	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S/FM The U/C / Chassis frame / Body Structure affected due to collision.
Onto/Timo, File Pass to?	ZED 1 6 APR 2019
WHITTIPIST IN THE	ays Of Repair: 2 Burvey No. of Trip: Survey Fee: 250+150 Transportation: 60 Site Insp (\$) S-RS_SI 80 Interview (\$) Fixed 80 Weekend (\$) Others Total (\$) Others
	WALL OF THE

Denise Tay (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Monday, 15 April 2019 5:14 PM

To:

Denise Tay (LKKAuto)

Subject:

RE: SHD 740G / TP / DOA: 20/01/2019 -- AAD1901-199

Hi Denise

We confirmed COR \$ 3,997.18.

Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Friday, 12 April, 2019 9:18 AM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Subject: RE: SHD 740G / TP / DOA: 20/01/2019 -- AAD1901-199

Dear Wai Yin,

I've check with Kenneth part by part \$3,997.18. 2days

Please check and confirm.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Thursday, 11 April 2019 1:35 PM

To: Denise Tay (LKKAuto) < denisetay@lkkauto.com>

Subject: RE: SHD 740G / TP / DOA: 20/01/2019 -- AAD1901-199

MTCS19009857 / Trans-Cab Services Pte Ltd - HQ ENTRY DATE & TIME: 21/01/2019 15:33 SUBMITTED BY: Kek ZheWei

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby cor aforesaid.	nsent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	21/01/2019 15:33
Date Of Accident	20/01/2019 21:55
Exact Location Of Accident	YISHUN CENTRAL
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHD740G
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 CVT ABS (A)
Exact Purpose for which vehicle was being used a time of accident	t HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver ZAKARIA B BAKAR NRIC No S0219034F Date Of Birth 03/07/1953 Occupation OUTDOOR Date Of Driving Pass 06/03/1980

38 YEARS AND 10 MONTHS **Driving Experience**

Gender MALE

Mobile Number (LOCAL) +65-96609579

Fax Number Contact Number

EMail Address NOEMAIL Address BLK 527 BUKIT BATOK ST 51

#01-76

Postcode 650527

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OTHER - HIRER

Insurance Company of Driver's Own Vehicle

-

2

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 3

Passenger 1 NAME: : UNKNOWN

GENDER: : FEMALE

Passenger 2 NAME: : UNKNOWN

Details of Police Action

Was the accident reported to the police? NO

a to the police!

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

ON 20/01/2019 AT ABOUT 2155HRS, I WAS TRAVELLING STRAIGHT ALONG THE FIRST LANE OF YISHUN CENTRAL. SUDDENLY I FELT AN IMPACT ON THE LEFT SIDE OF MY TAXI, VEHICLE B(SLG4462U) CAME OUT FROM YISHUN CENTRAL SERVICE ROAD AND HIT ONTO THE FRONT LEFT PORTION OF MY TAXI.

GENDER:

NO

: FEMALE

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES

Remarks/ Reasons: FILE SIZE TOO LARGE

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG4462U

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: Leve

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN Yishun Central DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Refer to GIA Reports DECLARATION I/We declare the foregoing particulars are true in every respect. Policyholder's Signature Driver's Signature Reporting Centre Personnel's Signature Date & Time: (If driver is not the policyholder) Name:

Date & Time:

NRIC/FIN No.:

2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	3878K
Vehicle No.:	SHD740G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003125
Chassis No.:	VF1ABL15AUC283353
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$19,998.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2025
PARF Rebate Amount: Intended COE Rebate Details	\$14,998.00
COE Expiry Date:	28 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,327.00
Total Rebate Amount: Message	\$42,325.00
	had about a second Through I do not be do not be added and COT and in any than the

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Jan 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

> Vehicle No.: Chassis No.: Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

CO./GST Reg. No. 201019626G

SHD 740G

AAD1901-199

Not AUTRORES

RESUMY BE PRIM

SHD 740G

VF1ABL15AUC283353

LILM \$3200

RENAULT LATITUDE 20.1.2019

UOI

	Date of Registration :	29/12/20	017
	PART		LIST
			Bull
1	BUMPER COVER FRT	\$	Bully 1,259.42 -
1	BUMPER SPOILER FRT	\$	181.75 X
1	BUMPER ABSORBER FRT	\$	√4 394.68 X
1	BUMPER RETAINER FRT LH	\$	D) y 151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER RETAINER FRT RH	\$	150.77
1	BUMPER SUPPORT FRT	\$	123.88 X
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	√ _{~ 266.80} /
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER BEAM FRT	\$	₱ 914.08
1	HEADLAMP LH	\$	mg cm 1,184.43
1	HEADLAMP PANEL FRT LH	\$	7 152.15 X
1	FENDER PANEL FRT LH	\$	R 783.83
1	WHEELARCH FRT LH	\$	278.84
1	FENDER BRACKET LOWER LH	\$	Sh 15.79
1	FENDER INSULATOR LH	\$	۶ 130.84
1	DOOR PANEL FRT LH	\$	7 2,844.66
1	RADIATOR GRILLE	\$	S- 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	√ 225.36 \
1	RADIATOR GRILLE FRAME	\$	55 1,353.75 X
1	RADIATOR FAN COWLING	\$	Sc 820.54
1	RADIATOR FAN MOTOR LH	\$	Sh 967.36
1	RADIATOR FAN MOTOR RH	\$	£ 1,479.46
1	RADIATOR GRILLE FRAME	\$	Sh 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	615.90
1	FRAME FULL SUPPORT BRACKET	\$	n 89.79
1	AIR CLEANER BOX	\$	Si 464.20
1	AIR CLEANER HOSE	\$	Sh 175.85)

	ab Auto Services Pte Ltd			AAD1901-199	
	Mo Kio Street 63 Singapore 569111				
Tel No. : 6					
	eg. No. 201019626G				
SHD 7400	i				
1	LOWER ARM LH L70Y		\$	° 685.76 ⊀	
1	KUNCKLE ARM LH L70Y		\$	Sm 846.98 X	
1	ABSORBER FRT LH L70Y		\$	∫~ 360.54 X	
		TOTAL	\$	20,784.28	
		10%	\$	2,078.43	
			\$	18,705.85	
	Specical Nett				
1SET	BUMPER CLIP FRT		\$	Nr 66.00	
1	BUMPER BRACKET CLIP FRT LH		\$	12.00	
1	BUMPER SUPPORT CLIP FRT LH		\$	へ 10.50	
1SET	BUMPER GRILLE LOWER CLIP		\$	1n 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP		\$	1n 70.00	
2	FRAME FULL SUPPORT PANEL NUT		\$	~~ 20.00 } X	
2	FRAME FULL SUPPORT PANEL STUD		\$	~~ 30.00 /	
1SET	WHEELARCH CLIP FRT RH		\$	12 30.50	
1	FRONT LEFT TYRE		\$	Sh 300.00	
1	FRONT LEFT TYRE RIM		\$	£ 380.00√	
		a	\$	988.00	
	TOTA	L PARTS	\$	19,693.85	
		:			
	LABOUR				
	Panel beating, knocking and straightenin				
	necessary portion, remove and renewal o	of parts,	101	6	
	adjust and realign the same		\$	3,500.00 4001 3,000.00 449	•
	Putty and spray painting of the affected p	portion.	\$	3,000.00 489	,
	To rust-proofing of the affected areas.		\$	170.00 34	
	To remove and refit interior fittings, trimi	ngs,			
	garnish, fittings and other, to enable repa	air.	\$	~~ 380.00 X	

Trans-cab Auto Services Pte Ltd

AAD1901-199

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 740G

PART-BY-PART (REPAIR DAY)	2days
Over All Total	\$ 28,783.85
TOTAL	\$ 9,090.00
To transfer of front door fittings, attachment and perform water seepage test.	\$ 280.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$ nn 170.00 X
To replace, refix and top up coolant for radiator	\$ 170.00 X
To vacuum, replace, refix and recharge air condenser	\$ n ≈ 380.00 ×
To transfer of front fender fittings, attachment and perform water seepage test.	\$ ~ 380.00 X
To Check Electrical Lighting Concerned.	\$ 170.00 2
To transfer of tire, rim and on wheel balancing.	\$ 170.00 X
To check steering geometry and computer wheel alignment	\$ Nn 220.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- » Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	tionale Des Experts En Automol	bile
UNIT	TED OVERSEAS II	NSURANCE LTD	Ref : CS/UOI19001448	NKtd3e2
	ISON ROAD #28-0 INGLEAF TOWER	SINGAPORE 079909	Date: 09-05-2019 Code: UOI2	
1.		Policy Particular	rs :- THIRD PARTY CLAIM	
	Insured Veh.	SLG 4462U	Veh. Inspected	SHD 740G
	Policy No.	DHOM120036071800	Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From	FELIS	Assign Date	22/01/2019
2.		Vehicle Par	rticulars & Condition	
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	VF1ABL15AUC283353	Colour	METALLIC WHITE / RED
	Odometer	182437	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cond	litions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	GITI	8 mm
	L/H Front Tyre	215/60 R16	GITI	8 mm
	R/H Rear Tyre	215/60 R16	GITI	7 mm
	L/H Rear Tyre	215/60 R16	GITI	7 mm
4.	DESCRIPTION A		otion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE I	N/S FRONT PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gene	eral Information	
	Accident Date	20/01/2019	Inspection Date	22/01/2019
	Survey held at	TRANS-CAB AUTO SERVICE	ES PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.			Remarks	
	A)THE INSPECTION B)IN ACCORDANGE	ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS	, WE HAVE NOT AUTHORISE	S. ED REPAIRS.
5b.			ite Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 740G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	BUCKLED / CUT	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	
1	BUMPER RETAINER FRT LH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP LH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	
1	FENDER PANEL FRT LH	BENT	783.83	783.83
1	WHEELARCH FRT LH	SERVICEABLE	278.84	
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	
1	FENDER INSULATOR LH	SERVICEABLE	130.84	3
1	DOOR PANEL FRT LH	TO REPAIR SEE LABOUR	2,844.66	
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	9
1	AIR CLEANER BOX	SERVICEABLE	464.20	
1	AIR CLEANER HOSE	SERVICEABLE	175.85	
1	LOWER ARM LH L70Y	SERVICEABLE	685.76	
1	KUNCKLE ARM LH L70Y	SERVICEABLE	846.98	

Report Ref No. CS/UOI19001448/Ktd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ABSORBER FRT LH L70Y	SERVICEABLE	360.54	-
	LESS 10% DISCOUNT		-2,078.43	-337.91
			18,705.84	3,041.18
	SPECIAL NETT ITEMS			
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	.=
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	9-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	:=
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	300.00	7-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	74
	# S		988.00	66.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, HEADLAMP PANEL FRT LH, DOOR PANEL FRT LH AND FRAME FULL SUPPORT BRACKET.		3,500.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-

Report Ref No. CS/UOI19001448/Ktd3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			9,090.00	890.00
	GRAND TOTAL		28,783.84	3,997.18

RECOMMENDED COST OF REPAIRS	3,997.18
-----------------------------	----------

Report Ref No. CS/UOI19001448/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.