



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YEO BOON TEE 4 EASTWOOD DRIVE SINGAPORE 486373 Contact No Mobile: 90188556	Cust No/Name	LCV05460/YEO BOON TEE
	Reg No/Reg Date	SGH9339P / 04/05/201
	Date In/Mileage	/ 0
	Chassis No	KNAPH81BMJ5448737
	Engine No	D4HBH364714
	Make/Model	KIA/SORENTO 2.2 A SX SR GDCO
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	22/01/2019/ 08:56	QUE	261 / Edwin Caina	43081		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							550 1900.00
RENEW & RE-ALIGN RR DAMAGED PORTION:							
-RENEW RR BUMPER							
-REPAIR RR END PNL & RR FENDER RH							420 1260.00
E PNT98000							
RESPRAY RR BUMPER , RR END PNL & RR FENDER RH							20 50.00
A 54900099							✓ 200.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							X 80.00
M SUNDRY							
APPLY ANTI CORROSION ON AFFECTED AREAS							60 80.00
E PNT88000							
REMOVE & REFIT REVERSE SENSOR							20 30.00
M SUNDRY							
Sundries							
M COVER-RR BUMPER,UPR				1.00	605.00	00.00	✓ 605.00
M COVER-RR BUMPER LWR				1.00	565.00	00.00	✓ 565.00
M SKID PLATE-RR BUMPER				1.00	90.00	00.00	✓ 90.00
M COVER-BLANKING RR FOG,RH				1.00	44.00	00.00	X 44.00
M BRACKET-RR BPR SIDE REINF,RH				1.00	5.00	00.00	? 5.00
M LAMP ASSY-REAR FOG & R/REFL,RH				1.00	129.00	00.00	X 129.00
M BRACKET-RR BUMPER SIDE LWR,RH				1.00	13.00	00.00	? 13.00
M BRACKET ASSY-RR BUMPER SIDE,RH				1.00	25.00	00.00	? 25.00
M ULTRASONIC SENSOR-S.P.A.S				4.00	187.00	00.00	? 748.00
M RAIL ASSY-REAR BUMPER				1.00	341.00	00.00	? 341.00
M COVER ASSY-RR BPR UNDER				1.00	30.00	00.00	? 30.00

SURVEYOR NAME: Tanpin 97495749SURVEYOR SIGNATURE: [Signature]DATE: 5/3/18 C SW

Confirm & accepted by

REMARKS: Resurvey new parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory and company stamp

7% GST on **Nett 6,195.00** **8,195.00**

Total Payable 6,628.65

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repair or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. Now must be required to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.