

Surveyor:

DOI:

Date:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 24/11/19

Sent By: 03

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: \$/P SS 4,085.19 (3 days) Reduction: 83 %

Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 07/11/19 Confirm with: WAT YIN

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 15

If NO or B 28, Ass. Lia:

Repair Cost: (W/GT) SS 4,371.15

OID changing lane

Loss of Rental (LOR): SS 175.83 (4.5 days) x 105.74

Loss of Use (LOU): SS - (\$ x days)

Loss of Income (LOI): SS 225.00 \$ 50 x 4.5 days

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search SS 7.49

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS 5,079.47 Global Sum SS: 5,070.00

Email ☐ Call ☐

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: SS 5,070.00

Name 1:

TRANS-ATB AUTO SERVICES PTB LTD

Payee 2: (Strike if N.A.) SS -

Name 2:

Payee 3: (Strike if N.A.) SS -

Name 3:

ASS. REC. BY:

REF:

LPC /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140 1000C

Yr Regn:

07.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

120917

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

V151 AB215AUC 283374

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

17/1/19

D.O.I.

21/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/1

File pass to Car

B 4085-19

CRAB: 20,043.09 (83%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + R.S. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 1000C**AAD1901-165***Not Authored**Refusing B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 1000C

VF1ABL15AUC283374

RENAULT

LATITUDE

17.1.2019

LONPAC

31/7/2017

*84085.19***PART****LIST**

1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	DOOR PANEL FRT RH
1	DOOR HINGE UPPER RH
1	DOOR HINGE LOWER RH
1	DOOR CHECK FRT RH
1	DOOR LOCK FRT RH
1	DOOR CATCH FRT RH
1	DOOR HANDLE OUTER FRT RH
1	DOOR HANDLE COVER FRT RH
1	DOOR HANDLE MODULE FRT RH
1	DOOR REGULATOR FRT RH
1	DOOR REGULATOR MOTOR FRT RH
1	DOOR REGULATOR GUIDE FRT RH
1	DOOR PANEL REAR RH
1	DOOR MIRROR ASSY RH

\$	<i>Sm</i> 1,184.43	}	<i>X</i>
\$	<i>N</i> 152.15		
\$	<i>N</i> 783.83		
\$	<i>Sm</i> 278.84		
\$	<i>Sm</i> 15.79		
\$	<i>Sm</i> 130.84	}	
\$	<i>Net/way</i> 2,844.66		
\$	<i>N</i> 261.28	}	<i>X</i>
\$	<i>N</i> 300.55		
\$	<i>Sm</i> 194.77		
\$	<i>N</i> 908.75		
\$	<i>Sm</i> 131.23		
\$	<i>Sm</i> 477.76		
\$	<i>Sm</i> 13.22		
\$	<i>Sm</i> 133.60		
\$	<i>N</i> 505.19		
\$	<i>N</i> 796.46		
\$	<i>Sm</i> 120.97	}	
\$	<i>N</i> 2,844.66		
\$	<i>Sm</i> 1,483.40	}	

\$ 13,562.3910% **\$ 1,356.24****\$ 12,206.15**

Trans-cab Auto Services Pte Ltd

AAD1901-165

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 1000C

Special Nett

1SET	WHEELARCH CLIP FRT RH	\$	nn 30.50 X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn 80.00 605n
1	FRONT DOOR STICKER 'Chassis'	\$	nn 300.00 155n
1	REAR DOOR STICKER '6555-3333'	\$	nn 80.00 605n
1	DOOR CHECK BOLT	\$	nn 22.69
1	DOOR GUIDE SCREW	\$	nn 10.85
1	DOOR HINGE BOLT	\$	nn 10.85
1	DOOR HINGE NUT RH	\$	nn 14.60
1	DOOR CHECK BOLT	\$	nn 22.69
1	DOOR CHECK NUT	\$	nn 3.75
1	DOOR LOCK SCREW L70Y	\$	nn 6.12
1	DOOR CATCH SCREW L70Y	\$	nn 10.06

TOTAL	\$	592.18
--------------	-----------	---------------

TOTAL PARTS	\$	12,798.28
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 4001
Putty and spray painting of the affected portion.	\$	4,200.00 8801
To rust-proofing of the affected areas.	\$	170.00 301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201

Trans-cab Auto Services Pte Ltd**AAD1901-165**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 1000C

To transfer of front fender fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 X

To transfer of front door fittings, attachment and
perform water seepage test.

\$ 380.00 *bol*

To transfer of Rear door fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 X

To transfer of Rear fender fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 X**TOTAL \$ 11,330.00****Over All Total \$ 24,128.28****PART-BY-PART (REPAIR DAY)***15 DAYS**3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/LPC19001453/Kfa3

Date: 24/01/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 1000C


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21/01/2019 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	24,128.28
Revised Estimate Amount	: S\$	4,085.19
"Check" Items Amount	: S\$	
Total (Including Check Items)	: S\$	4,085.19
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
O/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD1000C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	18 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003385
Chassis No.:	VF1ABL15AUC283374
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Jul 2017
First Registration Date:	31 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2025
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	30 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
Total Rebate Amount:	\$45,846.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 18 Jan 2019

OK

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Thursday, 24 January, 2019 2:16 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving SJH3416D (OI : LPC - TBA) and SHD1000C (TP : LKK REF - CC3/LPC19001453/Kfa3) on 17/01/2019
Attachments: 24012019141209.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK


Our Ref : 18/19/19/VP05/021337

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

The premium for the policy has been settled.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 24 January, 2019 1:36 PM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ONG LI LI; CS A Team; Admin A; Poh Kin (LKKAUTO)
Subject: Direct Settlement - Accident Involving SJH3416D (OI : LPC - TBA) and SHD1000C (TP : LKK REF - CC3/LPC19001453/Kfa3) on 17/01/2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHD 1000C at M/s Trans-cab Auto Services Pte Ltd (Ang Mo Kio).

Kindly verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Enclosed for your perusal is:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC3/LPC19001453/Kha3s2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-11-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 3416D	Veh. Inspected	SHD 1000C	
Policy No.	Z18VP05019451	Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/021337	Excess (\$)	0.00	
Assign From		Assign Date	21/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283374	Colour	METALLIC WHITE / RED	
Odometer	120917	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	7 mm	
L/H Front Tyre	215/60 R16	GITI	7 mm	
R/H Rear Tyre	215/60 R16	GITI	7 mm	
L/H Rear Tyre	215/60 R16	GITI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/01/2019	Inspection Date	21/01/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 1000C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	DOOR PANEL FRT RH	DENTED / WARPED	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	SERVICEABLE	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	TO REPAIR SEE LABOUR	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
	LESS 10% DISCOUNT		-1,356.23	-284.47
			12,206.15	2,560.19
SPECIAL NETT ITEMS				
1	SET WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00

Report Ref No. CC3/LPC19001453/Kha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR STICKER 'CHASSIS' (SN)	NECESSARY	300.00	15.00
1	REAR DOOR STICKER '6555-3333' (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			592.11	135.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL FRT RH, FENDER PANEL FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK FRT RH, DOOR REGULATOR FRT RH, DOOR REGULATOR MOTOR FRT RH AND DOOR PANEL REAR RH.		4,500.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	880.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			11,330.00	1,390.00
GRAND TOTAL			24,128.26	4,085.19
RECOMMENDED COST OF REPAIRS				4,085.19

Report Ref No. CC3/LPC19001453/Kha3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.