

INS. CASE OWNER:

CC 4 / LPC1900

4455 12/16/2012

LKK: IDAC:

Surveyor: Tan Tech

DOI: ASSIGNMENT 21/1/19

Date / Time: 21/1/19

Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No.:

8KC 8176C

Claim No.:

18/17/19/05/01337

Name of Insured:

ONG KOK LAM COMPANY

Policy No.:

317005015441

Insured Tel No.:

HP:

Make / Model:

CHEVROLET

Excess Sec II :SS

D.O.A.:

21/1/19

Place of Accident:

WOLSKEL RD

Is driver the owner? (YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

GBB 817A



INSRS: WSP: Tel: Liability: RMKS:

Sin Sheng



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: \$S (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: 19/9/19 Confirm with: Yes Sin Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL If NO or B 28, Ass. Lia:

Repair Cost: (w/hst) \$S 1230.50 OL HIT PARKED VEH

Loss of Rental (LOR): \$S - (days)

Loss of Use (LOU): \$S 500.00 (\$ 100 x 5 days)

Loss of Income (LOI): \$S - (\$ x days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search \$S 2.00

Medical: \$S -

Disbursement: \$S - (e.g. Tow/ Independent)

Legal Cost \$S -

Total: \$S 1732.50 Global Sum \$S:

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$S 1732.50 Name 1: Sin Sheng Engineering Services

Payee 2: (Strike if N.A.) \$S Name 2:

Payee 3: (Strike if N.A.) \$S Name 3:

21/9/19

1) Claim status: TP
2) Report Format: TP
3) Survey fee: \$450

Taylor

REF: JPC

ASSIGNMENT

From: 31/01/19
 Estimated Cost:
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: GBB 8317A
 at Workshop no/s: Sin Sheng Engineering
3 Tech park Crescent
 of:
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

Veh No: GBB 8317A Yr Rego: 2010 May
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Make. C.C. 2982
 Colour: Orange A/C: Insured / Std / NI / NA
 Sp. Reading: 228802 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: JTFHT02P500057161
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/165
 R:

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value:
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (up)
 Date: Person Contacted: Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli
 Front Rear
 R/Bal. 0 mm R/Bal. 6 mm
 L/Bal. 0 mm L/Bal. mm
 D.O.A. D.O.I. 3/1/19 @ Sin Sheng
 Survey held at Sin Sheng
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear O/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
4/3 - \$1150 (Red \$ 805.87 / 41%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?
 Days Of Repair:
 Resurvey No. of Trip:
 Add Fee: Site Insp. (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)
 Survey Fee:
 Transportation
) \$ + PS \$
) Photo
) Copy
)
 TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19001455/T1hb3

Date: 01.02.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GBB8317A


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31.01.2019 at the premises of M/s Sin Sheng Engineering Services and have the following to report:-

Workshop Estimate Amount	: S\$	<u>1,955.87</u>
Revised Estimate Amount	: S\$	<u>1,264.35</u>
"Check" Items Amount	: S\$	<u>180.00</u>
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

SIN SHENG ENGINEERING SERVICES

3-TECH PARK CRESCENT
SINGAPORE 638129
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

Estimate : ES002732

Date : 30/01/2019
Vehicle Num. : GBB8317A
Make/Model : TOYOTA KDH 200-2010
Chassis/Eng# : JTFHT02P500057161/1KD2001695
Accident Date : 21/01/2019
Claim No. :
Reference : SKC8176C
Policy No. : 29090793

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	2	REAR BUMPER		377.40 <i>de</i>
3.	1	BUMPER SIDE BRACKET	123.50 <i>de</i>	247.00 <i>RH - de</i>
4.	1	REAR LAMP, RHS		354.90 <i>CR</i>
5.	1	REAR LAMP GARNISH		165.20 <i>RX</i>
5.	6	BUMPER CLIP	5.00	30.00 <i>all</i>
		List Total S\$:	285.80	1,174.50
		25.00% Discount S\$:		293.63
			64.55	880.87
1.	1	NETT ITEMS :		200 <i>3 net</i>
		REVERSE SENSOR		250.00
		Nett Total S\$:		250.00
		10.00% Discount S\$:	150	25.00
				225.00
		LABOUR :		300
		TO PANEL BEAT/REPAIR REAR BODY		450.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT
 SINGAPORE 638129
 Tel No. : 6863-9595 Fax No. : 6863-6477
 E-Mail : sinsheng1981@gmail.com
 Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
 59 SENOKO ROAD
 SINGAPORE 758123

Attention : Motor Claim Department
 Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002732

Date : 30/01/2019
 Vehicle Num. : CBB8317A
 Make/Model : TOYOTA KDH 200-2010
 Chassis/Eng# : JTFHT02P500057161/1KD2001695
 Accident Date : 21/01/2019
 Claim No. :
 Reference : SKC8176C
 Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount SS
		SPRAY PAINTING		400.00 ^{3.00}
		LOSS OF USE : 4 DAYS @ \$ 120/DAY		
		Labour Total SS :	600	850.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tan Jiah 97495749
 WP
 31/1/19 @ 3:50pm
 3 days
 Resurvey after repair
 SUE Uthmanfow

Total SS : 1,955.87
 =====

SIN SHENG ENGINEERING SERVICES

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 22 January 2019 10:39 AM
To: sinsheng_engineeringservices; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Accident Involving GBB8317A with SKC8176C Our Ref: TBA
Attachments: GBB8317A_PRI.PDF; GBB8317A_TP search fee.pdf; SAS GBB8317A.PDF

10:41am @ 22/10/2019
person @ Susan
vNI

Without Prejudice


Dear Susan

Thank you for your confirmation on the appointment of a Single Joint Expert.

Dear Catherine/Nivitha

Please see below and arrange Mr Mohammad Rasul to conduct TP survey.

Dear
Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: sinsheng_engineeringservices [mailto:sinsheng1981@gmail.com]
Sent: Tuesday, 22 January, 2019 10:32 AM
To: ONG LI LI
Cc: MT_Claim_SG
Subject: Re: Accident Involving GBB8317A with SKC8176C Our Ref: TBA

Hi Ms Ong,

We are selected Mr Mohammad Rasul

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Tue, 22 Jan 2019 at 10:31, ONG LI LI <llong@lonpac.com> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

Our Insured has not reported the accident.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	<input type="checkbox"/>
2	Xing Guo Qiang	<input type="checkbox"/>
3	Mohamad Taufikh	<input type="checkbox"/>
4	Bryan Ang	<input type="checkbox"/>
5	Adrian Ling	<input type="checkbox"/>
6	Mohammed Rasul	<input type="checkbox"/>
7	Marcus Chua	<input type="checkbox"/>
8	Kenneth Kong	<input type="checkbox"/>
9	Muhammad Nazril Bin Abdullah	<input type="checkbox"/>
10	Sathya Sai Kathirrasen	<input type="checkbox"/>

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: sinsheng engineeringservices [mailto:sinsheng1981@gmail.com]

Sent: Tuesday, 22 January, 2019 10:20 AM

To: MT_Claim_SG

Subject: Accident Involving GBB8317A with SKC8176C

Dear Officer Incharge,

We are repairer of motor vehicle GBB8317A . Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 nominated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

Thank You
Regards

Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477

Shu Pei (LKKAuto)


From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 29 January 2019 9:54 AM
To: Shu Pei (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Accident Involving GBB8317A with SKC8176C Our Ref: TBA
Attachments: 29012019095041.pdf

Our Ref : 18/19/19/VP05/021357

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 29 January, 2019 9:29 AM
To: ONG LI LI
Cc: MT_Claim_SG; Admin A; Vic (LKKAuto)
Subject: RE: Accident Involving GBB8317A with SKC8176C Our Ref: TBA

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 22 January 2019 4:39 PM
To: 'ONG LI LI' <long@lonpac.com>; Admin A <admin-a@lkkauto.com>
Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>
Subject: RE: Accident Involving GBB8317A with SKC8176C Our Ref: TBA

Dear Li Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:long@lonpac.com>]
Sent: Tuesday, 22 January, 2019 10:39 AM
To: sinsheng engineerservices <sinsheng1981@gmail.com>; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Accident Involving GBB8317A with SKC8176C Our Ref: TBA

Without Prejudice

Dear Susan

Thank you for your confirmation on the appointment of a Single Joint Expert.

Dear Catherine/Nivitha

Please see below and arrange Mr Mohammad Rasul to conduct TP survey.

Dear


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: sinsheng engineerservices [<mailto:sinsheng1981@gmail.com>]
Sent: Tuesday, 22 January, 2019 10:32 AM
To: ONG LI LI
Cc: MT_Claim_SG
Subject: Re: Accident Involving GBB8317A with SKC8176C Our Ref: TBA

Hi Ms Ong,

We are selected Mr Mohammad Rasul

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129
Tel: 6863 9595
Fax: 6863 6477*

On Tue, 22 Jan 2019 at 10:31, ONG LI LI <long@lonpac.com> wrote:

Without Prejudice

Save as to Costs

Dear Sir/Mdm

Our Insured has not reported the accident.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick <input type="checkbox"/>
1	Kalvin Ang	<input type="checkbox"/>
2	Xing Guo Qiang	<input type="checkbox"/>
3	Mohamad Taufikh	<input type="checkbox"/>
4	Bryan Ang	<input type="checkbox"/>

5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



From: sinsheng engineerservices [mailto:sinsheng1981@gmail.com]

Sent: Tuesday, 22 January, 2019 10:20 AM

To: MT_Claim_SG

Subject: Accident Involving GBB8317A with SKC8176C

Dear Officer Incharge,

We are repairer of motor vehicle GBB8317A . Enclosed Accident Statement and LTA search fee for your attention please. Kindly assist to arrange for the Pre-Repair Inspection to be conducted within two (2) workings days upon received this email.

Kindly let us have your list of 10 norminated surveyors to conduct the Single-Joint Inspection.

Kindly assist to revert the liability issue or offer if direct settlement is in order

Thank You

Regards

Susan

Sin Sheng Engineering Services

3 Tech Park Crescent

Tuas Tech Park

Singapore 638129

Tel: 6863 9595

Fax: 6863 6477

Your Insured's vehicle : SKC8176C

Our customer's vehicle : **GBB8317A**

Date : 22/01/2019

LONPAC INSURANCE BHD

Dear Sirs,

DATE OF ACCIDENT : 21 JAN 2019 NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION

We have been appointed by Goldbell Leasing Pte Ltd repair their vehicle no. GBB8317A
Please be informed that the said vehicle can be inspected at :

Workshop : Sin Sheng Engineering Services
Address : 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129
Contact : Ms Susan / Ms Cheryl Yuan
Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below, Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passanger from claiming injury-related damage arising from this accident.

Your sincerely,

Susan

Acknowledgement

This is to confirm that I <i>Tajudin</i> [Full Name of Surveyor]	
of <i>LKK</i> [Surveyor's Company]	
have completed the pre-repair inspection on <i>23/1/19</i> [Date if Inspection]	
at <i>3.15pm</i> [Time of Inspection]	
<i>[Signature]</i>	<i>Susan</i>
Signature of Appointed Surveyor	Witnessed By:
Company Stamp	Date

Waiver

We waive our rights to an inspection/survey of the above vehicle.	
Signature _____	
Name :	
Date :	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19001455/T1db3n2	
300 BEACH ROAD		Date : 04-10-2019	
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKC 8176C	Veh. Inspected	GBB 8317A
Policy No.	Z17VP05015441	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021357	Excess (\$)	0.00
Assign From	GERALD	Assign Date	22/01/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JTFHT02P500057161	Colour	ORANGE
Odometer	228806	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	ROADSTONE	6 mm
L/H Front Tyre	195 R15	ROADSTONE	6 mm
R/H Rear Tyre	195 R15	ROADSTONE	6 mm
L/H Rear Tyre	195 R15	ROADSTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/01/2019	Inspection Date	31/01/2019
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 8317A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	377.40	377.40
2	BUMPER SIDE BRACKET @\$123.50	O/S DEFORMED	247.00	123.50
1	REAR LAMP,RHS	CRACKED	354.90	354.90
1	REAR LAMP GARNISH	TO REPAIR SEE LABOUR	165.20	-
6	BUMPER CLIP @\$5.00	NECESSARY	30.00	30.00
	LESS 25% DISCOUNT		-293.63	-221.45
			880.87	664.35
NETT ITEMS				
1	REVERSE SENSOR (N)	NECESSARY	250.00	200.00
	LESS 10% DISCOUNT		-25.00	-20.00
			225.00	180.00
LABOUR				
	TO PANEL BEAT/REPAIR REAR BODY.TO DISMANTLE /REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF REAR LAMP GARNISH .		450.00	300.00
	SPRAY PAINTING.		400.00	300.00
			850.00	600.00
GRAND TOTAL			1,955.87	1,444.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,150.00

Report Ref No. CC4/LPC19001455/T1db3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.