

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 24 Jan 2019

Preliminary Advice

Insured Vehicle No	: SKW8113D	Accident Date	: 18/01/2019
TP Vehicle No	: SKX9825X	Assignment Date	: 22/01/2019
Make	: TOYOTA VIOS	Est. Duration of Repair	: 7
Date of Inspection	: 23/01/2019		
Inspection At	: GUAN MOTOR WORKS (HQ) 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	8,184.35
Revised Amount	:S\$	4,521.71
Check Items (Estimated)	:S\$	1,073.15
Total	:S\$	5,594.86

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.