

ASS. REC. BY:

REF

es/MSG19001462/Uqd3n2

Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

M816

Date/Time:

22/1/19 @ 4:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Sjx 1644R

Insured:

SLT 5723S

at Workshop m/s

Jin Auto Services

Tel:

6289 8126

of

Blk 14, Defu Lane 10 # 01-410 / 412

Policy No:

A29043463QMY

Claim No:

582859

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/01/2019

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

4:58pm 22/1/19

Person Contacted:

Jenis

Vehicle IN/OUT

Date/Time

Action/Instruction ( ) Estimate

Sjx 1644R - NA/AG19001258/13

DOA: 19/01/2019

SLT 5723S - NA/MSG19001384/24

DOA: 19/01/2019

23/1/19 @ 9:20pm Informed Katherine Wong, we are pending estimate from repairer.  
 21/1/19 @ 1:52pm Revised to Katherine Wong via messenger.

(08/11/13) wef  
ASS. REC. BY: Morcos

REF: MS14/

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To inspect Vehicle No: 53X1644R  
at Workshop/mile Jan Ave  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.  
Bal. or Market Value: 29k  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 12 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: 53X1644R Yr Regn: 51 10  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: Toyota comry C.C. 1998  
Colour: Grey W/O: Insured / Std / NI / NA  
Sp. Reading: 124332 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: MR053BK 410 7056401  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or  
Brake: In order / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: 2.5/60R16  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: 6 mm Rear: 6 mm  
R/Bal: 6 mm L/Bal: 6 mm  
D.O.A. 19/1/19 D.O.I. 24/1/19  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
B. & R.  
The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time    | Action / Instruction  |
|----------------|---|
|                | <u>CNY 5-2-19 LIA 19530 net 9440</u>                          |
|                | <u>Lab grille 849.42</u>                                      |
|                | <u>Paint 1404.50</u>  |
| <u>21/2/19</u> | <u>4/5 @ 9000 confirmed w. li. Louis. Used @ 8527.45, 49%</u> |

RECEIVED 22 FEB 2019

Date/Time, File Pass to? ☐ : Preli. Report  
1) 21/2/19 TP ☐ : Final Report  
Date/Time, File Return to?

Days Of Repair: 12  
Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

|                 |     |
|-----------------|-----|
| Survey Fee:     |     |
| Transportation: | 200 |
|                 | 10  |
| Photos          |     |
| Others          |     |
| TOTAL           | 210 |

Report Format: WER-TP  
Lump Sum / I.B.I. (\$) 9000

Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 21 Feb 2019

## Preliminary Advice

|                    |  |                         |              |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : SLT5723S   | Accident Date           | : 19/01/2019 |
| TP Vehicle No      | : SJX1644R   | Assignment Date         | : 22/01/2019 |
| Make               | : TOYOTA CAMRY   | Est. Duration of Repair | : 14.00      |
| Date of Inspection | : 22/01/2019   |                         |              |
| Inspection At      | : JIN AUTO SERVICES PTE LTD (DEFU)<br>BLK 14 DEFU LANE 10, #01-410/412<br>SINGAPORE 539195 |                         |              |

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 17,527.45 |
| Revised Amount              | :S\$ | 11,273.45 |
| Check Items (Estimated)     | :S\$ | 0.00      |
| Total                       | :S\$ | 11,273.45 |
| Lump Sum Repair             | :S\$ | 9,000.00  |

### Total Loss Consideration

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified    | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 21 Jan 2019 |               | 22 Jan 2019<br>16:44<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

|                             |   |                        |   |
|-----------------------------|---|------------------------|---|
| Insured:                    | HAO LI, ID: S2677536A   |                        |   |
| Main Claimant:              | LOH HUEY WEN  |                        |   |
| Vehicle Reg. No.:           | SJX1644R  | Date of Loss:          | 19/01/2019 15:00 - :59<br>[103 Months and 30 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 582859   | Policy/Cover Note No.: | A29043463QMY (Comprehensive)<br>Coverage: 01/11/2018 - 31/10/2019             |
| Vehicle Reg. No. (Insured): | SLT5723S  | Policy No. (Claimant): |   |
|                             |   | Excess:                |   |
| Repairer:                   | Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126                  |                        |   |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544] |                        |   |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2019]                                    |                        |   |
| Driver/Custodian (Insured): | WANG RONG SHIRLEY (), NRIC: S9626920Z, Tel: +6596995804   |                        |   |
| Adj Asg. Remarks:           | on WP, TP Pre-Repair Survey, TP selected LKK to be SJE. Liability : 100% Contact : Ms Jouis Seow @ 6289 8126          |                        |   |

### ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

**Shiau Chan (LKKAuto)**

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Wednesday, 23 January 2019 2:20 PM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** VEHICLE SJX 1644R (YOUR REF: 582859)

This mail is associated with :

**\*SJX1644R (582859)**

**[SLT5723S]**

TP

LOH HUEY WEN

Jan 19 2019 3:00PM

[HAO LI]

Jin Auto Services Pte Ltd

Dear Katherine,

Please be informed that we have inspected the vehicle SJX 1644R on 22/01/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

## Das WeltAuto.

Used cars you can trust. Guaranteed.

camry

Price Range

Depreciation

2010

Vehicle Type

Home » Used Cars » Prem Roy Motoring » Toyota Camry 2.0A

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Toyota Camry 2.0A

Overview

Financial

Insurance


Accessories

Similar

Research

Photos

Map



COMPLETE CAR TRADE S

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

|              |  |   |
|--------------|--|---|
| Price        | \$27,800   |   |
| Depreciation | \$10,790 /yr<br>View models with similar depreciation  | ? |
| Reg Date     | 31-May-2010<br>(1yr 4mths 7days COE left)  |   |
| Manufactured | 2010   | ? |
| Mileage      | 150,185 km (17.4k /yr)   |   |
| Transmission | Auto   |   |
| Engine Cap   | 1,998 cc   |   |
| Road Tax     | \$1,210 /yr  | ? |
| Power        | 108.0 kW (144 bhp)<br>View specs of the Toyota Camry (2006-2012)   |   |
| Curb Weight  | 1,530 kg   | ? |
| Features     | 2.0L 4 Cylinders 16 Valves DOHC VVT-i Engine, Automatic Transmission, SRS Airbags, Auto Headlights And Rain Sensors, Traction Control, Cruise Control.   |   |
| Accessories  | Sports Rims, Leather Seats, Tom Tom Audio With Steering Controls/GPS, Reverse Camera And Sensors, Retractable Side Mirrors, Solar Film, Fog Lights.  |   |
| Description  | Father Transferred To Son(So 1 Transfer Added). Sporty Beautiful Grey In Beige Toyota Camry 2.0 Auto. Most Popular Toyota For Your Family And Daily Usage. Fuel Saving Yet Powerful Drive. Accident Free, Loan/Insurance Available. COE Renewal Available. Trade In Welcome. Call Now For A Viewing Appt. 6 Months Old Yokohama Tyres. Front/Rear Surveillance Camera. New Brake Disc Both Front/Back. |   |
| COE          | \$34,600   | ? |



## Seller Information

Company

Prem



» deale

» 143 v

availabl

Address

9 Tagor

Search

Location

9@Tag

Compare

Vehicle Number Plates

**BUY & SELL**

Your AUSPICIOUS & UNIQUE Vehicle No.

Do you know? We are Singapore's **BIGGEST PLAYER** with the most vehicle plate numbers for sale!

Click here to see all Auspicious Numbers!

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

RENEW  
YOUR COE1.99%\*P.A  
ONLY

\*Terms and Conditions apply

MEMBER

camry

Price Range

Depreciation

2010

Vehicle Type

Home » Used Cars » Swee Watt Motor Trading » Toyota Camry 2.0A

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres



## Toyota Camry 2.0A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

**Price** \$25,900**Depreciation** \$12,900 /yr

View models with similar depreciation

**Reg Date** 06-Jan-2010

(11mths 13days COE left)

**Manufactured** 2009**Mileage** 126,994 km (14k /yr)**Transmission** Auto**Engine Cap** 1,998 cc**Road Tax** \$1,210 /yr**Power** 108.0 kW (144 bhp)

View specs of the Toyota Camry (2006-2012)

**Curb Weight** 1,530 kg**Features** SRS Airbags, ABS, Side Mirror Indicator, Multi Function Steering, Electric Seats, Rear Aircon, Walnut Interior.**Accessories** Sports Rims, Leather Seats, DVD Player, Reverse Sensors/Camera, Fog Lamps, 3M Solar Films, LCD Monitor.**Description** (We Assure 100% Genuine Mileage), 6 Months New Road Tax, Excellent Condition, Well Maintained By Owner, Low Depreciation, Option To Renew 10 Years COE At \$57,900. Don't Miss, Call Now.**COE** \$19,003**OMV** \$27,271**ARF** \$27,271**Dereg Value** \$15,442 as of today (change)**No. of Owners** 2**Type of Veh** Luxury Sedan**Category** PARF Car**Availability** Available

## Seller Information

|                          |                          |
|--------------------------|--------------------------|
| <b>Company</b>           | Swee Watt Motor Trading  |
|                          | » dealer                 |
|                          | » 18 years experience    |
| <b>Address</b>           | 61 Ubi Avenue 1, #01-101 |
|                          | Search                   |
| <b>Location</b>          | Automotive               |
| <b>Office No</b>         | 634419                   |
| <b>Contact Person(s)</b> | Ms Ivy, Mr Ang           |

## Useful Services

Afraid of loan  
this car evaluation

Compare



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                           |
|-------------------------------------|---------------------------|
| <b>Vehicle Owner Particulars</b>    |                           |
| Owner ID Type:                      | Singapore NRIC            |
| Owner ID:                           | 4797B                     |
| <b>Vehicle Details</b>              |                           |
| Vehicle No.:                        | SJX1644R                  |
| Vehicle to be Exported:             | No                        |
| Intended Deregistration Date:       | 23 Jan 2019               |
| Vehicle Make:                       | TOYOTA                    |
| Vehicle Model:                      | CAMRY 2.0 AUTO ABS AIRBAG |
| Primary Colour:                     | Grey                      |
| Manufacturing Year:                 | 2010                      |
| Engine No.:                         | 1AZE167712                |
| Chassis No.:                        | MR053BK4107056401         |
| Maximum Power Output:               | 108.0 kW (144 bhp)        |
| Open Market Value:                  | \$26,443.00               |
| Original Registration Date:         | 20 May 2010               |
| First Registration Date:            | 20 May 2010               |
| Transfer Count:                     | 1                         |
| Actual ARF Paid:                    | \$26,443.00 1324          |
| <b>Intended PARF Rebate Details</b> |                           |
| PARF Eligibility:                   | Yes                       |
| PARF Eligibility Expiry Date:       | 19 May 2020               |
| PARF Rebate Amount:                 | \$14,543.00               |
| <b>Intended COE Rebate Details</b>  |                           |
| COE Expiry Date:                    | 19 May 2020               |
| COE Category:                       | E - Open Category         |
| COE Period(Years):                  | 10                        |
| QP Paid:                            | \$39,002.00               |
| COE Rebate Amount:                  | \$5,017.00                |
| <b>Total Rebate Amount:</b>         | <b>\$19,560.00</b>        |

The information contained herein is correct as at 23 Jan 2019

OK



> Back to OneMotoring

## Enquire Transfer Fee

### Vehicle Details

|                               |                           |
|-------------------------------|---------------------------|
| Vehicle No.:                  | SJX1644R                  |
| Vehicle Type:                 | P10 - Passenger Motor Car |
| Vehicle Attachment 1:         | No Attachment             |
| Vehicle Scheme:               | Normal                    |
| Vehicle Make:                 | TOYOTA                    |
| Vehicle Model:                | CAMRY 2.0 AUTO ABS AIRBAG |
| Chassis No.:                  | MR053BK4107056401         |
| Propellant:                   | Petrol                    |
| Engine No.:                   | 1AZE167712                |
| Engine Capacity:              | 1998 cc                   |
| Maximum Power Output:         | 108.0 kW ( 144 bhp )      |
| Maximum Laden Weight:         | 1970 kg                   |
| Unladen Weight:               | 1530 kg                   |
| Year Of Manufacture:          | 2010                      |
| Original Registration Date:   | 20 May 2010               |
| Lifespan Expiry Date:         | -                         |
| COE Category:                 | E - Open Category         |
| Quota Premium:                | \$39,002.00               |
| COE Expiry Date:              | 19 May 2020               |
| Road Tax Expiry Date:         | 19 May 2019               |
| PARF Eligibility Expiry Date: | 19 May 2020               |
| Inspection Due Date:          | 19 May 2019               |
| Intended Transfer Date:       | 24 Jan 2019               |
| CO2 Emission:                 | -                         |
| CO Emission:                  | -                         |
| HC Emission:                  | -                         |
| NOx Emission:                 | -                         |
| PM Emission:                  | -                         |

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable

|                              | Amount Before GST<br>(S\$) | GST Amount<br>(S\$) | Amount After GST<br>(S\$) |
|------------------------------|----------------------------|---------------------|---------------------------|
| Transfer Fee:                | 25.00                      | -                   | 25.00                     |
| <b>Total Amount Payable:</b> |                            |                     | <b>25.00</b>              |

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                    |
|----------------------------|--------------------|
| Date Of Report             | 21/01/2019 09:36   |
| Date Of Accident           | 19/01/2019 15:40   |
| Exact Location Of Accident | PIE TOWARDS CHANGI |
| Country/State of Loss      | SINGAPORE          |

### DETAILS OF OWN VEHICLE

|                             |                       |
|-----------------------------|-----------------------|
| Vehicle Registration Number | SJX1644R              |
| <b>Insured/Policyholder</b> |                       |
| Name Of Registered Owner    | LOH HUEY WEN          |
| NRIC No                     | S1724797B             |
| Email Address               | LOH.JESSLE9@GMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-93254969  |
| Alternative Phone No        | OFFICE-93254969       |

### Vehicle Particulars

|  |               |
|--|---------------|
| Manufacturer   | TOYOTA        |
| Model  | CAMRY-2.0 (A) |
| Exact Purpose for which vehicle was being used at time of accident           | PTE USE       |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO            |
| If No, Please state action to be taken                                       | THIRD PARTY   |
| Vehicle Category   | PRIVATE CAR   |

### Insurance Company

|                           |   |
|---------------------------|---|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                                 |
| Fleet Policy              | NO  |
| Policy Number             | DMPCSN3077821700                              |
| Cover Note Number         |   |

### Driver

|                      |                         |
|----------------------|-------------------------|
| Name of Driver       | CHAN WAE TING           |
| NRIC No              | S9144314G               |
| Date Of Birth        | 28/11/1991              |
| Occupation           | INDOOR                  |
| Date Of Driving Pass | 22/01/2013              |
| Driving Experience   | 5 YEARS AND 11 MONTHS   |
| Gender               | FEMALE                  |
| Mobile Number        | (LOCAL) +65-83822811    |
| Fax Number           |                         |
| Contact Number       |                         |
| Email Address        | JACELYNCHAN28@GMAIL.COM |

### SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.

NRUC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN

|  |                 |
|--|-----------------|
|  | D O A = 19-1-19 |
|  | A = SJX 1644R   |
|  | B = SLT 5723S   |
|  | C = SLH 2134A   |
|  | D = SMF 4516S   |

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along PIE heading towards Changi, when the front vehicle jam brake, I also followed suit and managed to stop in time, then I felt an impact collided into the rear portion of my vehicle and the great impact pushed my vehicle forward to hit into the rear portion of SLH 2134A. Upon checking, I realized that SLT 5723S had collided into my rear portion and SMF 4516S was also involved in the accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time: 19/1/19 1745h

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 19/1/19 1745h

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

FORM 201 (2018/2019) - 1/2

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Your ref :

Date:

21/1/2019

M/S MSIG INSURANCE (SINGAPORE) PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SJX1644R

DATE OF ACCIDENT :19/01/2019

TO SUPPLY :

## LIST ITEMS

|    |      |                                      |
|----|------|--------------------------------------|
| 1  | 1 PC | FRONT BUMPER                         |
| 2  | 1 PC | FRONT BUMPER CLIPS                   |
| 3  | 2PCS | FRONT BUMPER SIDE RETAINER           |
| 4  | 1 PC | TOW COVER                            |
| 5  | 1 PC | FRONT BUMPER PLATE GARNISH           |
| 6  | 1 PC | FRONT BUMPER SPONGE                  |
| 7  | 1 PC | FRONT BUMPER REINFORCEMENT           |
| 8  | 1 PC | FRONT GRILLE                         |
| 9  | 1 PC | BONNET                               |
| 10 | 1 PC | REAR WINDSCREEN MOULDING             |
| 11 | 1 PC | BOOTLID                              |
| 12 | 2PCS | BOOTLID HINGE                        |
| 13 | 1 PC | BOOTLID INNER INSULATOR              |
| 14 | 1 PC | REAR BOOT UPPER LOCK                 |
| 15 | 1 PC | REAR BOOT LOWER CATCH                |
| 16 | 1 PC | REAR BOOT WEATHERSTRIP               |
| 17 | 1 PC | REAR BOOT BADGE                      |
| 18 | 1 PC | REAR BOOT CAMRY EMBLEM               |
| 19 | 1 PC | REAR BOOT 2.0 EMBLEM                 |
| 20 | 2PCS | REAR BOOT REFLECTOR 380-70 n/s n     |
| 21 | 1 PC | REAR BOOT INNER PLATE GARNISH        |
| 22 | 1 PC | REAR BOOT INNER PLATE GARNISH CHROME |
| 23 | 2PCS | REAR LAMP                            |
| 24 | 2PCS | REAR FENDER                          |
| 25 | 1 PC | REAR BUMPER                          |

|        |    |          |      |
|--------|----|----------|------|
| 20/De  | \$ | 491.60   | ✓    |
| ru     | \$ | 38.00    | ✓    |
| Boat   | \$ | 146.40   | ✓    |
| Tow    | \$ | 21.40    | ✓    |
| 11     | \$ | 93.50    | ✓    |
| Tan    | \$ | 91.20    | ✓    |
| n      | \$ | 421.70   | X    |
| one    | \$ | 491.60   | ✓    |
| 20/Buc | \$ | 1,190.30 | ✓    |
| 11     | \$ | 88.20    | ✓    |
| Buc    | \$ | 863.70   | ✓    |
| n      | \$ | 271.60   | ✓    |
| De/Tan | \$ | 473.60   | ✓    |
| Boat   | \$ | 360.40   | ✓    |
| 11     | \$ | 29.10    | X    |
| 11     | \$ | 204.60   | ✓    |
| ru     | \$ | 66.70    | ✓    |
| nac    | \$ | 49.90    | ✓    |
| ru     | \$ | 43.30    | ✓    |
| 20/De  | \$ | 761.40   | 1 pc |
| Boat   | \$ | 363.10   | ✓    |
| 11     | \$ | 78.00    | X    |
| one    | \$ | 832.40   | ✓    |
| n      | \$ | 1,822.80 | X    |
| Dis    | \$ | 530.50   | ✓    |

not Allowed  
n/s  
n/s 9000/-  
22/1/19  
the phd. After again  
12 day



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19001462/UQD3N2

Date: 22/02/2019

## REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:           | A29043463QMY |
| Claimant Vehicle No : | SJX1644R                             | Insured Vehicle No : | SLT5723S     |
| Date of Loss:         | 19/01/2019                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 582859       |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SJX1644R                     | Engine No:  | 1AZE167712        |
| Make & Model:               | TOYOTA CAMRY, 2.0 (A)        | Chassis No: | MR053BK4107056401 |
| Reg. Date:                  | 20/05/2010 (Man. Year: 2010) | Odometer:   | 124332 km         |
| Colour:                     | Grey                         |             |                   |
| Engine Capacity:            | 1998 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

## CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 215/60 R16    | Rear Tyre Size:  | 215/60 R16    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

|  | Repairer's       | Adjuster's       | Difference      | Diff %       |
|--|------------------|------------------|-----------------|--------------|
| Parts                                    | 11,392.45        | 7,093.45         | 4,299.00        | 37.74        |
| Miscellaneous Items                      | 0.00             | 0.00             | 0.00            |              |
| Labour                                   | 6,135.00         | 4,180.00         | 1,955.00        | 31.87        |
| Paintwork Labour                         | 0.00             | 0.00             | 0.00            |              |
| Towing                                   | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>17,527.45</b> | <b>11,273.45</b> | <b>6,254.00</b> | <b>35.68</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>9,000.00</b>  |                 |              |
| <b>(S\$)</b>                             | <b>17,527.45</b> | <b>9,000.00</b>  | <b>8,527.45</b> | <b>48.65</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>1,226.92</b>  | <b>630.00</b>    | <b>596.92</b>   | <b>48.65</b> |
| <b>Nett Amount (S\$)</b>                 | <b>18,754.37</b> | <b>9,630.00</b>  | <b>9,124.37</b> | <b>48.65</b> |

## INSPECTION

|                             |            |  |
|-----------------------------|------------|--|
| Date of Assignment:         | 22/01/2019 |  |
| Date Inspected:             | 22/01/2019 | Inspected At: Jin Auto Services Pte Ltd (Defu)<br>Blk 14 Defu Lane 10, #01-410/412<br>Singapore 539195 |
| Estimated Period of Repair: | 12.0 days  |  |

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

## Reference

|               |  |  |
|---------------|--|--|
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 22 Feb 2019)          |
| Parts:        | 143  | TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                      |
| Print Code:   | (Unsubmitted, no print-code for SJX1644R)  |  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

## Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition                     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|-------------------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                         | Dented/Deformed               | 491.60 FL   | *491.60 FL   |
| 2   | 1   |          | *FRONT BUMPER CLIPS                   | Necessary                     | 38.00 FL    | *38.00 FL    |
| 3   | 2   |          | *FRONT BUMPER SIDE RETAINER           | Bent                          | 146.40 FL   | *146.40 FL   |
| 4   | 1   |          | *TOW COVER                            | Torn                          | 21.40 FL    | *21.40 FL    |
| 5   | 1   |          | *FRONT BUMPER PLATE GARNISH           | Not Necessary                 | 93.50 FL    | *- FL        |
| 6   | 1   |          | *FRONT BUMPER SPONGE                  | Torn                          | 91.20 FL    | *91.20 FL    |
| 7   | 1   |          | *FRONT BUMPER REINFORCEMENT           | Repair                        | 421.70 FL   | *- FL        |
| 8   | 1   |          | *FRONT GRILLE                         | Cracked                       | 491.60 FL   | *491.60 FL   |
| 9   | 1   |          | *BONNET                               | Dented/Buckled                | 1,190.30 FL | *1,190.30 FL |
| 10  | 1   |          | *REAR WINDSCREEN MOULDING             | Not Necessary                 | 88.20 FL    | *- FL        |
| 11  | 1   |          | *BOOTLID                              | Buckled                       | 863.70 FL   | *863.70 FL   |
| 12  | 2   |          | *BOOTLID HINGE                        | Repair                        | 271.60 FL   | *- FL        |
| 13  | 1   |          | *BOOTLID INNER INSULATOR              | Deformed/Torn                 | 473.60 FL   | *473.60 FL   |
| 14  | 1   |          | *REAR BOOT UPPER LOCK                 | Bent                          | 360.40 FL   | *360.40 FL   |
| 15  | 1   |          | *REAR BOOT LOWER CATCH                | Not Necessary                 | 29.10 FL    | *- FL        |
| 16  | 1   |          | *REAR BOOT WEATHERSTRIP               | Twisted                       | 204.60 FL   | *204.60 FL   |
| 17  | 1   |          | *REAR BOOT BADGE                      | Necessary                     | 66.70 FL    | *66.70 FL    |
| 18  | 1   |          | *REAR BOOT CAMRY EMBLEM               | Necessary                     | 49.90 FL    | *49.90 FL    |
| 19  | 1   |          | *REAR BOOT 2.0 EMBLEM                 | Necessary                     | 43.30 FL    | *43.30 FL    |
| 20  | 1   |          | *REAR BOOT REFLECTOR                  | O/s Cracked/N/s Not Necessary | 761.40 FL   | *380.70 FL   |
| 21  | 1   |          | *REAR BOOT INNER PLATE GARNISH        | Bent/Warped                   | 363.10 FL   | *363.10 FL   |
| 22  | 1   |          | *REAR BOOT INNER PLATE GARNISH CHROME | Not Necessary                 | 78.00 FL    | *- FL        |
| 23  | 2   |          | *REAR LAMP                            | Cracked                       | 832.40 FL   | *832.40 FL   |
| 24  | 2   |          | *REAR FENDER                          | Repair                        | 1,822.80 FL | *- FL        |
| 25  | 1   |          | *REAR BUMPER                          | Distorted                     | 530.50 FL   | *530.50 FL   |
| 26  | 1   |          | *REAR BUMPER CLIPS                    | Necessary                     | 50.00 FL    | *50.00 FL    |
| 27  | 2   |          | *REAR BUMPER SIDE RETAINER            | Bent                          | 114.40 FL   | *114.40 FL   |
| 28  | 1   |          | *REAR BUMPER REINFORCEMENT            | Bent                          | 420.70 FL   | *420.70 FL   |
| 29  | 2   |          | *REAR BUMPER RED REFLECTOR            | Not Necessary                 | 108.40 FL   | *- FL        |
| 30  | 2   |          | *REAR BUMPER SIDE RETAINER            | Repeated                      | 38.40 FL    | *- FL        |
| 31  | 2   |          | *REAR BUMPER SIDE REFLECTOR           | Repeated                      | 108.40 FL   | *- FL        |
| 32  | 1   |          | *REAR END PANEL                       | Badly Dented                  | 602.10 FL   | *602.10 FL   |
| 33  | 2   |          | *REAR FENDER INNER GARNISH            | Not Necessary                 | 783.20 FL   | *- FL        |
| 34  | 1   |          | *REAR END PANEL GARNISH               | Buckled                       | 353.80 FL   | *353.80 FL   |
| 35  | 1   |          | *SPARE TYRE PANEL                     | Crumpled/Buckled              | 708.80 FL   | *708.80 FL   |
| 36  | 1   |          | *SPARE TYRE BOARD                     | Torn                          | 195.40 FL   | *195.40 FL   |
| 37  | 2   |          | *REAR FENDER VENTILATOR BOX           | Not Necessary                 | 426.40 FL   | *- FL        |
| 38  | 1   |          | *REAR MUFFLE ASSY                     | Repair                        | 881.60 FL   | *- FL        |
| 39  | 1   |          | *FRONT NUMBER PLATE                   | Bent                          | 45.00 FS    | *40.00 FS    |
| 40  | 1   |          | *REAR NUMBER PLATE                    | Bent                          | 45.00 FS    | *40.00 FS    |
| 41  | 1   |          | *SEALANT REAR W/SCREEN                | Not Necessary                 | 60.00 FS    | *- FS        |

Report was unsubmitted during this print-out.

| No.   | Qty | Part No. | Particulars         | Condition | Repairer's | Amount     |
|---|-----|----------|---------------------|-----------|------------|------------|
| 42  | 1   |          | *SET REVERSE SENSOR | Shorted   | 280.00 FS  | *200.00 FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc.        |     |          |                     |           |            |            |
| Sub Total (\$\$)                                    |     |          |                     |           | 15,046.60  | 9,364.60   |
| - List Item Discount on L Items 25.00/25.00% (\$\$) |     |          |                     |           | 3,654.15   | 2,271.15   |
| Total Parts (\$\$)                                  |     |          |                     |           | 11,392.45  | 7,093.45   |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                       | Particulars                     | Lab.Type | Repairer's      | Amount          |
|--------------------------|---------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>      |                                 |          |                 |                 |
| 1                        | SPRAY PAINT (FRONT PORTION)     | New      | 580.00          | 500.00          |
| 2                        | LABOUR CHARGE (FRONT PORTION)   | New      | 480.00          | 400.00          |
| 3                        | TUFF KOTE                       | New      | 120.00          | 120.00          |
| 4                        | REMOVE AND RENEW REVERSE SENSOR | New      | 80.00           | 50.00           |
| 5                        | REMOVE AND REFIX WINDSCREEN     | New      | 120.00          | 0.00            |
| 6                        | SPRAY PAINT REAR PORTION        | New      | 1,800.00        | 1,200.00        |
| 7                        | LABOUR CHARGE REAR PORTION      | New      | 2,800.00        | 1,800.00        |
| 8                        | REMOVE & REFIX GARNISHES        | New      | 120.00          | 80.00           |
| 9                        | WIRING                          | New      | 35.00           | 30.00           |
| Gross Labour Cost (\$\$) |                                 |          | <b>6,135.00</b> | <b>4,180.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >