

INS CASE OWNER:

Wing Pte

CC 4, Arm 1900 1482, Rpa

94767

Syor.

Rpa

DOI

ASSIGNMENT

2/1/19

Date / Time:

2/1/19

Registered in Merimen:

Pre-assign: CCU / FTE



Insured Vehicle No.:

SLO 3173 B

Name of Insured:

MD. SDFIAN B. MD. SUHPI

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

19-01-19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLF 29842



INSRS:

WSP:

Tel:

Liability:

RMKS:

Vermogen



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

SS

3959.00

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

350.00 (\$50 x 7 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

6311.00

Global Sum SS: 4300.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4300.00

Name:

Vermogen Ace Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name:

Payee 3: (Strike if N.A.)

SS

Name:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
56/1/19

ACKNOWLEDGMENTS

Vehicle: SLF 29842 Reg: 2016 Aug
Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
☐ Truck / ☐ Trailer or

Make: **TOYOTA SIENTA 1.5XA** **1496**
 Colour: **GRN** AC Insured / Std / NI / NA
 Sp Reading: **188480** T/Radio Insured / Std / NI / NA

Eng/No: _____
Ctno: NSP1707040464

Gen. Cond: Good (Fair) Poor / Burnt

Steering: W / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nir / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15
R: ~

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or **ACHILLES**

67K

Front		Rear	
R/Bal	$\leq$ mm	R/Bal	$\leq$ mm

L/Bal	3	mm	L/Bal	5	mm
P.O.I	14/11/19		P.O.I	22/11/19	

D.O.A. 19/01/19 D.O.I. 22/01/19

Survey held at VERMOHEN

Vehicle IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision

2/17/19 Confirm C/S \$3700.00 with 5 working days

(200. ~~1612~~ 10
30%)

☐

5

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Terminology

Add Fee: Site Inap. 1\$

☐	Site trap	15
--------------------------	-----------	----

Report Format

Lump Sum / LEH / CS

☐ Interview (5)

Tech track IS

☐ Naked 15

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SLF2984Z
Vehicle Type:	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5X A
Chassis No.:	NSP1707040464
Propellant:	Petrol
Engine No.:	2NRB640227
Engine Capacity:	1496 cc
Maximum Power Output:	80.0 kW (107 bhp)
Maximum Laden Weight:	1705 kg
Unladen Weight:	1320 kg
Year Of Manufacture:	2016
Original Registration Date:	22 Aug 2016
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$53,000.00
COE Expiry Date:	21 Aug 2026
Road Tax Expiry Date:	21 Feb 2019
PARF Eligibility Expiry Date:	21 Aug 2026
Inspection Due Date:	21 Aug 2019
Intended Transfer Date:	12 Dec 2019
CO2 Emission:	119.00 (g/km)
CEV/VES Rebate Utilised	\$10,000.00
Amount:	
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 22 Feb 2019 to 21 Aug 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00

Amount Payable (From 22 Feb 2019 to 21 Feb 2020)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print



SLF2984Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 19/1/2019

Vehicle Reg. No. : SLF2984Z
Vehicle Reg. Date: 22-Aug-2016
Make / Model : T. SIENTA 1.5X A
Engine No. : 2NRB640227
Chassis No. : NSP1707040464

COST OF CLAIMS

Parts Cost / List Items : \$ 19,735.00
Plus/Less 25% \$ 4,933.75
Total Cost / List : \$ 14,801.25
Special Nett Items : \$ 995.00
Total Parts Amount : \$ 15,796.25
Total Labour Amount : \$ 4,850.00
Gross Total : \$ 20,646.25
GST % : 7% \$ 1,445.24
Nett Amount : \$ 22,091.49

Surveyor Name and Company :

RASUL (LKK)

Date of survey : 22/01/19 01145

Part by Part Lump Sum 5 days

Resurvey Before Paint After Paint

Authorize/Not Authorize/Without Prejudice

Email :

Fax No :

HP No : 90010068

This claim is handled by : MINOKO

LKK Auto Consultants hereby notify the Reparer of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confidentiality
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear bumper PC		\$ 838.80		497
2	1	Rear bumper cover center PC		\$ 182.40		182.40
3	2	Rear bumper cover LH/RH X sur		\$ 391.00		
4	1set	Rear bumper clips na		\$ 50.00		50
5	2	Rear bumper side retainer LH/RH X sur		\$ 164.00		
6	MP	Rear bumper bracket (LH/RH) na / RH-X na		\$ 180.00		82
7	1	Rear bumper sponge de		\$ 98.00		45
8	2	Rear bumper reflector LH/RH X 3an		\$ 216.00		
9	2	Rear bumper splash shield LH/RH X 3an		\$ 340.00		
10	1	Tail gate PC		\$ 1,360.00		125
11	1	Tail gate lock X 3sur		\$ 246.60		
12	1	Tail gate striker X 3sur		\$ 48.00		
13	2	Tail gate stay LH/RH X sur		\$ 320.00		
14	1	Tail gate logo na		\$ 50.00		50.00
15	1	Tail gate emblem RH X 3an		\$ 84.50		
16	1	Tail gate outer garnish X 3an		\$ 278.00		
17	1	Tail gate weatherstrip cut		\$ 145.00		145.00
18	2	Tail gate lamp LH/RH X 3an		\$ 720.00		
19	1	Tail gate inner board X 3an		\$ 280.00		
20	2	Tail gate rubber stopper LH/RH na		\$ 75.00		75.00
21	2	Tail lamp LH/RH X		\$ 780.00		
22	2	Tail lamp panel LH/RH X		\$ 360.00		
23	1	Tail gate inner handle X		\$ 90.00		
24	1	Tailgate windscreen glass X		\$ 1,877.50		
25	1set	Tailgate windscreen glass moulding na		\$ 168.40		115
26	1	Antenna sensor PC ? cm		\$ 190.00		130
27	1	Rear end panel outer repair bt		\$ 630.00		498
28	1	Rear end panel inner PC repair		\$ 504.00		
29	1	Rear end panel garnish PC		\$ 195.20		195.20
30	1	Spare tyre well panel X		\$ 822.60		
31	1	Spare tyre board X		\$ 256.00		
32	1	Spare tyre bracket X		\$ 60.00		
33	1	Spare tyre insulator X		\$ 280.00		
34	1	Spare tyre tool tray X		\$ 758.00		
35	2	Rear fender LH/RH X		\$ 3,352.00		
36	2	Rear fender garnish lower trim LH/RH X		\$ 1,214.00		
37	2	Rear fender garnish upper LH/RH X		\$ 936.00		
38	2	Rear fender air duct LH/RH X		\$ 144.00		
39	1set	Tail door trim clips na		\$ 50.00		50
40	1	Rear end panel sealant PC na		\$ 80.00		60

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF2984Z

Vehicle Reg. Date: 22/8/2016

Make / Model : T. SIENTA 1.5X A

Engine No. : #REF!

Chassis No. : NSP1707040464

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			\$ 80.00	
42	1	Spare tyre sound damper X			\$ 80.00	
43	1	Sundries X			\$ 80.00	
44	1	Tail gate seal X			\$ 80.00	60
45	1	Reverse sensor X			\$ 300.00	200
46	1	Rear number plate with frame X			\$ 55.00	
47	1	Rear windscreen lgass sealant X			\$ 80.00	40
48	1	Rear windscreen glass primer & cleaner X			\$ 80.00	
49	1	Rear windscreen glass support sponge X			\$ 80.00	
50	1	Exhaust muffler X		\$ 700.00		
51	1Set	Exhaust muffler mounting X		\$ 210.00		
52	1	Exhaust heat shield X		\$ 90.00		
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO: LKK-RASUL
Surveyor Name and Company

Date of Accident : **19/1/2019**

BILL TO: AXA
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SLF2984Z

Make / Model : T. SIENTA 1.5X A

COST OF CLAIMS

Parts Cost / List : \$ 4,122.80

Supp. Parts : \$ -

Special Nett : \$ 360.00

Total Parts : \$ 3,452.10

Total Labour : \$ 1,860.00

TOTAL REPAIR COST : \$ 5,312.10

Submitted by / Date : MINOKO

Confirmed by / Date :

Total Parts Cost/List :	\$	4,122.80
Plus / Less : 25%	\$	1,030.70
Total :	\$	3,092.10

Lump Sum Discount : 20%	\$	1,062.42
Lump Sum Amount:	\$	4,249.68

Final Lump Sum Amount : \$ 4,250.00

No. of Repair Days: 5

2429.70

360.00

1860.00

4589.70

20%

3671.76

4589.70

5 days

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF2984Z
 Vehicle Reg. Date: 22/8/2016
 Make / Model : T. SIENTA 1.5X A
 Engine No. : #REF1
 Chassis No. : N5P1707040464

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear bumper		\$ 838.80		\$ 838.80
2	1	Rear bumper cover center		\$ 182.40		\$ 182.40
3	2	Rear bumper cover LH/RH		\$ 391.00		
4	1set	Rear bumper clips		\$ 50.00		\$ 50.00
5	2	Rear bumper side retainer LH/RH		\$ 164.00		
6	2	Rear bumper bracket LH/RH <i>REF</i>		\$ 180.00		\$ 90.00
7	1	Rear bumper sponge		\$ 98.00		\$ 98.00
8	2	Rear bumper reflector LH/RH		\$ 216.00		
9	2	Rear bumper splash shield LH/RH		\$ 340.00		
10	1	Tail gate		\$ 1,360.00		\$ 1,360.00
11	1	Tail gate lock		\$ 246.60		
12	1	Tail gate striker		\$ 48.00		
13	2	Tail gate stay LH/RH		\$ 320.00		
14	1	Tail gate logo		\$ 50.00		\$ 50.00
15	1	Tail gate emblem RH		\$ 84.50		
16	1	Tail gate outer garnish		\$ 278.00		
17	1	Tail gate weatherstrip		\$ 145.00		\$ 145.00
18	2	Tail gate lamp LH/RH		\$ 720.00		
19	1	Tail gate inner board		\$ 280.00		
20	2	Tail gate rubber stopper LH/RH		\$ 75.00		\$ 75.00
21	2	Tail lamp LH/RH		\$ 780.00		
22	2	Tail lamp panel LH/RH		\$ 360.00		
23	1	Tail gate inner handle		\$ 90.00		
24	1	Tailgate windscreen glass		\$ 1,877.50		
25	1set	Tailgate windscreen glass moulding		\$ 168.40		\$ 168.40
26	1	Antenna sensor		\$ 190.00		\$ 190.00
27	1	Rear end panel outer		\$ 630.00		\$ 630.00
28	1	Rear end panel inner		\$ 504.00		
29	1	Rear end panel garnish		\$ 195.20		\$ 195.20
30	1	Spare tyre well panel		\$ 822.60		
31	1	Spare tyre board		\$ 256.00		
32	1	Spare tyre bracket		\$ 60.00		
33	1	Spare tyre insulator		\$ 280.00		
34	1	Spare tyre tool tray		\$ 758.00		
35	2	Rear fender LH/RH		\$ 3,352.00		
36	2	Rear fender garnish lower trim LH/RH		\$ 1,214.00		
37	2	Rear fender garnish upper LH/RH		\$ 936.00		
38	2	Rear fender air duct LH/RH		\$ 144.00		
39	1set	Tail door trim clips		\$ 50.00		\$ 50.00
40	1	Rear end panel sealant			\$ 60.00	

3239.60
 258
 2429.70

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLF2984Z

Vehicle Reg. Date: 22/8/2016

Make / Model : T. SIENTA 1.5X A

Engine No. : #REF!

Chassis No. : NSP1707040464

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant			\$ -	
42	1	Spare tyre sound damper			\$ -	
43	1	Sundries			\$ -	
44	1	Tail gate seal			\$ 60.00	
45	1	Reverse sensor			\$ 200.00	
46	1	Rear number plate with frame			\$ -	
47	1	Rear windscreen lgass sealant			\$ 40.00	
48	1	Rear windscreen glass primer & cleaner			\$ -	
49	1	Rear windscreen glass support sponge			\$ -	
50	1	Exhaust muffler		\$ 700.00		
51	1Set	Exhaust muffler mounting		\$ 210.00		
52	1	Exhaust heat shield		\$ 90.00		
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

300

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF2984Z**
Vehicle Reg. Date: **22/8/2016**
Make / Model : **T. SIENTA 1.5X A**
Engine No. : **#REF!**
Chassis No. : **NSP1707040464**

PAGE 1

Estimates on Labour

No	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR	AMOUNT	ADJUSTED AMOUNT
1	To remove and replace damaged parts and to panel beating accident area. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, SPARETYRE PANEL, RR FENDER LH/RH.	\$ 1,800.00	\$ 700.00
2	To check and rectify wiring after disconnect and connect.	\$ 150.00	
3	To remove and replace reverse sensor.	\$ 180.00	\$ 60.00
4	To remove and refit inner trim, inner seat, trim board, to assist repair.	\$ 200.00	\$ 60.00
5	To rustproof accident repair area.	\$ 180.00	\$ 60.00
6	To transfer tailgate mechanism to new tailgate.	\$ 180.00	\$ 60.00
7	To putty and respray replaced parts and accident repair area. TAILGATE, TAILGATE GARNISH, RR BUMPER, RR END PANEL, SPARETYRE PANEL, RR FENDER LH/RH.	\$ 1,800.00	\$ 800.00
8	To remove and refit rear windscreen.	\$ 180.00	\$ 120.00
9	To remove & refit Exhaust muffler	\$ 180.00	

1860

1860



SLF2984Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 19/1/2019

Vehicle Reg. No. : SLF2984Z
Vehicle Reg. Date: 22-Aug-2016
Make / Model : T. SIENTA 1.5X A
Engine No. : 2NR8640227
Chassis No. : NSP1707040464

COST OF CLAIMS

Parts Cost / List Items : \$ 19,735.00
Plus/Less 25% \$ 4,933.75
Total Cost / List : \$ 14,801.25
Special Nett Items : \$ 995.00
Total Parts Amount : \$ 15,796.25
Total Labour Amount : \$ 4,850.00
Gross Total : \$ 20,646.25
GST % : 7% \$ 1,445.24
Nett Amount : \$ 22,091.49

Surveyor Name and Company :

RASUL CLKK7

Date of survey : 22/01/19 01145

Part by Part Lump Sum 5 days

Resurvey Before Paint After Paint

Authorize/Not Authorize/Without Prejudice

Email : PK

Fax No : _____

HP No : 90010068

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF2984Z**

Vehicle Reg. Date: **22/8/2016**

Make / Model : **T. SIENTA 1.5X A**

Engine No. : **#REF!**

Chassis No. : **NSP1707040464**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear bumper DE		\$ 838.80		
2	1	Rear bumper cover center DE		\$ 182.40		
3	2	Rear bumper cover LH/RH X		\$ 391.00		
4	1set	Rear bumper clips ne		\$ 50.00		
5	2	Rear bumper side retainer LH/RH X		\$ 164.00		
6	PCP	Rear bumper bracket LH/RH X ne / RH-X		\$ 180.00		
7	1	Rear bumper sponge		\$ 98.00		
8	2	Rear bumper reflector LH/RH X		\$ 216.00		
9	2	Rear bumper splash shield LH/RH X		\$ 340.00		
10	1	Tail gate DE		\$ 1,360.00		
11	1	Tail gate lock X		\$ 246.60		
12	1	Tail gate striker X		\$ 48.00		
13	2	Tail gate stay LH/RH X		\$ 320.00		
14	1	Tail gate logo ne		\$ 50.00		
15	1	Tail gate emblem RH X		\$ 84.50		
16	1	Tail gate outer garnish X		\$ 278.00		
17	1	Tail gate weatherstrip cut		\$ 145.00		
18	2	Tail gate lamp LH/RH X		\$ 720.00		
19	1	Tail gate inner board X		\$ 280.00		
20	2	Tail gate rubber stopper LH/RH ne		\$ 75.00		
21	2	Tail lamp LH/RH X		\$ 780.00		
22	2	Tail lamp panel LH/RH X		\$ 360.00		
23	1	Tail gate inner handle X		\$ 90.00		
24	1	Tailgate windscreen glass X		\$ 1,877.50		
25	1set	Tailgate windscreen glass moulding ne		\$ 168.40		
26	1	Antenna sensor DE?		\$ 190.00		
27	1	Rear end panel outer repair by		\$ 630.00		
28	1	Rear end panel inner repair by		\$ 504.00		
29	1	Rear end panel garnish DE		\$ 195.20		
30	1	Spare tyre well panel X		\$ 822.60		
31	1	Spare tyre board X		\$ 256.00		
32	1	Spare tyre bracket X		\$ 60.00		
33	1	Spare tyre insulator X		\$ 280.00		
34	1	Spare tyre tool tray X		\$ 758.00		
35	2	Rear fender LH/RH X		\$ 3,352.00		
36	2	Rear fender garnish lower trim LH/RH X		\$ 1,214.00		
37	2	Rear fender garnish upper LH/RH X		\$ 936.00		
38	2	Rear fender air duct LH/RH X		\$ 144.00		
39	1set	Tail door trim clips ne		\$ 50.00		
40	1	Rear end panel sealant DE ne			\$ 80.00 60	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF2984Z**

Vehicle Reg. Date: **22/8/2016**

Make / Model : **T. SIENTA 1.5X A**

Engine No. : **#REF!**

Chassis No. : **NSP1707040464**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			\$ 80.00	
42	1	Spare tyre sound damper X			\$ 80.00	
43	1	Sundries X			\$ 80.00	
44	1	Tail gate seal as ✓			\$ 80.00	60
45	1	Reverse sensor as ✓			\$ 300.00	200
46	1	Rear number plate with frame X			\$ 55.00	
47	1	Rear windscreen lgass sealant as ✓			\$ 80.00	40
48	1	Rear windscreen glass primer & cleaner X			\$ 80.00	
49	1	Rear windscreen glass support sponge X			\$ 80.00	
50	1	Exhaust muffler X		\$ 700.00		
51	1Set	Exhaust muffler mounting X		\$ 210.00		
52	1	Exhaust heat shield X		\$ 90.00		
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

◀ Service Request Details

Claim

S9M01B6K

Reference

None 

Loss Date

January 19, 2019

Request Date

January 22, 2019

Due Date

January 29, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

7/20/2019 @ 9:35am
PLG veh in.
Busul

Actions

Next Step

Agree to perform service

Decline WorkAccept Work

Vehicle Information

Incident Vehicle Registration #

SLF2984Z

Make

TPVD TOYOTA

Service Address

Primary Contact/Insured

MOHAMMED SUHPI MOHAMMED SOFIAN BIN
BLK 308 PUNGOL WALK, #05-370, 822308, Singapore
94510106

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Pls proceed DS with quantum as proposed

Type

🔗 Question

Message

Reply

**Vermogen ACE Pte Ltd**

1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Co. Reg No.: 201606023C GST Reg No.: 201606023C
Tel: 6694 4919 Fax: 6694 4929
Email: vermogenace@gmail.com

Yr Ref : SLD3173B

Our Ref : SLF2984Z

09 JULY 2019

Without Prejudice

Attn: Motor Claim Dept

AXA INSURANCE (S) PTE LTD

8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811

Dear Sir/Mdm,

Accident involving SLF2984Z & SLD3173B on 19/01/2019 12:45 hrs at along SLIP RD OF AIRPORT RD TO EUNOS LINK.

We refer to the above said accident.

As instructed, we are claiming the following as stated below:-

1. Cost of repair	\$	3,959.00
2. Loss of use (\$100 x 11 days)	\$	1,100.00
3. GIA search fee	\$	2.00
Total	\$	5,061.00

We enclosed herewith relevant document as stated below:-

1. Accident report
2. Final Repair Bill
3. Letter of authority
4. GIA search receipt

We do not have the survey report and photographs as our client's motor vehicle was surveyed by your appointed surveyor.

Please kindly let us know whether you are prepared to settle our client's claim & we look forward to hear from you soonest.

Thank you.
Best Regards,



Ezel Tejano (Claim Dept)
Vermogen ACE PTE LTD
Tel: 6904 4596 | Fax: 6694 4929
Email: ezel.t@vermogen-group.com



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561 FAX : (065) 62564315

12 APR 2019

MOHAMMED SOFIAN BIN MOHAMMED SUHPI
Blk 308B Punggol Walk
#05-370
Singapore 822308

Dear Sir/ Mdm

OUR REF : CC4/ASM19001482/R1ga3

YOUR REF : SLD 3173B

**ACCIDENT INVOLVING SLD 3173B AND SLF 2984Z ALONG/AT HOUGANG AVE 3 ON
19/01/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from VERMOGEN ACE PTE LTD acting on behalf of the owner of SLF 2984Z against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ceciliachong@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at ceciliachong@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely



Cecilia Chong
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: ceciliachong@lkkauto.com

Cc *AXA Insurance Pte Ltd*
(Motor Claims Dept)

TO: AXA INSURANCE PTE LTD

Dear Sirs,

CLAIMANT: LCRF PTE LTD

ACCIDENT INVOLVING SLF2984Z and SLD3173B on 19TH JAN 2019 At 1243HRS

I/WE LCRF PTE LTD, am/are the registered Owner of Vehicle No. SLF2984Z

Please note that I have assigned all compensation monies due -to me/us in the above said accident to **Vermogen ACE Pte Ltd**.

I/We, hereby authorize you to release all compensation monies pertaining to the above said accident to **Vermogen ACE Pte Ltd** and forward your settlement cheque to **Vermogen ACE Pte Ltd** whom I/we had authorized to collect the said compensation monies .

Thank you



Signature of Claimant
(company Stamp, if applicable)

Name : LCRF PTE LTD
NRIC No. : 201624597K
Date : 27/1/2019



Vermogen ACE Pte Ltd
1 BUKIT BATOK CRESCENT #05-23 WCEGA PLAZA 5(658064)
TEL : 6694 4919 FAX : 6694 4929
Email : vermogenace@gmail.com
REG No : 201806023C

LETTER OF AUTHORITY & INDEMNITY

ACCIDENT INVOLVING VEHICLE NO. SLF2984Z & SLD3173B ALONG SLIP RD OF AIRPORT RD TO EUNOS LINK ON 19TH JAN 2019, 1243HRS.

I/We LCRF PTE LTD UEN/NRIC NO. 201624597K owner of Vehicle No. SLF2984Z, hereby authorise M/S Vermogen ACE Pte Ltd to commence repairs to my vehicle and to forward the claim for damages sustained in the above accident to the third party driver and /or his employer and /or the vehicle owner and /or the insurer concerned. I/We agree that in consideration of you giving up your repairer's lien, I/We agree to assign the whole proceeds of my/our third party claim to you and if applicable, our solicitors (to be appointed by you on my /our behalf) shall accept this as my /our irrevocable authority to pay the amount compensated direct to you after deduction of their costs on a solicitor & client basis. I/We undertake to co-operate fully with you and our solicitors to see the claim to a successful conclusion.

If third party driver and and/or his employer and/or the vehicle owner and/or insurer reject liability, I/We will fully be responsible for the repair costs and other incidentals.

I/We also authorise you to sign all discharge vouchers/indemnity forms and all necessary paper in connection with the above claim in my/our absence.

I/We authorise you to appoint such a firm of solicitors on my/our behalf as you shall deem fit for the purpose of the third party/own insurer's claim.

I/we undertake to inform you and/or the solicitors appointed by you on my/our behalf in the event of the third party's insurance company communicate with me/us directly by telephone or in writing and I/We further undertake not to accept any monies or offer of settlement from the third party's insurers without first communicating with you.

My/our vehicle is repaired by the repairer on my/our will without any inducement, threat and/or promise.

In the event that the repairer is compelled to enforce this undertaking, I/We agree that I/shall pay for the legal costs incurred by the repairer on a solicitor and client's full indemnity basis.



Owner Signature
(Company Stamp if applicable)



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SLD 3173B (Insd veh)	Model: <u>Toyota Sienna - 1496 cc</u>
	SLF 2984Z (TP veh)	
Date of Accident/Time:	19/01/2019	

Repair Estimate	: \$	22,071.49	
Final Repair Cost	: \$		
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$		
Others:	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	4,300.00	
Payee Name : VERMOGEN ACE PTE LTD			
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability <u>100</u> (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/i confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp

Name of Representative:

Date:

26/1/19

Signature of Witness / Workshop stamp (if applicable)

Name of Witness:

Date:

26/1/19

Signature of AXA's surveyor/representative:

Name of AXA's surveyor /Representative:

Date:

26/1/19



Vermogen ACE Pte Ltd
1 BUKIT BATOK CRESCENT #05-23
WCEGA PLAZA S(658064)
TEL : 6694 4919 FAX : 6694 4929
CO & GST REG NO : 201606023C

Tax Invoice: 21310

AXA Insurance Singapore Pte.Ltd.

8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Tel: +65 6880 4741 Fax: +65 6880 4838

Attn: Motor Claims Dept

Bill Date: 9/7/2019
Vehicle No: SLF2984Z
Vehicle Model: TOYOTA SIENTA
Date of Accident: 19/01/2019
Claim No:

S/N	QTY	Descriptions	Unit Price	Amount S\$
1		Lumpsum Repair		3700.00

E. & O.E.

Total	S\$	3700.00
GST 7%	S\$	259.00
Amount Due	S\$	3959.00



for Vermogen ACE Pte Ltd

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-011751

Date of Request: 21/01/2019

Your Ref No:

Online Purchase

Vermogen Ace Pte Ltd
Blk B, 44 Benoi Rd
Singapore 629904

Dear Sir/Madam,

Enquiry Date 21/01/2019

Enquiry By Nur Asyira Binte AB Rahman

Vehicle No. SLD3173B

Accident Date 19/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD.

Ref : CC4/ASM19001482/R1wa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:PETER

Date : 06-08-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 3173B	Veh. Inspected	SLF 2984Z
Policy No.	VPA/P1792175	Coverage (\$)	0.00
Claim No.	S9M01B6K	Excess (\$)	0.00
Assign From		Assign Date	22/01/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA 1.5X (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707040464	Colour	GREY
Odometer	188480	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	ACHILLES	5 mm
L/H Front Tyre	185/60 R15	ACHILLES	5 mm
R/H Rear Tyre	185/60 R15	ACHILLES	5 mm
L/H Rear Tyre	185/60 R15	ACHILLES	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/01/2019	Inspection Date	22/01/2019
Survey held at	6 BENOI SECTOR		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 2984Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED	838.80	497.00
1	REAR BUMPER COVER CENTER (CONSISTENT)	DEFORMED	182.40	182.40
2	REAR BUMPER COVER LH/RH (CONSISTENT)	SERVICEABLE	391.00	-
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER LH/RH (CONSISTENT)	SERVICEABLE	164.00	-
2	REAR BUMPER BRACKET LH/RH (CONSISTENT)	N/S NECESSARY / O/S SERVICEABLE	180.00	82.00
1	REAR BUMPER SPONGE (CONSISTENT)	DEFORMED	98.00	45.00
2	REAR BUMPER REFLECTOR LH/RH (CONSISTENT)	NOT NECESSARY	216.00	-
2	REAR BUMPER SPLASH SHIELD LH/RH (CONSISTENT)	NOT NECESSARY	340.00	-
1	TAIL GATE (CONSISTENT)	BENT	1,360.00	1,125.00
1	TAIL GATE LOCK (CONSISTENT)	SERVICEABLE	246.60	-
1	TAIL GATE STRIKER (CONSISTENT)	SERVICEABLE	48.00	-
2	TAIL GATE STAY LH/RH (CONSISTENT)	SERVICEABLE	320.00	-
1	TAIL GATE LOGO (CONSISTENT)	NECESSARY	50.00	50.00
1	TAIL GATE EMBLEM RH (CONSISTENT)	NOT NECESSARY	84.50	-
1	TAIL GATE OUTER GARNISH (CONSISTENT)	NOT NECESSARY	278.00	-
1	TAIL GATE WEATHERSTRIP (CONSISTENT)	CUT	145.00	145.00
2	TAIL GATE LAMP LH/RH (CONSISTENT)	NOT NECESSARY	720.00	-
1	TAIL GATE INNER BOARD (CONSISTENT)	NOT NECESSARY	280.00	-
2	TAIL GATE RUBBER STOPPER LH/RH (CONSISTENT)	NECESSARY	75.00	75.00
2	TAIL LAMP LH/RH (CONSISTENT)	NOT NECESSARY	780.00	-
2	TAIL LAMP PANEL LH/RH (CONSISTENT)	NOT NECESSARY	360.00	-
1	TAIL GATE INNER HANDLE (CONSISTENT)	NOT NECESSARY	90.00	-
1	TAILGATE WINDSCREEN GLASS (CONSISTENT)	NOT NECESSARY	1,877.50	-
1	SET TAILGATE WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	168.40	115.00
1	ANTENNA SENSOR (CONSISTENT)	CRACKED	190.00	130.00
1	REAR END PANEL OUTER (CONSISTENT)	BENT	630.00	498.00
1	REAR END PANEL INNER (CONSISTENT)	TO REPAIR SEE LABOUR	504.00	-
1	REAR END PANEL GARNISH (CONSISTENT)	DEFORMED	195.20	195.20

Report Ref No. CC4/ASM19001482/R1wa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE WELL PANEL (CONSISTENT)	NOT NECESSARY	822.60	-
1	SPARE TYRE BOARD (CONSISTENT)	NOT NECESSARY	256.00	-
1	SPARE TYRE BRACKET (CONSISTENT)	NOT NECESSARY	60.00	-
1	SPARE TYRE INSULATOR (CONSISTENT)	NOT NECESSARY	280.00	-
1	SPARE TYRE TOOL TRAY (CONSISTENT)	NOT NECESSARY	758.00	-
2	REAR FENDER LH/RH (CONSISTENT)	NOT NECESSARY	3,352.00	-
2	REAR FENDER GARNISH LOWER TRIM LH/RH (CONSISTENT)	NOT NECESSARY	1,214.00	-
2	REAR FENDER GARNISH UPPER LH/RH (CONSISTENT)	NOT NECESSARY	936.00	-
2	REAR FENDER AIR DUCT LH/RH (CONSISTENT)	NOT NECESSARY	144.00	-
1	SET TAIL DOOR TRIM CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	EXHAUST MUFFLER (CONSISTENT)	NOT NECESSARY	700.00	-
1	SET EXHAUST MUFFLER MOUNTING (CONSISTENT)	NOT NECESSARY	210.00	-
1	EXHAUST HEAT SHIELD (CONSISTENT)	NOT NECESSARY	90.00	-
	LESS 25% DISCOUNT		-4,933.75	-809.90
			14,801.25	2,429.70
	<u>SPECIAL NETT ITEMS</u>			
1	REAR END PANEL SEALANT (CONSISTENT) (SN)	NECESSARY	80.00	60.00
1	SPARE TYRE PANEL SEALANT (CONSISTENT) (SN)	NOT NECESSARY	80.00	-
1	SPARE TYRE SOUND DAMPER (CONSISTENT) (SN)	NOT NECESSARY	80.00	-
1	SUNDRIES (CONSISTENT) (SN)	NOT NECESSARY	80.00	-
1	TAIL GATE SEAL (CONSISTENT) (SN)	NECESSARY	80.00	60.00
1	REVERSE SENSOR (CONSISTENT) (SN)	NOT WORKING	300.00	200.00
1	REAR NUMBER PLATE WITH FRAME (CONSISTENT) (SN)	NOT NECESSARY	55.00	-
1	REAR WINDSCREEN GLASS SEALANT (CONSISTENT) (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN GLASS PRIMER & CLEANER (CONSISTENT) (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN GLASS SUPPORT SPONGE (CONSISTENT) (SN)	NOT NECESSARY	80.00	-
			995.00	360.00

Report Ref No. CC4/ASM19001482/R1wa3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA.TAILGATE,TAILGATE GARNISH,RR BUMPER ,RR END PANEL,SPARE TYRE PANEL (R),RR FENDER LH/RH.INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER.		1,800.00	700.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.	NOT NECESSARY	150.00	-
	TO REMOVE AND REPLACE REVERSE SENSOR .		180.00	60.00
	TO REMOVE AND REFIT INNER TRIM ,INNER SEAT ,TRIM BOARD ,TO ASSIST REPAIR.		200.00	60.00
	TO RUSTPROOF ACCIDENT REPAIR AREA.		180.00	60.00
	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.		180.00	60.00
	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA.TAILGATE,TAILGATE GARNISH,RR BUMPER ,RR END PANEL,SPARE TYRE PANEL,RR FENDER LH/RH.		1,800.00	800.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		180.00	120.00
	TO REMOVE & REFIT EXHAUST MUFFLER.	NOT NECESSARY	180.00	-
			4,850.00	1,860.00
	GRAND TOTAL		20,646.25	4,649.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00

Report Ref No. CC4/ASM19001482/R1wa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Actions	
Next Step	Wait for: Approve Invoice
	Send Invoice

Additional instructions:

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
----------	----------	---------	-----------	------------	---------	-------

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Inspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
 LKK Adjustment 1a (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
 LETTER TO OLA.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
 TP MANDATE JA-SLF 296A2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 TP ESTIMATE MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2019
 TP Video MP4	Evidence	Videos	WANG Peter	25 January 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	24 January 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PRU).msg	Letters and Correspondence	Workshop	KADRI Matten	22 January 2019

