



SLF2984Z

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 19/1/2019

Vehicle Reg. No. : SLF2984Z
Vehicle Reg. Date: 22-Aug-2016
Make / Model : T. SIENTA 1.5X A
Engine No. : 2NR8640227
Chassis No. : NSP1707040464

COST OF CLAIMS

Parts Cost / List Items :	\$	19,735.00
Plus/Less 25%	\$	4,933.75
Total Cost / List :	\$	14,801.25
Special Nett Items :	\$	995.00
Total Parts Amount :	\$	15,796.25
Total Labour Amount :	\$	4,850.00
Gross Total :	\$	20,646.25
GST % : 7%	\$	1,445.24
Nett Amount :	\$	22,091.49

Surveyor Name and Company :

RASUL (LKK)

Date of survey : 22/01/19 P1145

Part by Part Lump Sum 5 days

Resurvey Before Paint After Paint

Authorize/Not Authorize/Without Prejudice

Email : PK

Fax No : _____

HP No : 90010068

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF2984Z**
 Vehicle Reg. Date: **22/8/2016**
 Make / Model : **T. SIENTA 1.5X A**
 Engine No. : **#REF!**
 Chassis No. : **NSP1707040464**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear bumper <i>DE</i>		\$ 838.80		
2	1	Rear bumper cover center <i>DE</i>		\$ 182.40		
3	2	Rear bumper cover LH/RH <i>X</i>		\$ 391.00		
4	1set	Rear bumper clips <i>ne</i>		\$ 50.00		
5	2	Rear bumper side retainer LH/RH <i>X</i>		\$ 164.00		
6	<i>per</i>	Rear bumper bracket LH/RH <i>ne / RH-X</i>		\$ 180.00		
7	1	Rear bumper sponge		\$ 98.00		
8	2	Rear bumper reflector LH/RH <i>X</i>		\$ 216.00		
9	2	Rear bumper splash shield LH/RH <i>X</i>		\$ 340.00		
10	1	Tail gate <i>DE</i>		\$ 1,360.00		
11	1	Tail gate lock <i>X</i>		\$ 246.60		
12	1	Tail gate striker <i>X</i>		\$ 48.00		
13	2	Tail gate stay LH/RH <i>X</i>		\$ 320.00		
14	1	Tail gate logo <i>ne</i>		\$ 50.00		
15	1	Tail gate emblem RH <i>X</i>		\$ 84.50		
16	1	Tail gate outer garnish <i>X</i>		\$ 278.00		
17	1	Tail gate weatherstrip <i>cut</i>		\$ 145.00		
18	2	Tail gate lamp LH/RH <i>X</i>		\$ 720.00		
19	1	Tail gate inner board <i>X</i>		\$ 280.00		
20	2	Tail gate rubber stopper LH/RH <i>ne</i>		\$ 75.00		
21	2	Tail lamp LH/RH <i>X</i>		\$ 780.00		
22	2	Tail lamp panel LH/RH <i>X</i>		\$ 360.00		
23	1	Tail gate inner handle <i>X</i>		\$ 90.00		
24	1	Tailgate windscreen glass <i>X</i>		\$ 1,877.50		
25	1set	Tailgate windscreen glass moulding <i>ne</i>		\$ 168.40		
26	1	Antenna sensor <i>DE ?</i>		\$ 190.00		
27	1	Rear end panel outer <i>repair bt</i>		\$ 630.00		
28	1	Rear end panel inner <i>repair</i>		\$ 504.00		
29	1	Rear end panel garnish <i>DE</i>		\$ 195.20		
30	1	Spare tyre well panel <i>X</i>		\$ 822.60		
31	1	Spare tyre board <i>X</i>		\$ 256.00		
32	1	Spare tyre bracket <i>X</i>		\$ 60.00		
33	1	Spare tyre insulator <i>X</i>		\$ 280.00		
34	1	Spare tyre tool tray <i>X</i>		\$ 758.00		
35	2	Rear fender LH/RH <i>X</i>		\$ 3,352.00		
36	2	Rear fender garnish lower trim LH/RH <i>X</i>		\$ 1,214.00		
37	2	Rear fender garnish upper LH/RH <i>X</i>		\$ 936.00		
38	2	Rear fender air duct LH/RH <i>X</i>		\$ 144.00		
39	1set	Tail door trim clips <i>ne</i>		\$ 50.00		
40	1	Rear end panel sealant <i>DE ne</i>			\$ 80.00 60	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLF2984Z**
 Vehicle Reg. Date: **22/8/2016**
 Make / Model : **T. SIENTA 1.5X A**
 Engine No. : **#REF!**
 Chassis No. : **NSP1707040464**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			\$ 80.00	
42	1	Spare tyre sound damper X			\$ 80.00	
43	1	Sundries X			\$ 80.00	
44	1	Tail gate seal As			\$ 80.00	60
45	1	Reverse sensor As			\$ 300.00	200
46	1	Rear number plate with frame X			\$ 55.00	
47	1	Rear windscreen lgass sealant As			\$ 80.00	40
48	1	Rear windscreen glass primer & cleaner X			\$ 80.00	
49	1	Rear windscreen glass support sponge X			\$ 80.00	
50	1	Exhaust muffler X		\$ 700.00		
51	1Set	Exhaust muffler mounting X		\$ 210.00		
52	1	Exhaust heat shield X		\$ 90.00		
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

SLF2984Z

22/8/2016

T. SIENTA 1.5X A

#REF!

NSP1707040464

Estimates on Labour

[illegible]