


Vic

Finalized -HJ

Section A - Accident Details

Registration Number	SHB708L
Case Reference Number	TAX/01/19/2093
Registration Date	27/7/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SONDREX BIN SUNREH
Type of Accident	Side Swipe
Accident Date and Time	19/1/2019 4:00 AM
Accident Reported Date and Time	20/1/2019 4:06 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099757
Special Instruction to ARC, if any	TBA LATER
Prepared Date and Time	21/1/2019 9:24 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$750.00
Total Spray Cost	\$2,250.00	\$1,100.00
Total Spare Part Cost	\$6,648.58	\$1,505.53
Total Other Cost	\$1,040.00	\$200.00
TOTAL COST	\$10,952.58	\$3,555.53 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / EQ
ARC / Surveyor Sign Off Date	21/01/2019 10:34 AM	21/01/2019 3:21 PM
Signature		
Remarks		P/P REPAIR, PHOTO BEFORE PAINT.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1902-0242	Invoice Number	
Quotation Date	20.02.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	\$750.00
Total Labour	\$1,014.00	\$750.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
TO RESPRAY REAR FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESRAY REAR DOOR LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$2,250.00	\$1,100.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$240.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$40.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REMOVE AND REFIT WIRE HARDESS	\$120.00	\$0.00
Total Other Costs	\$1,040.00	\$200.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
		75374-47051	"NAME PLATE (HYBRID)"	1.00	\$51.90	25.00	\$38.93	Replace	Replace
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
		42611-47140 (Frt)	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		75922-47020	TAPE OUT WIN FRAME LHF, DOOR	0.00	\$45.60	0.00	\$0.00	Replace	Not Given

BVC

hec

nn

lc

mc

hec

nn

69040-47070	DOOR LOCK FRT/LH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given	X	nn
69210-74030	DOOR OUTER HANDLE FRT/LH	1.00	\$370.80	100.00	\$0.00	Replace	Repair	R	
68720-15151	HINGE UPPER LHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given	X	nn
68740-12120	HINGE LOWER LHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given	X	nn
68610-47021	CHECK ASSY, FR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	nn
87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given	X	nn
87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair	R	
81740-52040	MIRROR LAMP LH	1.00	\$65.30	10.00	\$58.77	Replace	Replace	/	scr
67004-47080	DOOR RR/LH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	/	BVC
	PIXEL STICKER	1.00	\$60.00	0.00	\$60.00	Replace	Replace	/	nee
68780-52031	HINGE LOWER LHR, DOOR	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X	nn
68760-20122	HINGE UPPER LHR, DOOR	0.00	\$81.70	0.00	\$0.00	Replace	Not Given	X	nn
68630-47031	CHECK ASSY, RR DOOR	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X	nn
75924-47020	TAPE OUT WIN FRAME LHR, DOOR	0.00	\$32.30	0.00	\$0.00	Replace	Not Given	X	nn
61602-47091	FENDER RR/LH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	R	
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	/	nee
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	/	nee
"52119-47930"	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair	R	
"52116-47040"	"BUMPER SUPPORT F/LH"	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X	nn
Total			\$8,801.90		\$1,505.53				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r}
 1505.53 \\
 + 750.00 \\
 + 1300.00 \\
 \hline
 3555.53
 \end{array}$$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: