

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0090/2019/PH
Date : 17-Jan-19

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Wong Chin Meng
Address : 6 Rivervale Link
#10-09
Singapore 545042
Telephone : Hp : +65 97359827
Type of Claim : Own Damage Claims
Policy No. : 1800024263
Vehicle No : **SLG 7486 G**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : Mar-18
Engine No : CVK 047895
Chassis No : WAUZZZF47JA051824
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 19-Jan-19
Place of Accident : Exit to Elemenceau Ave/Merchant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 7486 G

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 ✓
3	To respray front bumper, bonnet and hinges.	\$ 1,700.00 1100 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>4,352.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 7486 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>rehd</i>	\$	1,946.00 <i>1586.80</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	258.00 <i>x</i>
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 \$	64.00 <i>+</i>
4	FRONT BUMPER GRILLE - SATIN BLACK <i>new</i>	\$	178.00 <i>x</i>
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	191.00 <i>+</i>
6	FRONT BUMPER AIR GUIDE - LH/RH <i>new</i>	2 \$	112.00 <i>x</i>
7	RADIATOR GRILLE <i>Crushed</i>	\$	1,666.00 <i>1732.80</i>
8	AIR GUIDE GRILLE HIGH GLOSSY - LH/RH <i>new</i>	2 \$	666.00 <i>+</i>
9	FRONT BUMPER CARRIER <i>Bent</i>	\$	733.00 <i>? 586 ✓</i>
10	GUIDE SECTION - LH/RH <i>new</i>	2 \$	68.00 <i>x</i>
11	FRONT BUMPER BRACKET - LH <i>Bent</i>	\$	206.00 <i>? 165.70 ✓</i>
12	HEXAGON HEAD BOLT(COMBI) <i>new</i>	2 \$	26.00 <i>+</i>
13	FRONT BUMPER COVER <i>new</i>	\$	116.00 <i>? x</i>
14	FOAM FILLER PIECE <i>Crushed</i>	\$	113.00 <i>? 90.40 ✓</i>
15	BRACKET LOCK CARRIER <i>Crushed</i>	\$	125.00 <i>? 100 ✓</i>
16	LOCK CARRIER SUPPORT - LH/RH <i>new</i>	2 \$	52.00 <i>? x</i>
17	FRONT BONNET STRUT <i>new</i>	2 \$	217.00 <i>+</i>
18	STRIKER - LH/RH <i>new</i>	2 \$	92.00 <i>+</i>
19	LID LOCK <i>new</i>	2 \$	391.00 <i>+</i>
20	FLAT CONNECTOR HOUSING WITH CONTACT LOCK M <i>new</i>	2 \$	24.00 <i>+</i>
SUB SPARE PARTS		\$	7,244.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Bonnet Bent.

2554 ✓

Edge Protection *Na*

75 ✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 7486 G

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BOWDEN CABLE - CENTRE <i>Not m</i>	\$	53.00 <i>f</i>
22	BOWDEN CABLE <i>3 m</i>	\$	53.00 <i>f</i>
23	RELEASE LEVER <i>1 m</i>	\$	12.00 <i>f</i>
24	LED HEADLIGHT - LH <i>1 m</i>	\$	7,087.00 <i>f</i>
25	HEADLIGHT LIFT CYLINDER - LH <i>1 m</i>	\$	192.00 <i>f</i>
26	"CAUTION" STICKER <i>1 m</i>	\$	13.00 <i>X</i>
27	AIR GUIDE - LH/RH <i>2</i>	2 \$	50.00 <i>f</i>
28	AIR GUIDE - LH/RH <i>2</i>	2 \$	22.00 <i>f</i>
29	AIR GUIDE - UPPER <i>1</i>	\$	15.00 <i>f</i>
30	AIR GUIDE - LOWER <i>1</i>	\$	20.00 <i>f</i>
31	FRONT NUMBER PLATE <i>Best</i>	S/N \$	25.00 <i>f</i>
32	SUNDRIES <i>1 m</i>	\$	500.00 <i>X</i>
TOTAL SPARE PARTS		:	\$ 15,286.00 <i>17915</i>
TOTAL LABOUR CHARGES		:	\$ 4,352.00
GRAND TOTAL		:	\$ 19,638.00 <i>2267</i>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 22/01/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS Pays.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant