

ASS. REC. BY:

REF:

Tm1 /

CC3/Tm19001487/Ksd3

n2

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 1/2 days

Res.: Yes or No

Lum Sum:

1.41 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140 5005m

Yr Regn:

07, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perseus Longitude c.c 1995

Colour:

M. White / Red

A/C: Insured / Std / NI / NA

Sp. Reading

147976

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VI-1/ABL15/AUG 283485

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

18/1/19

D.O.A.

22/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S / Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/1

File pass to CA

S140 5005m - CC3/Tm19001487/Ksd3

SME 48175 - X

24-201018

23/1/2019 @ 1:00pm Sent GIA Report and estimate via email to tokio

1/1 @ 5,108.64 @ 2.5 days

( @ 23,975.21 Red - 82% )

RECEIVED 12 FEB 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

24/2/20

☒

: Final Report

Date/Time, File Return to?

Days Of Repair:

2.5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

Fuel:

Others:

11

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

261

Report Format:

Lump Sum (I.B.): (\$

5,108.64 p/p

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Wednesday, 23 January 2019 1:17 PM  
**To:** 'Motor Claims'  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 18/01/2019, SHD 5005M (TP VEHICLE), SME 4812S (OI VEHICLE)  
**Attachments:** ESTIMATE SHD 5005M.pdf; GIA SHD 5005M.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 5005M M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63, SINGAPORE 569111 on 22/1/2019

Enclosed herewith a copy of TP's GIA report, police report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Shirley Hiew (LKK Auto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Wednesday, 12 February 2020 10:57 am  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** SUR  
**Subject:** FW: TCS REF: AAD1901-191--Accident involving SHD 5005M & SME 4812S on 18/01/2019  
**Attachments:** ESTIMATE MARKED.pdf

Without Prejudice

Morning Shirley

Amount confirmed \$ 5,108.64 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Wednesday, 12 February, 2020 10:33 AM  
**To:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: TCS REF: AAD1901-191--Accident involving SHD 5005M & SME 4812S on 18/01/2019

Dear Wai Yin,

Please confirm final fig \$ 5,108.64 @ 2.5 days of repairs before GST.

Thank you.  
Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3878K
<b>Vehicle Details</b>	
Vehicle No.:	SHD5005M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003412
Chassis No.:	VF1ABL15AUC283485
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Jul 2017
First Registration Date:	03 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Jul 2025
PARF Rebate Amount:	\$14,998.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	02 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
<b>Total Rebate Amount:</b>	<b>\$45,846.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	
The information contained herein is correct as at 21 Jan 2019	

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/01/2019 13:18
Date Of Accident	18/01/2019 22:25
Exact Location Of Accident	UPPER PICKERING STREET TOWARDS SOUTH BRIDGE ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD5005M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
<b>Vehicle Particulars</b>	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
<b>Driver</b>	
Name of Driver	NG KIM SENG
NRIC No	S0178556G
Date Of Birth	21/11/1954
Occupation	OUTDOOR
Date Of Driving Pass	10/08/1983
Driving Experience	35 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90107580
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 144 SERANGOON NORTH AVENUE 1 #11-373
Postcode	550144
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 18.01.2019 at about 2225hrs, I was stationary on the second lane along Upper Pickering Street. When the traffic light turned green, I slowly made a right turn towards South Bridge Road. Suddenly I felt an impact. Vehicle B (SME4812S) which was travelling on my left and hit onto my taxi left side portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME4812S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LO JIAN HAO
NRIC/Passport Number	S9430509H
Contact Number	86133381
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)



**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach CIA report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Aminda

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5005M****AAD1901-191***Not written**Assembly B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 5005M**

VF1ABL15AUC283485

RENAULT

LATITUDE

18.1.2019

**TOKIO MARINE**

3/7/2017

**PART****LIST**

1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT LH
1	BUMPER SUPPORT FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE LH
1	BUMPER BEAM FRT
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	FENDER BRACKET LOWER LH
1	FENDER INSULATOR LH
1	DOOR PANEL FRT LH
1	RADIATOR GRILLE
1	RADIATOR GRILLE BADGE 'RENAULT'
1	RADIATOR GRILLE FRAME
1	RADIATOR FAN COWLING
1	RADIATOR FAN MOTOR LH
1	RADIATOR FAN MOTOR RH
1	RADIATOR GRILLE FRAME
1	FRAME FULL SUPPORT PANEL
1	FRAME FULL SUPPORT BRACKET
1	AIR CLEANER BOX
1	AIR CLEANER HOSE

\$	<i>Bul</i> 1,259.42 ✓
\$	<i>SL</i> 181.75 X
\$	<i>SL</i> 394.68 X
\$	<i>D.I</i> 151.41 ✓
\$	<i>SL</i> 123.88 X
\$	<i>SL</i> 150.77 X
\$	<i>SL</i> 123.88 X
\$	<i>SL</i> 472.83 X
\$	<i>SL</i> 266.80 X
\$	<i>SL</i> 207.21 X
\$	<i>R</i> 914.08 X
\$	<i>my</i> 1,184.43 ✓
\$	<i>R</i> 152.15 X
\$	<i>R</i> 783.83 ✓
\$	<i>CM</i> 278.84 ✓
\$	<i>SL</i> 15.79
\$	<i>SL</i> 130.84
\$	<i>R</i> 2,844.66
\$	<i>SL</i> 1,707.78
\$	<i>SL</i> 225.36
\$	<i>SL</i> 1,353.75
\$	<i>SL</i> 820.54
\$	<i>SL</i> 967.36
\$	<i>SL</i> 1,479.46
\$	<i>SL</i> 1,353.75
\$	<i>SL</i> 615.90
\$	<i>R</i> 89.79
\$	<i>SL</i> 464.20
\$	<i>SL</i> 175.85

X

**Trans-cab Auto Services Pte Ltd**

AAD1901-191

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5005M

1	LOWER ARM LH L70Y	\$	685.76	X
1	KUNCKLE ARM LH L70Y	\$	846.98	X
1	ABSORBER FRT LH L70Y	\$	360.54	X

<b>TOTAL</b>	<b>\$</b>	<b>20,784.28</b>
<b>10%</b>	<b>\$</b>	<b>2,078.43</b>
	<b>\$</b>	<b>18,705.85</b>

**Specical Nett**

1SET	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	X
1SET	WHEELARCH CLIP FRT RH	\$	30.50	✓
1	FRONT LEFT TYRE	\$	300.00	X
1	FRONT LEFT TYRE RIM	\$	380.00	✓
1	FRONT LEFT FENDER ADVERTISEMENT STICKER	\$	300.00	150.00
		<b>\$</b>	<b>1,288.00</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>19,993.85</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	4000
Putty and spray painting of the affected portion.	\$	3,000.00	6600
To rust-proofing of the affected areas.	\$	170.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1901-191

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5005M**

To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00	X
To replace, refix and top up coolant for radiator	\$	nn 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

**TOTAL \$ 9,090.00****Over All Total \$ 29,083.85****PART-BY-PART (REPAIR DAY)****10 DAYS***2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19001487/KSD3N2  
Date: 12/02/2020

### REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MT107688
Claimant Vehicle No :	SHD5005M	Insured Vehicle No :	SME4812S
Date of Loss:	18/01/2019	Nature of Claim:	TP
		Claim No:	M1900443

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5005M	Engine No:	M9R8839C003412
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC283485
Reg. Date:	03/07/2017 (Man. Year: 2016)	Odometer:	147976 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,993.84	3,918.64	16,075.20	80.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,090.00	1,190.00	7,900.00	86.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>29,083.84</b>	<b>5,108.64</b>	<b>23,975.20</b>	<b>82.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>2,035.87</b>	<b>357.60</b>	<b>1,678.27</b>	<b>82.44</b>
<b>Nett Amount (S\$)</b>	<b>31,119.71</b>	<b>5,466.24</b>	<b>25,653.47</b>	<b>82.43</b>

### INSPECTION

Date of Assignment:	23/01/2019	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
Date Inspected:	22/01/2019	Inspected At: 2, Ang Mo Kio Street 63
Estimated Period of Repair:	2.5 days	Singapore 569111

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2020)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHD5005M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER FRT	Buckled/Cracked	1,259.42 FL	-	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Serviceable	181.75 FL	-	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	-	*- FL
4	1		*BUMPER RETAINER FRT LH	Distorted	151.41 FL	-	*151.41 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	-	*- FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	150.77 FL	-	*- FL
7	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	-	*- FL
8	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	-	*- FL
9	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	-	*- FL
10	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	-	*- FL
11	1		*BUMPER BEAM FRT	Repair	914.08 FL	-	*- FL
12	1		*HEADLAMP LH	Mtg Cracked	1,184.43 FL	-	*1,184.43 FL
13	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	-	*- FL
14	1		*FENDER PANEL FRT LH	Bent	783.83 FL	-	*783.83 FL
15	1		*WHEELARCH FRT LH	Cracked	278.84 FL	-	*278.84 FL
16	1		*FENDER BRACKET COVER LH	Serviceable	15.79 FL	-	*- FL
17	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	-	*- FL
18	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	-	*- FL
19	1		*RADIATOR GRILLE	Serviceable	1,707.78 FL	-	*- FL
20	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	-	*- FL
21	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	-	*- FL
22	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	-	*- FL
23	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	-	*- FL
24	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	-	*- FL
25	1		*RADIATOR GRILLE FRAME	Serviceable	1,353.75 FL	-	*- FL
26	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	-	*- FL
27	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	-	*- FL
28	1		*AIR CLEANER BOX	Serviceable	464.20 FL	-	*- FL
29	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	-	*- FL
30	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	-	*- FL
31	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	-	*- FL
32	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	-	*- FL
33	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	-	*66.00 FS
34	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	-	*- FS
35	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	-	*- FS
36	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	-	*- FS
37	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	-	*- FS
38	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	-	*- FS
39	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	-	*- FS
40	1		*SET WHEELARCH CLIP FRT RH	Necessary	30.50 FS	-	*30.50 FS
41	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	-	*- FS
42	1		*FRONT LEFT TYRE RIM	Dented	380.00 FS	-	*380.00 FS
43	1		*FRONT LEFT FENDER ADVERTISEMENT STICKER	Necessary	300.00 FS	-	*150.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
				Sub Total (S\$)	22,072.27	4,284.43	
				- List Item Discount on L Items 10.00/10.00% (S\$)	2,078.43	365.79	
				Total Parts (S\$)	19,993.84		3,918.64

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,500.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	660.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
6	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	20.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
10	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
11	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER	New	170.00	0.00
12	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>9,090.00</b>	<b>1,190.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >