

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 JANUARY 2019

Third Party Insurer:

Vehicle No: SLZ9372M

Third Party Veh No: SKB7070K

Model: HONDA FIT 1.3GF CVT

Date of Accident: 22 JANUARY 20

Chassis: GK31314771 - 2018

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET	1		
2	FRONT BONNET INSULATOR	1		
3	FRONT BONNET LOCK	1		
4	FRONT UPPER PANEL	1		
5	FRONT UPPER PANEL COVER (TOP GARNISH)	1		
6	FRONT HEADLAMP LH	1		
7	FRONT HEADLAMP RH	1		
8	FRONT GRILLE	1		
9	FRONT GRILLE TOP CHROME MOULING	1		
10	FRONT GRILLE LOWER CHROME MOULING	1		
11	FRONT GRILLE EMBLEM	1		
12	FRONT GRILLE EMBLEM RETAINER GUIDE	1		
13	FRONT BUMPER	1		
14	FRONT BUMPER LOWER GRILLE	1		
15	FRONT BUMPER FIXING COVER (TOW HOOK)	1		
16	FRONT BUMPER SIDE GARNISH COVER UPPER RUBBER LH	1		
17	FRONT BUMPER SIDE GARNISH COVER UPPER RUBBER RH	1		
18	FRONT BUMPER UPPER SIDE RETAINER BRACKET LH(H/LAMP BRC	1		
19	FRONT BUMPER UPPER SIDE RETAINER BRACKET RH(H/LAMP BRC	1		
20	FRONT BUMPER SIDE BRACKET LH	1		
21	FRONT BUMPER SIDE BRACKET RH	1		
22	FRONT BUMPER REINFORCEMENT	1		
23	FRONT AIR CON CONDENSER	1		
24	FRONT DEFLECTOR COVER LH	1		
25	FRONT DEFLECTOR COVER RH	1		
26	FRONT FENDER LH	1		REPAIR
27	FRONT FENDER RH	1		REPAIR
SUB TOTAL				\$0.00
LESS 25%				\$0.00
PARTS TOTAL				\$0.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BONNET INSULATOR CLIPS	1 SET		\$35.00
2	FRONT GRILLE CLIPS	1 SET		\$40.00
3	FRONT BUMPER CLIPS	1 SET		\$50.00
4	FRONT NUMBER PLATE WITH CASING	1		\$50.00
S/N TOTAL				\$175.00

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 22 JANUARY 2019

Third Party Insurer:

Vehicle No: SLZ9372M

Third Party Veh No: SKB7070K

Model: HONDA FIT 1.3GF CVT

Date of Accident: 22 JANUARY 20

Chassis: GK31314771 - 2018

ESTIMATE

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$1,000.00 ?

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$1,000.00 809

TO TUFF KOTE / ANTI-RUST

\$80.00 301

TO DISMANTLE & REPLACED AIRCON SYSTEM, VACUUM WITH FLUSHING/REFILL AIRCON GAS/OIL

\$150.00 ?

TO CHECK WIRING AND WATER LEAK TEST

\$60.00 201

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD

\$150.00 ?

LABOUR TOTAL \$2,440.00

ONG

TOTAL \$2,615.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: