dello, NAC_PAYA_UBI_80	0601									Gener	alClaim
My Desktop Notice of Loss	Polic	y Query					• Chang	e Langua	ge • Cha	nge Password	· Log Ou
	Policy N Vehicle I	o. No.(For Motor)	SLM61	6М			of Accident		21/01/2019	11:00	· ·
					1	Search					
	Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence	Expiry Date
	0	5099600017		TAN MENG LIANG	S8032021C	GPC	drivo CLASSIC	SLM616M		Date 20/04/2018	19/04/2019

TP Claims against NTUC Income: Follow-Through Survey

Date: 6/3/2019

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1028852-002	SMRT TAXIS PTE LTD	SHF 434E	SLM 616M	21/1/2019	9:20	\$ 7,690.88	\$ 2,250.00

Shirley Hiew (LKK Auto)

From:

Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) <YeoPohsuan@smrt.com.sg>

Sent:

Monday, 4 March 2019 11:49 AM

To: Cc: Hwee Jie (LKK Auto) Shirley Hiew (LKK Auto)

Subject:

RE: SHF434E

Hi,

Amount confirmed as per your recommendation, thanks.

Regards Poh Suan

----Original Message-----

From: Hwee Jie (LKK Auto) [mailto:hweejie@lkkauto.com]

Sent: Monday, 4 March 2019 11:30 AM

To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Cc: Shirley Hiew (LKK Auto) Subject: RE: SHF434E

Hi poh suan,

Finalized L/S \$2,250/- 4days.

Best Regards,

Hwee Jie | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9180 3151 | Email: Hweejie@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,

#02-25 | S(408933)

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]

Sent: Wednesday, 27 February, 2019 5:33 PM

To: Hwee Jie (LKK Auto)

Cc: SUR; CS A Team; Leong Chee Kwong

Subject: SHF434E

Hi Hwee Jie,

Attached herewith the repair estimate of SHF 434E having Case No: TAX/01/19/2103.

There is no change to the approved amount of \$2,250 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards Poh Suan

----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Sent: Wednesday, 27 February 2019 5:00 PM To: Yeo Poh Suan (Auto Svcs/ARC/AR & SC/Taxis)

Subject: Scan Data from FX-D421D6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

建设的现在分词,是是不是一个一个	ACCIDENT STATEMENT
Date Of Report	21/01/2019 13:27
Date Of Accident	21/01/2019 09:20
Exact Location Of Accident	JALAN SULTAN
Country/State of Loss	SINGAPORE
美術學學科學科學科學科學	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHF434E
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
Driver	
Name of Driver	CHEE KHENG HOCK
NRIC No	S2012799F
Date Of Birth	02/07/1952
Occupation	OUTDOOR
Date Of Driving Pass	01/01/2000
Driving Experience	19 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	

NOEMAIL

Address

503

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

NO

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

110

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: UNKNOWN

GENDER:

: FEMALE

Passenger 2

NAME:

: UNKNOWN

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG JALAN SULTAN AT THE CENTRE LANE WHEN THE VEHICLE SLM616M DASHED OUT FROM MINTO ROAD AND CUT ACROSS INTO MY LANE. AS A RESULT, ITS RIGHT REAR PORTION COLLIDED WITH THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLM616M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

0 514 RT

Policyholder's Signature Date & Time: 8

Driver's Signature (If driver is not the policyholder) Date & Time: ala 2/1/2/9

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Sketch Plan Pg. 2

KETCH PLAN				
		7		
	MINTO RD			
	→ -1			
	<u> </u>			
A-SHF434 B-SLM 611	E	h		
SIM 616	iM A		11111	1
CONTRACTOR		JALAN SU	TAA!	
ESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT	JACAN JUL		
			Е.	
CLARATION S				
e declare the foregoing part	iculars are true in every respect.			
(-()-)	6		./	2/1/2019
1 51Kay			ali	и ((("))
cyholder's Signature	Driver's Signature	Repo	rting Centre Personne	's Signature
e & Time:	(If driver is not the policyhold Date & Time: 21/12/1	er) Name NRIC,		



Case Details

Case Reference Number: TAX/01/19/2103

Type of Repair : Accident Repair

Vehicle Registration Number : SHF434E

Company Type : SMRT Taxis Pte Ltd Estimation ID : EST-5442-ID

Assigned By: Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time: 21/01/2019 01:20 AM Vehicle Age(In Months): 61

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

nour		2011	12000 10 00	SMRT Reco								3	Surveyor Approval		
BOM Type	Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	542.55	Replace *		BU
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace *		NÉ
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give ▼		
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Not Give *		
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair ▼		
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give ▼		
One Time Key n	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	361,50	Replace •		pp
One Time Key	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give ▼		
One Time Key	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give *		
ime iey	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give *		
ime ey	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check ▼		

Total Spare Part Cost 5,029.88

Surveyor Total 1,793.65

Lump Sum Discount (%) 20.00

Lump Sum Dis (%)

Final Spare Part Cost 4,023.90

Final Sur Total 1,434.92

				SMRT Reco	mmend	dation						s	urveyor Approve	of .	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(S)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replac		
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give		
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10,00	850.68	Replace	1	850.68	Replace		ě
One Time Key In	Main			SUPPORT SUB- ASSY	1	1,460.40	1,460.40	25.00	1,095.30	Replace	0	0	Not Give		
						Т	otal Spare P	art Cost	5,029.88		S	Surveyor Total	1,793.65		
						Lump	Sum Disc	ount (%)	20.00		Lump	Sum Dis (%)	20		
						Fi	nal Spare P	art Cost	4,023.90		F	inal Sur Total	1,434.92		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	450	
Total:			845.00	450.00	

Spray Cost Detail

Vo.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER LH	378.00	200	
	Main	TO RESPRAY RIM	180.00	50	
i	Main	TO REPSRAY FRONT BUMPER	378.00	200	
	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
al:			1,116.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
5	Main	TO REMOVE AND REFIT TYRE	120.00	0	

•		٠			
ı	О	4	а	ı	

12				https://vacsweb	.smrt.com.sg/	Estimation.aspx
3	S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor	Remarks
	6.	Main	TO WASH AND VACUUM	60.00	0	
	7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
	Total:			700.00	140.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,023.90	1,434.92
Total Labour Cost	845.00	450.00
Total Spray Painting	1,116.00	450.00
Other	700.00	140.00
Overali Total	6,684,90	2,474.92
Lump Sum Repair Option	× .	*
Lump Sum Total	6,700.00	2.450.00
Surveyor Approved Amount		2,450.00
No of Repair Days*	5	4
Remarks	*	L/S repair, photo after paint.
Surveyor Name		Hwee jie
Signature		73/1/9
		Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- * Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date




SMRT Accident Vehicle Repair Estimates


SMRT Automotive Services Pie Lid 80 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592 Estimator Telephone Number : 68652623 Accident Reporting Number : 65652672

Date Generaled : 27/02/2013 : PohBuan

9

	Section A - Accident Details
Registration Number	SHF434E
Case Reference Number	TAX/01/19/2103
Registration Date	20/12/2013
Company Type	SMRT Taxis Pte Ltd
Make	ТОУОТА
Model	PRIUS
Name of Driver	CHEE KHENG HOCK
Type of Accident	Side Swipe
Accident Date and Time	21/1/2019 9:20 AM
Accident Reported Date and Time	21/1/2019 1:29 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24099772
Special Instruction to ARC, if any	TP
Prepared Date and Time	22/1/2019 9:16 AM
Chassis Number	
Mileage	
Vork Shop	
Repair Completion Date and	





hytekis

Summary of Repair Estimate	15	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$450,00
Total Spray Cost	\$1,116.00	\$450.00
Total Spare Part Cost	\$5,029.88	\$1,793.66
Total Other Cost	\$700.00	(\$443.66)
TOTAL COST	\$7,690.88	\$2,250.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Zhi Yang Phua	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	22/01/2019 6:38 PM	22/01/2019 4:10 PM
Signature		0
Remarks		L/S repair, photo after paint.
	2	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 63685592
Estimator Telephone Number: 68652823
Accident Reporting Number: 68652672

Date Generated: 27/02/2019 : PohSusn

ENN'S LINE	Section C - Quota	tion and Accident Invoice Details	usiding.
Quotation Number	QN-1902-0188	Invoice Number	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Quotation Date	18.02.2019	Invoice Date	
Invoice Amount		Prepared Date	y

	Section D - Details of Repair Estimates	
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$450.00
Total Labour	\$845.00	\$450.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,116.00	\$450.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, i applicable		
ump Sum Adjustment by Surveyor	\$0.00	(\$583.66)		
O APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00		
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00		
O DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60,00		
O REMOVE AND REFIT TYRE	\$120.00	\$0.00		
O REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00		
O REPLACE SUNDRY PARTS	\$100.00	\$0.00		
TO WASH AND VACUUM	\$60.00	\$0.00		
Fotal Other Costs	\$700.00	(\$443.66)		

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price	Estimator Approved	Surveyor
	NN	53852- 47020	FENDER LINER PAD, FR WHEEL. LH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given X
	OEF	52119- 47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace /
	nn	52611- 47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given X
	nn	57014- 47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given X
	nu	52021- 47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given
	nn	52115- 47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
	SCR	81170- 47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace
	nn	53201- 47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Not Given X
	nec	75374- 47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace /
	N.W		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685502 Estimator Telephone Number : 68685023

Accident Reporting Number 68862572

Date Generated : 27/02/2019 User ID : PohSuan

	hn	52116- 47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0,00	\$0.00	Replace	Check X
	Buc	53802- 47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace
	Repair	42611- 47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair /
	h'n	53876- 47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given
Total					\$6,475.24		\$1,793.66	1	

			ge After Surveyor Signed off			est and a bus			
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price	ARC Check	Surveyor Check
Total						1	1.54		-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

1793.66 + 590.00 + 590.00 - 20% - 20% - 20% - 20% - 20% - 20% - 20% - 20%

9136-24

4/3/19-Rimliced U/5 \$2250/- 4days.

2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTU	C INCOME INSUF	RANCE CO-OPERATIVE LTD	Ref:	NS/INC1900149	1/Jsd3e2
		D UNION HOUSESINGAPORE	Date:	07-03-2019 INC4	
1.	11.07	Policy Particulars			
	Insured Veh.	SLM 616M	_	nspected	SHF 434E
	Policy No.	5099600017	_	age (\$)	0.00
	Claim No.	MT/1028852-002	Exces		0.00
	Assign From		_	n Date	22/01/2019
2.		Vehicle Parti			
	Make & Model	TOYOTA PRIUS	c.c		1798
	Engine No.	HIDDEN	3.00	of Reg.	2013
	Chassis No.	JTDKN36U005719113	Colou	r	MAROON
	Odometer	538942	Steeri	ng	IN ORDER
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM
	General	GOOD			
3.		Conditi	ons of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	FALKE	N	6 mm
	L/H Front Tyre	195/65 R15	FALKE	N	6 mm
	R/H Rear Tyre	195/65 R15	FALKE	N	6 mm
	L/H Rear Tyre	195/65 R15	FALKE	N	6 mm
4.		Description	on of Da	amages	
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	BODY.		
	DAMAGES SEE D	ETAILS.			
5.		Genera	l Inform	ation	THE PERSON NAMED IN
	Accident Date	21/01/2019	Inspec	ction Date	22/01/2019
	Survey held at	SMRT AUTOMOTIVE SERVICE	S PTE L	TD	
		60 WOODLANDS INDUSTRIAL	PARK E	4 SINGAPORE 7577	705
5a.			emarks	CONTRACTOR OF STREET	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W			
5b.		Estimate			
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		4 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 434E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	FENDER FRT / LH (DISC 25%)	BUCKLED	723.40	542.55
1	HEAD LAMP LH (DISC 10%)	SCRATCHED	945.20	850.68
1	FENDER LINER PAD, FR WHEEL. LH	NOT NECESSARY	49.30	,
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	,
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	,
1	TYRE	NOT NECESSARY	126.74	,
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	,
1	FENDER LINER FRT/LH	NOT NECESSARY	171.70	,
1	WHEEL DISC.FRONT	TO REPAIR SEE LABOUR	1,484.20	
			6,475.24	1,793.66
	LABOUR			
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF WHEEL DISC. FRONT.		845.00	450.00
	SPRAY PAINT.		1,116.00	450.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.		120.00	60.00
	TO REMOVE AND REFIT TYRE.	NOT NECESSARY	120.00	
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	
			2,661.00	1,040.00
	GRAND TOTAL		9,136.24	2,833.66

Report Ref No. NS/INC19001491/Jsd3e2





RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)

2,250.00

Report Ref No. NS/INC19001491/Jsd3e2

ONG HWEE JIE

Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.