

ASS. SEC. BY:

REP:

es/CTI19001499/Ktd3

Special Instruction:

Surveyor: Kenneth Meinen

ASSIGNMENT (Office)

From (Person): Irene Tay

of CTI

Date/Time: 23/1/19 @ 11:50am

Estimated Cost:

Bill to:

OD  WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD1271C

Insured:

3LE 4323Z

at Workshop m/s:

C.S. Ong Auto

Tel:

6484 1933

of

10 Amk Ind. park 2A # 02-16

Policy No:

DMPCSN16485118022

Claim No:

8NM19D200353C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/01/2019

CA / REV / REP. / REV 24 HRS

hup

H.O.D. Endorsement:

Date/Time:

1230pm @ 23/1/19

Person Contacted:

Ms. Ong

Vehicle:

IN  OUT

Date/Time

Action/Instruction (✓) Estimate

SMD1271C-X

3LE 4323Z - CS3/MSG19001261/Gtd3

DoA: 18/1/19

lump sum \$3550/- Cred: 5380.17, 62%

ASS. REC. BY:

REF: C711

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OO / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_ C Sony

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 20% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMD 7271C Yr Regn: 00, 09

Type:  Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toy Bush cc 1495

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 129260 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: J200E . 0027080

Gen. Cond:  Good /  Fair /  Poor /  Burnt

Steering:  In order /  Jammed /  Leaked /  Burnt or

Brake:  In order /  Jammed /  Leaked /  Burnt or

Modf: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/65R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 18/1/19

Survey held at

Des. of Damages: Frt  Rear /  O/S /  N/S /  UIC /  Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 30 APR 2019

Date / Time	Action / Instruction
24/1	File pass to Car

Date/Time, File Pass to?  : Prell. Report  : Final Report

Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 4 Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$ )  Interview (\$ )  Tech Invs (\$ )  Weekend (\$ )

Survey Fee:
Transportation:
S - RS - SI
Fluorid
Others
TOTAL

Report Format: TP Lump Sum / I.B.I: (\$ 3550)

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Arch'ed	Status
Main	23 Jan 2019		23 Jan 2019 13:56 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant:	<b>LUXURIE LEASING PTE LTD</b>								
Vehicle Reg. No.:	<b>SMD1271C</b>	Date of Loss:	18/01/2019 09:00 - :59						
Claim Type:	<b>TP / SNM19D200353C02</b>	Policy/Cover Note No.:	DMPCSN16485118022						
Vehicle Reg. No. (Insured):	<b>SLE4323Z</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>C.s Ong Auto Pte Ltd (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #02-16 AMK AUTOPOINT, 56804 Ang Mo Kio - Tel:</b>								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</b>								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/02/2019]</b>								
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## **Nivitha (LKK Auto)**

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Wednesday, 23 January 2019 11:50 AM  
**To:** 'C. S. ONG AUTO PTE. LTD.'  
**Cc:** assignments; Admin A  
**Subject:** CTP REF NO. SNM19D200353C02 CS REF NO. SMD1271C - ACCIDENT INVOLVING SLE4323Z AND SMD1271C ON 18 JANUARY 2019  
**Attachments:** CS ONG WKSHP.pdf

### **WITHOUT PREJUDICE**

Dear Sir/Mdm,

We refer to the above matter and our telephone conversation a moment ago.

We will appoint LKK to conduct PRS.

Aside to LKK;

Please assist to liaise with C.S.ONG Auto Pte Ltd.

Thank you.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Direct (65) 6389 6192  
Fax (65) 62247478/62247175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

Ng Li Wah

SNM19D200353

(3)

PR S  
ARR

**From:** C. S. ONG AUTO PTE. LTD. <csongauto@yahoo.com.sg>  
**Sent:** Monday, January 21, 2019 9:58 AM  
**To:** Claims Dept of CTI  
**Subject:** Direct Settlement - SMD1271C  
**Attachments:** csongauto@starhub.net.sg\_20190121\_090846.pdf

Dear Sir / Madam,

T11754

Kindly arrange for PRS to be conducted the soonest, refer to attachment, thank you.

*Warmest Regards,*

**C. S. ONG AUTO PTE. LTD.**

Blk 10, Ang Mo Kio Ind Park 2A,  
#02-16 AMK AutoPoint, Singapore 568047  
Tel: 6484 1933 | Fax: 6484 1922  
E-Mail: csongauto@yahoo.com.sg

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

21 JAN 2019

## **C. S. ONG AUTO PTE. LTD.**

Business Reg. No. 201408619W  
10, Ang Mo Kio Ind. Park 2A, #02-16 AMK AutoPoint, Singapore (568047)  
Tel: 6484 1933 Fax: 6484 1922  
E-Mail: csongauto@yahoo.com.sg

### **NOTICE OF ACCIDENT**

To: Motor Claims Department (Do Direct Settlement)

**China Taiping Insurance (Singapore) Pte Ltd**

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Email: claimsdept@sg.cntaiping.com

Fax: 6222 1033

Dear Sir/ Madam,

We are instructed by our client to notify you of a road traffic accident on 18/01/2019 at about 0915hrs at LOYANG AVE

Involving our client's vehicle registration number SMD1271C and vehicle registration number SLE4323Z driven by you or your authorised driver at the material time.

A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of Workshop: **C. S. Ong Auto Pte Ltd**

Address: 10, Ang Mo Kio Industrial Park 2A  
AMK Autopoint #02-16  
Singapore (568047)

Telephone: 6484 1933

Fax: 6484 1922

Yours Faithfully,

C. S. ONG AUTO PTE LTD

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/01/2019 15:59
Date Of Accident	18/01/2019 09:15
Exact Location Of Accident	LOYANG AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD1271C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LUXURIE LEASING PTE LTD
Co Reg No	201707840K
Email Address	LUXURIELEASING@YAHOO.COM
Mobile Phone No	
Alternative Phone No	OFFICE-96988882

### Vehicle Particulars

Manufacturer	TOYOTA
Model	RUSH-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	DRIVING GO-JEK (PTE HIRE)
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090040257-01
Cover Note Number	08/08/2018 - 07/08/2019

### Driver

Name of Driver	SIM BO HAN
NRIC No	S8520309F
Date Of Birth	25/06/1985
Occupation	OUTDOOR
Date Of Driving Pass	22/04/2015
Driving Experience	3 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87885558
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

No. Of Passenger (Including Driver) 1

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBC1159E  
Vehicle Make/Model/Colour CITROEN BERLINGO  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver ASHOKKUMAR RUTHIRAPATHY  
NRIC/Passport Number 032100004  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage

No. Of Passenger (Including Driver) 2

Passenger 1  
NAME: :  
GENDER: :

#### DETAILS OF INJURED PERSON 1

Name SIM BO HAN KEN  
Approximate Age  
Injuries Sustain 4 DAYS MC  
Injured person in which vehicle? SMD1271C  
Were seat belts worn?  
Was this injured conveyed to hospital by ambulance?  
Address  
Postcode



## Sketch Plan #4



**SINGAPORE  
POLICE FORCE**



T/20190118/7012

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4

Report No. T/20190118/7012

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ashokkumar ruthirapathy	ID No.	0 3210004-
Related Vehicle	GBC1159E (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	sheril nadia binte isandar	ID No.	S9005651D
Related Vehicle	SLE4323Z (Car)	Contact No.	92767216
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	SIM BO HAN, KEN	ID No.	S8520309F
Related Vehicle	SMD1271C (Car)	Contact No.	87885558
Hospital/Clinic	SENGKANG GENERAL HOSPITAL PTE. LTD.	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	18/01/2019	Date Discharge	18/01/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

## Brief Details.

18/01/2019 - 0915Hrs i was travelling along loyang ave in the 2nd lane.  
The traffic ahead was slow and i slowed down, suddenly i felt an impact from my rear of my vehicle, hence i got off and realized that it was a 3 car collision with me being the first vehicle (SMD1271C) center vehicle (SLE4323Z) last vehicle (GBC1159E).  
After which i felt pain on my left hip and i went to sengkang general hospital and did a check up with xray and was referred to a specialist.  
i was given a 4 days medical leave 18/01/2019 - 21/01/2019

Sketch Plan #6



**SINGAPORE  
POLICE FORCE**



T/20190118/7012

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

4 of 4

Report No. T/20190118/7012

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Signature Of Interpreter:  
Not applicable

Date/Time:  
18/01/2019 15:37

Officer In Charge Of Case:  
TP / TPIB /  
MOHAMAD ZULFAZDLI BIN ABDULLAH  
Contact No.: 65476204

Classification Of Case:

Authentication Stamp  
NP168

Not Authorized  
 61 Day @ 355dp  
 Presumably After Paint  
 4- days

## C. S. ONG AUTO PTE. LTD.

Business Reg No.: 201408916W  
 GST Reg No.: 201408916W  
 10, Ang Mo Kio Ind. Park 2A, #02-16, AMK Autopoint, Singapore (568047).  
 Tel: 6484 1933 Fax: 6484 1922  
 E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,  
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Date: 19/01/2019

Accident Involving Vehicles SMD1271C & SLE4323Z [Your Insured] on 18/01/2019 @  
 0915Hrs along LOYANG AVENUE

### Estimated Repair Costs For SMD1271C [Toyota Rush]

J200E0027080

<u>Qty</u>	<u>Parts</u>	<u>Amount</u>
1Pc	Rear Tail Gate	Rt \$ 1,189.00 ✓
2Pcs	Rear Tail Gate Rubber Stopper @ \$10.20 Each	ln \$ 20.40 X
2Pcs	Rear Tail Gate Upper & Lower Hinges @ \$140.96 Each	\$ n 281.92 ✓
1Pc	Rear Tail Gate Inner Weatherstrip Rubber Photo Attached	ln \$ 316.60 X
1Pc	Rear Tailgate Inner Lock	\$ n 148.96 ✓
1Pc	Rear Tailgate Inner Trim Board	\$ n 469.85 X
1Set	Rear Tailgate Inner Trim Board Clips	\$ n 35.00 X
1Pc	Rear Spare Tyre Inner Holder Garnish. photo Attached	\$ n 405.80 ✓
1Pc	Rear Spare Tyre Cover	CM \$ 1,536.10 ✓
1Pc	Rear Bumper	Bca \$ 780.20 ✓
1Set	Rear Bumper Clips	\$ n 35.00 ✓
2Pcs	Rear Bumper Side Retainer @ \$41.58 Each	ln \$ 83.16 X
2Pcs	Rear Bumper RH & LH Reflector @ \$50.19 each	\$ n 100.38 X
1Pc	Rear End Panel	\$ n 268.94 X
1Set	Rear End Panel Inner Top Trim Garnish with Clips	\$ n 128.92 ✓
	Parts Sum:	\$ 5,800.23
	Parts Less 25%:	\$ 1,450.06
	Parts Total:	\$ 4,350.17
<u>Special Nett. Items</u>		
1Set	Rear Number Plate with Holder	\$ ln 80.00 X
1Set	Rear End Panel Sealants	n n \$ 100.00 X
1Pc	Rear Reverse Camera	\$ ln 400.00 X
2Pcs	Rear Reverse Sensor @ \$150.00 Each	\$ ln 300.00 X
	Special Nett. Items Total:	\$ 880.00

**Labour & MISC Charges**

<b><u>Description</u></b>	<b><u>Amount</u></b>
* To remove and replace rear windscreen to facilitate repair	\$ 200.00 <i>1201</i>
* To remove rear interior upholstery items to facilitate repair.	<i>no</i> \$ 300.00 <i>2</i>
* To cut & remove all rear damaged panels, replace new parts, refit and to realign all of the above items	\$ 1,500.00 <i>5001</i>
* To putty & re-spray new paintwork on all rear affected areas.	\$ 1,500.00 <i>8001</i>
* To conduct a check on all wiring systems.	\$ 200.00 <i>201</i>
* To replace and refit rear reverse sensors on new rear bumper.	\$ 200.00 <i>501</i>
* To anti rust all affected areas.	\$ 300.00 <i>301</i>
<b>Labour &amp; Charges Total:</b>	\$ 4,200.00
<b>Parts Total:</b>	\$ 4,350.17
<b>Special Nett. Items Total:</b>	\$ 880.00
<b>Labour &amp; Charges Total:</b>	\$ 4,200.00
<b>Total Cost of Repair:</b>	\$ 9,430.17
<b>(Non inclusive of 7% GST)</b>	

Not Notation  
 1/1 Day B?  
 Pre-Work After Pain  
 4-5 days

# C. S. ONG AUTO PTE. LTD.

Business Reg No.: 201408916W  
 GST Reg No.: 201408916W  
 10, Ang Mo Kio Ind. Park 2A, #02-16, AMK Autopoint, Singapore (568047).  
 Tel: 6484 1933 Fax: 6484 1922  
 E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,  
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Date: 19/01/2019

Accident Involving Vehicles SMD1271C & SLE4323Z [Your Insured] on 18/01/2019 @  
 0915Hrs along LOYANG AVENUE

## Estimated Repair Costs For SMD1271C [Toyota Rush]

**J200E0027080**

<u>Qty</u>	<u>Parts</u>	<u>Amount</u>
1Pc	Rear Tail Gate	B <sub>1</sub> \$ 1,189.00 ✓
2Pcs	Rear Tail Gate Rubber Stopper @ \$10.20 Each	In \$ 20.40 X
2Pcs	Rear Tail Gate Upper & Lower Hinges @ \$140.96 Each	\$ <sup>n</sup> 281.92 A
1Pc	Rear Tail Gate Inner Weatherstrip Rubber	\$ 316.60 ?
1Pc	Rear Tailgate Inner Lock	\$ <sup>n</sup> 148.96 A
1Pc	Rear Tailgate Inner Trim Board	\$ 469.85 ?
1Set	Rear Tailgate Inner Trim Board Clips	\$ 35.00 ?
1Pc	Rear Spare Tyre Inner Holder	\$ 405.80 ?
1Pc	Rear Spare Tyre Cover	CM \$ 1,536.10 ✓
1Pc	Rear Bumper	B <sub>2</sub> \$ 780.20 ✓
1Set	Rear Bumper Clips	\$ <sup>n</sup> 35.00 ✓
2Pcs	Rear Bumper Side Retainer @ \$41.58 Each	In \$ 83.16 X
2Pcs	Rear Bumper RH & LH Reflector @ \$50.19 each	\$ <sup>n</sup> 100.38 X
1Pc	Rear End Panel	\$ 268.94 ?
1Set	Rear End Panel Inner Top Trim Garnish with Clips	\$ <sup>n</sup> 128.92 A
	Parts Sum:	\$ 5,800.23
	Parts Less 25%:	\$ 1,450.06
	Parts Total:	\$ 4,350.17
<u>Special Nett. Items</u>		
1Set	Rear Number Plate with Holder	\$ In 80.00 X
1Set	Rear End Panel Sealants	\$ 100.00 ?
1Pc	Rear Reverse Camera	\$ In 400.00 X
2Pcs	Rear Reverse Sensor @ \$150.00 Each	\$ In 300.00 X
	<b>Special Nett. Items Total:</b>	\$ 880.00

LKK Auto Consultants hereby notify  
 the Repairer of the following:  
 • To display damaged part(s) during recovery  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be authorised (int)  
 is subject to final approval from Insurance Company

Acknowledged by: \_\_\_\_\_  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

**Labour & MISC Charges**

<b><u>Description</u></b>	<b><u>Amount</u></b>
* To remove and replace rear windscreen to facilitate repair	\$ 200.00 <i>1201</i>
* To remove rear interior upholstery items to facilitate repair.	\$ 300.00 <i>?</i>
* To cut & remove all rear damaged panels, replace new parts, refit and to realign all of the above items	\$ 1,500.00 <i>?</i>
* To putty & re-spray new paintwork on all rear affected areas.	\$ 1,500.00 <i>8001</i>
* To conduct a check on all wiring systems.	\$ 200.00 <i>201</i>
* To replace and refit rear reverse sensors on new rear bumper.	\$ 200.00 <i>501</i>
* To anti rust all affected areas.	\$ 300.00 <i>?</i>
<b>Labour &amp; Charges Total:</b>	\$ 4,200.00
<b>Parts Total:</b>	\$ 4,350.17
<b>Special Nett. Items Total:</b>	\$ 880.00
<b>Labour &amp; Charges Total:</b>	\$ 4,200.00
<b>Total Cost of Repair:</b>	\$ 9,430.17
<b>(Non inclusive of 7% GST)</b>	

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2019		23 Jan 2019 13:56 <a href="#">Edit Adj Rpt</a>	<b>\$43,550.00</b> <a href="#">Edit Estimates</a>	<b>\$43,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, ID: -								
Main Claimant:	<b>LUXURIE LEASING PTE LTD</b>								
Vehicle Reg. No.:	<b>SMD1271C</b>	Date of Loss:	18/01/2019 09:00 - :59 [113 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D200353C02</b>	Policy/Cover Note No.:	DMPCSN16485118022						
Vehicle Reg. No. (Insured):	<b>SLE4323Z</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>C.s Ong Auto Pte Ltd (HQ)</b> 10 ANG MO KIO INDUSTRIAL PARK 2A, #02-16 AMK AUTOPOINT, 56804 Ang Mo Kio - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 01/02/2019]								
Adj Atg. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SMD1271C (SNM19D200353C02)  
[SLE4323Z]  
TP  
LUXURIE LEASING PTE LTD  
Jan 18 2019 9:00AM  
[-]  
C.s Ong Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
2	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
3	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
4	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
5	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
6	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
7	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
8	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
9	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
10	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
11	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
12	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
13	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
14	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
15	30/04/19 09:35	General View		Load JPG	<input checked="" type="checkbox"/>						
16	30/04/19 09:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
17	30/04/19 09:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
18	30/04/19 09:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
19	30/04/19 09:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						
20	30/04/19 09:36	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>						

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119001499/KTD3Q2

**Date:** 06/05/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN16485118022	
Claimant Vehicle No: SMD1271C	Insured Vehicle No: SLE4323Z	
Date of Loss: 18/01/2019	Nature of Claim: TP	Claim No: SNM19D200353C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD1271C	
Make & Model:	TOYOTA RUSH, 1.5 X (A)	Engine No: 3SZ2313865
Reg. Date:	13/08/2009 (Man. Year: 2009)	Chassis No: J200E0027080
Colour:	Metallic Black	Odometer: 129260 km
Engine Capacity:	1495 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/65 R16	Rear Tyre Size:	225/65 R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,230.17	2,959.57	2,270.60	43.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,520.00	2,680.00	63.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,430.17</b>	<b>4,479.57</b>	<b>4,950.60</b>	<b>52.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,550.00</b>		
(S\$)	9,430.17	3,550.00	5,880.17	62.35
<b>+ GST 7.00/7.00% (S\$)</b>	<b>660.11</b>	<b>248.50</b>	<b>411.61</b>	<b>62.35</b>
<b>Nett Amount (S\$)</b>	<b>10,090.28</b>	<b>3,798.50</b>	<b>6,291.78</b>	<b>62.35</b>

#### INSPECTION

Date of Assignment:	23/01/2019	
Date Inspected:	23/01/2019 Inspected At:	C.s Ong Auto Pte Ltd (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #02-16 AMK AUTOPOINT Singapore 56804
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)	
<b>Parts:</b> M1-SUV	TOYOTA RUSH 1.5 X (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SMD1271C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR TAIL GATE	Bent	1,189.00 FL	*1,189.00 FL	
2	2		*REAR TAIL GATE RUBBER STOPPER	Serviceable	20.40 FL	*- FL	
3	2		*REAR TAIL GATE UPPER & LOWER HINGES	Repair	281.92 FL	*- FL	
4	1		*REAR TAIL GATE INNER WEATHERSTRIP RUBBER	Serviceable	316.60 FL	*- FL	
5	1		*REAR TAILGATE INNER LOCK	Repair	148.96 FL	*- FL	
6	1		*REAR TAILGATE INNER TRIM BOARD	Repair	469.85 FL	*- FL	
7	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Serviceable	35.00 FL	*- FL	
8	1		*REAR SPARE TYRE INNER HOLDER GARNISH	Cracked	405.80 FL	*405.80 FL	
9	1		*REAR SPARE TYRE COVER	Cracked	1,536.10 FL	*1,536.10 FL	
10	1		*REAR BUMPER	Buckled	780.20 FL	*780.20 FL	
11	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL	
12	2		*REAR BUMPER SIDE RETAINER	Serviceable	83.16 FL	*- FL	
13	2		*REAR BUMPER RH & LH REFLECTOR	Serviceable	100.38 FL	*- FL	
14	1		*REAR END PANEL	Repair	268.94 FL	*- FL	
15	1		*SET REAR END PANEL INNER TOP TRIM GARNISH WITH CLIPS	Serviceable	128.92 FL	*- FL	
16	1		*SET REAR NUMBER PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS	
17	1		*SET REAR END PANEL SEALANTS	Not Necessary	100.00 FS	*- FS	
18	1		*REAR REVERSE CAMERA	Serviceable	400.00 FS	*- FS	
19	2		*REAR REVERSE SENSOR	Serviceable	300.00 FS	*- FS	
					<b>Sub Total (\$\$)</b>	<b>6,680.23</b>	<b>3,946.10</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,450.06</b>	<b>986.53</b>
					<b>Total Parts (\$\$)</b>	<b>5,230.17</b>	<b>2,959.57</b>

F=Franchise part. S=SpcNett. L=ListItemDisc

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE REAR WINDSCREEN TO FACILITATE REPAIR	New	200.00	120.00
2	TO REMOVE REAR INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIR	New	300.00	0.00
3	TO CUT & REMOVE ALL REAR DAMAGED PANELS ,REPLACE NEW PARTS ,REFIT AND TO REALIGN ALL OF THE ABOVE ITEMS	New	1,500.00	500.00
4	TO PUTTY & RE-SPRAY NEW PAINTWORK ON ALL REAR AFFECTED AREAS	New	1,500.00	800.00
5	TO CONDUCT A CHECK ON ALL WIRING SYSTEMS	New	200.00	20.00
6	TO REPLACE AND REFIT REAR REVERSE SENSORS ON NEW REAR BUMPER	New	200.00	50.00
7	TO ANTI RUST ALL AFFECTED AREAS	New	300.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>4,200.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >