

22/03/2002

ASS. REC. BY:

REF

CS/INC19001504/Tlgd302

Special Instruction:

Surveyor

Taublich

ASSIGNMENT (Office)

From (Person):

Daniel Koh

of

INC

Date/Time:

23/1/19 @ 10:08am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KS927X

Insured:

8KX6165L

at Workshop m/s

Torque 5

Tel:

81316318

of

8 kaki Bukit Ave 4 #01-49

Policy No:

Claim No:

MT-1028915-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/1/2019

CA / REV / REP. / REV 24 HRS

1up)

H.O.D. Endorsement:

Date/Time:

10:00am @ 23/1/19

Person Contacted:

Stephanie

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	8KS927X-X
	8KX6165L-X

No

photo

upload

24/1

Tanjah

REF: INC

ASSIGNMENT

From:

Date:

30/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKS 927X

at Workshop m/s

Torque 5

of

8 Kaki Bukit Ave 4 #01-49

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SKS 927X

Yr Regn

2015 March

Type: M/Cas / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki Swift GLX 1.4 c.c.

1372

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

68378

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SSAF EC82500316361

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6

mm

L/Bal.

6 mm

L/Bal.

6

mm

D.O.A.

D.O.L.

23/1/19 1229pm

Survey held at

Torque 5

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt + N/S, U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/5/19

c/s \$5000, 6 days. Cited # 7649, 60%

RECEIVED 08 MAY 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 08/5 Torque

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

) S

TOTAL

250

250

Report Format :

Lump Sum / I.B.F. (\$)

7P
5000

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Wednesday, 23 January 2019 10:08 AM
To: 'assignments@lkkauto.com'
Cc: Toh Choon Hin; Thio Tse Kiat
Subject: FW: TP CASE FARMED OUT TO LKK ON 23/1/2019

Dear Veron / Catherine,

Please assist to survey the vehicles as per Mr Toh's / Tse Kiat instruction :-

S/NO	THIRD PARTY	OUR INSURED	WORKSHOP / CONTACT	DOA / REF / OFFICER	TIMING
1	SJT6991B	SFN7776D	TORQUE 5 PTE LTD / Lucas 81316318	18-1-2019 / MT-1028659-001	11:00-11:00
2	SKS927X	SKX6165L	TORQUE 5 PTE LTD / Lucas 81316318	22-1-2019 / MT-1028915-002 / Chryllis Quah	
3	SJZ7323S	FBG2003T	YOU YI AUTOMOBILE / Chris 67021555	18-1-2019 / MT-1029081-001 / Muhammad Airwan	

Please contact workshops.

Please ack.

Thank You

Daniel Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7901
www.income.com.sg

income

made different



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shiau Chan (LKKAuto)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Tuesday, 7 May 2019 1:24 PM
To: Taufikh (LKKAuto)
Cc: 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com
Subject: RE: SKS927X COR
Attachments: image010.wmz

Dear Taufikh ,



We hereby confirm the COR \$5000 with 06 days .

Thank you .

Warmest Regards,

Lucas Chow

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584
Mobile (65) 8131 6518
Email lucas.chow@torque5.com
Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8842E
Vehicle Details	
Vehicle No.:	SKS927X
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jan 2019
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT GLX 1.4 AT
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	K14B1104690
Chassis No.:	JSAFZC82S00316361
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$10,794.00
Original Registration Date:	26 Mar 2015
First Registration Date:	26 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$5,794.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2025
PARF Rebate Amount:	\$4,345.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,199.00
COE Rebate Amount:	\$35,303.00
Total Rebate Amount:	\$39,648.00

The information contained herein is correct as at 23 Jan 2019

OK

- 8th Gen Toyota Camry (XV70)
- Military talk thread
- Beware of scammers

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**New 5 Years Coe Renewal Toyota Altis 1.6A**

\$2700 Driveaway (inc: 1 Yr Insurance & Adv) 2.88%p.a
Monthly \$568 By Gv Finance
GV Credit Pte Ltd [Star Ad](#)

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD. GROUP OF COMPANIES)
With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

[Browse by Category](#)[Sort by Date Posted](#)[20 results/page](#)

2 vehicles

Suzuki Swift 1.4

[Advanced Search](#) [Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Suzuki Swift 1.4		Any	Any	2016	Any	Any	Any	Available
	Suzuki Swift 1.4A GLX		\$54,666	\$6,640 /yr	25-May-2016	1,372 cc	37,000 km	Hatchback	Available
	Various Loan Package To Cater Your Requirement, Hassle Free With Motor Workshop Service, Extended Warranty Available. Low Mileage At 37K Km. Almost New Car Feels Inside Out, Accident Free And Zero Wea...								
	Creative Auto								
	Posted: 10-Jan-2019 Tags: 2016 Suzuki Swift, 2016 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								
	Suzuki Swift 1.4A Special Edition		\$53,000	\$6,540 /yr	24-Mar-2016	1,372 cc	30,000 km	Hatchback	Available
	1 Owner, Agent Unit With Agent Warranty Till March 2019 And Full Service History With Champion Motors Since Day 1. Only Special Edition Unit In The Market. Flawless Condition In And Out. Welcome STA E...								
	Bavarian Marques Pte Ltd								
	Posted: 13-Dec-2018 Tags: 2016 Suzuki Swift, 2016 suzuki swift, Suzuki Swift, suzuki swift, Suzuki, Swift, swift, Used Suzuki								

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

[For old advertisements, view Expired ads](#)[20 results/page](#)
[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sport cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Suzuki Swift 1.4, Suzuki Swift 1.4 Singapore, used Suzuki Swift 1.4 Singapore, used Suzuki Swift 1.4, used vehicles Singapore or even buy used Suzuki Swift 1.4 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#)
[Careers](#)
[Contact Us](#)
[Sitemap](#)
[Terms of Service](#)
[Privacy Policy](#)
[Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 22/01/2019 (dd/mm/yy) Time of Accident: 07:45 (24-HR-FORMAT)
Vehicle No.: SKS 927X Vehicle Make & Model: Suzuki Swift GLX 1.4 AT
Exact location of Accident: Northvale Condo Carpark
Policyholder's Name / IC No.: Pang Sang Choi / S2508842E
Driver's Name / IC No.: Lee Shiao Ming / S25088416 (As Above) ☐
Driver's Contact No.: 9678 9543 Company Contact No.: _____
Driver's Address: 73 Choa Chu Kang Loop #11-08 Singapore 689674
Insurance Company: Tokio Marine Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please **TICK** one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

☒ Private use / ☐ Work purpose

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

No. of Passengers (Including Driver): 01

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: _____ Vehicle No.: SKX 6165L

Driver's Contact No.: _____ Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No.: _____

Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No.: _____

Preferred Workshop Name: _____ Contact No.: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' was travelling on the stated venue. I was travelling straight in my lane, suddenly vehicle 'B' on the left came at a very fast speed had collided against my vehicle front left portion.

I wish to state that vehicle 'B' did not stop behind the stop line before moving forward.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS927X

Estimation No. : E19010027

Make & Model : SUZUKI,SWIFT GLX 1.4 AT,JSAFZC82S00316361 DOA

: 22/01/2019

Year of : 2015

Manufacture

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper <i>de ✓</i>	1.00	0.00	0.00
2	Front bumper lower grille ✕	1.00	0.00	0.00
3	Front bumper retainer (LH) <i>new</i>	1.00	0.00	0.00
4	Front bumper retainer (RH) ✕	1.00	0.00	0.00
5	Front bumper sponge ✕	1.00	0.00	0.00
6	Front bumper reinforcement ✕	1.00	0.00	0.00
7	Front bumper lower beam ✕	1.00	0.00	0.00
8	Radiator grille ✕	1.00	0.00	0.00
9	Radiator grille emblem - Logo ✕	1.00	0.00	0.00
10	Fog lamp garnish (LH) <i>de ✓</i>	1.00	0.00	0.00
11	Fog lamp (LH) <i>new</i>	1.00	0.00	0.00
12	Day light lamp (LH) <i>new</i>	1.00	0.00	0.00
13	Bonnet <i>Ry</i>	1.00	0.00	0.00
14	Bonnet lock ✕	1.00	0.00	0.00
15	Bonnet insulator ✕	1.00	0.00	0.00
16	Head lamp (LH) <i>new</i>	1.00	0.00	0.00
17	Head lamp bracket (LH) <i>new</i>	1.00	0.00	0.00
18	Front fender (LH) <i>new</i>	1.00	0.00	0.00
19	Front fender inner shield (LH) <i>de ✓</i>	1.00	0.00	0.00
20	Front support top panel <i>Ry</i>	1.00	0.00	0.00
21	Front support panel <i>Ry</i>	1.00	0.00	0.00
22	Head lamp panel (LH) <i>bb ✓</i>	1.00	0.00	0.00
23	Front wheel rim (LH) <i>at ✓</i>	1.00	0.00	0.00
24	Front absorber (LH) ?	1.00	0.00	0.00
25	Absorber top mounting (LH) ?	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS927X

Estimation No. : E19010027

Make & Model : SUZUKI,SWIFT GLX 1.4 AT,JSAFZC82S00316361

DOA : 22/01/2019

Year of : 2015

Manufacture

No	Description	Qty	U/P	Amt
26	Front knuckle arm (LH) ?	1.00	0.00	0.00
27	Front knuckle bearing (LH) ?	1.00	0.00	0.00
28	Front lower arm (LH) ?	1.00	0.00	0.00
29	Front door (LH) X	1.00	0.00	0.00
30	Bonnet hinge (LH) Ry	1.00	0.00	0.00
31	Bonnet hinge (RH) Ry	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

32	Front bumper clip set	1.00	45.00	45.00 30. net
33	Front fender inner shield clip set	1.00	45.00	45.00 20 net
34	Front tyre (LH)	1.00	220.00	220.00 X
35	Front number plate & casing	1.00	45.00	45.00 X
36	Bonnet insulator clip set	1.00	45.00	45.00 X

Amt S\$ 400.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 400.00

Section: Labour Items

37	To check wiring & lighting system	1.00	80.00	80.00 30.
38	To supply under-coating / putty on parts replaced	1.00	60.00	60.00 30.
39	To perform anti-rust treatment on affected areas	1.00	60.00	60.00 30.
40	To conduct all wheel alignment before & after	1.00	160.00	160.00 80.
41	To conduct head lamp focus	1.00	60.00	60.00 30.
42	To R&R front LH under-carriage damaged parts	1.00	350.00	350.00 120? plus
43	To R&R front LH wheel rim, tyre & balacing	1.00	50.00	50.00 30

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS927X
Make & Model : SUZUKI, SWIFT GLX 1.4 AT, JSAFZC82S00316361
Year of Manufacture : 2015
Estimation No. : E19010027
DOA : 22/01/2019

No	Description	Qty	U/P	Amt
44	To repair, replace and realign damaged areas	1.00	1,400.00	1,400.00
45	To spray painting on affected areas	1.00	1,200.00	1,200.00

Amt S\$ 3,420.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 3,420.00

John
25/1/19

Tanfer 67418134
97495749.

wp 23/1/19 1200pm

lumpsum

Resurvey after repair

sure @ 14 days max.

06 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00

Special Nett Items S\$ 400.00

Subtotal

Labour Items Subtotal S\$

3,420.00

Total

S\$

3,820.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS927X

Estimation No. : E19010027

Make & Model : SUZUKI, SWIFT GLX 1.4 AT, JSAFZC82S00316361 DOA

: 22/01/2019

Year of : 2015

Manufacture

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Front bumper <i>de</i> ✓	1.00	0.00 860.00	0.00 659.55
2	Front bumper lower grille <i>x un</i>	1.00	0.00	0.00
3	Front bumper retainer (LH) <i>na</i>	1.00	0.00 36.00	0.00
4	Front bumper retainer (RH) <i>x un</i>	1.00	0.00 36.00	0.00
5	Front bumper sponge <i>x un</i>	1.00	0.00	0.00
6	Front bumper reinforcement <i>x un</i>	1.00	0.00	0.00
7	Front bumper lower beam <i>x un</i>	1.00	0.00	0.00
8	Radiator grille <i>x un</i> <i>24/1/19</i>	1.00	0.00 180.00	0.00
9	Radiator grille emblem - Logo <i>x un</i>	1.00	0.00 40.00	0.00
10	Fog lamp garnish (LH) <i>de</i> ✓	1.00	0.00 58.00	0.00
11	Fog lamp (LH) <i>na</i>	1.00	0.00 320.00	0.00 196
12	Day light lamp (LH) <i>na</i> ✓	1.00	0.00 679.20	0.00 565.35
13	Bonnet <i>Ry</i>	1.00	0.00	0.00
14	Bonnet lock <i>x un</i>	1.00	0.00	0.00
15	Bonnet insulator <i>x un</i>	1.00	0.00	0.00
16	Head lamp (LH) <i>na</i> ✓	1.00	0.00 630.00	0.00 510
17	Head lamp bracket (LH) <i>na</i> ✓	1.00	0.00 107.50	0.00
18	Front fender (LH) <i>blue</i> ✓	1.00	0.00 330.00	0.00
19	Front fender inner shield (LH) <i>de</i> ✓	1.00	0.00 198.00	0.00
20	Front support top panel <i>Ry</i>	1.00	0.00	0.00
21	Front support panel <i>Ry</i>	1.00	0.00	0.00
22	Head lamp panel (LH) <i>kt</i> ✓	1.00	0.00 85.00	0.00
23	Front wheel rim (LH) <i>at</i> ✓	1.00	0.00 650.00	0.00 350
24	Front absorber (LH) <i>?</i> ✓	1.00	0.00 370.00	0.00 <i>x un</i>
25	Absorber top mounting (LH) <i>?x</i>	1.00	0.00 97.00	0.00 <i>x un</i>

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS927X
Make & Model : SUZUKI, SWIFT GLX 1.4 AT, JSAFZC82500316361 DOA
Year of : 2015
Manufacture :
Estimation No. : E19010027
Date : 22/01/2019

No	Description	Qty	U/P	Amt	
26	Front knuckle arm (LH) ? /	1.00	0.00	420.00	0.00 bt
27	Front knuckle bearing (LH) ? /	1.00	0.00	183.80	0.00 bt
28	Front lower arm (LH) ? /	1.00	0.00	340.00	0.00 bt
29	Front door (LH) X ny	1.00	0.00	0.00	
30	Bonnet hinge (LH) Ry	1.00	0.00	0.00	
31	Bonnet hinge (RH) Ry	1.00	0.00	0.00	
				Amt	S\$ 0.00
				Discount (0.00%)	S\$ 0.00
				Subtotal	S\$ 0.00

Section: Special Nett Items

32	Front bumper clip set	1.00	45.00	45.00	30.00
33	Front fender inner shield clip set	1.00	45.00	45.00	30.00
34	Front tyre (LH)	1.00	220.00	220.00	X ny
35	Front number plate & casing	1.00	45.00	45.00	X ny
36	Bonnet insulator clip set	1.00	45.00	45.00	X ny
				Amt	S\$ 400.00
				Discount (0.00%)	S\$ 0.00
				Subtotal	S\$ 400.00

Section: Labour Items

37	To check wiring & lighting system	1.00	80.00	80.00	30.00
38	To supply under-coating / putty on parts replaced	1.00	60.00	60.00	30.00
39	To perform anti-rust treatment on affected areas	1.00	60.00	60.00	30.00
40	To conduct all wheel alignment before & after	1.00	160.00	160.00	80.00
41	To conduct head lamp focus	1.00	60.00	60.00	30.00
42	To R&R front LH under-carriage damaged parts	1.00	350.00	350.00	120.00 plus
43	To R&R front LH wheel rim, tyre & balacing	1.00	50.00	50.00	30.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS927X
Make & Model : SUZUKI, SWIFT GLX 1.4 AT, JSAFZC82S00316361 DOA
Year of : 2015
Manufacture :
Estimation No. : E19010027
: 22/01/2019

No	Description	Qty	U/P	Amt
44	To repair, replace and realign damaged areas	1.00	1,400.00	1,400.00
45	To spray painting on affected areas	1.00	1,200.00	1,200.00
				Amt S\$ 3,420.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,420.00

Tanfer 67418134
97495749.
WP 23/1/17C 1200p
Lumpsum
Resumy after repair
sure @ 11hants.com.
06 days.

9435.50
3713.50
12649

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 400.00
Labour Items Subtotal S\$ 3,420.00
Total S\$ 3,820.00



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SKS927X
Make & Model : SUZUKI, SWIFT GLX 1.4 AT, JSAFZC82S00316361 DOA
Year of Manufacture : 2015
Estimation No. : E19010033
Date : 22/01/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Reinforcement garnish <i>ca</i> ✓	1.00	0.00	120.00 0.00
2	Head lamp panel (LH) <i>bt</i> ✓	1.00	0.00	68.00 0.00
3	Front bumper under cover <i>ca</i> ✓	1.00	0.00	212.00 0.00
4	Front bumper bracket (LH) <i>de</i> ✓	1.00	0.00	36.00 0.00
5	Radiator ? /	1.00	0.00	920.00 0.00 <i>x nn</i>
6	A/C condenser ? /	1.00	0.00	685.00 0.00 <i>x nn</i>
7	Radiator fan motor & cowling set ? /	1.00	0.00	542.50 0.00 <i>x nn</i>
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items				
8	Engine coolant ? /	1.00	120.00	120.00 <i>x nn</i>
9	Auto transmission fluid 1 litre ? /	1.00	80.00	80.00 <i>x nn</i>
10	A/C condenser o'ring set ? /	1.00	30.00	30.00 <i>x nn</i>
				Amt S\$ 230.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 230.00

Section: Labour Items				
11	To R&R A/C condenser, radiator assy ? /	1.00	300.00	300.00 <i>x nn</i>
12	To top up 134a refrigerant ? /	1.00	100.00	100.00 <i>x nn</i>
				Amt S\$ 400.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 400.00

Parts = 8071 - 15% AAA
= 6860.35

S/N = 280

Labour = 1960

P + S + L = 9100.35 - 20% L/S
= \$ 7300

24/1/19

15%
4159.20
936
5095.20
4330.92
50
1750
180
6370.92

List Items Subtotal S\$ 0.00
Special Nett Items S\$ 230.00
Subtotal
Labour Items Subtotal S\$ 400.00
Total S\$ 630.00

17649

MOTOR STOP PTE LTD
NO 8 KAKI BUKIT AVENUE 4
PREMIER@KAKI BUKIT
#01-07 SINGAPORE 415875

TEL: 93261342

FAX: 64524584

EMAIL: motorstopoffice@gmail.com

Order: R003557
Vehicle: SKS927X
Date: 24.1.19 14:42

Vehicle: Swift : AZG412/AZG413D/AZG416 (2011-) : Type 4 (500001-) : Front Wheel Drive (except K12B DUALJE
Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-0°48'	-1°02'	-1°12' 0°48'
5°09'	5°09'	3°12' 7°12'
0°04'	0°05'	-0°02' 0°08'
13°47'	14°00'	10°54' 14°54'
12°59'	12°59'	9°42' 15°42'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°36'	-0°31'	-1°12' 0°48'
5°02'	5°02'	3°12' 7°12'
0°04'	0°01'	-0°02' 0°08'
13°06'	13°02'	10°54' 14°54'
12°31'	12°31'	9°42' 15°42'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°13'	-0°31'	
0°07'	0°07'	
0°41'	0°59'	
0°07'	0°06'	-0°04' 0°16'

Rear : Left

Actual	Before	Specified Range
-1°06'	-1°14'	-2°15' -0°15'
0°11'	0°11'	-0°01' 0°25'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°00'	-0°56'	-2°15' -0°15'
0°13'	0°15'	-0°01' 0°25'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°07'	-0°18'	
0°24'	0°26'	-0°02' 0°50'
-0°01'	-0°02'	

MOTOR STOP PTE LTD
NO 8 KAKI BUKIT AVENUE 4
PREMIER@KAKI BUKIT
#01-07 SINGAPORE 415875

TEL: 93261342

FAX: 64524584

EMAIL: motorstopoffice@gmail.com

Order: R003553
se: SKS927X
 23.1.19 15:19

iki : Swift : AZG412/AZG413D/AZG416 (2011-) : Type 4 (500001-) : Front Wheel Drive (except K12B DUALJE Thrust Line Alignment

Front : Left

Actual	Before	Specified Range
-1°22'	-1°22'	-1°12' 0°48'
4°49'	4°49'	3°12' 7°12'
0°06'	0°06'	-0°02' 0°08'
14°24'	14°24'	10°54' 14°54'
13°02'	13°02'	9°42' 15°42'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°37'	-0°39'	-1°12' 0°48'
4°38'	4°38'	3°12' 7°12'
-0°19'	-0°16'	-0°02' 0°08'
13°33'	13°34'	10°54' 14°54'
12°56'	12°56'	9°42' 15°42'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°45'	-0°43'	
0°12'	0°12'	
0°51'	0°49'	
-0°13'	-0°09'	-0°04' 0°16'

Rear : Left

Actual	Before	Specified Range
-1°04'	-1°04'	-2°15' -0°15'
0°14'	0°14'	-0°01' 0°25'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°58'	-0°58'	-2°15' -0°15'
0°10'	0°11'	-0°01' 0°25'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-0°05'	-0°05'	
0°24'	0°24'	-0°02' 0°50'
0°02'	0°02'	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19001504/T1qd3e2

73 BRAS BASAH ROAD

Date: 09-05-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 6165L	Veh. Inspected	SKS 927X
Policy No.		Coverage (\$)	0.00
Claim No.	MT-1028915-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	23/01/2019

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SWIFT GLX 1.4	c.c	1372
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JSAFZC82S00316361	Colour	BLUE
Odometer	68378 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	185/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	185/55 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/01/2019	Inspect Date / Time	23/01/2019 (12:29 PM)
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 927X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	860.00	659.55
1	FRONT BUMPER LOWER GRILLE (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER RETAINER (LH)	NECESSARY	36.00	36.00
1	FRONT BUMPER RETAINER (RH)	NOT NECESSARY	36.00	-
1	FRONT BUMPER SPONGE (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER REINFORCEMENT (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER LOWER BEAM (NPA)	NOT NECESSARY	-	-
1	RADIATOR GRILLE	CRACKED	180.00	180.00
1	RADIATOR GRILLE EMBLEM - LOGO	NECESSARY	40.00	40.00
1	FOG LAMP GARNISH (LH)	DEFORMED	58.00	58.00
1	FOG LAMP (LH)	CRACKED	320.00	196.00
1	DAY LIGHT LAMP (LH)	CRACKED	679.20	565.35
1	BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	BONNET LOCK (NPA)	NOT NECESSARY	-	-
1	BONNET INSULATOR (NPA)	NOT NECESSARY	-	-
1	HEAD LAMP (LH)	CRACKED	630.00	510.00
1	HEAD LAMP BRACKET (LH)	NECESSARY	107.50	107.50
1	FRONT FENDER (LH)	BUCKLED	330.00	330.00
1	FRONT FENDER INNER SHIELD (LH)	DEFORMED	198.00	198.00
1	FRONT SUPPORT TOP PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT SUPPORT PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
1	HEAD LAMP PANEL (LH)	BENT	85.00	85.00
1	FRONT WHEEL RIM (LH)	CUT	650.00	350.00
1	FRONT ABSORBER (LH)	NOT NECESSARY	370.00	-
1	ABSORBER TOP MOUNTING (LH)	NOT NECESSARY	92.00	-
1	FRONT KNUCKLE ARM (LH)	BENT	420.00	320.00
1	FRONT KNUCKLE BEARING (LH)	BENT	183.80	183.80
1	FRONT LOWER ARM (LH)	BENT	340.00	340.00
1	FRONT DOOR (LH) (NPA)	NOT NECESSARY	-	-

Report Ref No. CS/INC19001504/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE (LH) (NPA)	TO REPAIR SEE LABOUR	-	-
1	BONNET HINGE (RH) (NPA)	TO REPAIR SEE LABOUR	-	-
1	REINFORCEMENT GARNISH (ADDITIONAL)	CRACKED	120.00	120.00
1	HEAD LAMP PANEL (LH) (ADDITIONAL)	BENT	68.00	68.00
1	FRONT BUMPER UNDER COVER (ADDITIONAL)	CRACKED	212.00	212.00
1	FRONT BUMPER BRACKET (LH) (ADDITIONAL)	DEFORMED	36.00	36.00
1	RADIATOR (ADDITIONAL)	NOT NECESSARY	920.00	-
1	A/C CONDENSER (ADDITIONAL)	BENT	685.00	500.00
1	SET RADIATOR FAN MOTOR & COWLING (ADDITIONAL)	NOT NECESSARY	542.50	-
	LESS 15% DISCOUNT		-	-764.28
			8,199.00	4,330.92
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	45.00	20.00
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	220.00	-
1	FRONT NUMBER PLATE & CASING (SN)	NOT NECESSARY	45.00	-
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	45.00	-
1	ENGINE COOLANT (SN) (ADDITIONAL)	NOT NECESSARY	120.00	-
1	AUTO TRANSMISSION FLUID 1 LITRE (SN) (ADDITIONAL)	NOT NECESSARY	80.00	-
1	SET A/C CONDENSER O'RING (SN) (ADDITIONAL)	NOT NECESSARY	30.00	-
			630.00	50.00
	<u>LABOUR</u>			
	TO CHECK WIRING & LIGHTING SYSTEM.		80.00	30.00
	TO SUPPLY UNDER-COATING / PUTTY ON PARTS REPLACED.		60.00	30.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		60.00	30.00
	TO CONDUCT ALL WHEEL ALIGNMENT BEFORE & AFTER.		160.00	80.00
	TO CONDUCT HEAD LAMP FOCUS.		60.00	30.00
	TO R&R FRONT LH UNDER-CARRIAGE DAMAGED PARTS.		350.00	120.00

Report Ref No. CS/INC19001504/T1qd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO R&R FRONT LH WHEEL RIM, TYRE & BALANCING.		50.00	30.00
	TO REPAIR, REPLACE AND REALIGN DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF BONNET, FRONT SUPPORT TOP PANEL, FRONT SUPPORT PANEL, BONNET HINGE (LH) AND BONNET HINGE (RH).		1,400.00	700.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		1,200.00	700.00
	TO R&R A/C CONDENSER, RADIATOR ASSY. (ADDITIONAL)		300.00	100.00
	TO TOP UP 134A REFRIGERANT. (ADDITIONAL)		100.00	80.00
			3,820.00	1,930.00
GRAND TOTAL			12,649.00	6,310.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				5,000.00

Report Ref No. CS/INC19001504/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.